

REPORT NO: ER/2005/80027 DATE: Oct. 19, 2005



APPENDIX 3


PHOTOGRPHS OF EUT



REPORT NO: ER/2005/80027 DATE: Oct. 19, 2005



Open View of EUT



Internal of EUT -1



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

t (886-2) 2299-3939

f (886-2) 2298-2698


www.sgs.com.tw




REPORT NO: ER/2005/80027 DATE: Oct. 19, 2005



Internal of EUT-2



Internal of EUT-3



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw




REPORT NO: ER/2005/80027 DATE: Oct. 19, 2005



Internal of EUT-4



Internal of EUT-5



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw



REPORT NO: ER/2005/80027 DATE: Oct. 19, 2005



Internal of EUT-6

