Client: OSLINK Sp. z o.o.
Model: OSBRIDGE 5GXi
FCC ID: UEV-5GXI
Standard: FCC 15.247
Report #: 2007118

Appendix I: Test Photographs




Photograph 3: Conducted Emissions Front View

Client: OSLINK Sp. z o.o.
Model: OSBRIDGE 5GXi
FCC ID: UEV-5GXI
Standard: FCC 15.247
Report #: 2007118



Photograph 4: Conducted Emissions Rear View

Client: OSLINK Sp. z o.o.
Model: OSBRIDGE 5GXi
FCC ID: UEV-5GXI
Standard: FCC 15.247
Report #: 2007118



Photograph 5: Radiated Emissions Front View

Client: OSLINK Sp. z o.o.
Model: OSBRIDGE 5GXi
FCC ID: UEV-5GXI
Standard: FCC 15.247
Report #: 2007118



Photograph 6: Radiated Emissions Rear View