UbiDuo

FCC ID#: UPQ-UBI200A


Photo One A – Internal Open for Inspection



UbiDuo

FCC ID#: UPQ-UBI200A


Photo One B – Internal Open for Inspection



UbiDuo

FCC ID#: UPQ-UBI200A


Photo Two - Internal Right Side of RF Section, Shielded



UbiDuo


FCC ID#: UPQ-UBI200A

Photo Three – Internal Left Side of RF Section




UbiDuo FCC ID#: UPQ-UBI200A

Photo Four – Internal Close-Up of RF Section, Right Side, Shielded




UbiDuo FCC ID#: UPQ-UBI200A

Photo Five – Internal Close-up of RF Section, Right Side, Shield Removed



UbiDuo FCC ID#: UPQ-UBI200A

Photo Six – Internal Close-up of RF Section, Middle



UbiDuo FCC ID#: UPQ-UBI 200A

Photo Seven – Internal Close-up of RF Section, Left Side

