

Report No.: 0716764

Model No.: 24886


Sample No.: 1/I

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement



RBW 3 MHz Delta 1 [T1]
 *VBW 3 MHz 0.01 dB
 Ref -10 dBm Att 20 dB SWT 75 ms 18.150000 ms

1 AP
 CLRWR



Center 27.145 MHz

7.5 ms/

Tested By: Paul
 (Chen Hs Y)

Date: 12/07/2007

Checked By: [Signature]
 (Gang Li)


Date: 12/7/07

Test Result : Pass / Fail (NA)

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement



RBW 3 MHz Delta 1 [T1]
 *VBW 3 MHz 0.01 dB
 Ref -10 dBm Att 20 dB SWT 20 ms 18.200000 ms



Tested By: [Signature]
 (Chen Hb YH)

Date: 12/07/2007

Checked By: [Signature]
 (Gang Li)


Date: 12/7/07

Test Result: Pass / Fail / NA

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement



RBW 3 MHz Delta 1 [T1]
 *VBW 3 MHz 0.03 dB
 Ref -10 dBm Att 20 dB SWT 20 ms 1.520000 ms



Tested By: (Chen Hg Yin)

Date: 12/07/2007


Checked By: (Gang Li)

Date: 12/7/07

Test Result : Pass / Fail / NA

Report No.: 0716764
Model No.: 24886
Sample No.: 1/1

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement



Tested By: hnd
(Olan Ho Yin)

Date: 12/07/2007

Checked By: Li
(Guy Li)

Date: 17/1/07

Test Result: Pass / Fail / NA