

 Prüfbericht - Nr.:
 50129425 001
 Seite 19 von 23


 Test Report No.
 Page 19 of 23

5.2 Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)



Photograph 2: Set-up for Spurious Emissions (Back View 1)






Products

Prüfbericht - Nr.: 50129425 001

Seite 20 von 23 *Page 20 of 23*

Test Report No.

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing





Products

Prüfbericht - Nr.: 50129425 001 Test Report No.

Seite 21 von 23 *Page 21 of 23*

Photograph 5: Set-up for Conducted testing





 Prüfbericht - Nr.:
 50129425 001
 Seite 22 von 23

 Test Report No.
 Page 22 of 23

Photograph 6: Set-up for Mains Emissions (Front View)



Photograph 7: Set-up for Mains Emissions (Back View)

