

 Prüfbericht - Nr.:
 10041102 001
 Seite 31 von 34

 Test Report No.
 Page 31 of 34

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)



Photograph 2: Set-up for Spurious Emissions (Back View 1)








Prüfbericht - Nr.: 10041102 001

Test Report No.

Seite 32 von 34 *Page 32 of 34*

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing






Prüfbericht - Nr.: 10041102 001

Seite 33 von 34 *Page 33 of 34*

Test Report No.

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

