

Produkte Products

Prüfbericht - Nr.: 10044136 001 Test Report No.

Seite 39 von 43 *Page 39 of 43*

6. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)





Produkte Products

Prüfbericht - Nr.: 10044136 001 Test Report No.

Seite 40 von 43 *Page 40 of 43*

Photograph 2: Set-up for Spurious Emissions (Back View 1)





Produkte Products

Prüfbericht - Nr.: 10044136 001 Test Report No.

Seite 41 von 43 *Page 41 of 43*

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing








 Prüfbericht - Nr.:
 10044136 001
 Seite 42 von 43

 Test Report No.
 Page 42 of 43

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

