

Produkte Products

 Prüfbericht - Nr.:
 10044135 001
 Seite 40 von 44

 Test Report No.
 Page 40 of 44

6. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)






Produkte Products

Prüfbericht - Nr.: 10044135 001 Test Report No.

Seite 41 von 44Page 41 of 44

Photograph 2: Set-up for Spurious Emissions (Back View 1)





Produkte Products

Prüfbericht - Nr.: 10044135 001
Test Report No.

Seite 42 von 44Page 42 of 44

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing








 Prüfbericht - Nr.:
 10044135 001
 Seite 43 von 44

 Test Report No.
 Page 43 of 44

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

