Attachment 1 Photographs of the Test Configurations

No. 11, Lane 41, Fushuen St., Jungshan Chiu, Taipei, Taiwan, 104, R.O.C.

TEL.: 886-2-25984542 FAX.: 886-2-25984546 Report No.: RF- U070-1001-065

Radiated Emission Measurement

X axis




Y axis



TEL.: 886-2-25984542 FAX.: 886-2-25984546


Z axis



CENTRAL RESEARCH TECHNOLOGY CO.
No. 11, Lane 41, Fushuen St., Jungshan Chiu, Taipei, Taiwan, 104, R.O.C.
TEL.: 886-2-25984542
FAX.: 886-2-25984546

Conducted Emission Measurement





TEL.: 886-2-25984542 FAX.: 886-2-25984546