


Prüfbericht - Nr.: 15080186 001

Test Report No.

Seite 1 von 3
Page 1 of 3

## **Appendix II- Photographs of the Test Set-Up**

Photograph 1: Set-up for Conducted RF test at Antenna Port







Prüfbericht - Nr.: 15080186 001

Test Report No.


Seite 2 von 3 Page 2 of 3

Photograph 2: Set-up for Spurious Emissions below 1GHz









Produkte Products

Prüfbericht - Nr.: 15080186 001 Test Report No.

Seite 3 von 3
Page 3 of 3

Photograph 4: Set-up for Conducted Emission Test

