Report No. :FA611201-01


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 





Left Cheek

**Left Tilted** 

TEL: 86-029-8860-8767 / FAX: 86-029-8860-8791

Issued Date : Apr. 27, 2016 FCC ID: XAPGM5PLUS Page D1 of D3 Form version. : 151208





Front, Test Separation 10 mm



Report No. : FA611201-01

Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

TEL: 86-029-8860-8767 / FAX: 86-029-8860-8791

Issued Date: Apr. 27, 2016 Form version. : 151208 FCC ID: XAPGM5PLUS Page D2 of D3



Report No. : FA611201-01

Bottom Side, Test Separation 0 mm