


 Prüfbericht - Nr.:
 17032143 002
 Seite 166 von 168

 Test Report No.
 Page 166 of 168

6. Photographs of the Test Set-Up

Photograph 1: Setup for Spurious Emissions testing for below 1GHz



Photograph 2: Setup for Spurious Emissions testing for 1 - 18GHz





Products

Prüfbericht - Nr.: 17032143 002

Seite 167 von 168Page 167 of 168

Test Report No.

Photograph 3: Setup for Spurious Emissions testing for 18 - 26.5GHz



Photograph 4: Setup for Conducted disturbance

