


 Prüfbericht - Nr.:
 17032143 002
 Seite 198 von 201


 Test Report No.
 Page 198 of 201

## 6. Photographs of the Test Set-Up

Photograph 1: Setup for Spurious Emissions testing for below 1GHz



Photograph 2: Setup for Spurious Emissions testing for 1 - 18GHz






Products

Prüfbericht - Nr.: 17032143 002


Test Report No.

**Seite 199 von 201**Page 199 of 201

Photograph 3: Setup for Spurious Emissions testing for 18 - 26.5GHz



Photograph 4: Setup for Spurious Emissions testing for 26.5 - 40GHz





Produkte Products

Prüfbericht - Nr.: 17032143 002

**Seite 200 von 201**Page 200 of 201

Test Report No.

## Photograph 5: Setup for Conducted disturbance

