

 Prüfbericht - Nr.:
 17033717 001
 Seite 311 von 313


 Test Report No.
 Page 311 of 313

6. Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emissions



Photograph 2: Set-up for Spurious Emissions below 1GHz





Produkte Products

Prüfbericht - Nr.: 17033717 001

Seite 312 von 313 *Page 312 of 313*

Test Report No.

Photograph 3: Set-up for Spurious Emissions above 1GHz

