

Produkte Products

Prüfbericht - Nr.: 100437
Test Report No.

10043715 001

Seite 44 von 48 *Page 44 of 48*

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)





Produkte Products

Prüfbericht - Nr.: 10043715 001 Test Report No.

Seite 45 von 48 *Page 45 of 48*

Photograph 2: Set-up for Spurious Emissions (Back View 1)






Produkte Products


Prüfbericht - Nr.: 10043715 001 Test Report No.

Seite 46 von 48 *Page 46 of 48*

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Conducted testing





 Prüfbericht - Nr.:
 10043715 001
 Seite 47 von 48

 Test Report No.
 Page 47 of 48

Photograph 5: Set-up for for Mains Conducted testing Back



Photograph 6: Set-up for for Mains Conducted testing Front

