INTERNAL PHOTOCRAPHS	
INTERNAL PHOTOGRAPHS  This desument contains 7 photographs	
This document contains 7 photographs	


Photograph No.1 M800MGL magnet sensor (detector) internal view




## Photograph No.2 M800MGL magnet sensor (detector) view with battery




Photograph No.3 M800MGL magnet sensor (detector) with case removed



Photograph No.4 M800MGL magnet sensor (detector) with case removed



## Photograph No.5 M800MGL magnet sensor (detector) PCB front view



## Photograph No.6 M800MGL magnet sensor (detector) PCB second side view



## Photograph No.7 M800MGL magnet sensor (detector) PCB second side close view

