




#### 1.TEST PHOTOGRAPHS

## 1.1 Photos of power line conducted emission measurement




## 1.2. Photos of Radiated Emission Test (In Anechoic Chamber)

30~230MHz (X position)



230~1000MHz (X position)



Copyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

CENTRE OF TESTING SERVICE CO., LTD.

Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China Tel: +86-20-85543113 (32 lines) Fax: +86-20-38780406

Complaint line: +86-20-85533471 E-mail: cts@cts-lab.com.cn See Rev

See Reverse For Terms And Conditions of Service


**Report No.: C**GZ3101214-04363-O Page 1 of 2

#### **CENTRE OF TESTING SERVICE**






above 1000MHz (X position)



# 1.3. Band Edge Compliance Test

X position



Copyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

Complaint line: +86-20-85533471

E-mail: cts@cts-lab.com.cn

Page 2 of 2