

Reference No.:

Report No.: SZ100526B02-RP

PHOTOGRAPHS OF THE TEST CONFIGURATION

Radiated Emissions Setup Photos





FCC ID: YHD-SLY504 Page 1/2



Compliance Certification Services Inc.

Reference No.: Report No.: SZ090825B02-RP

Power Line Conducted Emissions Setup Photos





FCC ID: YHD-SLY504 Page 2