
Prüfbericht - Nr.:
 50087890 001
 Seite 28 von 31

 Test Report No.
 Page 28 of 31

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions TX (Front View)






Prüfbericht - Nr.: 50087890 001


Test Report No.

Seite 29 von 31Page 29 of 31

Photograph 2: Set-up for Spurious Emissions TX (Back View 1)



Photograph 3: Set-up for Spurious Emissions TX (Back View 2)






50087890 001 Prüfbericht - Nr.: Test Report No.

Seite 30 von 31 Page 30 of 31

Photograph 4: Set-up for Spurious EmissionsTX (Back View 3)



Photograph 5: Set-up for Conducted testing

