Produkte Products

> Prüfbericht - Nr.: 50117976 001

Test Report No.

Seite 14 von 17 Page 14 of 17

6. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)








Prüfbericht - Nr.: 50117976 001


Test Report No.

Seite 15 von 17 *Page 15 of 17*

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)






Prüfbericht - Nr.: 50117976 001

Test Report No.

Seite 16 von 17 *Page 16 of 17*

Photograph 4: Set-up for Spurious Emissions (Back View 3)



Photograph 5: Set-up for Spurious Emissions (Back View 4)

