

 Prüfbericht - Nr.:
 50299306 001
 Seite 46 von 50

 Test Report No.
 Page 46 of 50

Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)



Photograph 2: Set-up for Spurious Emissions (Back View 1)



Produkte Products

Prüfbericht - Nr.: 50299306 001


Test Report No.

Seite 47 von 50 *Page 47 of 50*

Photograph 3: Set-up for Spurious Emissions (Back View 2)



Photograph 4: Set-up for Spurious Emissions (Back View 3)







 Prüfbericht - Nr.:
 50299306 001
 Seite 48 von 50

 Test Report No.
 Page 48 of 50

Photograph 5: Set-up for Conducted testing



Photograph 6: Set-up for Conducted testing





Prüfbericht - Nr.: 50299306 001 Test Report No.

Seite 49 von 50Page 49 of 50

Photograph 7: Set-up for Mains Conducted testing (Back View)



Photograph 8: Set-up for Mains Conducted testing (Front View)

