

 Prüfbericht - Nr.:
 50296846 001
 Seite 34 von 38

 Test Report No.
 Page 34 of 38

## 7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View 1)



Photograph 2: Set-up for Spurious Emissions (Front View 2)





**Produkte Products** 

> Prüfbericht - Nr.: 50296846 001


Test Report No.

Seite 35 von 38 Page 35 of 38

Photograph 3: Set-up for Spurious Emissions (Back View 1)



Photograph 4: Set-up for Spurious Emissions (Back View 2)






**Produkte Products** 

Test Report No.


Prüfbericht - Nr.: 50296846 001

Seite 36 von 38 Page 36 of 38

Photograph 5: Set-up for Spurious Emissions (Back View 3)



Photograph 6: Set-up for Spurious Emissions (Back View 4)





50296846 001 Prüfbericht - Nr.: Test Report No.

Seite 37 von 38 Page 37 of 38

## Photograph 7: Set-up for Conducted testing



Photograph 8: Set-up for Conducted testing

