


Products

Prüfbericht - Nr.: 10051279 001
Test Report No.

**Seite 31 von 35** *Page 31 of 35* 

## 7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)






Prüfbericht - Nr.: 10051279 001


Test Report No.

**Seite 32 von 35** *Page 32 of 35* 

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)







 Prüfbericht - Nr.:
 10051279 001
 Seite 33 von 35

 Test Report No.
 Page 33 of 35

## Photograph 4: Set-up for Spurious Emissions - For IC (Front)



Photograph 5: Set-up for Spurious Emissions – For IC (Back)





Products

Prüfbericht - Nr.: 10051279 001

Test Report No.

**Seite 34 von 35** *Page 34 of 35* 

## Photograph 6: Set-up for Conducted testing

