


Produkte Products

> Prüfbericht - Nr.: 10055297 001 Seite 27 von 30 Page 27 of 30

Test Report No.

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)







 Prüfbericht - Nr.:
 10055297 001
 Seite 28 von 30

 Test Report No.
 Page 28 of 30

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)





Produkte Products

> 10055297 001 Prüfbericht - Nr.: Test Report No.

Seite 29 von 30 Page 29 of 30

Photograph 4: Set-up for Conducted testing

