Products


Prüfbericht - Nr.: 50117032 001

Seite 29 von 34 *Page 29 of 34*

Test Report No.

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View)






Products

Prüfbericht - Nr.: 50117032 001


Test Report No.


Seite 30 von 34 *Page 30 of 34*

Photograph 2: Set-up for Spurious Emissions (Back View 1)



Photograph 3: Set-up for Spurious Emissions (Back View 2)






Produkte Products

Test Report No.


Prüfbericht - Nr.: 50117032 001

Seite 31 von 34 Page 31 of 34

Photograph 4: Set-up for Spurious Emissions (Back View 3)



Photograph 5: Set-up for Spurious Emissions (Back View 4)









 Prüfbericht - Nr.:
 50117032 001
 Seite 32 von 34

 Test Report No.
 Page 32 of 34

Photograph 6: Set-up for Conducted testing I



Photograph 7: Set-up for Conducted testing II





Prüfbericht - Nr.: 50117032 001

Test Report No.

Seite 33 von 34 *Page 33 of 34*

Photograph 8: Set-up for Mains Conducted testing Back



Photograph 9: Set-up for Mains Conducted testing Front

