

Prüfbericht - Nr.: 50128210 001

Test Report No.

Seite 28 von 33 *Page 28 of 33*

7. Photographs of the Test Set-Up

Photograph 1: Set-up for Spurious Emissions (Front View 1)




Prüfbericht - Nr.: 50128210 001


Seite 29 von 33 *Page 29 of 33*

Test Report No.

Photograph 2: Set-up for Spurious Emissions (Front View 2)



Photograph 3: Set-up for Spurious Emissions (Back View 1)




Photograph 4: Set-up for Spurious Emissions (Back View 2)




Prüfbericht - Nr.: 50128210 001

Test Report No.

Seite 30 von 33 *Page 30 of 33*



Photograph 5: Set-up for Spurious Emissions (Back View 3)



Photograph 6: Set-up for Spurious Emissions (Back View 4)




Prüfbericht - Nr.: 50128210 001

Test Report No.

Seite 31 von 33 *Page 31 of 33*




Photograph 7: Set-up for Conducted testing



Photograph 8: Set-up for Conducted testing





Prüfbericht - Nr.: 50128210 001

Test Report No.

Seite 32 von 33 *Page 32 of 33*



Photograph 9: Set-up for Conducted testing

