


Class C Safety HIL Validation Report

Total Frames Analyzed: 2871

Average Latency: 0.04 ms

P99 Latency: 0.12 ms

Status: PASS (P99 < 50ms)



Digitally Signed by Automated HIL Rig Pipeline