



DRILLHOLE RECORD

CONTRACT NO. GE/2022/08

HOLE NO. **DH 3**

SHEET **1** of **2**

PROJECT Ground Investigation - New Territories East, PWP Item No. 9199WC, Water Supply to New Housing Developments along Route Twisk

METHOD **ROTARY**

CO-ORDINATES
E 829001.64
N 827502.52

TASK ORDER NO. **GE/2022/08.11B**

MACHINE **EW06**

DATE **19.12.2022** to **21.12.2022**

FLUSHING MEDIUM **WATER**

ORIENTATION **VERTICAL**

GROUND LEVEL **+178.57 mPD**

Drilling Progress	Casing Size	Water Level (m) Shift Start/End	Water Return%	TCR%	SCR%	RQD%	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description
19.12.2022	PW													Brownish yellow (10YR 6/6), slightly clayey sandy SILT with some angular to subangular fine to medium gravel. (FILL)
1														
2			60	40										Light yellowish brown (10YR 6/4), angular to subangular, coarse GRAVEL of rock fragments. (FILL)
3			60	100									IV	Weak, pale yellow (2.5Y 7/4) dappled yellowish red, highly decomposed, coarse ash TUFF. (Angular, slightly silty sandy fine to medium GRAVEL of highly decomposed tuff fragments)
4			60	100									IV	Weak, brownish yellow (10YR 6/8) dappled dark grey, highly decomposed, TUFF BRECCIA. (Angular, slightly silty sandy fine to coarse GRAVEL of highly decomposed tuff breccia fragments)
5			60	100										
6			60	99										
7			60	100									V	Extremely weak to very weak, light yellowish brown (2.5Y 6/4) and brownish yellow (10YR 6/8), completely decomposed, coarse ash TUFF. (Slightly clayey silty fine to coarse SAND with much angular fine to medium gravel)
8			60	86										
9			60	60										
10			60	60										

- SMALL DISTURBED SAMPLE
- LARGE DISTURBED SAMPLE
- U76 SAMPLE
- PISTON SAMPLE (76mm)
- MAZIER SAMPLE
- SPT LINER SAMPLE
- WATER SAMPLE
- U100 SAMPLE

- STANDARD PENETRATION TEST
- IN-SITU VANE SHEAR TEST
- PACKER TEST
- PERMEABILITY TEST
- PRESSUREMETER TEST
- BOREHOLE TELEVIEWER
- PIEZOMETER TIP
- STANDPIPE TIP

LOGGED **C. Chan**
DATE **28.12.2022**
CHECKED **R. Chu**
DATE **03.01.2023**

REMARKS

- An inspection pit was excavated to 1.10m deep by hand tools.
- Constant head permeability tests were carried out at sections from 3.40m to 4.90m and from 8.60m to 10.10m.
- A standpipe was installed to 2.00m.
- A piezometer was installed with tip at 14.50m.

DRiL TECH DRILLHOLE RECORD CONTRACT NO. GE/2022/08 HOLE NO. DH 3 SHEET 2 of 2														
PROJECT Ground Investigation - New Territories East, PWP Item No. 9199WC, Water Supply to New Housing Developments along Route Twisk														
METHOD ROTARY					CO-ORDINATES		TASK ORDER NO. GE/2022/08.11B							
MACHINE EW06					E 829001.64 N 827502.52		DATE 19.12.2022 to 21.12.2022							
FLUSHING MEDIUM WATER					ORIENTATION VERTICAL		GROUND LEVEL +178.57 mPD							
Drilling Progress	Casing Size	Water Level (m) Shift Start/End	Water Return %	TCR %	SCR %	RQD %	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description
20.12.2022 21.12.2022		1800 7.94 at 0800					15.0		19	+188.47	10.10	V	III	As sheet 1 of 2.
11			60	74	18	9	NI		T2-101	+168.07	10.50	V	IV	Moderately weak to moderately strong, light brownish grey, moderately decomposed, coarse ash TUFF. (CORESTONE)
12			60	96	6	0	NR		T2-101	+167.42	11.15	V	V	Weak to moderately weak, light yellowish brown (2.5Y 6/4), highly decomposed, coarse ash TUFF. (Angular, slightly sandy clayey silty fine to coarse GRAVEL of highly decomposed tuff fragments)
13			60	83	0	0	NR		T2-101	+167.06	11.51	V	IV	From 11.15m to 11.51m: No recovery, assumed to be completely decomposed TUFF.
14	HW 14.00m		60	0			NI		T2-101	+165.18	13.39	V	V	Weak to moderately weak, light grey (10YR 7/1) mottled light brownish grey, highly decomposed, TUFF BRECCIA. (Angular, fine to coarse GRAVEL and occasional cobble of highly decomposed tuff breccia fragments)
21.12.2022		9.89 at 1800	60	100	19	19	>20		T2-101	+164.41	14.16	V	III	From 13.39m to 13.60m: No recovery, assumed to be completely decomposed TUFF BRECCIA.
16							18.8			+163.56	15.01	V	V	Weak to moderately weak, light yellowish brown (2.5Y 6/4), highly decomposed, TUFF BRECCIA. (Angular, slightly silty sandy fine to coarse GRAVEL of highly decomposed tuff breccia fragments)
17														Moderately weak to moderately strong, light greyish brown, moderately decomposed, TUFF BRECCIA. Joints are very closely to closely spaced, rough planar and rough stepped, iron and manganese oxide stained, dipping at 15° to 25°, 25° to 35° and 65° to 75°.
18														End of hole at 15.01 m.
19														
20														

SMALL DISTURBED SAMPLE
 LARGE DISTURBED SAMPLE
 U76 SAMPLE
 PISTON SAMPLE (76mm)
 MAZIER SAMPLE
 SPT LINER SAMPLE
 WATER SAMPLE
 U100 SAMPLE

STANDARD PENETRATION TEST
 IN-SITU VANE SHEAR TEST
 PACKER TEST
 PERMEABILITY TEST
 PRESSUREMETER TEST
 BOREHOLE TELEVIEWER
 PIEZOMETER TIP
 STANDPIPE TIP

LOGGED C. Chan

DATE 28.12.2022

CHECKED R. Chu

DATE 03.01.2023

REMARKS