



BACHY SOLETANCHE GROUP
SOIL & FOUNDATIONS SPECIALISTS

DRILLHOLE RECORD

HOLE NO. DH29

CONTRACT

SHEET 1 of 3

PROJECT LINCOLN HOUSE DEVELOPMENT, QUARRY BAY

METHOD ROTARY

CO-ORDINATES

W.O. W-518

MACHINE & No. LY-09

E 839895.54
N 816569.15

DATE from 1/2/96 to 5/2/96

FLUSHING MEDIUM WATER

ORIENTATION Vertical

GROUND-LEVEL 3.52 mPD

Drilling Progress	Casing size	Water level (m) Shift start/end	Total core Recovery %	Solid core Recovery %	R.Q.D.	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description
1	SX		100					PERFORATION	3.32	0.20	Concrete Slab.		
									2.92	0.60	Brown, gravelly silty medium to coarse SAND. (FILL)		
								SX	2.18	1.34	Concrete with Cobbles and Gravels of moderately decomposed granite. (FILL)		
2			19					SX		1.50	Sub-angular Boulders, Cobbles and Gravels of moderately decomposed granite and tuff with some brown, silty SAND and some red bricks. (FILL)		
3	SX 3.10m PX		44					PX		3.10			
4			50					PX		4.00			
										4.30			3.75m-4.00m: boulder.
5													
6			11					T2-101					
7	PX 7.00m HX		67					T2-101		7.00			
										7.30			7.35m-7.55m: boulder.
8			62					T2-101					
									-4.78	8.30			
9													Wash boring. (No recovery)
10													

• SMALL DISTURBED SAMPLE	▲ WATER SAMPLE
■ LARGE DISTURBED SAMPLE	▲ PIEZOMETER TIP
▨ SPT LINER SAMPLE	□ STANDPIPE
▨ U76 UNDISTURBED SAMPLE	↓ STANDARD PENETRATION TEST
▨ U100 UNDISTURBED SAMPLE	⊥ PERMEABILITY TEST
▨ MAZIER SAMPLE (70mm)	∨ IN-SITU VANE SHEAR TEST
▨ PISTON SAMPLE	

LOGGED FRANK CHAN

DATE 06/02/96

APPROVED C.LUN

DATE 07/02/96

REMARKS
Hole termination depth at 29.39m.
Inspection Pit from 0.00m to 0.60m.



BACHY SOLETANCHE GROUP
SOIL & FOUNDATIONS SPECIALISTS

DRILLHOLE RECORD

HOLE NO. DH29

CONTRACT

SHEET 2 of 3

PROJECT LINCOLN HOUSE DEVELOPMENT, QUARRY BAY

METHOD ROTARY

CO-ORDINATES

W.O. W-518

MACHINE & No. LY-09

E 839895.54

DATE from 1/2/96 to 5/2/96

N 816569.15

FLUSHING MEDIUM WATER

ORIENTATION Vertical

GROUND-LEVEL 3.52 mPD

Drilling Progress	Casing size	Water level (m) Shift start/end	Total core Recovery %	Solid core Recovery %	R.Q.D.	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description
11													AS SHEET 1 OF 3.
12													
13													
14													
15													
16													
17													
18	HX 18.00m NX								-14.48	18.00			
19			60						-14.95	18.47			
20									-15.38	18.90			
									-15.48	19.00			Sub-rounded Boulder, Cobbles and Gravels of moderately decomposed granite and tuff with some brown silty SAND. 18.47m-18.90m: boulder. Wash boring. (No recovery)

- SMALL DISTURBED SAMPLE
- ▮ LARGE DISTURBED SAMPLE
- ▮ SPT LINER SAMPLE
- ▮ U76 UNDISTURBED SAMPLE
- ▮ U100 UNDISTURBED SAMPLE
- ▮ MAZIER SAMPLE (70mm)
- ▮ PISTON SAMPLE
- △ WATER SAMPLE
- ▲ PIEZOMETER TIP
- STANDPIPE
- ┃ STANDARD PENETRATION TEST
- ┃ PERMEABILITY TEST
- ∨ IN-SITU VANE SHEAR TEST

LOGGED FRANK CHAN

DATE 06/02/96

APPROVED C.LUN

DATE 07/02/96

REMARKS



BACHY SOLETANCHE GROUP
SOIL & FOUNDATIONS SPECIALISTS

DRILLHOLE RECORD

HOLE NO. DH29

CONTRACT

SHEET 3 of 3

PROJECT LINCOLN HOUSE DEVELOPMENT, QUARRY BAY

METHOD ROTARY

CO-ORDINATES

W.O. W-518

MACHINE & No. LY-09

E 839895.54
N 816569.15

DATE from 1/2/96 to 5/2/96

FLUSHING MEDIUM WATER

ORIENTATION Vertical

GROUND-LEVEL 3.52 mPD

Drilling Progress	Casing size	Water level (m) Shift start/end	Total core Recovery %	Solid core Recovery %	R.Q.D.	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description
02/02/96													AS SHEET 2 OF 3.
21									-17.48	21.00			
			50					↑ T-76 ↓	-18.48	22.00			Cobbles and Gravels of moderately decomposed granite and tuff with some brown silty SAND.
22													
03/02/96													Wash boring. (No recovery)
23													
24	NX 24.00m								-20.48	24.00			
25			100	100	93	3.1		↑ T-76 ↓		25.34		III/II	Moderately strong to strong, greyish pink spotted black and white, moderately to slightly decomposed medium to coarse grained GRANITE with widely to medium spaced and occasionally closely spaced, very narrow to extremely narrow, rough planar, limonite, manganese stained, kaolin coated joints, dipping 10°-20°, 40°-50°, 65°-75° and occasionally vertical joints.
26			100	100	89	12.5		↑ T-76 ↓		26.25			
05/02/96										26.65			
27			100	100	98	2.8		↑ T-76 ↓		27.91			
28			100	100	100			↑ T-76 ↓		28.42			
										28.48			
29			100	100	97	2.2		↑ T-76 ↓					
									-25.87	29.39			End of hole at 29.39m.
30													

- SMALL DISTURBED SAMPLE
- LARGE DISTURBED SAMPLE
- SPT LINER SAMPLE
- U75 UNDISTURBED SAMPLE
- U100 UNDISTURBED SAMPLE
- MAZIER SAMPLE (70mm)
- PISTON SAMPLE
- WATER SAMPLE
- PIEZOMETER TIP
- STANDPIPE
- STANDARD PENETRATION TEST
- PERMEABILITY TEST
- IN-SITU VANE SHEAR TEST

LOGGED FRANK CHAN

DATE 06/02/96

APPROVED C.LUN

DATE 07/02/96

REMARKS