

PROPERTY CONDITION REPORT

PROPERTY INFORMATION

Address Imagery Date 2022-02-20

9850 KEY WEST AVE Date of Report 2022-04-06 (PDT)

CAPE Property ID 579990174

PROPERTY IMAGES

ROCKVILLE, MD 20850

Oblique View

North | South

East | West











PROPERTY CONDITION REPORT

PROPERTY IMAGES (CONTINUED)

Orthogonal View



Street View



Map View





PROPERTY CONDITION REPORT

PROPERTY CONDITION INFORMATION

Roof Condition Rating


Accessory Structure Roof Condition

Pool Condition Rating

Pool Presence Accessory Structure Count

Yard Debris Coverage Area

Yard Debris Coverage Percentage



ADDITIONAL FEATURE AND CONDITION INFORMATION

Roof Occlusion

Tree Overhang

Diving Board

Pool Enclosure

Pool Occlusion

Pool Slide
Pool Structure Type

Roof Covering

Roof Covering

Roof Extension

Roof Geometry

Roof Solar Panel

Trampoline Presence

Not Available			

False

Not Available

Not Available

Not Available

Membrane

False

Flat

False False

ADDITIONAL PARCEL INFORMATION

Neighbor Structure Setback 73 feet

Structure Count Zone 12 structuresStructure Count Zone 214 structures

Structure Density Zone 1 61% Structure Density Zone 2 6%

USDA Wildfire Hazard PotentialNon burnable land

Vegetation Coverage Zone 13%Vegetation Coverage Zone 27%Vegetation Coverage Zone 37%Vegetation Setback0 feet

This report is provided by CAPE Analytics. For any questions regarding this report, please contact report@capeanalytics.com