
				<b>Batch Record</b>
	<b>CapsuleFillMachin / ControlSystem</b>			Ref.: 003 / PV-AT
	Machine name: ZLAB			
	Batch: 169			
	Date printed: 06/07/2021	Time printed: 16:04:29	Page 1 / 3	

## Audit Trail Record

Machine Number:	900X905020
Operator:	Operater
Product:	pq070621for1
Date printed:	06/07/2021
Time printed:	16:04:29
Order:	1
Customer:	Pachkov
Remark:	

<b>Date / Name / Signature</b>	
--------------------------------	--

	<b>Batch Record</b>		
	<b>CapsuleFillMachin / ControlSystem</b>		
	Ref.: 003 / PV-AT		
	Machine name:	ZLAB	
Batch:	169		
Date printed:	06/07/2021	Time printed:	16:04:29
			Page 2 / 3

ID	Date	Time	No.	Description	New value	Reason
	Operator			Old value		
1	06/07/2021	15:47:29	3035	active start button		校验状态
2	06/07/2021	15:47:30	3037	active reset button		校验状态
3	06/07/2021	15:47:30	3037	active reset button		校验状态
4	06/07/2021	15:47:31	3037	active reset button		校验状态
5	06/07/2021	15:47:31	3035	active start button		校验状态
6	06/07/2021	15:49:00	3036	active stop button		校验状态
7	06/07/2021	15:49:23	3037	active reset button		校验状态
8	06/07/2021	15:49:23	3037	active reset button		校验状态
9	06/07/2021	15:49:23	3037	active reset button		校验状态
10	06/07/2021	15:49:24	3035	active start button		校验状态
11	06/07/2021	16:04:22	3037	active reset button		校验状态
12	06/07/2021	16:04:22	3037	active reset button		校验状态
13	06/07/2021	16:04:22	3037	active reset button		校验状态
14	06/07/2021	16:04:23	3037	active reset button		校验状态



Batch Record

CapsuleFillMachin / ControlSystem

Ref.: 003 / PV-AT

Machine name:	ZLAB	
Batch:	169	
Date printed:	06/07/2021	Time printed: 16:04:29
		Page 3 / 3

ID	Date	Time	No.	Description		
	Operator			Old value	New value	Reason
15	06/07/2021	16:04:23	3037	active reset button		
	Operator					校验状态