

CERTIFICATE OF CONFORMITY

|                  |                |
|------------------|----------------|
| PRODUCTION ORDER | PO-39922834    |
| MODEL / VARIANT  | PX-STD         |
| SERIAL NUMBER    | MX185695318328 |
| INSPECTION PLAN  | QP-56.2        |
| DECISION         | ACCEPTED       |

Inspection summary

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |

Inspector signature:



QR CODE <https://example.invalid/more/0>



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 410 443 20

Document: MXQD-002-7905

PAGE 02/60

DATE: 13/07/2026 00:31

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | PARKING SENSOR        | RF-43052  | L557766 | OK            |
| 02   | REAR CAMERA MODULE    | RF-74937  | L703971 | REVIEW        |
| 03   | BATTERY SUPPORT       | RF-23698  | L620559 | OK            |
| 04   | CLIMATE CONTROL UNIT  | RF-24773  | L764138 | REVIEW        |
| 05   | BRAKE HOSE SUPPORT    | RF-27775  | L379416 | OK            |
| 06   | ENGINE WIRING HARNESS | RF-97319  | L899815 | REVIEW        |
| 07   | PARKING SENSOR        | RF-19210  | L379239 | REVIEW        |
| 08   | RIGHT SIDE PANEL      | RF-36796  | L918096 | OK            |
| 09   | SEAT RAIL FIXING      | RF-22485  | L523476 | OK            |
| 10   | REAR CAMERA MODULE    | RF-63561  | L884384 | OK            |
| 11   | FRONT AXLE BRACKET    | RF-28332  | L706688 | OK            |
| 12   | AIRBAG CONTROL MODULE | RF-80453  | L666290 | OK            |
| 13   | ENGINE WIRING HARNESS | RF-20010  | L475923 | OK            |
| 14   | FRONT AXLE BRACKET    | RF-15168  | L519381 | OK            |
| 15   | FRONT AXLE BRACKET    | RF-11847  | L261823 | OK            |
| 16   | CLIMATE CONTROL UNIT  | RF-98695  | L298532 | OK            |
| 17   | FRONT AXLE BRACKET    | RF-35052  | L501011 | REVIEW        |
| 18   | BRAKE HOSE SUPPORT    | RF-31291  | L794403 | OK            |
| 19   | AIRBAG CONTROL MODULE | RF-50783  | L286585 | OK            |
| 20   | DOOR LOCK ASSEMBLY    | RF-59779  | L550356 | OK            |
| 21   | FRONT AXLE BRACKET    | RF-81124  | L890262 | OK            |

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 313 991 69

Document: MXQD-003-7083

PAGE 03/60

DATE: 13/07/2026 16:28

## FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL    |                                                                                                                 | FUNCTION / IDI          |                                                                                                  |
|-------------------------|-----------------------------------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------|
| Protective film removed | <br>DATA MATRIX: 3001908248844 | Harness routing         | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Fastener witness mark   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | No visible damage       | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Reference matches order | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Seal continuous         | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                           | Fastener witness mark   | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Fastener witness mark   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                | Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 440 169 82  
Document: MXQD-004-7919

PAGE 04/60

DATE: 13/07/2026 23:46  
FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                    |
|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                    | No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A     |
| Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        |
| No visible damage <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                  | mark <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                             |
| Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                       |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Cover installed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 749 126 77

Document: MXQD-005-7446

PAGE 05/60

DATE: 13/07/2026 13:47

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B279994

STATION QC-10

SERIAL SN2661862880

DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| SEAT RAIL FIXING      | 20.21 | 39.53 | 33.22 | V    | PASS   |
| BATTERY SUPPORT       | 34.19 | 47.24 | 39.34 | deg  | PASS   |
| REAR CAMERA MODULE    | 54.55 | 88.64 | 80.22 | deg  | PASS   |
| BATTERY SUPPORT       | 54.59 | 59.50 | 58.09 | V    | PASS   |
| DOOR LOCK ASSEMBLY    | 49.12 | 84.39 | 51.42 | V    | HOLD   |
| CLIMATE CONTROL UNIT  | 47.00 | 72.29 | 71.72 | deg  | PASS   |
| FRONT AXLE BRACKET    | 16.64 | 26.74 | 16.75 | Nm   | PASS   |
| SEAT RAIL FIXING      | -2.47 | 16.22 | 5.65  | mm   | HOLD   |
| BATTERY SUPPORT       | 37.67 | 71.29 | 42.69 | Nm   | PASS   |
| DOOR LOCK ASSEMBLY    | 4.43  | 32.77 | 29.94 | mm   | PASS   |
| SEAT RAIL FIXING      | 19.73 | 35.03 | 21.74 | V    | PASS   |
| LOWER ARM FASTENER    | -1.99 | 17.18 | 0.51  | Nm   | PASS   |
| DOOR LOCK ASSEMBLY    | 22.28 | 40.88 | 39.84 | deg  | HOLD   |
| BRAKE HOSE SUPPORT    | 25.88 | 51.11 | 30.40 | Nm   | PASS   |
| SEAT RAIL FIXING      | 17.64 | 27.93 | 21.69 | V    | PASS   |
| BATTERY SUPPORT       | 6.06  | 10.00 | 6.41  | mm   | PASS   |
| BATTERY SUPPORT       | 25.26 | 56.21 | 27.37 | V    | PASS   |
| AIRBAG CONTROL MODULE | 18.82 | 32.78 | 29.43 | deg  | PASS   |
| BATTERY SUPPORT       | 32.87 | 63.02 | 52.44 | mm   | PASS   |
| CLIMATE CONTROL UNIT  | 36.90 | 46.24 | 40.71 | mm   | PASS   |
| LOWER ARM FASTENER    | 1.09  | 11.29 | 6.86  | Nm   | PASS   |
| PARKING SENSOR        | 44.04 | 64.69 | 46.38 | V    | PASS   |
| REAR CAMERA MODULE    | 26.97 | 57.81 | 52.18 | deg  | PASS   |
| CLIMATE CONTROL UNIT  | 34.27 | 54.31 | 38.48 | mm   | PASS   |

## Sequence: 688 384 33

PAGE 06/60

DATE: 13/07/2026 08:58

CONTROL CERTIFICATE

PRODUCTION ORDER

PO-90033148

MODEL / VARIANT

MX-A7

SERIAL NUMBER

MX982519054273

INSPECTION PLAN

QP-97.1

### DECISION

ACCEPTED

### Inspection summary



CODE 39 MX-06-03-6806



CODE 128 LOT-486887-P06



CODE 39 MX-06-04-6660



CODE 128 PO51461438668



CODE 128 PO9873434232

Inspector signature: \_\_\_\_\_

QC  
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 728 651 60

Document: MXQD-007-3604

PAGE 07/60

DATE: 13/07/2026 23:30

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | SEAT RAIL FIXING      | RF-55032  | L941105 | OK            |
| 02   | BATTERY SUPPORT       | RF-77097  | L264088 | REVIEW        |
| 03   | ENGINE WIRING HARNESS | RF-77102  | L770984 | REVIEW        |
| 04   | AIRBAG CONTROL MODULE | RF-24319  | L253120 | OK            |
| 05   | RIGHT SIDE PANEL      | RF-84490  | L288658 | OK            |
| 06   | BRAKE HOSE SUPPORT    | RF-25370  | L561134 | REVIEW        |
| 07   | AIRBAG CONTROL MODULE | RF-69421  | L382098 | OK            |
| 08   | BRAKE HOSE SUPPORT    | RF-48158  | L695692 | OK            |
| 09   | AIRBAG CONTROL MODULE | RF-73806  | L137262 | OK            |
| 10   | LOWER ARM FASTENER    | RF-72280  | L104641 | OK            |
| 11   | RIGHT SIDE PANEL      | RF-69001  | L669607 | OK            |
| 12   | LOWER ARM FASTENER    | RF-79396  | L232250 | OK            |
| 13   | PARKING SENSOR        | RF-55808  | L722725 | OK            |
| 14   | REAR CAMERA MODULE    | RF-31680  | L395064 | REVIEW        |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 596 952 70

Document : MXQD-008-9687

PAGE 08/60

DATE: 13/07/2026 05:40

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | BRAKE HOSE SUPPORT    | RF-60317  | L454170 | OK            |
| 02   | FRONT AXLE BRACKET    | RF-40531  | L725891 | OK            |
| 03   | RIGHT SIDE PANEL      | RF-69375  | L812366 | OK            |
| 04   | SEAT RAIL FIXING      | RF-16218  | L399744 | OK            |
| 05   | FRONT AXLE BRACKET    | RF-28348  | L216498 | OK            |
| 06   | CLIMATE CONTROL UNIT  | RF-97151  | L637369 | REVIEW        |
| 07   | ENGINE WIRING HARNESS | RF-91368  | L158958 | REVIEW        |
| 08   | PARKING SENSOR        | RF-52169  | L221110 | OK            |
| 09   | PARKING SENS          | RF-75375  | L787007 | REVIEW        |
| 10   | SEAT RAIL FIX         | RF-73542  | L100834 | OK            |
| 11   | IT SIDE PANEL         | RF-10549  | L737142 | OK            |
| 12   | BRAKE HOSE SUPPORT    | RF-58174  | L305993 | OK            |
| 13   | DOOR LOCK ASSEMBLY    | RF-79510  | L731307 | OK            |
| 14   | REAR CAMERA MODULE    | RF-83095  | L186573 | OK            |
| 15   | BATTERY SUPPORT       | RF-71048  | L911862 | OK            |
| 16   | REAR CAMERA MODULE    |           | L123171 | REVIEW        |
| 17   | DOOR LOCK ASSEMBLY    | RF-33801  | L492215 | REVIEW        |
| 18   | LOWER ARM FASTENER    | RF-60874  | L596843 | OK            |
| 19   | PARKING SENSOR        | RF-26853  | L368979 | OK            |
| 20   | FRONT AXLE BRACKET    | RF-38494  | L973168 | OK            |
| 21   | RIGHT SIDE PANEL      | RF-73277  | L990952 | OK            |

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 631 903 66

Document: MXQD-009-8927

PAGE 09/60

DATE: 13/07/2026 03:36

## FINAL INSPECTION CHECKLIST

### VISUAL / DIMENSIONAL

### FUNCTION / IDENTITY

Connector locked ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

Surface condition ☐ OK ☐ NOK ☐ N/A

Cover installed ☒ OK ☐ NOK ☐ N/A

Seal continuous ☒ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

Harness routing ☐ OK ☐ NOK ☐ N/A

Reference matches order ☒ OK ☐ NOK ☐ N/A



ad



CODE 128 LOT-925465-P09



☒ OK ☐ NOK ☐ N/A



Protective film removed ☒ OK ☐ NOK ☐ N/A

Reference matches order ☐ OK ☐ NOK ☐ N/A

Cover installed ☒ OK ☐ NOK ☐ N/A

Fastener witness mark ☒ OK



DATA MATRIX D46MX(P009)05(L876)

Harness routing ☒ OK ☐ NOK ☐ N/A

Reference matches order ☒ OK ☐ NOK ☐ N/A

Cover installed ☐ OK ☐ NOK ☐ N/A



DATA MATRIX 1

Torque confirmed ☒ OK ☐ NOK ☐ N/A

Reference matches order ☐ OK ☐ NOK ☐ N/A

Harness routing ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

Torque confirmed ☒ OK ☐ NOK ☐ N/A

Label presence ☒ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 293 174 20  
Document: MXQD-010-4955

PAGE 10/60

DATE: 13/07/2026 07:31

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B487863 SERIAL SN1333045641  
STATION QC-25 DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| REAR CAMERA MODULE    | 12.86 | 28.81 | 23.12 | deg  | PASS   |
| BRAKE HOSE SUPPORT    | 17.16 | 49.77 | 44.09 | deg  | PASS   |
| CLIMATE CONTROL UNIT  | 38.44 | 65.08 | 48.63 |      | HOLD   |
| AIRBAG CONTROL MODULE | 48.01 | 67.77 | 64.03 |      | PASS   |
| DOOR LOCK ASSEMBLY    | 45.07 | 74.58 | 48.69 |      | HOLD   |
| AIRBAG CONTROL MODULE | 50.38 | 59.51 | 57.70 | Nm   | PASS   |
| REAR CAMERA MODULE    | 4.56  | 10.23 | 4.88  | V    | PASS   |
| FRONT AXLE BRACKET    | 16.81 | 44.89 | 29.07 | mm   | PASS   |
| REAR CAMERA           |       |       |       | deg  | PASS   |
| PARKING SENSOR        |       |       |       | Nm   | PASS   |
| RIGHT SIDE PANEL      |       |       |       | deg  | PASS   |
| ENGINE WIRING HARNESS |       |       |       | Nm   | PASS   |
| SEAT RAIL FIXING      |       |       |       | deg  | PASS   |
| FRONT AXLE BRACKET    |       |       |       |      | PASS   |
| DOOR LOCK ASSEMBLY    |       |       |       |      | PASS   |
| PARKING SENSOR        | 17.73 | 35.47 | 23.16 |      | HOLD   |
| REAR CAMERA MODULE    | 45.80 | 56.93 |       |      | HOLD   |
| DOOR LOCK ASSEMBLY    | 21.80 | 28.21 |       | mm   | HOLD   |
| RIGHT SIDE PANEL      | 17.26 | 49.73 | 17.52 | V    | PASS   |
| AIRBAG CONTROL MODULE | 24.75 | 56.07 | 28.26 | deg  | PASS   |
| LOWER ARM FASTENER    | 26.65 | 49.04 | 29.04 | V    | HOLD   |
| FRONT AXLE BRACKET    | 32.24 | 63.78 | 57.76 | deg  | PASS   |
| RIGHT SIDE PANEL      | 38.75 | 67.41 | 54.62 | mm   | PASS   |
| ENGINE WIRING HARNESS | 53.57 | 89.09 | 76.44 | deg  | HOLD   |

Sequence: 884 585 99  
Document: MXQD-011-7324

CONTROL CERTIFICATE

|                  |                |
|------------------|----------------|
| PRODUCTION ORDER | PO-54401906    |
| MODEL / VARIANT  | K9-VU          |
| SERIAL NUMBER    | MX805386154146 |
| INSPECTION PLAN  | QP-66.6        |
| DECISION         | ACCEPTED       |

QR CODE <https://example.museonline.org/1011/01>

Inspector signature: \_\_\_\_\_

QC  
PASS

Document: MXQD-012-5215

CONTROL CERTIFICATE

## DECISION \_\_\_\_\_ ACCEPTED \_\_\_\_\_

[illegible]

Inspector signature: \_\_\_\_\_

QC  
PASS

SYNTHETIC MIXED QUALITY DOSSIER

PAGE 13/60

DATE: 13/07/2026 06:12

COMPONENT TRACEABILITY LOG

Sequence: 466 335 86  
Document: MXQD-013-8988

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | BATTERY SUPPORT       | RF-53593  | L981560 | OK            |
| 02   | RIGHT SIDE PANEL      | RF-75348  | L177898 | OK            |
| 03   | AIRBAG CONTROL MODULE | RF-34885  | L486285 | REVIEW        |
| 04   | PARKING SENSOR        | RF-56288  | L150540 | OK            |
| 05   | BRAKE HOSE SUPPORT    | RF-69143  | L709444 | REVIEW        |
| 06   | FRONT AXLE BRACKET    | RF-66673  | L122461 | OK            |
| 07   | RIGHT SIDE PANEL      | RF-68090  | L764217 | REVIEW        |
| 08   | BRAKE HOSE SUPPORT    | RF-27019  | L274470 | OK            |
| 09   | LOWER ARM FASTENER    | RF-83808  | L995418 | OK            |
| 10   | BATTERY SUPPORT       | RF-34261  | L699230 | OK            |
| 11   | CLIMATE CONTROL UNIT  | RF-51821  | L583667 | OK            |
| 12   | AIRBAG CONTROL MODULE | RF-27193  | L631620 | OK            |
| 13   | DOOR LOCK ASSEMBLY    | RF-50591  | L997135 | REVIEW        |
| 14   | ENGINE WIRING HARNESS | RF-48592  | L641818 | OK            |
| 15   | REAR CAMERA MODULE    | RF-32909  | L238592 | OK            |
| 16   | LOWER ARM FASTENER    | RF-72630  | L295072 | OK            |
| 17   | REAR CAMERA MODULE    | RF-27229  | L149470 | OK            |
| 18   | DOOR LOCK ASSEMBLY    | RF-29981  | L860499 | OK            |
| 19   | PARKING SENSOR        | RF-23616  | L841274 | REVIEW        |
| 20   | SEAT RAIL FIXING      | RF-53990  | L575292 | OK            |
| 21   | AIRBAG CONTROL MODULE |           | L730694 | REVIEW        |



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 278 243 57  
Document: MXQD-014-3685

PAGE 14/60  
DATE: 13/07/2026 14:09  
FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL    |                                        |                                                           | FUNCTION / IDENTITY     |                                        |                                                           |
|-------------------------|----------------------------------------|-----------------------------------------------------------|-------------------------|----------------------------------------|-----------------------------------------------------------|
| Seal continuous         | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Reference matches order | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Protective film removed | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Fastener witness mark   | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Surface condition       | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Torque confirmed        | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Surface condition       | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit        | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed         | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Fastener witness mark   | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Harness routing         | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Gap within limit        | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark   | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit        | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input type="checkbox"/> OK            | <input type="checkbox"/> NOK <input type="checkbox"/> N/A |



# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 196 657 48  
Document: MXQD-015-8260

PAGE 15/60

DATE: 13/07/2026 23:03

MEASUREMENT AND TRACEABILITY

## BATCH / CONTROL INFORMATION

BATCH B266397  
STATION QC-23

SERIAL SN5022856224  
DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| RIGHT SIDE PANEL      | 27.31 | 45.26 | 27.52 | Nm   | PASS   |
| RIGHT SIDE PANEL      | 15.71 | 30.33 | 29.25 |      |        |
| REAR CAMERA MODULE    | 3.70  | 34.88 | 19.33 |      |        |
| AIRBAG CONTROL MODULE | 7.95  | 16.11 | 12.71 |      |        |
| DOOR LOCK ASSEMBLY    | 23.00 | 45.89 | 41.35 |      |        |
| ENGINE WIRING         |       | 51.95 | 51.13 | deg  | PASS   |
| AIRBAG CONTROL        |       | 4.72  | -1.88 | Nm   | PASS   |
| AIRBAG CONTROL        |       | 76.47 | 58.09 | mm   | PASS   |
| PARKING SENSOR        | 9.25  | 33.07 | 12.02 | deg  | HOLD   |
| LOWER ARM FASTENER    | 52.57 | 83.18 | 71.44 | V    | HOLD   |
| SEAT RAIL FIXING      | 2.25  |       | 3.02  | V    | PASS   |
| ENGINE WIRING HARNESS | 0.76  |       | 24.01 | deg  | PASS   |
| LOWER ARM FASTENER    | 0.74  | 35.87 | 23.11 | V    | PASS   |
| FRONT AXLE BRACKET    | 50.43 | 62.19 | 60.88 | V    | PASS   |
| DOOR LOCK ASSEMBLY    | 21.76 | 26.93 | 25.58 | mm   | PASS   |
| PARKING SENSOR        | 46.66 | 82.26 | 71.34 | V    | PASS   |
| ENGINE WIRING HARNESS | 54.23 | 56.78 | 54.53 | deg  | HOLD   |
| PARKING SENSOR        | 34.01 | 53.50 | 44.39 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 5.25  | 33.28 | 7.01  | Nm   | HOLD   |
| SEAT RAIL FIXING      | 50.37 | 61.96 | 52.02 | mm   | PASS   |
| ENGINE WIRING HARNESS | 48.57 | 73.21 | 64.68 | V    | HOLD   |
| AIRBAG CONTROL MODULE | 45.45 | 65.51 | 56.99 | V    | PASS   |
| PARKING SENSOR        | 35.26 | 39.41 | 38.41 | deg  | PASS   |
| DOOR LOCK ASSEMBLY    | 45.08 | 63.24 | 45.45 | deg  | PASS   |

CODE 128 LOT-608901-P15  
CODE 128 PO36676600213

CODE 39 MX-15-03-2348

QR CODE <https://neca>

DATA MATRIX DM

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 299 949 22  
Document: MXQD-016-9445

BATCH / CONTROL INFORMATION

BATCH B898445  
STATION QC-08

SERIAL SN9664402416  
DECISION REVIEW

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| SEAT RAIL FIXING      | 15.43 | 44.06 | 33.14 | deg  | HOLD   |
| CLIMATE CONTROL UNIT  | 41.83 | 64.97 | 46.11 | V    | PASS   |
| FRONT AXLE BRACKET    | 5.17  | 10.19 | 9.88  | mm   | PASS   |
| AIRBAG CONTROL MODULE | 34.99 | 39.52 | 36.45 | deg  | HOLD   |
| PARKING SENSOR        | 18.91 | 50.51 | 19.22 | deg  | PASS   |
| SEAT RAIL FIXING      | 51.55 | 82.79 | 71.08 | Nm   | PASS   |
| BATTERY SUPPORT       | 4.26  | 16.99 | 15.08 | Nm   | PASS   |
| CLIMATE CONTROL UNIT  | 0.45  | 11.82 | 1.78  | mm   | PASS   |
| RIGHT SIDE PANEL      | 46.04 | 63.80 | 60.71 | deg  | PASS   |
| REAR CAMERA MODULE    | 12.46 | 31.11 | 28.15 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 25.55 | 57.72 | 46.43 | mm   | PASS   |
| RIGHT SIDE PANEL      | 36.00 | 57.19 | 53.84 | deg  | PASS   |
| FRONT AXLE BRACKET    | 39.73 | 52.29 | 40.60 | mm   | HOLD   |
| RIGHT SIDE PANEL      | 34.30 | 65.58 | 64.49 | V    | PASS   |
| DOOR LOCK ASSEMBLY    | 51.28 | 53.76 | 53.01 | V    | PASS   |
| REAR CAMERA           | 33.16 | 51.24 | 46.44 | Nm   | PASS   |
| AIRBAG CONTROL MODULE | 5.80  | 33.70 | 31.94 | deg  | PASS   |
| ENGINE WIRING HARNESS | 19.55 | 23.86 | 22.53 | Nm   | HOLD   |
| REAR CAMERA MODULE    | 29.95 | 61.44 | 42.49 | deg  | PASS   |
| SEAT RAIL FIXING      | 37.49 | 62.71 | 38.00 | mm   | HOLD   |
| SEAT RAIL FIXING      | 24.05 |       | 35.55 | Nm   | PASS   |
| BATTERY SUPPORT       | 51.40 |       | 73.97 |      |        |
| CLIMATE CONTROL UNIT  | 13.16 | 36.99 | 24.32 |      |        |
| RIGHT SIDE PANEL      | 52.87 | 57.84 | 54.00 | V    | PASS   |

## PAGE 17/60

Sequence: 955 757 48

DATE: 13/07/2026 07:20

Document: MXQD-017-9524

CONTROL CERTIFICATE

## CERTIFICATE OF CONFORMITY

PRODUCTION ORDER

PO-25147823

MODEL / VARIANT

K9-VU

SERIAL NUMBER

MX989993913534

## INSPECTION PLAN

QP-69.8

### DECISION

CONDITIONAL

## Inspection summary

[illegible]

Inspector signature: \_\_\_\_\_

QC  
PASS

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 658 560 29

Document: MXQD-018-1521

PAGE 18/60

DATE: 13/07/2026 04:37

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | DOOR LOCK ASSEMBLY    | RF-95699  | L502181 | OK            |
| 02   | PARKING SENSOR        | RF-57568  | L135594 | OK            |
| 03   | DOOR LOCK ASSEMBLY    | RF-46163  | L218229 | OK            |
| 04   | FRONT AXLE BRACKET    | RF-25701  | L505775 | OK            |
| 05   | RIGHT SIDE PANEL      | RF-73752  | L251424 | OK            |
| 06   | BRAKE HOSE SUPPORT    | RF-96287  | L512198 | REVIEW        |
| 07   | SEAT RAIL FIXING      | RF-94755  | L690700 | OK            |
| 08   | SEAT RAIL FIXING      | RF-64281  | L557252 | OK            |
| 09   | AIRBAG CONTROL MODULE | RF-14604  | L273892 | OK            |
| 10   | ENGINE WIRING HARNESS | RF-48252  | L108159 | REVIEW        |
| 11   | SEAT RAIL FIXING      | RF-45139  | L975148 | OK            |
| 12   | AIRBAG CONTROL MODULE | RF-51000  | L738264 | OK            |
| 13   | LOWER ARM FASTENER    | RF-40321  | L311301 | OK            |
| 14   | ENGINE WIRING HARNESS | RF-82654  | L143599 | OK            |
| 15   | LOWER ARM FASTENER    | RF-15499  | L139416 | REVIEW        |
| 16   | DOOR LOCK ASSEMBLY    | RF-78107  | L223745 | OK            |
| 17   | BATTERY SUPPORT       | RF-97123  | L462903 | REVIEW        |
| 18   | FRONT AXLE BRACKET    | RF-89721  | L236814 | OK            |
| 19   | BATTERY SUPPORT       | RF-83333  | L846277 | OK            |
| 20   | RIGHT SIDE PANEL      | RF-73920  | L461324 | OK            |
| 21   | LOWER ARM FASTENER    | RF-85954  | L256505 | OK            |



DATA MATRIX (01)00506000274592(21)00

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 918 598 96  
Document: MXQD-019-2595

PAGE 19/60  
DATE: 13/07/2026 07:19  
FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                    |
|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Surface condition <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A          | No visible damage <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                |
| Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   | Surface condition <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A          | No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A     |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 337 502 70

Document: MXQD-020-1268

| VISUAL / DIMENSIONAL    |                                                                                                  | FUNCTION / IDENTITY                                                                                           |                                                                                                  |
|-------------------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|
| No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage                                                                                             | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Reference matches order                                                                                       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Label presence                                                                                                | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No                         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Harness routing                                                                                               | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Label presence            | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| No visible damage       | <input type="checkbox"/> N/A                                                                     | Seal continuous                                                                                               | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit        | <input type="checkbox"/> N/A                                                                     | Seal continuous          | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input type="checkbox"/> N/A                                                                     | Torque confirmed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
|                         | <input type="checkbox"/> N/A                                                                     | Protective film removed  | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Cover installed         | <input type="checkbox"/> N/A                                                                     | Cover installed                                                                                               | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input type="checkbox"/> N/A                                                                     | Seal continuous                                                                                               | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |

## SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 382 104 17

Document: MXQD-021-9095

PAGE 21/60

DATE: 13/07/2026 19:04

MEASUREMENT AND TRACEABILITY

## BATCH / CONTROL INFORMATION

BATCH B971674  
STATION QC-03SERIAL SN5089519912  
DECISION OK

CHARAC

CLIMATE C

ENGINE W

PARKING S

RIGHT SIDE PANEL

QR CODE <https://example.invalid/mixed021016731>

CODE 128 LOT-411907-P21

|                       | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
|                       | -0.33 | 2.82  | -0.13 | deg  | PASS   |
|                       | 5.18  | 32.50 | 19.83 | deg  | HOLD   |
|                       | 9.49  | 41.03 | 20.16 | V    | PASS   |
|                       | 33.36 | 43.10 | 40.38 | deg  | HOLD   |
|                       | 8.68  | 32.36 | 10.36 | Nm   | HOLD   |
|                       | 24.50 | 34.35 | 25.24 | deg  | PASS   |
|                       | 34.35 | 40.58 | 39.73 | V    | PASS   |
| BATTERY SUPPORT       | 32.81 | 52.29 | 41.49 | Nm   | PASS   |
| ENGINE WIRING HARNESS | 29.56 | 59.23 | 58.15 | mm   | PASS   |
| PARKING SENSOR        | 49.81 | 64.43 | 54.15 | mm   | PASS   |
| BRAKE HOSE SUPPORT    | 10.96 | 31.71 | 15.09 | Nm   | HOLD   |
| LOWER ARM FASTENER    | 10.68 | 33.88 | 11.64 | deg  | HOLD   |
| PARKING SENSOR        | 29.65 | 57.53 | 50.58 | deg  | PASS   |
| READ CAMERA MODULE    | 49.41 | 54.64 | 54.44 | mm   | PASS   |
| RIG                   | 8.92  | 40.38 | 23.28 | mm   | HOLD   |
| LOW                   | 9.15  | 25.83 | 13.39 | mm   | PASS   |
| RIG                   | 12.82 | 38.05 | 26.51 | deg  | PASS   |
| LOWER ARM FASTENER    | 14.88 | 21.42 | 16.80 | mm   | HOLD   |
| AIRBAG CONTROL MODULE | 51.34 | 70.96 | 65.78 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 43.11 | 72.61 | 71.35 | Nm   | PASS   |
| SEAT RAIL FIXING      | 25.29 | 35.87 | 27.23 | V    | PASS   |
| CLIMATE CONTROL UNIT  | 47.77 | 53.50 | 51.38 | V    | PASS   |
| RIGHT SIDE PANEL      | 47.86 | 55.97 | 50.17 | deg  | HOLD   |
| CLIMATE CONTROL UNIT  | 1.69  | 18.49 | 9.92  | V    | PASS   |
| CLIMATE CONTROL UNIT  |       |       |       |      |        |

Document: MXQD-022-6884

PAGE 22/60

DATE: 13/07/2026 23:20

CONTROL CERTIFICATE

**CERTIFICATE OF CONFORMITY**

PRODUCTION ORDER

PO-70430420

MODEL / VARIANT

PX-STD

SERIAL NUMBER

MX329512512162

INSPECTION PLAN

QP-14.4

### DECISION

ACCEPTED



CODE 39 MX-22-03-6802

### Inspection summary



CODE 128 PO30273656615

Inspector signature: \_\_\_\_\_



DATA MATRIX DIMENSIONS

QC  
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 688 846 94  
Document: MXQD-023-5515

PAGE 23/60

DATE: 13/07/2026 06:42

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION  | REFERENCE                                                                                                     | LOT     | STATUS / NOTE |
|------|------------------------|---------------------------------------------------------------------------------------------------------------|---------|---------------|
| 01   | CLIMATE CONTROL UNIT   | RF-53483                                                                                                      | L176440 | OK            |
| 02   | CLIMATE CONTROL UNIT   | RF-95364                                                                                                      | L465895 | OK            |
| 03   | REAR CAMERA MODULE     | RF-45156                                                                                                      | L895880 | OK            |
| 04   | FRONT AXLE BRACKET     | RF-65944                                                                                                      | L853853 | OK            |
| 05   | CLIMATE CONTROL UNIT   | <br>CODE 39 MX-23-02-4286 |         | REVIEW        |
| 06   | AIRBAG CONTROL MODULE  |                                                                                                               |         | REVIEW        |
| 07   | BATTERY SUPPORT        |                                                                                                               |         | REVIEW        |
| 08   | DOOR LOCK ASSEMBLY     | RF-80239                                                                                                      | L278113 | REVIEW        |
| 09   | REAR CAMERA MODULE     | RF-90586                                                                                                      | L103453 | OK            |
| 10   | RIGHT SIDE PANEL       | RF-38233                                                                                                      | L717822 | REVIEW        |
| 11   | DOOR LOCK ASSEMBLY     | RF-64995                                                                                                      | L295793 | REVIEW        |
| 12   | SEAT RAIL FIXING       | RF-21491                                                                                                      | L596093 | OK            |
| 13   | ENGINE WIRING HARNESS  | RF-77074                                                                                                      | L231743 | OK            |
| 14   | BATTERY SUPPORT        | RF-89513                                                                                                      | L468779 | OK            |
| 15   | CLIMATE CONTROL UNIT   | RF-43882                                                                                                      | L681544 | OK            |
| 16   |                        | RF-24895                                                                                                      | L918537 | OK            |
| 17   | CODE 128 PO38403092702 | RF-42359                                                                                                      | L902605 | OK            |
| 18   | PARKING SENSOR         | RF-89856                                                                                                      | L778993 | OK            |
| 19   | AIRBAG CONTROL MODULE  | RF-10971                                                                                                      | L658422 | OK            |
| 20   | DOOR LOCK ASSEMBLY     | RF-20686                                                                                                      | L298940 | OK            |
| 21   | DOOR LOCK ASSEMBLY     | RF-87286                                                                                                      | L559708 | OK            |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 934 604 27  
Document: MXQD-024-5752

PAGE 24/60  
DATE: 13/07/2026 10:20  
COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION                                                                                        | REFERENCE | LOT     | STATUS / NOTE                                                                         |
|------|--------------------------------------------------------------------------------------------------------------|-----------|---------|---------------------------------------------------------------------------------------|
| 01   | CLIMATE CONTROL UNIT                                                                                         | RF-89496  | L194357 | OK                                                                                    |
| 02   | LOWER ARM FASTENER                                                                                           | RF-11876  | L760459 | OK                                                                                    |
| 03   | REAR CAMERA MODULE                                                                                           | RF-48253  | L383873 | OK                                                                                    |
| 04   | FRONT AXLE BRACKET                                                                                           | RF-62374  | L441545 | OK                                                                                    |
| 05   | BATTERY SUPPORT                                                                                              | RF-98910  | L119270 | OK                                                                                    |
| 06   | BRAKE HOSE SUPPORT                                                                                           | RF-51184  | L623906 | OK                                                                                    |
| 07   | LOWER ARM FASTENER                                                                                           | RF-91413  | L195673 | OK                                                                                    |
| 08   | PARKING SENSOR                                                                                               | RF-55664  | L534524 | OK                                                                                    |
| 09   | DOOR LOCK ASSEMBLY                                                                                           | RF-30674  | L751216 | OK                                                                                    |
| 10   | BRAKE HOSE SUPPORT                                                                                           | RF-41333  | L266282 | REVIEW                                                                                |
| 11   | ENGINE WIRING HARNESS                                                                                        | RF-75815  | L332694 | OK                                                                                    |
| 12   | <br>CODE 39 MX-24-03-3707 | RF-20641  | L533217 | REVIEW                                                                                |
| 13   |                                                                                                              | RF-95013  | L410935 | REVIEW                                                                                |
| 14   | FRONT AXLE BRACKET                                                                                           | RF-61502  | L406081 | OK                                                                                    |
| 15   | BRAKE HOSE SUPPORT                                                                                           | RF-83930  | L155864 | REVIEW                                                                                |
| 16   | ENGINE WIRING HARNESS                                                                                        | RF-98199  | L606656 |  |
| 17   | FRONT AXLE BRACKET                                                                                           | RF-69910  | L948503 |                                                                                       |
| 18   | ENGINE WIRING HARNESS                                                                                        | RF-96088  | L382593 | OK                                                                                    |
| 19   | ENGINE WIRING HARNESS                                                                                        | RF-51836  | L969220 | OK                                                                                    |
| 20   | PARKING SENSOR                                                                                               | RF-98690  | L651890 | OK                                                                                    |
| 21   | BATTERY SUPPORT                                                                                              | RF-55836  | L783153 | REVIEW                                                                                |

| VISUAL / DIMENSIONAL    |                                                                                                  | FUNCTION / IDENTITY     |                                                                                                  |
|-------------------------|--------------------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------|
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |                         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |                         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 961 622 29  
Document: MXQD-026-5376

DATE: 13/07/2026 08:51

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B262533  
STATION QC-18

SERIAL SN4551010371  
DECISION REVIEW

| CHARACTERISTIC        | LOW   | HIGH  | VALUE                   | UNIT                    | RESULT |
|-----------------------|-------|-------|-------------------------|-------------------------|--------|
| BRAKE HOSE SUPPORT    | 20.61 | 37.76 | 33.30                   | mm                      | PASS   |
| CLIMATE CONTROL UNIT  | 0.59  | 3.17  | 1.12                    | mm                      | PASS   |
| BATTERY SUPPORT       | 27.04 | 47.79 | 40.46                   | deg                     | PASS   |
| PARKING SENSOR        | 53.59 | 85.47 | 59.73                   | deg                     | PASS   |
| SEAT RA               | 27.54 | 35.46 | CODE 128 LOT-667566-P26 | mm                      | HOLD   |
| BATTERY SUPPORT       | 13.92 | 20.59 | 17.81                   | mm                      | PASS   |
| BRAKE HOSE SUPPORT    | 32.28 | 54.22 | 35.15                   | deg                     | HOLD   |
| BRAKE HOSE SUPPORT    | 40.53 | 50.33 | 47.46                   | deg                     | PASS   |
| AIRBAG CONTROL MODULE | 5.43  | 33.55 | 12.28                   |                         | PASS   |
| REAR CAMERA MODULE    | 42.58 | 63.29 | 57.85                   | CODE 128 LOT-761505-P26 | PASS   |
| LOWER ARM FASTENER    | 8.17  | 32.46 | 12.61                   | mm                      | PASS   |
| REAR CAMERA MODULE    | 24.84 | 49.86 | 25.33                   | deg                     | PASS   |
| LOWER ARM FASTENER    | 22.09 | 40.28 | 35.32                   | mm                      | PASS   |
| FRONT AXLE BRACKET    | 25.10 | 32.00 | 28.00                   | mm                      | PASS   |
| CLIMATE CONTROL UNIT  | 5.21  | 25.84 | 7.48                    | deg                     | PASS   |
| BATTERY SUPPORT       | 9.29  | 32.88 | 28.94                   | V                       | PASS   |
| AIRBAG CONTROL MODULE | 40.09 | 63.32 | 61.14                   | deg                     | PASS   |
| DOOR LOCK ASSEMBLY    | 14.93 | 27.16 | 19.33                   | V                       | PASS   |
| REAR CAMERA MODULE    | 34.80 | 37.95 | 37.67                   | Nm                      | PASS   |
| BRAKE HOSE SUPPORT    | 26.78 | 49.20 | 29.11                   | V                       | PASS   |
| SEAT RAIL FIXING      | 48.26 | 70.76 | 53.67                   | mm                      | PASS   |
| REAR CAMERA MODULE    | 43.28 | 77.84 | 63.53                   | mm                      | PASS   |
| PARKING SENSOR        | 1.75  | 34.45 | 3.42                    | deg                     | PASS   |
| BATTERY SUPPORT       | 48.68 | 50.83 | 50.66                   | Nm                      | PASS   |

**SYNTHETIC MIXED QUALITY DOSSIER**

Sequence: 288 107 76  
Document: MXQD-027-2590

PAGE 27/60

DATE: 13/07/2026 11:00

CONTROL CERTIFICATE

**CERTIFICATE OF CONFORMITY**

|                  |                |
|------------------|----------------|
| PRODUCTION ORDER | PO-53240670    |
| MODEL / VARIANT  | K9-VU          |
| SERIAL NUMBER    | MX832277898338 |
| INSPECTION PLAN  | QP-85.4        |
| DECISION         | CONDITIONAL    |

**Inspection summary**

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 331 924 74

Document: MXQD-028-2244

PAGE 28/60

DATE: 13/07/2026 16:42

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY



CODE 128 PO10443509450

PRODUCTION ORDER

PO-27690588

MODEL / VARIANT

K9-VU



CODE 128 LOT-531486-P28

SERIAL NUMBER

MX763620642502

INSPECTION PLAN

QP-22.3

DECISION

ACCEPTED

Inspection summary



Inspector signature:

QC  
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 695 626 87  
Document: MXQD-029-5628

PAGE 29/60

DATE: 13/07/2026 09:21  
COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | AIRBAG CONTROL MODULE | RF-47571  | L865445 | OK            |
| 02   | LOWER ARM FASTENER    | RF-46677  | L144194 | OK            |
| 03   | LOWER ARM FASTENER    | RF-39917  | L281750 | OK            |
| 04   | CLIMATE CONTROL UNIT  | RF-98543  | L192765 | OK            |
| 05   | CLIMATE CONTROL UNIT  | RF-17801  | L671636 | OK            |
| 06   | PARKING SENSOR        | RF-73008  | L208141 | OK            |
| 07   | FRONT AXLE BRACKET    | RF-94271  | L216148 | OK            |
| 08   | CLIMATE CONTROL UNIT  | RF-56569  | L773405 | REVIEW        |
| 09   | AIRBAG CONTROL MODULE | RF-37213  | L630131 | OK            |
| 10   | FRONT AXLE BRACKET    | RF-41413  | L322531 | OK            |
| 11   | BRAKE HOSE SUPPORT    | RF-41037  | L638998 | OK            |
| 12   | DOOR LOCK ASSEMBLY    | RF-11805  | L858646 | OK            |
| 13   | AIRBAG CONTROL MODULE | RF-93625  | L901866 | OK            |
| 14   | BRAKE HOSE SUPPORT    | RF-48834  | L729217 | OK            |
| 15   | BATTERY SUPPORT       | RF-48806  | L672957 | REVIEW        |
| 16   | RIGHT SIDE PANEL      | RF-13521  | L413111 | OK            |
| 17   | RIGHT SIDE PANEL      | RF-80826  | L952993 | OK            |
| 18   | CLIMATE CONTROL UNIT  | RF-24819  | L940340 | REVIEW        |
| 19   | RIGHT SIDE PANEL      | RF-47065  | L189345 | OK            |
| 20   | BATTERY SUPPORT       | RF-13710  | L584284 | OK            |
| 21   | BATTERY SUPPORT       | RF-15987  | L316448 | OK            |



DATA MATRIX: 01/09500002332310

SYNTHETIC MIXED QUALITY DOSSIER



Sequence: 854 350 20  
Document: MXQD-030-8221

PAGE 30/60

DATE: 13/07/2026 08:43

FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                      |
|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                     | No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Label presence <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                     |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Torque confirmed <input type="checkbox"/> N/A                                                                            | Surface <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                 |
| Seal continuous                                                                                                          | Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing                                                                                                          | No visible damage <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                  |
| Cover installed                                                                                                          | Label presence <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                     |
| Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   |
| Reference matches order <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Connector locked <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                   |
| Protective film removed <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                        |                                                                                                                          |



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 919 223 19  
Document: MXQD-031-2522

PAGE 31/60  
DATE: 3/07/2026 08:58  
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B508838  
STATION QC-12

SERIAL SN1038693955  
DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| RIGHT SIDE PANEL      | 42.34 |       | 42.57 | V    | HOLD   |
| RIGHT SIDE PANEL      | 45.93 |       | 59.06 | mm   | HOLD   |
| ENGINE WIRING HARNESS |       | 32.73 | 32.38 | N/A  | HOLD   |
| REAR CAMERA MODULE    |       | 45.06 | 21.58 | mm   | PASS   |
| CLIMATE CONTROL UNIT  |       | 77.86 | 65.16 | deg  | PASS   |
| PARKING SENSOR        | 48.55 | 81.54 | 56.82 | V    | PASS   |
| REAR CAMERA MODULE    | 18.77 | 31.81 | 21.06 | deg  | HOLD   |
| ENGINE WIRING HARNESS | 7.63  | 33.74 |       |      |        |
| CLIMATE CONTROL UNIT  | 20.50 | 28.28 |       |      |        |
| LOWER ARM FASTENER    | 1.72  | 12.00 |       |      |        |
| CLIMATE CONTROL UNIT  | 53.89 | 75.23 |       |      |        |
| BATTERY SUPPORT       | 44.89 | 70.72 |       |      |        |
| REAR CAMERA MODULE    | 31.72 | 50.33 |       |      |        |
| RIGHT SIDE PANEL      | 22.92 | 51.54 |       |      |        |
| AIRBAG CONTROL MODULE | 12.11 | 30.45 |       |      |        |
| DOOR LOCK ASSEMBLY    | 44.24 | 64.78 |       |      |        |
| SEAT RAIL FIXING      | 27.36 | 52.62 | 36.84 | V    | HOLD   |
| FRONT AXLE BRACKET    | 38.60 | 73.68 | 41.16 | V    | HOLD   |
| DOOR LOCK ASSEMBLY    | 43.98 | 75.26 | 51.32 | mm   | PASS   |
| SEAT RAIL FIXING      | 45.23 | 56.64 | 55.37 | N/A  | PASS   |
| SEAT RAIL FIXING      | 23.83 | 25.89 | 25.73 | N/A  | PASS   |
| REAR CAMERA MODULE    | 28.43 | 59.15 | 48.58 | V    | PASS   |
| AIRBAG CONTROL MODULE | 2.41  | 14.54 | 4.78  | V    | PASS   |
| PARKING SENSOR        | 30.02 | 56.88 | 36.30 | V    | PASS   |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 788 582 79  
Document: MXQD-032-4797

PAGE 32/60  
DATE: 13/07/2026 09:32  
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B103333  
STATION QC-11


SERIAL SN5576082217  
DECISION REVIEW

| CHARACTERISTIC        | VALUE | UNIT | RESULT |
|-----------------------|-------|------|--------|
| PARKING SENSOR        | 7.38  | mm   | PASS   |
| RIGHT SIDE PANEL      | 15.01 |      |        |
| LOWER ARM FASTENER    | 3.64  |      |        |
| BRAKE HOSE SUPPORT    | 24.34 |      |        |
|                       | 49.98 |      |        |
|                       | 44.66 | mm   | PASS   |
|                       | 20.70 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 7.02  | V    | PASS   |
| LOWER ARM FASTENER    | 12.25 | deg  | HOLD   |
| ENGINE WIRING HARNESS | 0.91  | Nm   | HOLD   |
| PARKING SENSOR        | 11.55 | V    | PASS   |
| AIRBAG CONTROL MODULE | -3.00 | Nm   | HOLD   |
| LOWER ARM FASTENER    | 41.81 | Nm   | PASS   |
| CLIMATE CONTROL UNIT  | 52.58 | Nm   | PASS   |
| BRAKE HOSE SUPPORT    | 17.96 | deg  | PASS   |
| BRAKE HOSE SUPPORT    | 54.87 | deg  | HOLD   |
| CLIMATE CONTROL UNIT  | 11.82 | Nm   | PASS   |
| AIRBAG CONTROL MODULE | 34.21 | deg  | PASS   |
| DOOR LOCK ASSEMBLY    | 10.25 | mm   | PASS   |
| BATTERY SUPPORT       | 24.10 | deg  | PASS   |
| AIRBAG CONTROL MODULE | 30.82 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 12.50 | deg  | PASS   |
| AIRBAG CONTROL MODULE | 47.62 | deg  | PASS   |
| RIGHT SIDE PANEL      | 24.56 | deg  | HOLD   |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 178 386 95  
Document: MXQD-033-2935

PAGE 33/60  
DATE: 13/07/2026 01:10  
CONTROL CERTIFICATE



CERTIFICATE OF CONFORMITY

|                  |                |
|------------------|----------------|
| PRODUCTION ORDER | PO-81314478    |
| MODEL / VARIANT  | K9-VU          |
| SERIAL NUMBER    | MX841089939802 |
| INSPECTION PLAN  | QP-58.4        |
| DECISION         |                |




Inspection summary

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |



QR CODE <https://example.invalid/mixed/033/03/1961>

Inspector signature:



# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 978 941 98

Document: MXQD-034-9911

PAGE 34/60

DATE: 13/07/2026 18:28

## COMPONENT TRACEABILITY LOG

### REFERENCE / LOT / VALIDATION RECORD

| STEP                                                                                          | COMPONENT / OPERATION                                                                   | REFERENCE                                                                                                      | LOT     | STATUS / NOTE |
|-----------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|---------|---------------|
| 01                                                                                            | CLIMATE CONTROL UNIT                                                                    | RF-11419                                                                                                       | L924245 | OK            |
| 02                                                                                            | BATTERY SUPPORT                                                                         | RF-76709                                                                                                       | L462407 | REVIEW        |
| 03                                                                                            | LOWER ARM FASTENER                                                                      | RF-42470                                                                                                       | L435909 | OK            |
| 04                                                                                            | CLIMATE CONTROL UNIT                                                                    | RF-40877                                                                                                       | L966268 | REVIEW        |
| 05                                                                                            | PARKING SENSOR                                                                          | RF-97993                                                                                                       | L852435 | REVIEW        |
| 06                                                                                            | RIGHT SIDE PANEL                                                                        | RF-91764                                                                                                       | L430833 | OK            |
| 07                                                                                            | FRONT AXLE BRACKET                                                                      | RF-94070                                                                                                       | L281550 | OK            |
| 08                                                                                            | BATTERY SUPPORT                                                                         | RF-87965                                                                                                       | L986512 | OK            |
| 09                                                                                            | BATTERY SUPPORT                                                                         | RF-96771                                                                                                       | L112692 | REVIEW        |
| 10                                                                                            | PARKING SENSOR                                                                          | RF-45224                                                                                                       | L652970 | OK            |
| 11                                                                                            | BRAKE HOSE SUPPORT                                                                      | RF-34213                                                                                                       | L946337 | OK            |
| 12                                                                                            |  IIT | RF-14168                                                                                                       | L558649 | OK            |
| 13                                                                                            | AIRBAG CONTROL MODULE                                                                   | RF-62041                                                                                                       | L385201 | OK            |
| 14                                                                                            | LOWER ARM FASTENER                                                                      | RF-87198                                                                                                       | L135880 | OK            |
| 15                                                                                            | CLIMATE CONTROL UNIT                                                                    | RF-94203                                                                                                       | L792625 | OK            |
| 16                                                                                            | BRAKE HOSE SUPPORT                                                                      | RF-39936                                                                                                       | L184129 | OK            |
| 17                                                                                            | BATTERY SUPPORT                                                                         | RF-96959                                                                                                       | L919461 | REVIEW        |
| 18                                                                                            | REAR CAMERA MODULE                                                                      | RF-45692                                                                                                       | L473499 | OK            |
| 19                                                                                            | BATTERY SUPPORT                                                                         | RF-91218                                                                                                       | L397619 | OK            |
|  DATA MATR | REAR CAMERA MODULE                                                                      |                                                                                                                | L455213 | OK            |
| 21         | LOWER ARM FASTENER                                                                      |  DATA MATR: 04560P034/018 | L127475 | OK            |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 602 581 67  
Document: MXQD-035-7801

| VISUAL / DIMENSIONAL    |                                                                                                  | FUNCTION / IDENTITY   |                                                                                                  |
|-------------------------|--------------------------------------------------------------------------------------------------|-----------------------|--------------------------------------------------------------------------------------------------|
| Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed       | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Torque confirmed      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Gap within limit      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Harness routing       | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Protective film removed | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Surface condition     | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage     | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Gap within limit      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Gap within limit      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 773 632 74

Document: MXQD-036-6566

PAGE 36/60

DATE: 13/07/2026 22:22

FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                      |
|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|
| No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | No visible damage <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                  |
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Protective film removed <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        |
| No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         |
| Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       |
| Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         |
| Protective film removed <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 475 455 20  
Document: MXQD-037-4799

DATE: 13/07/2026 22:03

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

|         |         |          |              |
|---------|---------|----------|--------------|
| BATCH   | B183854 | SERIAL   | SN9658604754 |
| STATION | QC-12   | DECISION | OK           |

| CHARACTERISTIC        | LOW   | HIGH                       | VALUE | UNIT | RESULT |
|-----------------------|-------|----------------------------|-------|------|--------|
| REAR CAMERA MODULE    | -1.40 | 14.16                      | -0.05 | Nm   | PASS   |
| SEAT RAIL             | 21.58 | 54.82                      | 49.38 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 13.95 | 41.93                      | 28.38 | V    | PASS   |
| PARKING SENSOR        | 54.80 | 57.00                      | 56.01 | Nm   | HOLD   |
| REAR CAMERA MODULE    | 45.79 | 80.34                      | 76.37 | V    | PASS   |
| FRONT AXLE BRACKET    | 11.29 | 42.59                      | 27.46 | V    | PASS   |
| CLIMATE CONTROL UNIT  | 35.70 | 53.92                      | 44.34 | V    | PASS   |
| FRONT AXLE BRACKET    | 40.27 | 54.99                      | 53.36 | mm   | PASS   |
| RIGHT SIDE PANEL      | 29.64 | 47.78                      | 37.09 | Nm   | PASS   |
| DOOR LOCK ASSEMBLY    | 39.74 | 49.64                      | 45.03 | V    | PASS   |
| REAR CAMERA MODULE    | 41.71 | 60.13                      | 52.86 | V    | HOLD   |
| RIGHT SIDE PANEL      | 4.93  | 39.43                      | 16.07 | deg  | PASS   |
| RIGHT SIDE PANEL      | 17.37 | 51.67                      | 24.16 | deg  | PASS   |
| AIRBAG CONTROL MODULE | 23.02 | 38.11                      | 35.48 | V    | HOLD   |
| ENGINE WIRING HARNESS | 28.45 | 59.03                      | 44.43 | V    | PASS   |
| BRAKE HOSE SUPPORT    | 12.67 | 2                          | 43.86 | mm   | HOLD   |
| PARKING SENSOR        | 42.56 | DATA MATRIX DM(MX(P037)) 8 | 42.97 | V    | PASS   |
| RIGHT SIDE PANEL      | 50.81 | 75.96                      | 56.67 | mm   | HOLD   |
| SEAT RAIL FIXING      | 30.26 | 52.51                      | 36.58 | deg  | PASS   |
| BRAKE HOSE SUPPORT    | 51.69 | 73.47                      | 52.64 | Nm   | PASS   |
| ENGINE WIRING HARNESS | 38.33 | 49.22                      | 41.11 | Nm   | HOLD   |
| ENGINE WIRING HARNESS | 18.51 | 35.77                      | 23.05 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 7.70  | 17.06                      | 14.44 | deg  | PASS   |
| RIGHT SIDE PANEL      | 46.70 | 77.64                      | 49.93 | mm   | PASS   |

CERTIFICATE OF CONFORMITY

|                  |                |
|------------------|----------------|
| PRODUCTION ORDER | PO-26815478    |
| MODEL / VARIANT  | PX-STD         |
| SERIAL NUMBER    | MX582814352860 |
| INSPECTION PLAN  | QP-14.7        |
| DECISION         | CONDITIONAL    |

Inspection summary

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |
|  |  |  |  |

Inspector signature:

CODE 128 PO38300417744



S



## SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 931 572 76

Document: MXQD-039-5105

PAGE 39/60

DATE: 13/07/2026 02:20

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE                                                                            | LOT     | STATUS / NOTE |
|------|-----------------------|--------------------------------------------------------------------------------------|---------|---------------|
| 01   | BRAKE HOSE SUPPORT    | RF-33277                                                                             | L267795 | REVIEW        |
| 02   | SEAT RAIL FIXING      | RF-18598                                                                             | L419280 | OK            |
| 03   | SEAT RAIL FIXING      | RF-90000                                                                             | L189430 | OK            |
| 04   | ENGINE WIRING HARNESS | RF-74436                                                                             | L927493 | OK            |
| 05   | CLIMATE CONTROL UNIT  | RF-43173                                                                             | L146308 | OK            |
| 06   | RIGHT SIDE PANEL      | RF-17840                                                                             | L219605 | OK            |
| 07   | LOWER ARM FASTENER    |  | L786938 | REVIEW        |
| 08   | DOOR LOCK ASSEMBLY    |                                                                                      | L651650 | REVIEW        |
| 09   | LOWER ARM FASTENER    | RF-3bU08                                                                             | L267276 | OK            |
| 10   | BRAKE HOSE SUPPORT    | RF-25597                                                                             | L797388 | REVIEW        |
| 11   | BATTERY SUPPORT       | RF-30917                                                                             | L160389 | OK            |
| 12   | REAR CAMERA MODULE    | RF-28435                                                                             | L391380 | OK            |
| 13   | SEAT RAIL FIXING      | RF-98097                                                                             | L245748 | REVIEW        |
| 14   | AIRBAG CONTROL MODULE | RF-43109                                                                             | L231970 | OK            |
| 15   | BRAKE HOSE SUPPORT    | RF-27396                                                                             | L393936 | OK            |
|      |                       | -35393                                                                               | L353541 | OK            |
|      |                       | -66639                                                                               | L984792 | OK            |
|      |                       | -15293                                                                               | L702066 | REVIEW        |
|      |                       | RF-36793                                                                             | L133140 | OK            |
| 19   | FRONT AXLE BRAKE      |                                                                                      |         |               |
| 20   | BRAKE HOSE SUPPORT    | RF-68910                                                                             | L529516 | OK            |
| 21   | AIRBAG CONTROL MODULE | RF-61440                                                                             | L959182 |               |

QR CODE: <https://example.invalid/mixed/039/05/>

CODE 39 MX-39-02-7101

CODE 128 PO92489047823

CODE 39 MX-39-01-8265

QR CODE: 371448X-039-03

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 426 786 17

Document: MXQD-040-1480

REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION |          | LOT     | STATUS / NOTE |
|------|-----------------------|----------|---------|---------------|
| 01   | DOOR LOCK ASSEMBLY    |          | L842683 | OK            |
| 02   | FRONT AXLE BRACKET    |          | L176258 | REVIEW        |
| 03   | REAR CAMERA MODULE    |          | L776972 | OK            |
| 04   | BRAKE HOSE SUPPORT    |          | L216158 | OK            |
| 05   | SEAT RAIL FIXING      | RF-22042 | L927101 | OK            |
| 06   | ENGINE WIRING HARNESS | RF-95694 | L567319 | OK            |
| 07   | SEAT RAIL FIXING      | RF-50943 | L414517 | OK            |
| 08   | BATTERY SUPPORT       | RF-27390 | L634303 | REVIEW        |
| 09   |                       | RF-62080 | L444467 | REVIEW        |
| 10   |                       | RF-70131 | L552427 | OK            |
| 11   |                       | RF-41955 | L413039 | REVIEW        |
| 12   | LOWER ARM FASTENER    | RF-86290 | L785466 | OK            |
| 13   | REAR CAMERA MODULE    | RF-93899 | L347692 | OK            |
| 14   | BRAKE HOSE SUPPORT    | RF-92320 | L722784 | OK            |

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 552 332 47

Document: MXQD-041-9848

PAGE 41/60

DATE: 13/07/2026 15:02

## FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|
| Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A   | Surface condition <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                              |
| Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                   |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                    |
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                   |
|                                                                                                                          |                                                                 |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Fastener witness mark <input checked="" type="checkbox"/> OK <small>QR CODE: <a href="https://example.invalid/">https://example.invalid/</a></small> |
| Cover installed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                    |
| Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                   |
| No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                      |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Gap within limit <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                               |
| Fastener witness mark <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                    |
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                    |
| No visible damage <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                     |

## SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 944 781 15

Document: MXQD-042-8528

PAGE 42/60

DATE: 13/07/2026 22:03

MEASUREMENT AND TRACEABILITY

## BATCH / CONTROL INFORMATION

BATCH B671136

STATION QC-25

SERIAL SN2862647899

DECISION REVIEW

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| SEAT RAIL FIXING      | 21.25 | 54.30 | 31.08 | Nm   | PASS   |
| ENGINE WIRING HARNESS | 7.57  | 26.47 | 13.81 | deg  | PASS   |
| REAR CAMERA MODULE    | 0.85  | 22.01 | 13.85 | mm   | PASS   |
| REAR CAMERA MODULE    | 15.48 | 43.18 | 15.78 | deg  | PASS   |
| REAR CAMERA MODULE    | 5.36  | 29.74 | 10.92 | V    | PASS   |
| REAR CAMERA MODULE    | 33.53 | 43.75 | 40.93 | Nm   | PASS   |
| REAR CAMERA MODULE    | 53.54 | 84.22 | 73.43 | mm   | PASS   |
| REAR CAMERA MODULE    | 54.04 | 73.69 | 68.35 | deg  | PASS   |
| ENGINE WIRING HARNESS | 48.01 | 71.55 | 49.57 | Nm   | HOLD   |
| PARKING SENSOR        | 53.81 | 82.41 | 65.52 | Nm   | PASS   |
| BRAKE HOSE SUPPORT    | 51.49 | 75.21 | 60.50 | deg  | PASS   |
| FRONT AXLE BRACKET    | 16.26 | 29.10 | 18.38 | deg  | PASS   |
| SEAT RAIL FIXING      | 36.70 | 44.47 | 40.30 | Nm   | PASS   |
| AIRBAG CONTROL MODULE | 14.09 | 41.52 | 19.50 | Nm   | PASS   |
| RIGHT SIDE PANEL      | 39.75 | 67.15 | 43.06 | mm   | PASS   |
| DOOR LOCK ASSEMBLY    | 10.72 | 19.34 | 18.63 | deg  | HOLD   |
| BATTERY SUPPORT       | 25.09 | 42.98 | 33.61 | deg  | PASS   |
| LOW                   | 11.04 | 37.13 | 20.62 | deg  | PASS   |
| LOW                   | 19.67 | 33.57 | 27.47 | Nm   | PASS   |
| RIGH                  | 30.83 | 62.85 | 60.12 | Nm   | PASS   |
| BATTERY SUPPORT       | 10.71 | 37.91 | 22.25 | Nm   | PASS   |
| REAR CAMERA MODULE    | 33.80 | 57.37 | 36.75 | V    | PASS   |
| BRAKE HOSE SUPPORT    | 51.16 | 67.27 | 62.28 | V    | PASS   |
| PARKING SENSOR        | 32.11 | 63.26 | 45.04 | mm   | HOLD   |



DATA MATRIX 010



QR CODE: https://

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 480 943 78

Document: MXQD-043-1863

PAGE 43/60

DATE: 13/07/2026 22:33

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER

PO-14465253

MODEL / VARIANT

K9-VU

SERIAL NUMBER

MX785354620942

INSPECTION PLAN

QP-71.1

DECISION

ACCEPTED

Inspection summary

|                                                                                     |  |                                                                                                                 |                                                                                                              |
|-------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------|
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|  |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  |                                                                                                                 |                                                                                                              |
|                                                                                     |  | <br>CODE 128 LOT-415752-P43 | <br>JE 39 MX-43-01-7541 |

Inspector signature:

QC  
PASS



## SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 871 780 24

Document: MXQD-045-9221

PAGE 45/60

DATE: 13/07/2026 19:44

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | PARKING SENSOR        | RF-78561  | L855258 | OK            |
| 02   | CLIMATE CONTROL UNIT  | RF-65559  | L880281 | OK            |
| 03   | CLIMATE CONTROL UNIT  | RF-22801  | L365983 | REVIEW        |
| 04   | SEAT RAIL FIXING      | RF-62594  | L217132 | OK            |
| 05   | AIRBAG CONTROL MODULE | RF-96421  | L474666 | OK            |
| 06   | LOWER ARM FASTENER    | RF-72683  | L906833 | OK            |
| 07   | BATTERY SUPPORT       | RF-33366  | L833982 | OK            |
| 08   | REAR CAMERA MODULE    | F-92662   | L643868 | REVIEW        |
| 09   | LOWER ARM FASTENER    | RF-47597  | L721500 | OK            |
| 10   | LOWER ARM FASTENER    | RF-35602  | L811975 | OK            |
| 11   | SEAT RAIL FIXING      | RF-99696  | L784967 | REVIEW        |
| 12   | RIGHT SIDE PANEL      | RF-69959  | L880679 | OK            |
| 13   | PARKING SENSOR        | RF-86921  | L922490 | OK            |
| 14   | ENGINE WIRING HARNESS | RF-42747  | L608302 | OK            |
| 15   | DOOR LOCK ASSEMBLY    | RF-35524  | L292950 | OK            |
| 16   | BATTERY SUPPORT       | RF-41940  | L291967 | OK            |
| 17   | ENGINE WIRING HARNESS |           |         |               |
| 18   | DOOR LOCK ASSEMBLY    |           |         |               |
| 19   | ENGINE WIRING HARNESS |           |         |               |
| 20   | FRONT AXLE BRACKET    |           | L755334 | REVIEW        |
| 21   | SEAT RAIL FIXING      |           | L444160 | OK            |

|                                                                                                   |                                                                                          |
|---------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|
| <b>SYNTHETIC MIXED QUALITY DOSSIER</b><br><br>Sequence: 571 357 31<br><br>Document: MXQD-046-4412 | <b>PAGE 46/60</b><br><br>DATE: 13/07/2026 21:42<br><br><b>FINAL INSPECTION CHECKLIST</b> |
|---------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|

| VISUAL / DIMENSIONAL                                                                                               |                                                                                                                                                                                                   | FUNCTION / IDENTITY                                                                                                    |
|--------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------|
| Torque confirmed                                                                                                   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Seal continuous                                                                                                    | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Harness routing                                                                                                    | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A     |
| Torque confirmed                                                                                                   |                                                                                                               | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| <br>DATA MATRIX: DMXQD-046-4412 | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                             | Reference matches order <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A          |
| Connector locked                                                                                                   | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                             | Protective film removed <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A          |
| Label presence                                                                                                     | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A<br><br>DATA N | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        |
| Seal continuous                                                                                                    | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A     |
| Label presence                                                                                                     | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Fastener witness mark                                                                                              | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Torque confirmed <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                 |
| Harness routing                                                                                                    | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A      |
| Connector locked                                                                                                   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                  | No visible damage <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 997 890 66  
Document: MXQD-047-7886

PAGE 47/60

DATE: 13/07/2026 18:55

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B548992  
STATION QC-21

SERIAL SN4125589789  
DECISION OK

| CHARACTERISTIC       | LOW   | HIGH  | VALUE | UNIT | RESULT |
|----------------------|-------|-------|-------|------|--------|
| DOOR LOCK ASSEMBLY   | 49.71 | 74.73 | 61.96 | deg  | PASS   |
| RIGHT SIDE PANEL     | 40.15 | 55.68 | 51.12 | Nm   | PASS   |
| LOWER ARM FASTENER   | 8.83  | 41.74 | 17.19 | deg  | PASS   |
| CLIMATE CONTROL UNIT | 17.04 | 49.49 | 38.53 | V    | PASS   |
| BRAKE HOSE SUPPORT   | 19.58 | 37.96 | 33.47 | deg  | PASS   |
| RIGHT SIDE PANEL     | 34.75 | 69.79 | 48.05 | deg  | HOLD   |
| REAR CAMERA MODULE   | 39.65 | 54.48 | 53.27 | Nm   | PASS   |
| CLIMATE CONTROL UNIT | 43.65 | 53.92 | 46.27 | V    | HOLD   |
| PARKING SENSOR       | 35.93 | 53.58 | 47.08 | V    | PASS   |
| FRONT AXLE BRACKET   | 16.03 | 25.89 | 17.34 | deg  | PASS   |
| RIGHT SIDE PANEL     | 34.73 | 58.93 | 46.53 | deg  | HOLD   |
| SEAT RAIL FIXING     | 34.53 | 55.97 | 40.44 | Nm   | PASS   |
| SEAT RAIL FIXING     | 40.59 |       |       |      |        |
| RIGHT SIDE PANEL     | 39.91 |       |       | V    | PASS   |
| CLIMATE CONTROL UNIT | 29.81 | 36.58 | 32.18 | V    | HOLD   |
| BATTERY SUPPORT      | 43.10 | 60.27 | 48.98 | Nm   | PASS   |
|                      |       |       |       | deg  | PASS   |



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 559 365 94  
Document: MXQD-048-3809

PAGE 48/60

DATE: 13/07/2026 18:06

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B940890  
STATION QC-31

SERIAL SN5309398424  
DECISION OK

| CHARACTERISTIC        | LOW   | HIGH                                                                                 | VALUE | UNIT | RESULT |
|-----------------------|-------|--------------------------------------------------------------------------------------|-------|------|--------|
| RIGHT SIDE PANEL      | 1.80  | 28.25                                                                                | 27.71 | V    | PASS   |
| FRONT AXLE BRACKET    | 42.67 | 56.83                                                                                | 49.92 | deg  | PASS   |
| FRONT AXLE BRACKET    | 23.23 |  |       | deg  | PASS   |
| FRONT AXLE BRACKET    | 44.80 |                                                                                      |       | mm   | HOLD   |
| BRAKE HOSE SUPPORT    | 50.71 | 82.81                                                                                | 65.38 | V    | PASS   |
| SEAT RAIL FIXING      | 37.74 | 63.87                                                                                | 61.66 | mm   | PASS   |
| CLIMATE CONTROL UNIT  | 32.65 | 46.75                                                                                | 34.65 | Nm   | HOLD   |
| PARKING SENSOR        | 44.53 | 56.02                                                                                | 47.80 | Nm   | PASS   |
| DOOR LOCK ASSEMBLY    | 9.96  | 44.69                                                                                | 40.78 | mm   | PASS   |
| AIRBAG CONTROL MODULE | 34.00 | 49.96                                                                                | 38.97 | mm   | HOLD   |
| DOOR LOCK ASSEMBLY    | 54.48 | 83.08                                                                                | 64.26 | Nm   | PASS   |
| AIRBAG CONTROL MODULE | 22.13 | 49.49                                                                                | 32.65 | mm   | PASS   |
| LOWER ARM FASTENER    | 52.35 | 74.21                                                                                | 60.75 | mm   | HOLD   |
| AIRBAG CONTROL MODULE | 28.11 | 36.85                                                                                | 35.73 | mm   | PASS   |
| BATTERY SUPPORT       | 7.74  | 28.53                                                                                | 10.57 | Nm   | PASS   |
| DOOR LOCK ASSEMBLY    | 47.34 | 54.70                                                                                | 51.30 | V    | HOLD   |
| PARKING SENSOR        | 4.23  | 24.62                                                                                | 22.64 | V    | PASS   |
| AIRBAG CONTROL MODULE | 22.46 | 66.28                                                                                | 53.14 | Nm   | PASS   |
| ENGINE WIRING HARNESS | 19.55 | 54.15                                                                                | 46.79 | V    | HOLD   |
| REAR CAMERA MODULE    | 44.32 | 61.64                                                                                | 53.24 | Nm   | PASS   |
| AIRBAG CONTROL MODULE | 51.61 | 69.96                                                                                | 62.96 | mm   | PASS   |
| ENGINE WIRING HARNESS | 18.78 | 42.73                                                                                | 38.46 | mm   | HOLD   |
| REAR CAMERA MODULE    | 7.82  | 42.41                                                                                | 32.72 | mm   | HOLD   |
| DOOR LOCK ASSEMBLY    | 3.21  | 24.01                                                                                | 18.11 | Nm   | PASS   |

Sequence: 885 603 50

Document: MXQD-049-8678

PAGE 49/60

DATE: 13/07/2026 06:57

CONTROL CERTIFICATE



PRODUCTION ORDER

PO-26579440

MODEL / VARIANT

PX-STD

SERIAL NUMBER

MX142476961155

## INSPECTION PLAN

QP-92.3

### DECISION

ACCEPTED



CODE 39 MX-49-05-5900

  
CODE 39 MX-49-01-3906

Inspector signature: \_\_\_\_\_

QC  
PASS

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 713 909 71

Document: MXQD-050-7488

PAGE 50/60

DATE: 13/07/2026 18:19

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | DOOR LOCK ASSEMBLY    | RF-21409  | L967022 | REVIEW        |
| 02   | REAR CAMERA MODULE    | RF-30018  | L253297 | OK            |
| 03   | PARKING SENSOR        |           | L446479 |               |
| 04   | DOOR LOCK             |           | L304345 |               |
| 05   | FRONT AXLE            |           | L189657 |               |
| 06   | BRAKE HOSE SUPPORT    |           | L705511 |               |
| 07   | CLIMATE CONTROL UNIT  |           | L754660 |               |
| 08   | CLIMATE CONTROL UNIT  |           | L820993 |               |
| 09   | BRAKE HOSE SUPPORT    |           | L224394 |               |
| 10   | AIRBAG CONTROL MODULE |           | L147655 |               |
| 11   | FRONT AXLE BRACKET    |           | L884169 |               |
| 12   | FRONT AXLE BRACKET    |           | L635798 | OK            |
| 13   | CLIMATE CONTROL UNIT  | RF-30926  | L704197 | OK            |
| 14   | PARKING SENSOR        | RF-85612  | L619651 | OK            |
| 15   | BRAKE HOSE SUPPORT    |           |         |               |
| 16   | ENGINE WIRING HARNESS |           |         |               |
| 17   | LOWER ARM FASTENER    |           |         | REVIEW        |
| 18   | REAR CAMERA MODULE    |           |         | OK            |
| 19   | ENGINE WIRING HARNESS |           |         | OK            |
| 20   | SEAT RAIL FIXING      |           |         | OK            |
| 21   | SEAT RAIL FIXING      | RF-21895  | L165760 | OK            |

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 969 134 93

Document: MXQD-051-6814

PAGE 51/60

DATE: 13/07/2026 12:27

## FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL    |                                                                                                  | FUNCTION / IDENTITY     |                                                                                                  |
|-------------------------|--------------------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------|
| Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Gap within limit        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Torque confirmed        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Fastener witness mark   | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Connector locked *      | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Fastener witness mark   | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | No visible damage       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |



QR CODE: <https://example.invalid/mixed0516814282>

QR CODE: <https://example.invalid/mixed0516814282>

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 741 882 81

Document: MXQD-052-3062

PAGE 52/60

DATE: 13/07/2026 04:21

## FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL                                                                                                     | FUNCTION / IDENTITY                                                                                                                                                                                                      |
|--------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Seal continuous  <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A<br>CODE 39 MX-52-04-8845       |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                       |
| Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Harness routing <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                         |
| Gap within limit <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Cover installed <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                                    |
| Surface condition <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A       | Fastener witness mark <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                   |
| Reference matches order <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A | Connector locked <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                        |
| <br>CODE 128 MX0520142856224          | Label presence <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                                     |
| <br>CODE 39 MX-52-03-8306             | Reference matches order  <input type="checkbox"/> OK <input type="checkbox"/> N/A<br>CODE 39 MX-52-05-5475                          |
| Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Seal co  <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A<br>CODE 128 PO99000560663 |
| Cover inst <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Label presence <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                          |
| Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A         | Seal continuous <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                         |
| Torque confirmed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A        | Protective film removed <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                                                                                                 |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 331 736 70  
Document: MXQD-053-5987

PAGE 53/60  
DATE: 13/07/2026 09:17  
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B162550  
STATION QC-25

SERIAL SN9719198169  
DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| PARKING SENSOR        | -2.20 | 16.91 | 1.82  | Nm   | PASS   |
| RIGHT SIDE PANEL      | 47.69 | 73.42 | 71.35 | mm   | PASS   |
| ENGINE WIRING HARNESS | 10.89 | 32.53 | 27.44 | deg  | PASS   |
| BRAKE HOSE SUPPORT    | 39.95 | 53.57 | 43.63 | Nm   | HOLD   |
| AIRBAG CONTROL MODULE | 19.69 | 24.24 | 21.05 | V    | HOLD   |
| DOOR LOCK ASSEMBLY    | 32.91 | 38.20 | 33.36 | deg  | PASS   |
| PARKING SENSOR        | 45.88 | 50.95 | 48.02 | V    | PASS   |
| SEAT RAIL FIXING      | 48.46 | 65.85 | 49.90 | Nm   | PASS   |
| REAR CAMERA MODULE    | 16.57 | 27.86 | 24.37 | deg  | PASS   |
| REAR CAMERA MODULE    | 22.10 | 48.16 | 41.68 | deg  | PASS   |
| DOOR LOCK ASSEMBLY    | 16.52 | 23.93 | 20.83 | V    | PASS   |
| ENGINE WIRING HARNESS | 0.38  | 13.46 | 10.47 | mm   | PASS   |
| BRAKE HOSE SUPPORT    | 52.42 | 54.88 | 54.53 | deg  | PASS   |
| AIRBAG CONTROL MODULE | 48.41 | 81.73 | 78.44 | mm   | PASS   |
| ENGINE WIRING HARNESS | 7.07  | 25.81 | 22.56 | Nm   | PASS   |
| ENGINE WIRING HARNESS | 46.78 | 72.33 | 62.72 | V    | PASS   |
| CLIMATE CONTROL UNIT  | 38.00 | 59.81 | 59.02 | V    | PASS   |
| FRONT AXLE BRACKET    | 46.68 | 51.68 | 48.23 | V    | PASS   |
| REAR CAMERA MODULE    | 49.42 | 84.73 | 61.62 | V    | PASS   |
| CLIMATE CONTROL UNIT  | 44.19 | 73.42 | 68.63 | deg  | PASS   |
| PARKING SENSOR        | 45.50 | 70.70 | 54.45 | mm   | PASS   |
| BATTERY SUPPORT       | 50.35 | 63.80 | 63.34 | mm   | PASS   |
| REAR CAMERA MODULE    | 4.27  | 25.78 | 14.06 | deg  | HOLD   |
| DOOR LOCK ASSEMBLY    | 13.02 | 24.94 | 21.96 | Nm   | HOLD   |

## Sequence: 103 451 71

Document: MXQD-054-9191

PAGE 54/60

DATE: 13/07/2026 04:55

CONTROL CERTIFICATE

PRODUCTION ORDER

PO-47310260

MODEL / VARIANT  
MX-A7

SERIAL NUMBER

MX880156960591

INSPECTION PLAN QP-90.6

DECISION

ACCEPTED

### Inspection summary

Inspector signature: \_\_\_\_\_

QC  
PASS

## SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 762 404 81

Document: MXQD-055-9393

PAGE 55/60

DATE: 13/07/2026 19:06

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE                                                                                                                                                                          | LOT                                                                                                            | STATUS / NOTE                                                                                                   |
|------|-----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| 01   | PARKING SENSOR        | RF-75620                                                                                                                                                                           | L188736                                                                                                        | <br>CODE 128 LOT-663301-P55 |
| 02   | PARKING SENSOR        | RF-58550                                                                                                                                                                           | L574891                                                                                                        |                                                                                                                 |
| 03   | CLIMATE CONTROL UNIT  | RF-28137                                                                                                                                                                           | L153183                                                                                                        | REVIEW                                                                                                          |
| 04   | ENGINE WIRING HARNESS | RF-51426                                                                                                                                                                           | L818309                                                                                                        | OK                                                                                                              |
| 05   | REAR CAMERA MODULE    | <br>QR CODE: <a href="https://example.com/track/055-009">https://example.com/track/055-009</a> | L371756                                                                                                        | OK                                                                                                              |
| 06   | SEAT RAIL FIXING      |                                                                                                                                                                                    | L388937                                                                                                        | OK                                                                                                              |
| 07   | BRAKE HOSE SUPPORT    |                                                                                                                                                                                    | L364551                                                                                                        | OK                                                                                                              |
| 08   | AIRBAG CONTROL MODULE |                                                                                                                                                                                    | L796406                                                                                                        | OK                                                                                                              |
| 09   | DOOR LOCK ASSEMBLY    | RF-18826                                                                                                                                                                           | <br>CODE 39 MX-55-01-7525 | OK                                                                                                              |
| 10   | REAR CAMERA MODULE    | RF-13456                                                                                                                                                                           |                                                                                                                | REVIEW                                                                                                          |
| 11   | ENGINE WIRING HARNESS | RF-85763                                                                                                                                                                           | L211611                                                                                                        | OK                                                                                                              |
| 12   | PARKING SENSOR        | RF-67840                                                                                                                                                                           | L998491                                                                                                        | OK                                                                                                              |
| 13   | FRONT AXLE BRACKET    | RF-24751                                                                                                                                                                           | L645821                                                                                                        | OK                                                                                                              |
| 14   | BATTERY SUPPORT       | RF-36771                                                                                                                                                                           | L594430                                                                                                        | OK                                                                                                              |
| 15   | DOOR LOCK ASSEMBLY    | RF-11226                                                                                                                                                                           | L142728                                                                                                        | OK                                                                                                              |
| 16   | ENGINE WIRING HARNESS | RF-36168                                                                                                                                                                           | L630503                                                                                                        | OK                                                                                                              |
| 17   | BATTERY SUPPORT       | RF-37375                                                                                                                                                                           | L694591                                                                                                        | OK                                                                                                              |
| 18   | BATTERY SUPPORT       | RF-36043                                                                                                                                                                           | L441111                                                                                                        | OK                                                                                                              |
| 19   | RIGHT SIDE PANEL      | RF-97216                                                                                                                                                                           | L304012                                                                                                        | OK                                                                                                              |
| 20   | FRONT AXLE BRACKET    | RF-15148                                                                                                                                                                           | L113195                                                                                                        | OK                                                                                                              |
| 21   | FRONT AXLE BRACKET    | RF-78320                                                                                                                                                                           | L450145                                                                                                        | OK                                                                                                              |

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 732 504 88

Document: MXQD-056-6878

PAGE 56/60

DATE: 13/07/2026 09:37

COMPONENT TRACEABILITY LOG

## REFERENCE / LOT / VALIDATION RECORD

| STEP | COMPONENT / OPERATION | REFERENCE | LOT     | STATUS / NOTE |
|------|-----------------------|-----------|---------|---------------|
| 01   | CLIMATE CONTROL UNIT  | RF-70599  | L816092 | OK            |
| 02   | ENGINE WIRING HARNESS | RF-37974  | L156287 | OK            |
| 03   | CLIMATE CONTROL UNIT  | RF-65988  | L274453 | OK            |
| 04   | PARKING SENSOR        | RF-58343  | L405152 | OK            |
| 05   | FRONT AXLE BRACKET    | RF-79963  | L433484 | OK            |
| 06   | REAR CAMERA MODULE    | RF-66850  | L857887 | OK            |
| 07   | CLIMATE CONTROL UNIT  | RF-66883  | L788275 | REVIEW        |
| 08   | BATTERY SUPPORT       | RF-69233  | L766452 | OK            |
| 09   | BRAKE HOSE SUPPORT    | RF-43454  | L507332 | REVIEW        |
| 10   | BATTERY SUPPORT       | RF-67873  | L776052 | OK            |
| 11   | RIGHT SIDE PANEL      | RF-66696  | L255913 | OK            |
| 12   | PARKING SENSOR        | RF-40473  | L983920 | OK            |
| 13   | FRONT AXLE BRACKET    | RF-81876  | L310039 | OK            |
| 14   | ENGINE WIRING HARNESS | RF-42941  | L369557 | OK            |
| 15   | SEAT RAIL FIXING      | RF-86594  | L351053 | OK            |
| 16   | AIRBAG CONTROL MODULE | RF-72414  | L143896 | REVIEW        |
| 17   | BRAKE HOSE SUPPORT    | RF-72491  | L260297 | OK            |
| 18   | RIGHT SIDE PANEL      | RF-28578  | L780427 | OK            |
| 19   | FRONT AXLE BRACKET    | RF-29174  | L770129 | REVIEW        |
| 20   | LOWER ARM FASTENER    | RF-55527  | L633754 | OK            |
| 21   | ENGINE WIRING HARNESS | RF-11896  | L969551 | OK            |



DATA MATRIX: 010950600027395

# SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 450 908 28  
Document: MXQ: 057-8074

PAGE 57/60

DATE: 13/07/2026 06:54

## FINAL INSPECTION CHECKLIST

| VISUAL / DIMENSIONAL    |                                                                                                               | FUNCTION / IDENTITY     |                                                                                                  |
|-------------------------|---------------------------------------------------------------------------------------------------------------|-------------------------|--------------------------------------------------------------------------------------------------|
| Protective film removed | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Connector locked        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                         | Connector locked        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Surface condition       | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Gap within limit        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                         | Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| No visible damage       | <br>CODE 128 PO58346999914 | matches order           | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Label presence          | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Fastener witness mark   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Fastener witness mark   | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              |                         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Seal continuous         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              |                         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
|                         | CODE 128 PO47733539880                                                                                        |                         |                                                                                                  |
| Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Cover installed         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A                         | Harness routing         | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |
| Reference matches order | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Torque confirmed        | <input type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A            |
| Torque confirmed        | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A              | Label presence          | <input checked="" type="checkbox"/> OK <input type="checkbox"/> NOK <input type="checkbox"/> N/A |

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 676 110 87

Document: MXQD-058-4245

BATCH / CONTROL INFORMATION

BATCH B402550

STATION QC-26

SERIAL SN1172932423

DECISION OK

| CHARACTERISTIC        | LOW   | HIGH  | VALUE | UNIT | RESULT |
|-----------------------|-------|-------|-------|------|--------|
| ENGINE WIRING HARNESS | 4.75  | 33.95 | 20.02 | Nm   | PASS   |
| FRONT AXLE BRACKET    | 21.38 | 52.16 | 42.89 | Nm   | PASS   |
| LOWER ARM FAST        | 35.30 | 57.98 | 56.94 |      | HOLD   |
| BRAKE HOSE SUPP       | -2.88 | 11.49 | 11.00 |      | PASS   |
| SEAT RAIL FIXING      | 38.11 | 43.11 | 41.06 |      | HOLD   |
| DOOR LOCK ASSEMBLY    | 48.24 | 80.88 | 69.84 |      | HOLD   |
| PARKING SENSOR        | 16.72 |       | 38.95 | V    | PASS   |
| FRONT AY              |       |       |       |      | PASS   |
| SEAT RAIL             |       |       |       |      | HOLD   |
| DOOR LO               |       |       |       |      |        |
| ENGINE WIRING HARNESS | 31.30 | 44.25 |       |      |        |
| BRAKE HOSE SUPPORT    | 24.12 | 47.42 |       |      |        |
| RIGHT SIDE PANEL      | 8.39  | 30.08 |       |      | PASS   |
| AIRBAG CONTROL MODULE | 26.66 | 47.15 |       |      | PASS   |
| LOWER ARM FASTENER    | 41.06 | 60.33 |       |      | PASS   |
| AIRBAG CONTROL MODULE | -0.09 | 14.53 |       |      | PASS   |

## Sequence: 517 946 72

Document: MXQD-059-3646

PAGE 59/60

DATE: 13/07/2026 06:21

## CONTROL CERTIFICATE

PRODUCTION ORDER PO-92110526

PO-92110526

MODEL / VARIANT MX-A7

MX-A7

SERIAL NUMBER MX287783733 046

MX287783733 146

INSPECTION PLAN QP-22.4

QP-22.4

DECISION

CONDITIONAL

CONDITIONAL

## Inspection summary

[illegible]

Inspector signature: \_\_\_\_\_

QC  
PASS

Sequence: 849 219 28  
Document: MXQD-060-7768

DATE: 13/07/2026 15:59

## CERTIFICATE OF CONFORMITY

PO-94868296

PX-STD

MX449420999525

QP-52.7

ACCEPTED

