

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 221 390 56
Document: BMQD-001-7250

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
No visible damage	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Harness routing	☐ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Label presence	☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Label pres	☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 486 864 53

Document: BMQD-002-8872


PAGE 02/50

DATE: 14/07/2026 21:12

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-41711146
MODEL / VARIANT	K9-VU
SERIAL NUMBER	MX593363366498
INSPECTION PLAN	QP-61.3
DECISION	ACCEPTED



Inspection summary

CODE 128 BM0020151968405			
CODE 128 PO49327686098			

Inspector signature:



BATCH / CONTROL INFORMATION

BATCH	B853399	SERIAL	SN4118006576
STATION	QC-02	DECISION	REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
FRONT AXLE BRACKET	49.27	57.21	56.43	Nm	HOLD
DOOR LOCK ASSEMBLY	-0.90	27.52	26.09	mm	PASS
FRONT AXLE BRACKET	49.62	69.28	60.29	Nm	HOLD
REAR CAMERA MODULE	37.28	56.37	46.55	Nm	PASS
PARKING SENSOR	51.72	74.39	60.70	mm	PASS
BRAKE HOSE SUPPORT	21.24	34.67	27.17	mm	PASS
REAR CAMERA MODULE	10.98	17.92	12.95	deg	PASS
SEAT RAIL FIXING	38.85	63.92	63.16	V	PASS
RIGHT SIDE PANEL	6.28	27.16	26.88	Nm	PASS
PARKING SENSOR	3.58	18.99	4.23	mm	HOLD
REAR CAMERA MODU	53.18	83.16	81.07	mm	PASS
SEAT RAIL FIXING	2.47	8.47	7.91	V	PASS
AIRBAG CONTROL MODULE	5.99	10.51	6.75	mm	PASS
ENGINE WIRING HARNESS	37.33	65.17	60.70	V	HOLD
FRONT AXLE BRACKET	36.78	56.64	49.91	deg	PASS
BRAKE HOSE SUPPORT	27.14	54.12	53.71	mm	HOLD
PARKING SENSOR	42.92	49.58	47.95	mm	PASS
FRONT AXLE BRACKET	37.81	64.62	44.30	Nm	PASS
RIGHT SIDE PANEL	13.39	39.44	29.66	mm	PASS
AIRBAG CONTROL MODULE	15.58	29.74	27.49	Nm	HOLD
LOWER ARM FASTENER	17.62	21.37		Nm	HOLD
DOOR LOCK ASSEMBLY	23.65	49.86		deg	PASS
FRONT AXLE BRACKET	6.32	19.15		deg	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 837 937 36
Document : BMQD-004-2939

PAGE 04/50
DATE: 14/07/2026 10:30
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Gap within limit ☐ OK	Connector locked ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Reference matches order ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 190 340 54
Document: BMQD-005-4081

PAGE 05/50
DATE: 14/07/2026 14:32
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B177406
STATION QC-08
SERIAL SN5967910418
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	34.58	58.73	49.65	mm	PASS
ENGINE WIRING HARNESS	8.66	23.38	22.55	Nm	HOLD
REAR CAMERA MODULE	47.26	50.44	48.17	V	HOLD
SEAT RAIL FIXING	12.19	15.51	14.92	V	PASS
AIRBAG CONTROL MODULE	38.38	65.10	44.64	mm	HOLD
FRONT AXLE BRACKET	25.49	44.89	34.44	V	HOLD
REAR CAMERA MODULE	6.37	32.70	23.49	deg	HOLD
LOWER ARM FASTENER	50.94	67.45	58.38	Nm	PASS
DOOR LOCK ASSEMBLY	-0.95	2.22	0.58	mm	PASS
CLIMATE CONTROL UNIT	28.78	56.47	50.33	deg	PASS
RIGHT SIDE PANEL			47.36	deg	PASS
LOWER ARM FASTENER			30.10	Nm	PASS
AIRBAG CONTROL MODULE	25.10	31.22	25.41	deg	HOLD
REAR CAMERA MODULE	2.67	20.61	19.26	V	HOLD
BATTERY SUPPORT	12.03	26.38	14.92	Nm	PASS
SEAT RAIL FIXING	12.56	33.35	23.66	V	PASS
RIGHT SIDE PANEL	17.80	31.04	23.57	mm	PASS
BATTERY SUPPORT	39.96	64.34	57.32	Nm	PASS
DOOR LOCK ASSEMBLY	51.19	56.40	55.90	V	HOLD
CLIMATE CONTROL UNIT	9.64	12.87	10.72	Nm	PASS
LOWER ARM FASTENER	0.84	16.54	5.78	deg	HOLD
RIGHT SIDE PANEL	4.64	13.22	12.75	Nm	PASS
LOWER ARM FASTENER	37.29	44.15	42.55	Nm	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 471 943 56

Document: BMQD-006-7057

PAGE 06/50

DATE: 14/07/2026 15:51

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Connector locked	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐		☐ OK ☐ NOK ☐ N/A
Harness routing	☐ OK ☐		☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Harness routing	☐ OK ☐ NOK ☐ N/A	Label presence	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Label presence	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Gap within limit	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ NOK ☐ N/A



CODE 39 BM-06-01-2338



CODE 128 BM0060212376692

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 263 750 63

Document: BMQD-007-5886

PAGE 07/50

DATE: 14/07/2026 08:43

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-85046021
MODEL / VARIANT	PX-STD
SERIAL NUMBER	MX328106363124
INSPECTION PLAN	QP-68.4
DECISION	ACCEPTED

Inspection summary

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 280 698 83

Document : BMQD-008-8563

PAGE 08/50

DATE: 14/07/2026 02:30

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B831934

SERIAL SN4530255560

STATION QC-19

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
REAR CAMERA MODULE	39.11	54.95	43.15	deg	PASS
ENGINE WIRING HARNESS	39.63	45.89	43.61		PASS
FRONT AXLE BRACKET	51.09	75.41	53.98		
BATTERY SUPPORT	48.21	61.89	50.63		
REAR CAMERA MODULE	45.78	68.26	65.26	deg	
CLIMATE CONTROL UNIT	11.66	41.51	17.00	V	
FRONT AXLE BRACKET	0.67	3.57	1.03	V	HOLD
REAR CAMERA MODULE	16.28	25.10	18.85	deg	PASS
FRONT AXLE BRACKET	27.06	52.20	30.95	mm	PASS
REAR CAMERA MODULE	11.11	26.11	20.73	deg	PASS
CLIMATE CONTROL UNIT	45.40	51.77	48.74	Nm	HOLD
CLIMATE CONTROL UNIT	46.92	72.74	59.50	mm	PASS
SEAT RAIL FIXING	9.99	17.73	12.44	deg	PASS
SEAT RAIL FIXING	29.75			V	PASS
ENGINE WIRING HARNESS	12.10			mm	HOLD
PARKING SENSOR	17.70	43.98	40.38	V	PASS
FRONT AXLE BRACKET	25.63	45.83	28.45	V	PASS
CLIMATE CONTROL UNIT	49.44	62.40	56.22	Nm	HOLD
CLIMATE CONTROL UNIT	50.57	54.60	52.82	Nm	PASS
BATTERY SUPPORT	11.68	41.62	25.99	V	PASS
SEAT RAIL FIXING	0.87	20.13	1.78	V	PASS
CLIMATE CONTROL UNIT	7.51	19.58	10.20	mm	PASS
BRAKE HOSE SUPPORT	43.58	68.86	63.40	deg	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 246 608 86

Document: BMQD-009-5554

PAGE 09/50

DATE: 14/07/2026 13:47

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
No visible damage	CODE 128 PO34596789606 	☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
No visible damage		☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Gap within limit		☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Connector locked		☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A
Seal continuous		☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
		☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
DATA MATRIX DMJBM/P009J01/L334602		☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Torque confirmed		☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Fastener witness mark		☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Fastener witness mark		☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Gap within limit		☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
			Surface condition ☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 289 369 16

Document: BMQD-010-3786

PAGE 10/50

DATE: 14/07/2026 11:42

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B797244

STATION QC-13

SERIAL SN1764440010

DECISION OK



DATA MATRIX (0109508000375299(21)E)



CODE 128 PO55449362251



CODE 39 BM-10-01-3754




CODE 128 LOT-465242-B10

CHARACTERISTIC	LOW	HIGH	VALUE		
BATTERY SUPPORT	24.98	40.51	34.58		
CLIMATE CONTROL UNIT	6.43	23.61	20.00		
BRAKE HOSE SUPPORT	17.60	43.02	28.25	V	PASS
RIGHT SIDE PANEL	8.73	17.92	10.46	V	HOLD
SEAT RAIL FIXING				deg	
REAR CAMERA MODULE				Nm	
DOOR LOCK ASSEMBLY				mm	PASS
RIGHT SIDE PANEL	17.74	23.89	22.19	V	
PARKING SENSOR	9.51	26.82	22.61	mm	
BRAKE HOSE SUPPORT	2.05	11.99	4.57	Nm	PASS
SEAT RAIL FIXING	34.98	61.46	61.27	mm	PASS
CLIMATE CONTROL UNIT	29.18	46.88	45.39		
RIGHT SIDE PANEL	3.48	6.48	3.97		
SEAT RAIL FIXING	23.92	47.73	30.80	deg	PASS
PARKING SENSOR	16.21	29.35	26.59	deg	PASS
FRONT AXLE BRACKET	13.55	32.76	31.90	deg	PASS
DOOR LOCK ASSEMBLY	1.02	17.20	8.25	Nm	PASS
AIRBAG CONTROL MODULE	14.99	31.81			
CLIMATE CONTROL UNIT	9.51	20.15			
	7.75	26.03			
	28.59	36.58	35.11	V	PASS
AIRBAG CONTROL MODULE	28.22	46.30	29.95	Nm	PASS
AIRBAG CONTROL MODULE	20.69	41.42	22.17	V	PASS



CODE 39 BM-10-07-5378



CODE 128 LOT-298212-B10

SYNTHETIC MIXED QUALITY DOSSIER


Sequence: 189 851 22

Document: BMQD-011-7286

PAGE 11/50

DATE: 14/07/2026 00:09

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Reference matches order ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Surface condition ☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK	 CODE 128 BM0110185623283  DATA MATRIX DM(BM)P011J02JL614372
Seal continuous ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Torque confirmed ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 720 649 17
Document: BMQD-012-4655

PAGE 12/50
DATE: 14/07/2026 01:14
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-97973380
MODEL / VARIANT	MX-A7
	MX822953303050
	QP-47.7
	ACCEPTED



QR CODE <https://example.invalid/balanced012>

Inspection summary

 DATA MATRIX DM1BM(P012)03L611562			

Inspector signature:



CODE 39 BM-12-01-1498



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 807 582 49
Document: BMQD-013-5848

PAGE 13/50
DATE: 14/07/2026 12:10
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B111518
STATION QC-09
SERIAL SN6954172224
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
CLIMATE CONTROL UNIT	10.97	26.13	21.53	Nm	HOLD
FRONT AXLE BRACKET	12.70	21.81	19.72	deg	HOLD
BATTERY SUPPORT	29.16	42.62	34.72	Nm	PASS
PARKING SENSOR	37.62	62.97	54.14	V	PASS
LOWER ARM FASTENER	45.94	66.77	52.15	mm	HOLD
ENGINE WIRING HARNESS	26.17	32.42	28.93	V	PASS
RIGHT SIDE PANEL	15.02	25.57	15.46	Nm	HOLD
REAR CAMERA MODULE	15.12	44.12	27.24	deg	HOLD
PARKING SENSOR	47.93	67.87	59.44	mm	PASS
ENGINE WIRING HARNESS	35.28	43.13	40.38	Nm	PASS
SEAT RAIL FIXING	30.68	37.	 QR CODE: https://example.invalid/balanced/013/01	mm	PASS
FRONT AXLE BRACKET	48.09	57.1		mm	PASS
BATTERY SUPPORT	7.11	26.:		mm	PASS
BRAKE HOSE SUPPORT	8.58	14.45	11.05	Nm	PASS
RIGHT SIDE PANEL	15.12	41.58	28.79	mm	HOLD
DOOR LOCK ASSEMBLY	13.22	23.53	16.09	 CODE 128 LOT-633077-B13	
REAR CAMERA MODULE	-0.46	9.34	2.32		
AIRBAG CONTROL MODULE	15.92	19.54	19.10		
DOOR LOCK ASSEMBLY	ξ		47.95	Nm	PASS
BRAKE HOSE SUPPORT	ξ		55.19	V	PASS
DOOR LOCK ASSEMBLY	ξ		23.45	V	PASS
CLIMATE CONTROL UNIT	ξ		65.11	V	PASS
CLIMATE CONTROL UNIT	53.46	67.53	63.26	deg	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 621 746 82

Document: BMQD-014-8039

PAGE 14/50

DATE: 14/07/2026 14:49

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Fastener witness mark ☐ OK☐ NOK☐ N/A	Torque confirmed ☐ OK☐ NOK☐ N/A
Fastener witness mark ☐ OK☐ NOK☐ N/A	Harness routing ☐ OK☐ NOK☐ N/A
Reference matches order ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Reference matches order ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
Harness routing ☐ OK☐ NOK☐ N/A	Reference matches order ☐ OK☐ NOK☐ N/A
Gap within limit  ☐ OK☐ NOK☐ N/A	Label presence ☐ OK☐ NOK☐ N/A
Harness routing  DATA MATRIX (01)09509000331359(21)6M141 ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Connector locked ☐ OK☐ NOK☐ N/A	Gap within limit  CODE 128 PO59714895583 ☐ OK☐ NOK☐ N/A
No visible damage ☐ OK☐ NOK☐ N/A	Fastener witness mark ☐ OK☐ NOK☐ N/A
No visible damage  DATA MATRIX DM(BM/P014)01IL7 ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
Surface condition ☐ OK☐ NOK☐ N/A	Reference matches order ☐ OK☐ NOK☐ N/A
Harness routing ☐ OK☐ NOK☐ N/A	Reference matches order ☐ OK☐ NOK☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 817 600 36

Document: BMQD-015-7542

PAGE 15/50

DATE: 14/07/2026 18:36

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B998791

SERIAL SN5009761043

STATION QC-23

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	54.62	78.05	68.51	deg	PASS
ENGINE WIRING HARNESS	27.92	38.66	29.78	deg	PASS
FRONT AXLE BRACKET	54.22	70.48	55.23	Nm	PASS
PARKING SENSOR	3.40	7.78	4.46	Nm	PASS
RIGHT SIDE PANEL	34.70	50.81	 DATA MATRIX @10950000532861	V	HOLD
PARKING SENSOR	29.57	52.61		Nm	PASS
BRAKE HOSE SUPPORT	14.50	16.79		deg	PASS
AIRBAG CONTROL MODULE	12.53	38.71		V	PASS
BATTERY SUPPORT	21.70	29.85	22.34	mm	PASS
BRAKE HOSE SUPPORT	33.14	51.85	39.39	deg	PASS
AIRBAG CONTROL MODULE	5.21	9.79	5.84	mm	PASS
RIGHT SIDE PANEL	51.11	62.78	61.40	mm	PASS
BATTERY SUPPORT	 QR CODE QR(BMPAGE=015)INDEX=011,LOT=4071	36.52	27.64	deg	HOLD
BATTERY SUPPORT		46.18	44.67	deg	PASS
BRAKE HOSE SUPPORT		42.15	39.35	mm	HOLD
LOWER ARM FASTENER		46.94	46.39	mm	HOLD
DOOR LOCK ASSEMBLY	49.36	54.24	51.40	mm	HOLD
DOOR LOCK ASSEMBLY	3.17	18.84	12.31	V	PASS
SEAT RAIL FIXING	10.93	35.41	33.37	mm	PASS
REAR CAMERA MODULE	27.78	51.60	32.68	deg	PASS
LOWER ARM FASTENER	1.97	23.53	3.37	mm	PASS
REAR CAMERA MODULE	30.14	37.30	31.22	mm	HOLD
DOOR LOCK ASSEMBLY	43.32	71.01	65.89	V	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 446 108 52
Document: BMQD-016-8221

PAGE 16/50

DATE: 14/07/2026 02:40
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Seal continuous ☐ OK ☐ NOK ☐ N/A	Harness routing [*] ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Reference matches order ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Reference matches order ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Surface condition ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Torque confirmed ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A


CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-59534675
MODEL / VARIANT	MX-A7
SERIAL NUMBER	MX921734069038
INSPECTION PLAN	QP-95.6
DECISION	CONDITIONAL

Inspection summary



DATA MATRIX DM(BM(P017)01)L



CODE 39 BM-17-02-9005

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 606 544 86

Document: BMQD-018-7257

BATCH / CONTROL INFORMATION

BATCH B271175

STATION QC-27

SERIAL SN2155224487

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
LOWER ARM FASTENER	15.69	25.39	24.96	Nm	PASS
DOOR LOCK ASSEMBLY	6.84	13.95			HOLD
RIGHT SIDE PANEL	26.78	31.33			HOLD
ENGINE WIRING HARNESS	49.87	58.48			PASS
LOWER ARM FASTENER	46.62	58.63			PASS
AIRBAG CONTROL MODULE	3.43	17.99			PASS
BRAKE HOSE SUPPORT	34.30	52.39	51.62	V	HOLD
AIRBAG CONTROL MODULE	47.89	70.85	52.52	mm	PASS
BATTERY SUPPORT	21.21	44.30	40.71	mm	PASS
ENGINE WIRING HARNESS	32.29	43.46	38.16	deg	HOLD
AIRBAG CONTROL MODULE	36.46	45.83	38.33	deg	PASS
REAR CAMERA MODULE	54.25	79.99	61.25	deg	HOLD
SEAT RAIL FIXING	34.96	51.34	37.36	V	PASS
SEAT RAIL FIXING	21.61	47.64	35.44	Nm	PASS
BRAKE HOSE SUPPORT	30.90	43.43	41.35	Nm	PASS



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 597 401 75

Document: BMQD-019-2191

PAGE 19/50


DATE: 14/07/2026 07:38

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Harness routing	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK	ition	☐ OK ☐ NOK ☐ N/A
Seal continuous			☐ OK ☐ NOK ☐ N/A
Gap within limit			☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A



DATA MATRIX DM[BM/P019/J01][L854681



CODE 128 BM0190248659903

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 104 956 84
Document: BMQD-020-5450

BATCH / CONTROL INFORMATION

BATCH B358694
STATION QC-24

SERIAL SN9357939025
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	13.31	28.13	19.05	mm	PASS
RIGHT SIDE PANEL	29.68	56.69	30.38	deg	HOLD
ENGINE WIRING HARNESS	-0.07	23.00	13.25	deg	PASS
RIGHT SIDE PANEL	18.04	27.67	26.37	V	PASS
RIGHT SIDE PANEL	10.62	18.96	13.30	mm	PASS
SEAT RAIL FIXING	15.14	33.72	15.86	mm	HOLD
SEAT RAIL FIXING	42.51	52.37	45.23	deg	PASS
SEAT RAIL FIXING	2.95	16.13	14.01	Nm	PASS
REAR CAMERA MODULE	48.37	56.03	52.78	mm	PASS
LOWER ARM FASTENER	27.85	39.25	29.93	mm	PASS
ENGINE WIRING HARNESS	27.83	57.01	39.73	V	PASS
RIGHT SIDE PANEL	3.34	27.23	18.91	V	PASS
	1.80	10.79	2.48	V	HOLD
	51.46	66.74	54.77	Nm	PASS
	50.99	64.35	54.43	V	PASS
BATTERY SUPPORT	7.55	36.51	15.70	mm	PASS
SEAT RAIL FIXING	30.75	40.94	37.05	Nm	HOLD
CLIMATE CONTROL UNIT	15.42	41.49	32.32	deg	PASS
SEAT RAIL FIXING	33.06	40.79	38.89	mm	PASS
DOOR LOCK ASSEMBLY	7.97	12.10	8.40	Nm	HOLD
AIRBAG CONTROL MODULE	7.62	20.02	15.70	mm	PASS
SEAT RAIL FIXING	7.16	14.88	11.32	V	HOLD
BRAKE HOSE SUPPORT	26.64	30.64	27.35	V	PASS



CODE 128 PO76361423099

DATA MATRIX DMBAF020101L4801



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 264 602 67
Document: BMQD-021-9381

PAGE 21/50
DATE: 14/07/2026 08:33
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Connector lock ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Seal continuous: QR CODE QR(BMPAGE=021)INDEX=02)LOT=4 ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	CODE 128 PO32177176967 ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ N/A

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-51502437
MODEL / VARIANT	MX-A7
SERIAL NUMBER	MX566945454310
INSPECTION PLAN	QP-20.1
DECISION	CONDITIONAL

Inspection summary



QR CODE QR/IMPAGE-422/INDEX-0

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 505 368 94
Document: BMQD-023-5898

PAGE 23/50
DATE: 14/07/2026 06:26
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B957181
STATION QC-19
SERIAL SN4409998618
DECISION REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BATTERY SUPPORT	13.73	21.86	17.83	deg	HOLD
REAR CAMERA MODULE	2.50	26.46	21.62	mm	HOLD
ENGINE WIRING HARNESS	33.67	58.07	39.93	mm	PASS
BATTERY SUP	35.21	63.43	48.63	V	HOLD
CLIMATE CON	-0.89	27.90	7.93	V	PASS
PARKING SENSOR	12.24	22.54	16.83	V	PASS
ENGINE WIRING HARNESS	51.99	80.70	63.39	V	HOLD
FRONT AXLE BRACKET	6.96	24.91	11.35	Nm	PASS
DOOR LOCK ASSEMBLY	44.00	55.78	47.00	Nm	PASS
ENGINE WIRING HARNESS	44.04	66.19	56.56	mm	PASS
BRAKE HOSE SUPPORT	49.12	72.73	67.80	mm	PASS
FRONT AXLE BRACKET	28.66	56.25	45.52	deg	PASS
CLIMATE CONTROL UNIT	20.78	25.16	24.30	V	HOLD
ENGINE WIRING HARNESS	-1.77	22.09		V	PASS
RIGHT SIDE PANEL	43.52	47.78		Nm	PASS
PARKING SENSOR	44.95	57.13	54.24	deg	PASS
FRONT AXLE BRACKET	33.29	58.68	37.88	deg	PASS
BATTERY SUPPORT	9.11	16.79	15.50	mm	HOLD
BRAKE HOSE SUPPORT	36.72	42.39	38.47	V	PASS
BRAKE HOSE SUPPORT	0.67	21.21	5.02	deg	PASS
LOWER ARM FASTENER	46.63	73.02	51.27	Nm	PASS
LOWER ARM FASTENER	27.41	35.19	32.05	Nm	PASS
CLIMATE CONTROL UNIT	23.57	34.84	24.97	V	HOLD

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 710 972 85
Document: BMQD-024-5659

PAGE 24/50

DATE: 14/07/2026 12:43
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
No visible damage ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK	☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK	☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Torque confirmed ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 633 414 33

Document: BMQD-025-3230

BATCH / CONTROL INFORMATION

BATCH B905041
STATION QC-22

SERIAL SN4849633110
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
AIRBAG CC	49.21	75.22	53.73	deg	PASS
LOWER AR	10.43	30.36	28.09	mm	PASS
SEAT RAIL FIXING	34.63	69.51		deg	HOLD
CLIMATE CONTRO*	20.72			deg	HOLD
CLIMATE CONTRO				mm	PASS
REAR CAMERA MO	36.39	51.45	40.10	mm	PASS
PARKING SENSOR	53.95	61.61	57.03	mm	PASS
AIRBAG CONTROL MODULE	12.71	40.48	29.66	V	PASS
AIRBAG CONTROL MODULE	28.15	50.05	35.80	mm	PASS
SEAT RAIL FIXING	11.63	20.19	18.05	deg	PASS
BRAKE HOSE SUPPORT					
ENGINE WIRING HARNESS					
AIRBAG CONTROL MODULE					
RIGHT SIDE PANEL					
CLIMATE CONTROL UNIT					

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 688 327 73
Document: BMQD-026-1629

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
 CODE 128 BM0260259679472 Seal continuous ☐ OK ☐ NOK ☐ N/A		Seal continuous ☐ OK ☐ NOK ☐ N/A	
Seal continuous ☐ OK ☐ NOK ☐ N/A		Surface condition ☐ OK ☐ NOK ☐ N/A	
Reference matches order ☐ OK ☐ NOK ☐ N/A		No visible damage ☐ OK ☐ NOK ☐ N/A	
Torque confirmed ☐ OK ☐ NOK ☐ N/A		Torque confirmed ☐ OK ☐ NOK ☐ N/A	
 DATA MATRIX DM(BM)P026(j01)1L775261 ☐ OK ☐ NOK ☐ N/A		Fastener witness mark ☐ OK ☐ NOK ☐ N/A	
Label presence ☐ OK ☐ NOK ☐ N/A		Harness routing ☐ OK ☐ NOK ☐ N/A	
Seal continuous ☐ OK ☐ NOK ☐ N/A		Seal continuous ☐ OK ☐ NOK ☐ N/A	
Connector locked ☐ OK ☐ NOK ☐ N/A		Torque confirmed ☐ OK ☐ NOK ☐ N/A	
Torque  CODE 39 BM-26-03-8911		Harness routing ☐ OK ☐ NOK ☐ N/A	
Gap within limit ☐ OK ☐ NOK ☐ N/A		Connector locked ☐ OK ☐ NOK ☐ N/A	
Connector locked ☐ OK ☐ NOK ☐ N/A		Surface condition ☐ OK ☐ NOK ☐ N/A	
Gap within limit ☐ OK ☐ NOK ☐ N/A		No visible damage ☐ OK ☐ NOK ☐ N/A	

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 174 274 16

Document: BMQD-027-4768

PAGE 27/50

DATE: 14/07/2026 07:31

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER

PO-34949320

MODEL / VARIANT

PX-STD

SERIAL NUMBER

MX269142303379

INSPECTION PLAN

QP-52.4

DECISION

CONDITI



Inspection summary

QR CODE <https://example.invalid/balanced/027/01>



CODE 128 BM0270292095476

Inspector signature:

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 570 909 13

Document: BMQD-028-7042

PAGE 28/50

DATE: 14/07/2026 14:37

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B331878

SERIAL SN6307953534

STATION QC-10

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
LOWER ARM FASTENER	51.34	59.53	57.33	mm	PASS
LOWER ARM FASTENER	54.14	56.61	56.48	deg	PASS
SEAT RAIL FIXING	9.01	36.77	23.31	V	PASS
AIRBAG CONTROL MODULE	1.31	25.59	3.56	V	PASS
CLIMATE CONTROL UNIT	54.08	82.96	54.97	Nm	PASS
REAR CAMERA MODULE	30.27	35.75	33.64	Nm	HOLD
SEAT RAIL FIXING	36.88	55.45	39.37	V	PASS
CLIMATE CONTROL UNIT	27.89	55.19	42.33	mm	PASS
BATTERY SUPPORT	35.97	56.36	41.63	mm	PASS
LOWER ARM FASTENER	38.17	46.55	41.85	mm	PASS
ENGINE WIRING HARNESS	3.78	30.30	29.67	deg	PASS
FRONT AXLE BRACKET	40.44	54.03	43.86	deg	PASS
DOOR LOCK ASSEMBLY	53.31	76.83	64.57	V	PASS
RIGHT SIDE PANEL	38.40	41.84	41.13	Nm	PASS
BRAKE HOSE SUPPORT	31.34	60.70	38.88	mm	PASS
RIGHT SIDE PANEL	54.16	80.03	61.06	mm	PASS
CLIMATE CONTROL UNIT	20.45	24.33	22.23	mm	HOLD
SEAT RAIL FIXING	10.91	33.58	18.41	deg	PASS
AIRBAG CONTROL MODULE	36.03	58.57	47.10	deg	PASS
RIGHT SIDE PANEL	41.07	69.19	61.54	mm	PASS
PARKING SENSOR	3.66	18.06	16.55	V	HOLD
BATTERY SUPPORT	13.79	28.12	26.18	V	PASS
RIGHT SIDE PANEL	32.72	52.54	38.52	mm	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 559 226 83
Document : BMQD-029-8608

PAGE 29/50

DATE: 14/07/2026 12:48

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Gap within limit ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	 DATA MATRIX DM(BM/P028)01(L228874 ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	 CODE 39 BM-29-02-8872 ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☐ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Surface condition ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 330 204 76
Document: BMQD-030-3057

PAGE 30/50
DATE: 14/07/2026 21:35
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B958476
STATION QC-15
SERIAL SN7704696737
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
CLIMATE CONTROL UNIT	13.14	36.63	26.90	Nm	HOLD
AIRBAG CONTROL MODULE	50.84	74.47	59.49	Nm	PASS
DOOR LOCK ASSEMBLY	11.42	15.13	13.12	deg	PASS
RIGHT SIDE PANEL	24.28	48.40	28.65	deg	HOLD
BATTERY SUPPORT	-0.72	19.60	0.73	deg	PASS
LOWER ARM FASTENER	11.13	18.10	15.21	V	HOLD
FRONT AXLE BRACKET	39.19	45.18	39.96	deg	HOLD
CLIMATE CONTROL UNIT	11.43	32.39	11.98	V	PASS
RIGHT SIDE PANEL	11.24	35.65	31.22	deg	PASS
CLIMATE CONTROL UNIT	39.54	45.04	43.12	mm	PASS
FRONT AXLE BRACKET	41.15	48.64	47.92	V	PASS
CLIMATE CONTROL UNIT	12.15		17.92	deg	PASS
SEAT RAIL FIXING	41.43		41.94	deg	PASS
BATTERY SUPPORT	50.86		56.56	Nm	PASS
REAR CAMERA MODULE	50.34	78.59	53.97	mm	PASS
SEAT RAIL FIXING	53.47	75.22	58.46	Nm	HOLD
DOOR LOCK ASSEMBLY	39.06	56.64	42.07	mm	HOLD
BRAKE HOSE SUPPORT	0.29	14.19	13.07	deg	PASS
PARKING SENSOR	44.41	71.77	59.64	Nm	PASS
AIRBAG CONTROL MODULE	33.09	63.07	56.72	Nm	PASS
CLIMATE CONTROL UNIT	31.80	58.53	46.19	deg	PASS
REAR CAMERA MODULE	38.07	47.07	43.43	Nm	PASS
FRONT AXLE BRACKET	18.12	38.74	27.12	Nm	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 548 534 66

Document: BMQD-031-5449

PAGE 31/50

DATE: 14/07/2026 17:06

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Seal continuous	☐ OK ☐ NOK ☐ N/A	Gap within limit	☐ OK ☐ NOK ☐ N/A
 CODE 39 BM-31-02-9594			
Fastener witness mark	☐ OK		☐ OK ☐ NOK ☐ N/A
Gap within limit	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Harness routing	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
 CODE 39 BM-31-01-8295			
Label presence			☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 189 511 29
Document: BMQD-032-8307

PAGE 32/50
DATE: 14/07/2026 07:51
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-64055943
MODEL / VARIA	
SERIAL NUMBE	
INSPECTION PL	
DECISION	CODE 39 BM-32-01-7579 CONDITIONAL

Inspection summary

Inspector signature:

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 946 362 37
Document: BMQD-033-1593

PAGE 33/50
DATE: 14/07/2026 03:50
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B254316
STATION QC-13
SERIAL SN5792909923
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT	
REAR CAMERA MODULE	3.40	18.02	11.15	mm	HOLD	
BRAKE HOSE SUPPORT	53.45	64.56	60.38	deg	PASS	
FRONT AXLE BRACKET	10.01	29.63	15.12	Nm	PASS	
BATTERY SUPPORT	 CODE 128 LOT-295789-B33				HOLD	
PARKING SENSOR					PASS	
BRAKE HOSE SUPPORT					PASS	
CLIMATE CONTROL UNIT	 DATA MATRIX DM[BM/P033]01[L392981	1.22	40.73	deg	PASS	
AIRBAG CONTROL MODULE		1.13	4.12	deg	PASS	
RIGHT SIDE PANEL		1.37	54.88	mm	HOLD	
CLIMATE CONTROL UNIT	44.92	57.08	54.64	mm	PASS	
DOOR LOCK ASSEMBLY	2.98	31.36	30.45	V	PASS	
BRAKE HOSE SUPPORT	32.27	36.37	35.22	mm	PASS	
BRAKE HOSE SUPPORT	6.38	15.54	8.40	Nm	PASS	
CLIMATE CONTROL UNIT	12.68	35.45	12.82	deg	PASS	
LOWER ARM FASTENER	37.94	54.58	42.15	V	PASS	
SEAT RAIL FIXING	20.5	 CODE 39 BM-33-02-9196			deg	PASS
REAR CAMERA MODULE	36.6				mm	PASS
AIRBAG CONTROL MODULE	42.35	49.25	44.96	V	PASS	
RIGHT SIDE PANEL	45.62	60.55	55.37	deg	PASS	
BRAKE HOSE SUPPORT	2.61	31.32	5.36	mm	HOLD	
SEAT RAIL FIXING	52.44	69.00	52.66	deg	PASS	
DOOR LOCK ASSEMBLY	11.82	34.25	26.40	deg	PASS	
LOWER ARM FASTENER	19.34	38.92	26.75	V	PASS	

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 264 718 80

Document: BMQD-034-9899

PAGE 34/50

DATE: 14/07/2026 02:17

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Seal continuous ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Surface condition ☐ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
 ☐ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A

DATA MATRIX CODE:BMQD034101L43310

BATCH / CONTROL INFORMATION

BATCH

B107933

SERIAL

SN6812170769

STATION

QC-20

DECISION

REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BATTERY SUPPORT	5.56	18.79	6.42	mm	HOLD
BATTERY SUPPORT	11.58	34.50	28.57	V	HOLD
RIGHT SIDE PANEL	18.98	35.06	32.67	deg	HOLD
CLIMATE CONTROL UNIT	48.31	54.84	51.02	mm	PASS
DOOR LOCK ASSEMBLY	51.99	78.65	61.51	V	PASS
DOOR LOCK ASSEMBLY	37.58	66.99	52.56	deg	PASS
BATTERY SUPPORT	29.75	50.47	32.32	V	PASS
LOWER ARM FASTENER	51.41	62.09	53.88	V	PASS
BATTERY SUPPORT	-0.16	15.06	0.04	V	PASS
ENGINE WIRING HARNESS	5.81	32.44	27.06	V	PASS
PARKING SENSOR	35.98	58.45	38.93	Nm	PASS
FRONT AXLE BRACKET	28.65	55.41	CODE 39 BM-35-01-4872		
REAR CAMERA MODULE	51.04	54.66			
CLIMATE CONTROL UNIT	5.19	29.28			
BRAKE HOSE SUPPORT	34.06	61.67	34.73	mm	PASS
FRONT AXLE BRACKET	5.03	31.99	30.47	Nm	PASS
DOOR LOCK ASSEMBLY	2.21	26.76	11.45	deg	PASS
BATTERY SUPPORT	18.91	38.89	32.48	Nm	HOLD
PARKING SENSOR	8.78	32.01	9.57	V	HOLD
ENGINE WIRING HARNESS	47.25	67.08	53.01	Nm	PASS
BATTERY SUPPORT	2.49	12.72	10.91	deg	HOLD
ENGINE WIRING HARNESS	-1.54	11.27	8.78	V	PASS
FRONT AXLE BRACKET	38.67	62.45	52.46	mm	PASS


SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 186 425 35
Document: BMQD-036-4173

PAGE 36/50

DATE: 14/07/2026 09:54

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Harness routing ☐ OK☐ NOK☐ N/A	Label presence ☐ OK☐ NOK☐ N/A
Surface condition ☐ OK☐ NOK☐ N/A	Fastener witne ☐ OK☐ NOK☐ N/A 
Harness routing ☐ OK☐ NOK☐ N/A	Surface conditi... ☐ OK☐ NOK☐ N/A DATA MATRIX (01)09508000351558(2)
Label presence ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Reference matches order ☐ OK☐ NOK☐ N/A	Torque confirmed ☐ OK☐ NOK☐ N/A
Reference matches order  CODE 128 PO94640036224	 CODE 39 BM-36-03-5397 ☐ N/A
Seal continuous  DATA MATRIX (01)09508000353909(21)	☐ OK☐ NOK☐ N/A
Reference matches order ☐ OK☐ NOK☐ N/A	Torque confirmed ☐ OK☐ NOK☐ N/A
Surface condition ☐ OK☐ NOK☐ N/A	Torque confirmed ☐ OK☐ NOK☐ N/A
Label presence ☐ OK☐ NOK☐ N/A	Surface condition ☐ OK☐ NOK☐ N/A
Label presence ☐ OK☐ NOK☐ N/A	Harness routing ☐ OK☐ NOK☐ N/A
Fastener witness mark ☐ OK☐ NOK☐ N/A	Seal continuous ☐ OK☐ NOK☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 346 511 43
Document: BMQD-037-6430

PAGE 37/50
DATE: 14/07/2026 12:37
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-21873220
MODEL / VARIANT	MX-A7
SERIAL NUMBER	MX700190647131
INSPECTION PLAN	QP-58.1
DECISION	ACCEPTED

Inspection summary



CODE 128 BM0370126977372



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 701 929 81
Document: BMQD-038-7821

BATCH / CONTROL INFORMATION

BATCH	B257012	SERIAL	SN5383608034
STATION	QC-17	DECISION	REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BATTERY SUPPORT	38.71	42.21	41.15	deg	PASS
DOOR LOCK ASSEMBLY	34.26	38.65	37.89	V	PASS
LOWER ARM FASTENER	8.63	36.47	16.87	mm	PASS
DOOR LOCK ASSEMBLY	37.87	47.86	46.22	Nm	PASS
REAR CAMERA MODULE	44.70	58.42	50.80	deg	PASS
LOWER ARM FASTENER	-1.59	12.10	11.04	deg	HOLD
RIGHT SIDE PANEL	33.83	56.05	44.65	mm	PASS
BAT	51.58	67.36	56.69	mm	PASS
ENG	53.85	60.70	57.85	V	PASS
FRC	35.81	65.64	64.55	mm	HOLD
SEAT RAIL FIXING	4.50	17.43	10.91	Nm	PASS
BATTERY SUPPORT				mm	PASS
LOWER ARM FASTENER				mm	PASS
RIGHT SIDE PANEL				V	PASS
AIRBAG CONTROL MODULE	12.43	14.71	14.59	V	HOLD
	36.24	41.74	39.83	Nm	PASS
	13.09	38.09	15.09	mm	PASS
BRAKE HOSE SUPPORT	24.33	45.43	41.33	mm	PASS
RIGHT SIDE PANEL	8.63	34.69	10.60	deg	HOLD
PARKING SENSOR		37.50	25.38	mm	PASS
REAR CAMERA MODULE		45.73	39.85	V	PASS
REAR CAMERA MODULE	16.82	42.60	35.27	deg	PASS
BRAKE HOSE SUPPORT	10.85	34.60	33.97	deg	HOLD

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 718 263 98

Document: BMQD-039-2487

PAGE 39/50

DATE: 14/07/2026 20:01

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Seal continuous ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Seal continuous ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
Gap within limit ☐ OK☐ NOK☐ N/A	Gap within limit ☐ OK☐ NOK☐ N/A
Seal continuous ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Seal continuous ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Torque confirmed ☐ OK☐ NOK☐ N/A	Connector locked ☐ OK☐ NOK☐ N/A
Connector locked ☐ OK☐ NOK☐ N/A	Fastener witness mark ☐ OK☐ NOK☐ N/A
Label presence ☐ OK☐ NOK☐ N/A	Harness routing ☐ OK☐ NOK☐ N/A
Label presence ☐ OK☐ NOK☐ N/A	Gap within limit ☐ OK☐ NOK☐ N/A
Connector locked ☐ OK☐ NOK☐ N/A	Seal continuous ☐ OK☐ NOK☐ N/A
Harness routing ☐ OK☐ NOK☐ N/A	Gap within limit ☐ OK☐ NOK☐ N/A
Seal continuous ☐ OK☐ NOK☐ N/A	Harness routing ☐ OK☐ NOK☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 143 932 83
Document: BMQD-040-6573

PAGE 40/50
DATE: 14/07/2026 00:22
MEASUREMENT AND TRACEABILITY

RATCH / CONTROL INFORMATION



SERIAL SN6008583863
DECISION OK

	HIGH	VALUE	UNIT	RESULT
	24.99	9.88	V	HOLD
	40.84	33.86	 QR CODE: https://example.invalid/balanced/040/03	
	62.33	58.68		
	19.62	17.02		
	48.17	31.78		
	24.75	19.73	deg	PASS
	35.51	14.76	V	HOLD
	60.88	59.74	Nm	PASS
	65.17	48.82	Nm	HOLD
	59.65	32.57	mm	PASS
	43.82	33.51	Nm	HOLD
	57.45	41.95	mm	PASS
	44.26	41.71	deg	PASS
	41.56	36.48	V	HOLD
	37.20	33.35	mm	HOLD
	30.29	20.07	 CODE 39 BM-40-01-8172	
	75.24	58.91		
	30.53	13.33		
	61.94	52.47	mm	PASS
	75.62	62.80	deg	PASS
	27.99	16.29	Nm	HOLD
	27.63	20.36	mm	PASS
	26.66	25.79	Nm	PASS



QR CODE https://example.invalid/balanced040/03



QR CODE QR(BMPAGE=040)INDEX=04JL



CODE 39 BM-40-01-8172

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 414 611 24

Document: BMQD-041-5686

PAGE 41/50

DATE: 14/07/2026 20:30

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Harness routing ☐ OK ☐ NOK ☐ N/A		Fastener witness mark ☐ OK ☐ NOK ☐ N/A	
Fastener witness mark ☐ OK ☐ NOK ☐ N/A		No visible damage ☐ OK ☐ NOK ☐ N/A	
Seal continuous ☐ OK ☐ NOK ☐ N/A		Label presence ☐ OK ☐ NOK ☐ N/A	
		tion ☐	
		e ☐	
		Surface condition ☐	
Label presence ☐ OK ☐ NOK ☐ N/A		Label presence ☐ OK ☐ NOK ☐ N/A	
Label presence ☐ OK ☐ NOK ☐ N/A		Reference matches order ☐ OK ☐ NOK ☐ N/A	
No visible damage ☐ OK ☐ NOK ☐ N/A		Torque confirmed ☐ OK ☐ NOK ☐ N/A	
No visible damage ☐ OK ☐ NOK ☐ N/A		Reference matches order ☐ OK ☐ NOK ☐ N/A	
Harness routing ☐ OK ☐ NOK ☐ N/A		Seal continuous ☐ OK ☐ NOK ☐ N/A	
Reference matches order ☐ OK ☐ NOK ☐ N/A		Seal continuous ☐ OK ☐ NOK ☐ N/A	

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 928 105 21

Document: BMQD-042-9654

PAGE 42/50

DATE: 14/07/2026 04:23

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-29035804
MODEL / VARIANT	PX-STD
SERIAL NUMBER	MX750135970051
INSPECTION PLAN	QP-44.2
DECISION	ACCEPTED

Inspection summary



Inspector signature:



BATCH / CONTROL INFORMATION

BATCH

B701070

STATION

QC-26

SERIAL

SN1794938060

DECISION

OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BATTERY SUPPORT	43.17	56.23	55.28	V	PASS
ENGINE WIRING HARNESS	-0.64	27.55	15.76	deg	HOLD
ENGINE WIRING HARNESS	30.79	51.09	33.80	deg	PASS
RIGHT SIDE PANEL	4.73	23.77	5.76	Nm	HOLD
DOOR LOCK ASSEMBLY	40.34	55.98	48.63	deg	PASS
FRONT AXLE BRACKET	45.58	68.20	47.71	Nm	PASS
PARKING SENSOR	49.19	52.01	51.41	mm	PASS
BATTERY SUPPORT	38.81	66.91	64.68	deg	PASS
REAR CAMERA MODULE	 CODE 128 BM0430351093599	24.98	14.10	Nm	PASS
FRONT AXLE BRACKET		55.76	53.42	Nm	HOLD
SEAT RAIL FIXING	46.06	58.57	47.06	deg	PASS
DOOR LOCK ASSEMBLY	26.61	51.29	41.48	deg	PASS
PARKING SENSOR	7.66	20.38	10.37	deg	HOLD
CLIMATE CONTROL UNIT	33.89	57.89	44.41	V	PASS
REAR CAMERA MODULE	2.40	14.27	11.35	Nm	PASS



VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Harness routing ☐ OK☐ NOK☐ N/A	Harness routing ☐ OK☐ NOK☐ N/A  QR CODE https://example.invalid/balanced/044/01
Connector locked ☐ OK☐ NOK☐ N/A	Seal continuous ☐ OK☐ NOK☐ N/A
Gap within limit ☐ OK☐ NOK☐ N/A *	Fastener witness mark ☐ OK☐ NOK☐ N/A
Torque confirmed ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
Fastener witness mark ☐ OK☐ NOK☐ N/A	Reference matches order ☐ OK☐ NOK☐ N/A
Harness routing ☐ OK☐ NOK☐ N/A	Fastener witness mark ☐ OK☐ NOK☐ N/A
Surface condition ☐ OK☐ NOK☐ N/A *	Seal continuous ☐ OK☐ NOK☐ N/A
Seal continuous ☐ OK☐ NOK☐ N/A	Seal continuous ☐ OK☐ NOK☐ N/A
Connector locked ☐ OK☐ NOK☐ N/A	Fastener witness mark ☐ OK☐ NOK☐ N/A
Harness routing ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
Gap within limit ☐ OK☐ NOK☐ N/A	No visible damage ☐ OK☐ NOK☐ N/A
No visible damage ☐ OK☐ NOK☐ N/A	Gap within limit ☐ OK☐ NOK☐ N/A *

BATCH / CONTROL INFORMATION

BATCH

B935422

SERIAL

SN3340692373

STATION

QC-04

DECISION

REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	-1.82	25.65	3.54	mm	PASS
REAR CAMERA MODULE	53.93	68.15	57.18	deg	PASS
SEAT RAIL FIXING	47.05	66.80	66.60	mm	HOLD
DOOR LOCK ASSEMBLY	52.27	78.36	76.43	mm	PASS
AIRBAG CONTROL MODULE	42.42	60.16	51.36	V	PASS
ENGINE WIRING HARNESS	46.71	59.37	50.88	Nm	PASS
AIRBAG CONTROL MODULE	44.02	49.64	44.16	Nm	PASS
LOWER ARM FASTENER	32.18	40.99	37.21	Nm	PASS
ENGINE WIRING HARNESS	-1.36	27.96	13.73	mm	PASS
BRAKE HOSE SUPPORT	54.87	73.65	60.38	V	PASS
REAR CAMERA MODULE	18.66	22.01	21.03	Nm	PASS
REAR CAMERA MODULE	4.67	32.25	12.35	V	PASS
CLIMATE CONTROL UNIT	21.78	37.93	34.58	deg	PASS
AIRBAG CONTROL MODULE	2.62	16.28	12.19	Nm	PASS
RIGHT SIDE PANEL	42.59	67.29	60.08	deg	PASS
PARKING SENSOR	46.12	62.48	59.06	Nm	PASS
LOWER ARM FASTENER	34.62	48.62	42.00	deg	PASS
SEAT RAIL FIXING	13.72			V	PASS
AIRBAG CONTROL MODULE	23.42			deg	PASS
DOOR LOCK ASSEMBLY	36.23	44.95	43.62	Nm	PASS
REAR CAMERA MODULE	26.37	32.01	26.73	deg	PASS
AIRBAG CONTROL MODULE	5.48	29.02	8.96	deg	PASS
REAR CAMERA MODULE	11.32	20.33	12.38	V	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 108 543 30

Document: BMQD-046-9003

PAGE 46/50

DATE: 14/07/2026 10:32

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK		☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK		☐ OK ☐ NOK ☐ N/A
Seal continuous			☐ OK ☐ NOK ☐ N/A
Torque confirmed			☐ OK ☐ NOK ☐ N/A
Harness routing	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Gap within limit		Surface condition	☐ OK ☐ NOK ☐ N/A
Reference match		No visible damage	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A
Gap within limit	☐ OK ☐ NOK ☐	atches order	☐ OK ☐ NOK ☐ N/A
Fastener witness mark	☐ OK ☐ NOK ☐	Gap within limit	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 994 330 35

Document: BMQD-047-4988

PAGE 47/50

DATE: 14/07/2026 22:21

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-73760087
MODEL / VARIANT	R2-HYB
SERIAL NUMBER	MX100777789416
INSI	QP-39.6
DEC	ACCEPTED



CODE 128 PO33962621203

Inspection summary

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 641 912 54
Document: BMQD-048-6944

PAGE 48/50

DATE: 14/07/2026 20:54

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B424068 SERIAL SN1154420840
STATION QC-02 DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	53.13	69.14	56.60	mm	HOLD
ENGINE WIRING HARNESS	41.35	52.86	52.42	deg	PASS
FRONT AXLE BRACKET	35.63	58.85	45.93	deg	HOLD
BATTERY SUPPORT	23.28	46.98	37.69	Nm	PASS
RIGHT SIDE PANEL	9.36	17.88	12.94	mm	PASS
SEAT RAIL FIXING	14.86	22.61	15.58	V	PASS
PARKING SENSOR	1.74	23.55	4.22	mm	HOLD
DOOR LOCK ASSEMBLY	48.24	55.84	55.20	mm	PASS
REAR CAMERA MODULE	29.28	54.88	48.33	Nm	HOLD
DOOR LOCK ASSEMBLY	26.51	54.44	47.06	Nm	PASS
BRAKE HOSE SUPPORT	44.78	55.12	50.62	mm	PASS
FRONT AXLE BRACKET	11.60	33.04	14.89	V	PASS
BRAKE HOSE SUPPORT	4.48	21.10	14.81	deg	PASS
SEAT RAIL FIXING	2.57	11.59	7.40	mm	HOLD
BRAKE HOSE SUPPORT	50.08	78.51	50.94	Nm	PASS
BRAKE HOSE SUPPORT	50.37	58.01	56.00	deg	HOLD
BATTERY SUPPORT	49.42	74.73	62.06	mm	PASS
PARKING SENSOR	-0.09	18.02	7.32	Nm	PASS
ENGINE WIRING HARNESS	53.50	74.76	64.10	V	HOLD
PARKING SENSOR	25.77	33.64	33.23	deg	PASS
BRAKE HOSE SUPPORT	9.43	14.51	11.48	V	PASS
ENGINE WIRING HARNESS	0.41	19.55	8.13	deg	PASS
RIGHT SIDE PANEL	8.97	32.91	18.37	Nm	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 159 373 72

Document : BMQD-049-5994

PAGE 49/50

DATE: 14/07/2026 08:02

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Gap within limit	☐ OK ☐ NOK ☐ N/A
Gap within limit	☐ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Seal continuous	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Label presence	☐ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
DATA MATRIX 01095060003538731BM4901		CODE 39 BM-49-02-3201	
Reference matches order	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 554 527 64
Document: BMQD-050-2316

DATE: 14/07/2026 21:16


MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B681403
STATION QC-03

SERIAL SN7425900252
DECISION REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	15.14	17.88	15.34	Nm	PASS
PARKING SENSOR	-1.95	1.73	-0.54	deg	PASS
RIGHT SIDE PANEL	42.20	52.69	46.16	Nm	PASS
SEAT RAIL FIXING	32.92	48.06	39.57	deg	HOLD
SEAT RAIL FIXING	16.50	34.03	20.18	deg	HOLD
CLIMATE CONTROL UNIT	48.02	50.41	48.61	Nm	PASS
SEAT RAIL FIXING	52.56	61.40	57.78	Nm	PASS
FRONT AXLE BRACKET	27.54	39.44	38.08	V	PASS
	29.09	48.85	34.29	V	HOLD
	11.70	39.11	29.96	V	PASS
	13.74	33.81	32.33	V	HOLD
	2.80	17.70	5.34	Nm	PASS
	51.29	62.67	53.55	mm	HOLD
	33.39	46.45	44.69	mm	PASS
SEAT RAIL FIXING	35.55	38.85	35.74	deg	PASS
BATTERY SUPPORT	54.24	79.03	65.61	mm	PASS
SEAT RAIL FIXING	34.57	49.84	49.33	V	HOLD
ENGINE WIRING HARNESS	25.92	43.46	26.18	Nm	PASS
PARKING SENSOR	2.59	11.10	3.6~	Nm	PASS
FRONT AXLE BRACKET	4.40	15.07	7.3	V	PASS
SEAT RAIL FIXING	13.52	27.18	24.	Nm	HOLD
BRAKE HOSE SUPPORT	32.92	52.75	46.27	Nm	PASS
LOWER ARM FASTENER	54.82	57.93	57.12	V	PASS



CODE 128 PO17643518436



DATA MATRIX DA(BM)P050J02L8907