

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 692 488 98
Document: SQ2D-001-8106

PAGE 01/50
DATE: 12/07/2026 00:18
MEASUREMENT REPORT

BATCH B353839 STATION QC-18
SERIAL SN7692554410 DECISION HOLD

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	34.05	39.30	39.16	deg	PASS
REAR CAMERA MODULE	41.72	60.13	46.44	V	PASS
DOOR LOCK ASSEMBLY	29.89	40.92	39.60	Nm	PASS
ENGINE WIRING HARNESS	32.24	40.31	33.21	deg	PASS
CLIMATE CONTROL UNIT	10.31	43.89	28.13	Nm	PASS
REAR CAMERA MODULE	20.24	39.35	38.44	deg	PASS
SEAT RAIL FIXING	22.67	41.79	31.48	mm	PASS
AIRBAG CONTROL MODULE	26.58	47.21	37.64	V	PASS
FRONT AXLE BRACKET	40.14	49.77	42.85	deg	PASS
FRONT AXLE BRACKET	9.52	43.30	41.33	mm	PASS
BATTERY SUPPORT	0.08	11.80	1.76	mm	PASS
LOWER ARM FASTENER	43.55	63.56	50.00	V	PASS
DOOR LOCK ASSEMBLY	29.29	60.95	30.60	mm	PASS
CLIMATE CONTROL UNIT	50.02	55.63	51.71	Nm	PASS
RIGHT SIDE PANEL	38.15	43.43	39.49	Nm	PASS
DOOR LOCK ASSEMBLY	27.44	43.05	35.95	Nm	PASS
CLIMATE CONTROL UNIT	33.21	50.99	40.14	V	PASS
ENGINE WIRING HARNESS	44.91	74.94	54.74	mm	PASS
BATTERY SUPPORT	34.18	67.44	61.26	Nm	PASS
RIGHT SIDE PANEL	1.34	20.81	17.34	Nm	PASS
RIGHT SIDE PANEL	48.36	54.14	52.62	Nm	QR CODE SYNTHETIC-QC-001-1774086172 
REAR CAMERA MODULE	19.11	38.91	34.69	deg	
CLIMATE CONTROL UNIT	30.66	48.17	30.89	mm	
BATTERY SUPPORT	52.49	60.05	58.97	mm	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 320 694 82
Document: SQ2D-002-7446

PAGE 02/50
DATE: 12/07/2026 07:27
FINAL QUALITY GATE

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Surface condition ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A
Cover installed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Label readable ☒ OK ☐ NOK ☐ N/A	Harness routed ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	 QR CODE QR(SQ2D(PAGE=002)INDEX=1 ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Surface condition ☐ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
Label readable ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Inspector: 	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 582 457 35
Document: SQ2D-003-9157

PAGE 03/50

DATE: 12/07/2026 05:47
COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	REAR CAMERA MODULE	RF-71712	L719317	OK
02	RIGHT SIDE PANEL	RF-43971	L962185	OK
03	SEAT RAIL FIXING	RF-98262	L271848	OK
04	AIRBAG CONTROL MODULE	RF-95546	L683675	OK
05	BRAKE HOSE SUPPORT	RF-96989	L546142	OK
06	BRAKE HOSE SUPPORT	RF-95524	L184425	REVIEW
 DATA MATRIX (01)095060001602416	ING SENSOR	RF-28341	L288759	OK
	VE WIRING HARNESS	RF-97075	L795266	OK
	RAIL FIXING	RF-62803	L608140	REVIEW
10	PARKING SENSOR	RF-61131	L347332	REVIEW
11	CLIMATE CONTROL UNIT	RF-29601	L839150	REVIEW
12	ENGINE WIRING HARNESS	RF-60677	L686974	OK
13	CLIMATE CONTROL UNIT	RF-96255	L663105	OK
14	FRONT AXLE BRACKET	RF-68168	L535051	OK
15	LOWER ARM FASTENER	RF-31796	L568444	OK
16	DOOR LOCK ASSEMBLY	RF-76414	L457102	OK
17	AIRBAG CONTROL MODULE	RF-45700	L767057	OK
18	ENGINE WIRING HARNESS	RF-96696	L788729	REVIEW
19	AIRBAG CONTROL MODULE	RF-29184	L557799	 DATA MATRIX DM(SQ2D)P003(I)2IL
20	PARKING SENSOR	RF-67611	L925152	
21	FRONT AXLE BRACKET	RF-77474	L370198	REVIEW

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 369 777 92

Document: SQ2D-004-2329

PAGE 04/50

DATE: 12/07/2026 22:33

MEASUREMENT REPORT

BATCH B781852

SERIAL SN2181885473

STATION QC-14

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
ENGINE WIRING HARNESS	1.58	10.42	3.23	deg	PASS
AIRBAG CONTROL MODULE	41.35	58.89	54.55	mm	PASS
DOOR LOCK ASSEMBLY	4.81	27.53	8.80	deg	PASS
SEAT RAIL FIXING	30.57	38.00	33.82	Nm	PASS
FRONT AXLE BRACKET	37.52	64.03	59.59	Nm	PASS
ENGINE WIRING HARNESS	11.59	30.84	16.97	V	PASS
SEAT RAIL FIXING	46.73	69.05	56.22	deg	PASS
FRONT AXLE BRACKET	29.71	54.60	31.13	Nm	PASS
PARKING SENSOR	30.50	37.73	30.95	Nm	PASS
CLIMATE CONTROL UNIT	41.44	67.69	42.66	deg	PASS
REAR CAMERA MODULE	14.10	25.77	18.65	Nm	PASS
FRONT AXLE BRACKET	29.77	61.73	43.30	Nm	PASS
LOWER ARM FASTENER	31.69	55.12	48.91	Nm	PASS
CLIMATE CONTROL UNIT	11.97	36.51	18.56	mm	PASS
AIRBAG CONTROL MODULE	45.01	77.08	50.96	V	PASS
CLIMATE CONTROL UNIT	21.12	48.07	28.19	deg	PASS
ENGINE WIRING HARNESS		44.38	32.24	Nm	PASS
ENGINE WIRING HARNESS		30.16	18.80	V	PASS
BRAKE HOSE SUPPORT		14.93	9.60	deg	PASS
DOOR LOCK ASSEMBLY	34.35	56.21	51.24	V	PASS
CLIMATE CONTROL UNIT	5.86	12.70	10.57	Nm	PASS
BATTERY SUPPORT	50.14	78.61	63.10	Nm	PASS
ENGINE WIRING HARNESS	40.96	67.61	45.14	mm	PASS
ENGINE WIRING HARNESS	-1.66	26.60	0.19	Nm	PASS

DATA MATRIX: DM(SQ2D(P004)I1JL

BATCH B902995
SERIAL SN2827118614

STATION QC-18
DECISION HOLD

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
LOWER ARM FASTENER	40.32	75.28	54.93	V	PASS
BRAKE HOSE SUPPORT	41.63	58.11	49.34	Nm	PASS
FRONT AXLE BRACKET	26.90	41.22	28.52	deg	PASS
SEAT RAIL FIXING	25.10	40.61	35.58	Nm	PASS
BATTERY SUPPORT	2.25	7.57	3.86	V	PASS
FRONT AXLE BRACKET	11.74	41.86	21.18	Nm	PASS
PARKING SENSOR	23.28	52.97	41.74	deg	PASS
SEAT RAIL FIXING	11.77	29.34	27.71	Nm	PASS
FRONT AXLE BRACKET	21.56	37.16	34.90	deg	PASS
BRAKE HOSE SUPPORT	23.91	30.14	27.91	Nm	PASS
LOWER ARM FASTENER	28.54	55.21	31.56	deg	PASS
RIGHT SIDE PANEL	51.78	55.59	55.25	V	PASS
DOOR LOCK ASSEMBLY	43.89	56.76	54.78	deg	PASS
SEAT RAIL FIXING	41.99	62.04	44.16	mm	PASS
FRONT AXLE BRACKET	8.48	31.72	21.15	mm	PASS
DOOR LOCK ASSEMBLY	41.65	74.59	55.34	deg	PASS
AIRBAG CONTROL MODULE	16.75	49.06	44.81	mm	PASS
CLIMATE CONTROL UNIT	13.80	37.34	20.24	mm	PASS
ENGINE WIRING HARNESS	10.05	33.13	19.93	Nm	PASS
ENGINE WIRING HARNESS	12.99	38.88	27.67	deg	PASS
PARKING SENSOR	45.65	58.47	50.99	mm	PASS
PARKING SENSOR	28.17	57.35	41.65	deg	PASS
FRONT AXLE BRACKET	1.77	32.30	10.77	deg	PASS
CLIMATE CONTROL UNIT	43.66	51.88	45.88	mm	PASS



DATA MATRIX: SN810241783

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Cover installed ☒ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Label readable ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Protective film removed ☐ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Cover installed ☐ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Label readable ☐ OK ☐ NOK ☐ N/A
Fastener mark present ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Fastener mark present ☒ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Inspector:	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 858 302 29

Document: SQ2D-007-7549

PAGE 07/50

DATE: 12/07/2026 21:35

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

DATA MATRIX (01)09506000137682(21)DM		NT / OPERATION	REFERENCE		LOT	STATUS / NOTE
		SENSOR	RF-71329		28510	REVIEW
	02	AIRBAG CONTROL MODULE	RF-13066		L522759	OK
	03	FRONT AXLE BRACKET	RF-21324		L610611	OK
	04	DOOR LOCK ASSEMBLY	RF-97978		L699854	OK
	05	BRAKE HOSE SUPPORT	RF-53295		L383597	OK
	06	CLIMATE CONTROL UNIT	RF-60810		L303035	REV 
	07	FRONT AXLE BRACKET	RF-97873		L546256	OK
	08	LOWER ARM FASTENER	RF-18007		L472420	OK
	09	BRAKE HOSE SUPPORT	RF-36077		L832823	OK
	10	BATTERY SUPPORT	RF-28001		L382040	REVIEW
	11	ENGINE WIRING HARNESS	RF-24891		L690098	OK
	12	CLIMATE CONTROL UNIT	RF-72837		L775100	OK
	13	ENGINE WIRING HARNESS	RF-11561		L786283	REVIEW
	14	PARKING SENSOR	RF-25270		L830594	REVIEW
	15	FRONT AXLE BRACKET	RF-30002		L333284	OK
	16	BATTERY SUPPORT	RF-30810		L938024	OK
	17	REAR CAMERA MODULE	RF-94978		L724365	OK
	18	DOOR LOCK ASSEMBLY	RF-33594		L238831	OK
	19	CLIMATE CONTROL UNIT	RF-51569		L911723	OK
	20	BATTERY SUPPORT	RF-13609		L499291	REVIEW
	21	CLIMATE CONTROL UNIT	RF-17932		L617223	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 806 370 72

Document: SQ2D-008-1911

PAGE 08/50

DATE: 12/07/2026 01:47

MEASUREMENT REPORT

BATCH B678085

SERIAL SN2772615017



STATION QC-18

DECISION OK

CHARACTERISTIC	LO	HI	VALUE	UNIT	RESULT
CLIMATE CONTROL UNIT	48.5	55.23	55.23	deg	PASS
BRAKE HOSE SUPPORT	44.55	54.09	53.18	mm	PASS
RIGHT SIDE PANEL	18.90	47.20	41.47	Nm	PASS
LOWER ARM FASTENER	26.98	58.46	31.61	V	PASS
DOOR LOCK ASSEMBLY	12.36	34.39	15.08	V	PASS
ENGINE WIRING HARNESS	28.54	45.94	42.19	mm	PASS
SEAT RAIL FIXING	-1.95	14.95	0.03	deg	PASS
BRAKE HOSE SUPPORT	49.61	82.12	74.67	Nm	PASS
ENGINE WIRING HARNESS	17.35	22.21	18.13	V	PASS
BATTERY SUPPORT	28.67	37.03	29.00	Nm	PASS
FRONT AXLE BRACKET	46.97	68.97	50.26	mm	PASS
RIGHT SIDE PANEL	27.88	56.17	29.43	mm	PASS
PARKING SENSOR	51.98	65.34	56.81	V	PASS
RIGHT SIDE PANEL	44.61	77.08	58.76	V	PASS
DOOR LOCK ASSEMBLY	20.57	40.34	24.17	mm	PASS
RIGHT SIDE PANEL	44.91	67.42	59.56	mm	PASS
LOWER ARM FASTENER	49.08	61.02	51.85	mm	PASS
RIGHT SIDE PANEL	-0.35	3.26	0.21	mm	PASS
DOOR LOCK ASSEMBLY	23.44	43.24	33.43	V	PASS
BRAKE HOSE SUPPORT	6.42	27.80	9.35	deg	PASS
AIRBAG CONTROL MODULE	26.09	55.12	26.76	V	PASS
SEAT RAIL FIXING	22.24	25.94	22.36	mm	PASS
BATTERY SUPPORT	32.86	53.53	39.02	mm	PASS
BRAKE HOSE SUPPORT	17.94	24.28	23.17	V	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 486 972 77
Document: SQ2D-009-9080

PAGE 09/50
DATE: 12/07/2026 08:16
FINAL QUALITY GATE

VISUAL / DIMENSIONAL

Reference matches order

☒ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☐ OK ☐ NOK ☐ N/A

Harness routed

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☒ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Gap within limit

☐ OK ☐ NOK ☐ N/A

Connector locked

☐ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

Torque confirmed

☒ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

Inspector:

FU

Torc



DATA MATRIX (01)09506000191536(21)

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☒ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

No visible damage

☐ OK ☐ NOK ☐ N/A

Protective film removed

☒ OK ☐ NOK ☐ N/A

Label readable

☒ OK ☐ NOK ☐ N/A

Harness routed

☒ OK ☐ NOK ☐ N/A

No visible damage

☐ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Label readable

☐ OK ☐ NOK ☐ N/A

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 613 929 73

Document: SQ2D-010-5155

PAGE 10/50

DATE: 12/07/2026 20:20

FINAL QUALITY GATE

VISUAL / DIMENSIONAL

Seal continuous

☐

DATA MATRIX SN196084580647-P10

Cover installed

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☒ OK ☐ NOK ☐ N/A

Cover installed

☒ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Protective film removed

☒ OK ☐ NOK ☐ N/A

Label readable

☒ OK ☐ NOK ☐ N/A

Torque confirmed

☒ OK ☐ NOK ☐ N/A

Seal continuous

☐ OK ☐ NOK ☐ N/A

Inspector:

FUNCTION / IDENTITY

Cover installed

☒ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Connector locked

☐ OK ☐ NOK ☐ N/A

Gap within limit

☐ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Label readable

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☒ OK ☐ NOK ☐ N/A

Seal continuous

☐ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 635 996 10

Document: SQ2D-011-9516

DATE: 12/07/2026 18:05

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-74404	L589903	OK
02	SEAT RAIL FIXING	RF-22682	L723371	OK
03	BATTERY SUPPORT	RF-51432	L485138	OK
04	PARKING SENSOR	RF-50926	L752707	OK
05	RIGHT SIDE PANEL	RF-74334	L346156	OK
06	RIGHT SIDE PANEL	RF-53842	L776420	OK
07	ENGINE WIRING HARNESS	RF-65221	L261170	OK
08	REAR CAMERA MODULE	RF-58237	L386061	REVIEW
09	DOOR LOCK ASSEMBLY	RF-82851	L319514	OK
10	AIRBAG CONTROL MODULE	RF-82327	L127419	OK
11	ENGINE WIRING HARNESS	RF-39234	L925031	REVIEW
12	BATTERY SUPPORT	RF-13399	L242576	OK
13	ENGINE WIRING HARNESS	RF-15980	L416916	OK
14	FRONT AXLE BRACKET	RF-91448	L827848	OK
15	CLIMATE CONTROL UNIT	RF-10688	L914823	REVIEW
16	REAR CAMERA MODULE	RF-37633	L617395	REVIEW
17	ENGINE WIRING HARNESS	RF-92165	L547726	OK
18	CLIMATE CONTROL UNIT	RF-87699	L616988	OK
19	CLIMATE CONTROL UNIT	RF-73242	L839361	REVIEW
20	LOWER ARM FASTENER	RF-56940	L245080	OK
21	REAR CAMERA MODULE	RF-81978	L367340	OK



BATCH

B916797

STATION

QC-04

SERIAL

SN7925070008

DECISION

OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
LOWER ARM FASTENER	26.38	33.3		mm	PASS
BATTERY SUPPORT	36.78	51.2		deg	PASS
DOOR LOCK ASSEMBLY	29.27	45.3		deg	PASS
ENGINE WIRING HARNESS	36.70	55.5		V	PASS
FRONT AXLE BRACKET	52.69	84.5	 QR CODE https://example.invalid/synthetic/qc/012/2/48994	mm	PASS
BATTERY S	54.65	62.44		mm	PASS
SEAT RAIL	45.73	74.28		V	PASS
SEAT RAIL	46.25	75.35		V	PASS
SEAT RAIL	23.83	50.62	47.29	deg	PASS
ENGINE WI QR CODE SYNTHETIC-QC-012-1-203218343	30.41	32.47	30.61	Nm	PASS
BRAKE HOSE SUPPORT	23.19	55.05	36.51	V	PASS
DOOR LOCK ASSEMBLY	41.15	67.68	61.33	mm	PASS
DOOR LOCK ASSEMBLY	8.26	15.46	9.74	Nm	PASS
LOWER ARM FASTENER	17.38	31.39	27.67	mm	PASS
BRAKE HOSE SUPPORT	-1.87	24.60	20.28	V	PASS
AIRBAG CONTROL MODULE	34.77	38.96	36.35	V	PASS
LOWER ARM FASTENER	49.65	69.06	58.55	deg	PASS
DOOR LOCK ASSEMBLY	38.11	65.43	61.62	Nm	PASS
LOWER ARM FASTENER	52.96	71.55	66.65	Nm	PASS
BATTERY SUPPORT	19.59	52.20	51.27	V	PASS
REAR CAMERA MODULE	5.73	22.39	14.94	V	PASS
AIRBAG CONTROL MODULE	6.46	22.56	11.65	mm	PASS
PARKING SENSOR	-0.13	24.85	2.47	deg	PASS
BRAKE HOSE SUPPORT	38.12	40.47	39.36	Nm	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 449 291 13

Document: SQ2D-013-5863

PAGE 13/50

DATE: 12/07/2026 01:58

FINAL QUALITY GATE

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Seal continuous	☒ OK ☐ NOK ☐ N/A	Label rea	☐ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	 DATA MATRIX DMISQ2D(P013)2(L512721	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Label readable	☐ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Conner	☐ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
 DATA MATRIX DMISQ2D(P013)3(L48	☒ OK ☐ NOK ☐ N/A	Harness routed	☒ OK ☐ NOK ☐ N/A
Label readable	☐ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☒ OK ☐ NOK ☐ N/A	 DATA MATRIX DMISQ2D(P013)4	☒ OK ☐ NOK ☐ N/A
Harness routed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Inspector: 	 DATA MATRIX SN446560799499-P13	Reference matches order	☒ OK ☐ NOK ☐ N/A

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 731 562 25

Document: SQ2D-014-7459

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	SEAT RAIL FIXING	RF-77773	L832191	OK
02	FRONT AXLE BRACKET	 DATA MATRIX DMISQ2DIP014I13IL633687	L500586	REVIEW
03	SEAT RAIL FIXING		L285386	REVIEW
04	ENGINE WIRING HARNESS		L731944	OK
05	BATTERY SUPPORT	RF-36924	L310968	REVIEW
06	BRAKE HOSE SUPPORT	RF-16259	L117441	REVIEW
07	ENGINE WIRING HARNESS	RF-63558	L370450	OK
08	FRONT AXLE BRACKET	RF-43527	L250013	OK
09	RIGHT SIDE PANEL	RF-65104	L316812	OK
10	DOOR LOCK ASSEMBLY	RF-26706	L422514	OK
11	PARKING SENSOR	RF-83515	L924400	REVIEW
12	PARKING SENSOR	R  DATA MATRIX (01)09506000141	L261238	OK
13	CLIMATE CONTROL UNIT	R	L369874	REVIEW
14	ENGINE WIRING HARNESS	RF-79928	L792988	OK



QR CODE <https://example.invalid/synthetic/qc/014/1/58592>

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 816 170 11

Document: SQ2D-015-2807

PAGE 15/50

DATE: 12/07/2026 22:58

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

REF	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
02		RF-30391	L147016	REVIEW
	SUPPORT	RF-50267	L243303	OK
03	SEAT RAIL FIXING	RF-53963	L485588	OK
04	ENGINE WIRING HARNESS	RF-77598	L948516	OK
05	LOWER ARM FASTENER	RF-24931	L995118	REVIEW
06	CLIMATE CONTROL UNIT	RF-66511	L186930	OK
07	SEAT RAIL FIXING	RF-36625	L539382	OK
08	DOOR LOCK ASSEMBLY	RF-73133	L982383	OK
09	REAR CAMERA MODULE	 QR CODE SYNTHETIC-QC-015-2-128626108	L694822	OK
10	PARKING SENSOR		L287377	OK
11	AIRBAG CONTROL MODULE		L403213	OK
12	SEAT RAIL FIXING	RF-88009	L352804	OK
13	PARKING SENSOR	RF-39742	L916466	OK
14	RIGHT SIDE PANEL	RF-58414	L865574	OK
15	BRAKE HOSE SUPPORT	RF-41543	L573817	OK
16	LOWER ARM FASTENER	RF-62893	L695007	REVIEW
17	ENGINE WIRING HARNESS	RF-29054	L500836	OK
18	BATTERY SUPPORT	RF-65990	L453975	OK
19	RIGHT SIDE PANEL	RF-66880	L930874	OK
20	ENGINE WIRING HARNESS	RF-21405	L154706	OK
21	RIGHT SIDE PANEL	RF-34779	L365342	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 716 866 80

Document: SQ2D-016-9191

PAGE 16/50

DATE: 12/07/2026 13:29

MEASUREMENT REPORT

BATCH B438809
SERIAL SN1018487847

STATION QC-20
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
FRONT AXLE BRACKET	25.56	56.67	46.15	Nm	PASS
	26.20	59.39	37.00	V	PASS
	50.27	54.83	53.61	mm	PASS
PARKING SENSOR	37.24	50.82	42.28	mm	PASS
ENGINE WIRING HARNESS	10.22	41.62	27.27	deg	PASS
FRONT AXLE BRACKET	35.96	67.11	52.58	V	PASS
AIRBAG CONTROL MODULE	32.94	52.91	41.43	V	PASS
DOOR LOCK ASSEMBLY	45.44	66.26	61.95	Nm	PASS
BRAKE HOSE SUPPORT	5.71	19.69	19.58	deg	PASS
SEAT RAIL FIXING	1.56	8.52	4.71	deg	PASS
RIGHT SIDE PANEL	0.53	24.30	13.59	mm	PASS
CLIMATE CONTROL UNIT	50.57	83.65	53.12	Nm	PASS
AIRBAG CONTROL MODULE	43.92	64.54	55.38	mm	PASS
RIGHT SIDE PANEL	32.99	59.75	40.53	Nm	PASS
BRAKE HOSE SUPPORT	14.43	35.84	19.96	V	PASS
DOOR LOCK ASSEMBLY	48.53	83.01	50.51	Nm	PASS
DOOR LOCK ASSEMBLY	37.67	65.49	38.71	deg	PASS
FRONT AXLE BRACKET	11.28	21.47	12.46	deg	PASS
LOWER ARM FASTENER	3.86	10.17	4.98	mm	PASS
ENGINE WIRING HARNESS	22.91	25.71	24.83	mm	PASS
CLIMATE CONTROL UNIT	53.44	87.44	64.67	deg	PASS
PARKING SENSOR	4.26	10.87	10.24	V	PASS
AIRBAG CONTROL MODULE	27.25	55.79	37.10	Nm	PASS
DOOR LOCK ASSEMBLY	4.01	26.66	17.82	deg	PASS



2D CODE SYNTHETIC-QC-016-148

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 105 145 43

Document: SQ2D-017-4756

PAGE 17/50

DATE: 12/07/2026 09:41

FINAL QUALITY GATE

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Label readable 
Reference matches order ☐ OK ☐ NOK ☐ N/A	Surface condition
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☐ OK ☐ NOK ☐ N/A
Protective film removed ☐ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Fastener mark present ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Inspector: _____	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 133 946 53

Document: SQ2D-018-4558

PAGE 18/50

DATE: 12/07/2026 17:52

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	 KET	RF-86008	L817239	OK
02	QR CODE SYNTHETIC-QC-018-1-38KET	RF-22406	L665685	OK
03	FRONT AXLE BRACKET	RF-85616	L479315	OK
04	PARKING SENSOR	RF-70417	L985707	OK
05	FRONT AXLE BRACKET	RF-52013	L396281	REVIEW
06	AIRBAG CONTROL MODULE	RF-59240	L256124	OK
07	REAR CAMERA MODULE	RF-27528	L697525	OK
08	REAR CAMERA MODULE	RF-50368	L943513	OK
09	CLIMATE CONTROL UNIT	RF-18203	L250570	OK
10	RIGHT SIDE PANEL	RF-87071	L891576	REVIEW
11	PARKING SENSOR	RF-83976	L659480	OK
12	DOOR LOCK ASSEMBLY	RF-29293	L857146	OK
13	BRAKE HOSE SUPPORT	RF-28422	L941427	OK
14	PARKING SENSOR	RF-21015	L504512	OK
15	CLIMATE CONTROL UNIT	RF-56234	L718850	OK
16	PARKING SENSOR	RF-21225	L342962	OK
17	FRONT AXLE BRACKET	RF-74680	L264304	OK
		RF-21099	L465528	OK
		RF-94282	L749846	OK
		RF-66992	L498999	OK
		RF-97861	L949107	OK



QR CODE QRSD2DPAGE=018INDEX=2LOT=557798

BATCH

B896628

STATION

QC-27

SERIAL

SN2405694813

DECISION

OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BATTERY SUPPORT	13.87	31.14	30.97	deg	PASS
AIRBAG CONTROL MODULE	6.86	37.98	16.26	V	PASS
RIGHT SIDE PANEL	27.04	54.82	45.84	mm	PASS
FRONT AXLE BRACKET	28.12	57.33	38.77	Nm	PASS
AIRBAG CONTROL MODULE	34.56	54.82	35.83	mm	PASS
PARKING SENSOR	43.47	47.80	45.92	V	PASS
ENGINE WIRING HARNESS	31.89	47.45	35.73	mm	PASS
FRONT AXLE BRACKET	12.26	27.74	18.08	V	PASS
SEAT RAIL FIXING	9.65	14.79	10.85	Nm	PASS
FRONT AXLE BRACKET	15.71	33.29	20.51	mm	PASS
REAR CAMERA MODULE	13.79	29.81	26.29	deg	PASS
BATTERY SUPPORT	50.10	74.31	67.73	V	PASS
LOWER ARM FASTENER	13.07	21.64	13.69	Nm	PASS
AIRBAG CONTROL MODULE	31.33	58.74	56.92	V	PASS
AIRBAG CONTROL MODULE	31.93	66.64	39.35	V	PASS
CLIMATE CONTROL UNIT	16.22	43.77	25.46	deg	PASS
FRONT AXLE BRACKET	24.88	27.42	25.71	V	PASS
BATTERY SUPPORT	18.54	46.53	45.81	deg	PASS
SEAT RAIL FIXING	33.58	35.80	33.71	V	PASS
DOOR LOCK ASSEMBLY	14.14	36.29	21.73	deg	PASS
DOOR LOCK ASSEMBLY	4.83	22.89	17.64	V	PASS
CLIMATE CONTROL UNIT	45.85	60.08	52.90	V	PASS
AIRBAG CONTROL MODULE	0.99	14.15	5.26	V	PASS
SEAT RAIL FIXING	24.82	32.30	29.65	mm	PASS



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 844 532 54
Document : SQ2D-020-9303

BATCH B758158
STATION QC-13
SERIAL SN6312341869
DECISION HOLD

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	22.69	38.50	28.80	V	 DATA MATRIX: DMSQ2DP020
RIGHT SIDE PANEL	36.83	69.10	57.89	V	
PARKING SENSOR	32.02	57.81	56.92	Nm	PASS
ENGINE WIRING HARNESS	14.25	18.35	17.79	mm	PASS
REAR CAMERA MODULE	47.10	70.80	47.66	Nm	PASS
BATTERY SUPPORT	11.72	38.42	19.72	V	PASS
BRAKE HOSE SUPPORT	10.40	15.72	10.97	deg	PASS
RIGHT SIDE PANEL	25.39	46.63	34.28	Nm	PASS
PARKING SENSOR	40.94	59.12	48.39	mm	PASS
PARKING SENSOR	25.52	45.90	34.65	V	PASS
CLIMATE CONTROL UNIT	14.79	31.12	20.31	Nm	PASS
PARKING SENSOR	24.09	47.68	43.06	mm	PASS
BRAKE HOSE SUPPORT	24.07	58.05	45.91	deg	PASS
LOWER ARM FASTENER	17.10	46.41	23.09	V	PASS
FRONT AXLE BRACKET	34.03	51.33	39.28	deg	PASS
REAR CAMERA MODULE	23.16	29.86	24.79	V	PASS
PARKING SENSOR	20.40	31.39	28.50	deg	PASS
BATTERY SUPPORT	41.65	44.76	42.89	deg	PASS
BATTERY SUPPORT	2.83	27.95	11.95	deg	PASS
RIGHT SIDE PANEL	26.63	60.64	43.85	deg	PASS
SEAT RAIL FIXING	24.36	45.31	31.50	mm	PASS
LOWER ARM FASTENER	45.62	59.17	47.73	Nm	PASS
LOWER ARM FASTENER	44.70	69.69	60.24	mm	PASS
REAR CAMERA MODULE	52.45	56.91	53.29	Nm	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 180 420 40

Document: SQ2D-021-3577

PAGE 21/50

DATE: 12/07/2026 00:30

FINAL QUALITY GATE

VISUAL / DIMENSIONAL

Gap within limit

☒ OK ☐ NOK ☐ N/A

Sur



Fas

QR CODE SYNTHETIC-QC-021-3-3

Label readable

☐ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

Connector locked

☒ OK ☐ NOK ☐ N/A

Fastener mark present

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Label readable

☒ OK ☐ NOK ☐ N/A

Cover installed

☐ OK ☐ NOK ☐ N/A

Gap within limit

☐ OK ☐ NOK ☐ N/A

Harness routed

☒ OK ☐ NOK ☐ N/A

Inspector:

FUNCTION / IDENTITY

Connector locked

☒ OK ☐ NOK ☐ N/A

Connector locked

☐ OK ☐ NOK ☐ N/A

Reference matches order

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Connector locked

☒ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Harness routed

☒ OK ☐ NOK ☐ N/A

Gap within limit

☒ OK ☐ NOK ☐ N/A

Harness routed

☒ OK ☐ NOK ☐ N/A

Label readable

☒ OK ☐ NOK ☐ N/A

Protective film removed

☒ OK ☐ NOK ☐ N/A

DATA MATRIX DM(SQ2D/P021J1)1



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 247 197 91

Document: SQ2D-022-2090

PAGE 22/50

DATE: 12/07/2026 11:49

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BATTERY SUPPORT	RF-86848	L817134	OK
02	BATTERY SUPPORT	RF-58695	L526795	OK
03	FRONT AXLE BRACKET	RF-63562	L465460	OK
04	RIGHT SIDE PANEL	RF-22440	L371254	OK
05	RIGHT SIDE PANEL	RF-83935	L746008	OK
06	FRONT AXLE BRACKET	RF-59588	L409744	REVIEW
07	PARKING SENSOR	RF-35441	L207022	OK
08	LOWER ARM FASTENER	RF-51344	L214819	REVIEW
09	SEAT RAIL FIXING	RF-36312	L381504	OK
10	LOWER ARM FASTENER	RF-41761	L691597	OK
11	CLIMATE CONTROL UNIT	RF-37071	L982113	OK
12	FRONT AXLE BRACKET	RF-87061	L360257	OK
13	ENGINE WIRING HARNESS	RF-23201	L122558	OK
14	REAR CAMERA MODULE	RF-52407	L546642	OK
15	DOOR LOCK ASSEMBLY	RF-80400	L121286	OK
16	LOWER ARM FASTENER	RF-10115	L853735	OK
17	ENGINE WIRING HARNESS	RF-80030	L384328	REVIEW
18	AIRBAG CONTROL MODULE	RF-23740	L942375	OK
19	FRONT AXLE BRACKET	RF-68238	L295920	OK
20	PARKING SENSOR	RF-70241	L475280	REVIEW
21	SEAT RAIL FIXING	RF-68194	L683137	OK



DATA MATRIX: 8072021941

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 872 163 29
Document: SQ2D-023-9523

PAGE 23/50

DATE: 12/07/2026 18:14

MEASUREMENT REPORT

BATCH B523653
SERIAL SN8129423775

STATION QC-26
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
CLIMATE CONTROL UNIT	54.02	62.27	57.85	V	PASS
BATTERY SUPPORT	34.00	45.86	37.12	deg	PASS
AIRBAG CONTROL MODULE	41.54	68.15	51.42	Nm	PASS
SEAT RAIL FIXING	20.86	29.17	28.90	Nm	PASS
ENGINE WIRING HARNESS	20.75	49.26	45.99	Nm	PASS
DOOR LOCK ASSEMBLY	17.17	42.84	39.77	V	PASS
RIGHT SIDE PANEL	27.73	54.83	38.52	V	PASS
PARKING SENSOR	49.42	53.56	52.56	Nm	
ENGINE WIRING HARNESS	32.23	51.89	37.82	Nm	
CLIMATE CONTROL UNIT	10.71	38.01	16.14	deg	
BRAKE HOSE SUPPORT	13.64	18.37	14.59	mm	PASS
AIRBAG CONTROL MODULE	49.07	65.57	63.75	deg	PASS
BATTERY SUPPORT	31.77	56.08	44.61	V	PASS
FRONT AXLE BRACKET	38.85	54.63	51.74	Nm	PASS
BATTERY SUPPORT	23.29	55.15	30.89	mm	PASS
BATTERY SUPPORT	38.08	47.07	40.32	V	PASS
AIRBAG CONTROL MODULE	48.59	56.21	52.90	Nm	PASS
PARKING SENSOR	42.60	45.09	44.97	Nm	PASS
LOWER ARM FASTENER	25.90	52.55	39.99	Nm	PASS
ENGINE WIRING HARNESS	-1.41	33.05	27.87	deg	PASS
PARKING SENSOR	45.16	71.78	45.50	deg	PASS
BATTERY SUPPORT	7.56	22.53	7.77	deg	PASS
FRONT AXLE BRACKET	24.93	52.72	28.53	deg	PASS
AIRBAG CONTROL MODULE	51.14	59.68	58.39	deg	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 603 178 31

Document: SQ2D-024-6892

PAGE 24/50

DATE: 12/07/2026 12:14

FINAL QUALITY GATE

VISUAL		FUNCTION / IDENTITY	
No visible	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
	☐ OK ☐ NOK ☐ N/A	Label readable	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☐ OK ☐ NOK ☐ N/A
Label readable	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Label readable	☒ OK ☐ NOK ☐ N/A	Torque confirmed	
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Cover installed	
Fastener mark present	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Label readable	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Harness routed	☒ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Inspector:			

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 177 474 69

Document: SQ2D-025-5713

PAGE 25/50

DATE: 12/07/2026 09:28

FINAL QUALITY GATE

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☐ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Protective film removed ☐ OK ☐ NOK ☐ N/A	Torque confirmed  N/A DATA MATRIX (01)09506000145106(
Cover installed ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☐ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Label readable ☒ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Connector locked ☐ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Inspector: _____	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 509 868 27

Document: SQ2D-026-2885

PAGE 26/50

DATE: 12/07/2026 00:33

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION		LOT	STATUS / NOTE
01	AIRBAG CONTROL MODULE	 DATA MATRIX: (01)09506000120390(21)DM0261	L802641	OK
02	PARKING SENSOR		L594812	OK
03	REAR CAMERA MODULE		L194405	OK
04	BRAKE HOSE SUPPORT	RF-58000	L584172	OK
05	CLIMATE CONTROL UNIT	RF-61213	L922101	OK
06	LOWER ARM FASTENER	RF-13295	L159142	OK
07	REAR CAMERA MODULE	RF-71016	L917016	OK
08	BATTERY SUPPORT	RF-76046	L231535	OK
09	BRAKE HOSE SUPPORT	RF-11892	L394504	REVIEW
10	DOOR LOCK ASSEMBLY	RF-10924	L316563	OK
11	LOWER ARM FASTENER	RF-56967	L726219	OK
12	CLIMATE CONTROL UNIT	RF-26869	L200477	OK
13	CLIMATE CONTROL UNIT	RF-19751	L788801	OK
14	BRAKE HOSE SUPPORT	RF.	L299953	REVIEW
15	ENGINE WIRING HARNESS	RF.	L197514	OK
16	PARKING SENSOR	RF. DATA MATRIX: SN141724318006-P26	L863211	OK
17	REAR CAMERA MODULE	RF-43829	L705895	OK
18	DOOR LOCK ASSEMBLY	RF-14106	L768634	OK
19	LOWER ARM FASTENER	F-81510	L213193	OK
20	PARKING SENSOR	DATA MATRIX: SN1357002712252 F-42175	L204688	OK
21	FRONT AXLE BRACKET	RF-15282	L223654	OK



QR CODE: QR(SQ2D)PAGE-026INDEX-LOT-540203

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 656 933 63
Document: SQ2D-027-1380

PAGE 27/50
DATE: 12/07/2026 04:40
MEASUREMENT REPORT

BATCH

B417479

SERIAL

SN3168829852

STATION

QC-19

DECISION

OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	26.61	49.38	34.66	mm	PASS
ENGINE WIRING HARNESS	24.16	28.49	25.94	Nm	PASS
BATTERY SUPPORT	38.27	50.18	44.41	mm	PASS
AIRBAG CONTROL MODULE	3.66	18.16	11.53	V	PASS
LOWER ARM FASTENER	50.18	82.49	67.54	V	PASS
CLIMATE CONTROL UNIT	39.40	63.88	42.66	deg	PASS
REAR CAMERA MODULE	16.95	47.92	35.64	V	PASS
RIGHT SIDE PANEL	45.26	74.94	69.42	V	PASS
REAR CAMERA MODULE	14.61	37.55	30.06	mm	PASS
BATTERY SUPPORT	28.06	42.79	41.72	Nm	PASS
RIGHT SIDE PANEL	52.80	57.58	53.61	Nm	PASS
CLIMATE CONTROL UNIT	49.85	56.39	50.95	mm	PASS
BATTERY SUPPORT	34.96	40.27	37.06	deg	PASS
PARKING SENSOR	46.59	58.07	56.14	V	PASS
LOWER ARM FASTENER	33.88	57.65	57.00	mm	PASS
SEAT RAIL FIXING	24.65	58.97	46.77	V	PASS
BATTERY SUPPORT	37.59	58.50	52.19	V	PASS
BATTERY SUPPORT	12.47	17.67	17.03	V	P/
BRAKE HOSE SUPPORT	26.64	49.51	35.68	V	P/
ENGINE WIRING HARNESS	7.97	17.40	13.23	mm	PASS
AIRBAG CONTROL MODULE	12.75	15.61		mm	PASS
BRAKE HOSE SUPPORT	49.05	62.65		Nm	PASS
DOOR LOCK ASSEMBLY	18.20	47.08		deg	PASS
FRONT AXLE BRACKET	1.71	26.78		Nm	PASS

DATA MATRIX SN4237340665-P27



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 206 977 28

Document: SQ2D-028-1253

PAGE 28/50

DATE: 12/07/2026 17:17

FINAL QUALITY GATE

VISUAL / DIMENSIONAL

FUNCTION / IDENTITY

Label readable ☒ OK ☐ NOK ☐ N/A

No visible damage ☒ OK ☐ NOK ☐ N/A

Protective film removed ☒ OK ☐ NOK ☐ N/A

Seal continuous ☒ OK ☐ NOK ☐ N/A

Fastener mark present ☒ OK ☐ NOK ☐ N/A

Torque confirmed ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

Cover installed ☒ OK ☐ NOK ☐ N/A

Protective film removed ☒ OK ☐ NOK ☐ N/A

No visible damage ☒ OK ☐ NOK ☐ N/A



QR CODE SYNTHETIC-QC-028-1-312708744



QR CODE QR(SQ2D(PAGE=028)INDEX=3)LOT=783906

☒ OK ☐ NOK ☐ N/A

Seal continuous ☒ OK ☐ NOK ☐ N/A

☒ OK ☐ NOK ☐ N/A

Surface condition ☐ OK ☐ NOK ☐ N/A

Cover installed ☐ OK ☐ NOK ☐ N/A

No visible damage ☒ OK ☐ NOK ☐ N/A

Harness routed ☒ OK ☐ NOK ☐ N/A

Harness routed ☒ OK ☐ NOK ☐ N/A

Seal continuous ☒ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

No visible damage ☐ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

Label readable ☒ OK ☐ NOK ☐ N/A

Inspector:



QR CODE SYNTHETIC-QC-028-2-791467

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	ENGINE WIRING HARNESS	RF-75341	L857573	OK
02	ENGINE WIRING HARNESS	RF-46702		REVIEW
03	DOOR LOCK ASSEMBLY	RF-93637		OK
04	SEAT RAIL FIXING	RF-18844		OK
QR CODE https://example.invalid/synthetic/qc/029/1/				
05	ENGINE WIRING HARNESS	RF-98557	L285701	REVIEW
06	FRONT AXLE BRACKET	RF-67112	L482828	REVIEW
07	ENGINE WIRING HARNESS	RF-65205	L445399	REVIEW
08	ENGINE WIRING HARNESS	RF-63808	L761780	REVIEW
09	REAR CAMERA MODULE	RF-85593	L985966	OK
10	BRAKE HOSE SUPPORT	RF-29341	L307098	OK
11	CLIMATE CONTROL UNIT	RF-98114	L687412	OK
12	LOWER ARM FASTENER	RF-46410	L311062	REVIEW
13	DOOR LOCK ASSEMBLY	RF-80095	L552884	OK
14	SEAT RAIL FIXING	RF-98075	L932806	OK
15	PARKING SENSOR	RF-59987	L311673	OK
16	RIGHT SIDE PANEL	RF-43683	L622044	OK
17	PARKING SENSOR	RF-10162	L761985	OK
18	REAR CAMERA MODULE	RF-94779	L808469	OK
19	BATTERY SUPPORT	RF-55432	L268945	REVIEW
20	SEAT RAIL FIXING	RF-44791	L770162	OK
21	DOOR LOCK ASSEMBLY	RF-42726	L402979	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 864 148 78
Document: SQ2D-030-7251

PAGE 30/50
DATE: 12/07/2026 12:52
COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	SEAT RAIL FIXING	RF-20817	L755044	OK
02	BATTERY SUPPORT	RF-84392	L261174	OK
03	 QR CODE SYNTHETIC-OC-030-157384916	RF-53511	L591632	OK
04		RF-61683	L581631	OK
05	ENGINE WIRING HARNESS	RF-10971	L484017	REVIEW
06	PARKING SENSOR	RF-86494	L853947	OK
07	BATTERY SUPPORT	RF-78262	L405830	OK
08	BATTERY SUPPORT	RF-50709	L960620	OK
09	REAR CAMERA MODULE	RF-75655	L417261	OK
10	AIRBAG CONTROL MODULE	RF-86472	L621163	OK
11	PARKING SENSOR	RF-76394	L861545	OK
12	PARKING SENSOR	RF-47446	L479628	OK
13	AIRBAG CONTROL MODULE	RF-47014	L745762	OK
14	SEAT RAIL FIXING	RF-37178	L498999	OK
15	AIRBAG CONTROL MODULE	RF-20199	L829435	OK
16	FRONT AXLE BRACKET	RF-11699	L653731	OK
17	REAR CAMERA MODULE	RF-80283	L364767	OK
18	AIRBAG CONTROL MODULE	RF-46174	L750739	OK
19	BRAKE HOSE SUPPORT	RF-70488	L684235	REVIEW
20	REAR CAMERA MODL	RF-97799	L876636	REVIEW
21	AIRBAG CONTROL MC  DATA MATRIX (01)09506000174663(21)	RF-60062	L555739	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 273 736 93

Document: SQ2D-031-9752

PAGE 31/50

DATE: 12/07/2026 06:17

MEASUREMENT REPORT

BATCH B329828
SERIAL SN1143160222

STATION QC-13
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
REAR CAMERA MODULE	9.05	23.51	12.26	deg	PASS
ENGINE WIRING HARNESS	16.90	22.32	19.10	V	PASS
ENGINE WIRING HARNESS	9.14	32.07	24.55	mm	PASS
SEAT RAIL FIXING	25.20	37.75	29.78	mm	PASS
ENGINE WIRING HARNESS	41.87	57.00	56.75	Nm	PASS
CLIMATE CONTROL UNIT	52.04	60.43	56.48	deg	PASS
FRONT AXLE BRACKET	34.83	55.53	45.20	mm	PASS
ENGINE WIRING HARNESS	27.34	38.49	35.39	mm	 QR CODE QR SQ2D PAGE=031 INDEX=1 LOT=956104
BRAKE HOSE SUPPORT	0.52	19.33	16.78	mm	
PARKING SENSOR	45.86	52.97	47.98	deg	
PARKING SENSOR	4.69	11.76	11.14	deg	
SEAT RAIL FIXING	53.28	70.20	70.05	V	PASS
BRAKE HOSE SUPPORT	15.68	22.16	16.17	V	PASS
AIRBAG CONTROL MODULE	29.40	32.22	30.40	Nm	PASS
ENGINE WIRING HARNESS	24.44	29.35	26.38	mm	PASS
PARKING SENSOR	43.87	55.56	51.95	deg	PASS
LOWER ARM FASTENER	23.01	28.37	27.50	V	PASS
DOOR LOCK ASSEMBLY	-1.42	8.82	2.19	deg	PASS
AIRBAG CONTROL MODULE	4.96	24.77	7.72	Nm	PASS
RIGHT SIDE PANEL	48.71	73.06	51.12	mm	PASS
LOWER ARM FASTENER	1.72	8.59	4.32	Nm	PASS
REAR CAMERA MODULE	29.77	60.13	58.83	mm	PASS
PARKING SENSOR	32.31	44.37	43.25	V	PASS
LOWER ARM FASTENER	19.58	32.75	29.41	deg	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 855 678 63
Document: SQ2D-032-1626

PAGE 32/50
DATE: 12/07/2026 19:43
FINAL QUALITY GATE

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Connector locked	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Harness routed	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Protective film removed	☐ OK ☐ NOK ☐ N/A
Cover installed	☐ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Harness routed	☐ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Inspector:		 DATA MATRIX SN839724549408-P32	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 441 180 72

Document: SQ2D-033-1744

PAGE 33/50

DATE: 12/07/2026 00:33

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	 DATA MATRIX: (01)9950000193314	RF-29760	L173520	OK
02		RF-70613	L375219	OK
03		RF-22800	L243396	OK
04	PARKING SENSOR	RF-71956	L394365	OK
05	LOWER ARM FASTENER	RF-53845	L108268	OK
06	BRAKE HOSE SUPPORT	RF-13363	L234908	OK
07	BATTERY SUPPORT	RF-80384	L675798	OK
08	SEAT RAIL FIXING	RF-98478	L959547	OK
09	PARKING SENSOR	RF-83829	L840618	OK
10	REAR CAMERA MODULE	RF-73154	L363700	OK
11	ENGINE WIRING HARNESS	RF-70529		REVIEW
12	PARKING SENSOR	RF-42597		OK
13	CLIMATE CONTROL UNIT	RF-89100		REVIEW
14	DOOR LOCK ASSEMBLY	RF-16450		REVIEW
15	REAR CAMERA MODULE	RF-76937	L800296	OK
16	CLIMATE CONTROL UNIT	RF-30773	L903688	OK
17	REAR CAMERA MODULE	RF-29693	L211632	OK
18	CLIMATE CONTROL UNIT	RF-11197	L240224	REVIEW
19	REAR CAMERA MODULE	RF-45440	L958210	OK
20	RIGHT SIDE PANEL	RF-80638	L113795	OK
21	REAR CAMERA MODULE	RF-28949	L490195	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 348 284 69
Document: SQ2D-034-9561

PAGE 34/50
DATE: 12/07/2026 13:52
MEASUREMENT REPORT

BATCH
SERIAL

STATION
DECISION

QC-10
HOLD



CHARACTER	LOW	HIGH	VALUE	UNIT	RESULT
REAR C	15.98	26.37	18.86	V	PASS
LOWER ARM FASTENER	2.69	25.16	16.66	deg	PASS
PARKING SENSOR	53.98	72.18	69.73	V	PASS
AIRBAG CONTROL MODULE	4.42	24.33	6.87	mm	PASS
RIGHT SIDE PANEL	5.61	30.32	15.56	Nm	PASS
ENGINE WIRING HARNESS	38.86	70.30	48.08	mm	PASS
BRAKE HOSE SUPPORT	19.35	22.81	21.33	V	PASS
BATTERY SUPPORT	40.98	73.27	64.83	V	PASS
BRAKE HOSE SUPPORT	52.72	87.58	77.31	V	PASS
DOOR LOCK ASSEMBLY	-0.39	25.98	-0.16	V	PASS
RIGHT SIDE PANEL	30.08	47.85	31.05	V	PASS
CLIMATE CONTROL UNIT	9.59	30.85	21.60	V	PASS
BRAKE HOSE SUPPORT	9.82	28.02	27.28	mm	PASS
PARKING SENSOR	28.42	31.39	30.66	mm	PASS
PARKING SENSOR	0.03	24.70	4.60	deg	PASS
LOWER ARM FASTENER	33.46	57.33	38.03	mm	PASS
RIGHT SIDE PANEL	0.98	24.35	12.05	mm	PASS
AIRBAG CONTROL MODULE	5.76	14.20	13.76	Nm	PASS
SEAT RAIL FIXING	23.36	35.72	34.48	deg	PASS
CLIMATE CONTROL UNIT	8.54	30.13	19.94	V	PASS
CLIMATE CONTROL UNIT	20.83	29.11	24.62	mm	PASS
LOWER ARM FASTENER	12.08	35.43	18.92	mm	PASS
REAR CAMERA MODULE	6.97	10.52	9.33	Nm	PASS
RIGHT SIDE PANEL	44.53	64.65	63.14	Nm	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 799 563 53

Document: SQ2D-035-1154

DATE: 12/07/2026 06:36

MEASUREMENT REPORT

BATCH B820742
SERIAL SN9509331431

STATION QC-04
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	42.70	50.34	49.81	V	PASS
BATTERY SUPPORT	1.02	8.29	7.95	Nm	PASS
RIGHT SIDE PANEL	5.79	7.99	6.75	V	PASS
BRAKE HOSE SUPPORT	46.37	77.98	57.74	mm	PASS
RIGHT SIDE PANEL	15.82	43.97	31.25	deg	PASS
ENGINE WIRING HARNESS	35.51	°1.14	56.55	V	PASS
BRAKE HOSE SUPPORT	25.11	0.29	25.54	deg	PASS
PARKING SENSOR	35.86	6.87	52.80	mm	PASS
SEAT RAIL FIXING	16.58	50.48	20.33	deg	PASS
CLIMATE CONTROL UNIT	18.11	37.50	19.96	V	PASS
DOOR LOCK ASSEMBLY	33.10	47.90	36.72	Nm	PASS
DOOR LOCK ASSEMBLY	13.92	42.27	36.56	V	PASS
FRONT AXLE BRACKET	12.34	14.95	13.87	mm	PASS
REAR CAMERA MODULE	20.99	38.24	33.51	Nm	PASS
PARKING SENSOR	43.34	76.04	65.31	V	PASS
BATTERY SUPPORT	14.04	19.07	17.07	deg	PASS



DATA MATRIX SN241799092915



DATA MATRIX SN16290341



DATA MATRIX SN85367246

SYNTHETIC QUALITY DOSSIER - 2D


Sequence: 359 137 94

Document: SQ2D-036-4004

PAGE 36/50

DATE: 12/07/2026 01:51

FINAL QUALITY GATE

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Gap within limit	☐ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
No vi:  DATA MATRIX (01)09506000126385;	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Cover installed	☐ OK ☐ NOK ☐ N/A
Harness routed	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Label readable	☐ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☒ OK ☐ NOK ☐ N/A	Label  DATA MATRIX SN44482188956	☐ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Inspector: 			

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 955 798 15

Document: SQ2D-037-8408

PAGE 37/50

DATE: 12/07/2026 02:07

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BRAKE HOSE SUPPORT	RF-43558	L293562	OK
02	BRAKE HOSE SUPPORT	RF-40570	L568628	REVIEW
03	LOWER ARM FASTENER	RF-84901	L610236	REVIEW
04	SEAT RAIL FIXING	RF-56456	L194212	REVIEW
05	BRAKE HOSE SUPPORT	RF-23022	L578746	OK
06	RIGHT SIDE PANEL	RF-70923	L648389	OK
07	BRAKE HOSE SUPPORT	RF-15330	L619797	REVIEW
08	SEAT RAIL FIXING	RF-69789	L359430	OK
09	RIGHT SIDE PANEL	RF-77565	L517508	OK
10	ENGINE WIRING HARNESS	RF-75358	L534027	OK
11	LOWER ARM FASTENER	RF-31461		REVIEW
12	FRONT AXLE BRACKET	RF-10194		OK
13	CLIMATE CONTROL UNIT	RF-68213	L260182	OK
14	ENGINE WIRING HARNESS	RF-57083	L850495	OK
15	RIGHT SIDE PANEL	RF-79133	L756881	REVIEW
16	DOOR LOCK ASSEMBLY	RF-80350	L360901	OK
17	SEAT RAIL FIXING	RF-95874	L350570	OK
18	RIGHT SIDE PANEL	RF-25895	L174102	OK
19	BATTERY SUPPORT	RF-32842	L686053	OK
20	ENGINE WIRING HARNESS	RF-36676	L917635	OK
21	ENGINE WIRING HARNESS	RF-52804	L361433	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 708 257 50
Document: SQ2D-038-8568

PAGE 38/50
DATE: 12/07/2026 05:29
MEASUREMENT REPORT

BATCH

B198600

STATION

QC-18

SERIAL

SN7713944923

DECISION

OK

CHARACTERISTIC		LOW	HIGH	VALUE	UNIT	RESULT
SEAT RAIL FIXING	 QR CODE https://example.invalid/synthetic/qc/038/1/97318	13.76	30.73	17.28	deg	PASS
AIRBAG CONTROL MODULE		7.11	28.18	20.52	Nm	PASS
BRAKE HOSE SUPPORT		32.23	55.25	42.31	V	PASS
BRAKE HOSE SUPPORT		24.67	50.00	32.53	Nm	PASS
FRONT AXLE BRACKET		20.05	29.20	25.68	mm	PASS
LOWER ARM FASTENER		49.25	66.63	64.08	mm	PASS
BATTERY SUPPORT		27.20	46.18	38.74	deg	PASS
BATTERY SUPPORT		1.85	17.71	6.22	Nm	PASS
BRAKE HOSE SUPPORT		-1.49	32.31	6.74	Nm	PASS
SEAT RAIL FIXING		11.10	37.46	24.64	deg	PASS
BATTERY SUPPORT		52.60	66.40	60.65	V	PASS
ENGINE WIRING HARNESS		23.78	34.39	28.04	Nm	PASS
AIRBAG CONTROL MODULE		44.73	51.93	45.14	V	PASS
LOWER ARM FASTENER		30.84	41.13	39.29	V	PASS
ENGINE WIRING HARNESS		27.06	30.35	27.47	V	PASS
SEAT RAIL FIXING		38.83	56.31	39.37	V	PASS
ENGINE WIRING HARNESS		11.77	14.46	13.56	Nm	PASS
REAR CAMERA MODULE		3.30	14.41	4.45	deg	PASS
BATTERY SUPPORT		32.20	40.50	39.31	V	PASS
REAR CAMERA MODULE		16.36	28.00	20.12	mm	PASS
REAR CAMERA MODULE		19.55	43.21	34.75	deg	PASS
SEAT RAIL FIXING		15.50	43.14	20.07	Nm	PASS
SEAT RAIL FIXING		2.90	32.92	28.34	Nm	PASS
CLIMATE CONTROL UNIT		46.56	75.42	68.91	deg	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 597 175 37

Document: SQ2D-039-2554

PAGE 39/50

DATE: 12/07/2026 19:33

FINAL QUALITY GATE

VISUAL / DIMENSIONAL		FUNC	
Gap within limit	☒ OK ☐ NOK ☐ N/A	 QR CODE QR(SQ2D)PAGE=039(INDEX=4)LOT=697334	☒ OK ☐ NOK ☐ N/A
Harness routed	☒ OK ☐ NOK ☐ N/A		☐ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☒ OK ☐ NOK ☐ N/A	Harness routed	 DATA MATRIX SN223386764933 ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Connector locked	☐ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Torque confirmed	 DATA MATRIX DM(SQ2D)P039(I2)IL651206 ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Cover installed	☐ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Inspector: 	 QR CODE QR(SQ2D)PAGE=039(INDEX=3)LOT=697334		

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 572 763 25

Document: SQ2D-040-4058

PAGE 40/50

DATE: 12/07/2026 17:51

FINAL QUALITY GATE

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Reference matches order ☐ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Harness routed ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Fastener mark present ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Label readable ☒ OK ☐ NOK ☐ N/A	Harness routed ☐ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Label readable ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Inspector: _____	



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 828 343 50

Document: SQ2D-041-8554

PAGE 41/50

DATE: 12/07/2026 07:17

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	RIGHT SIDE PANEL	RF-40297	L560665	OK
02	BRAKE HOSE SUPPORT	RF-12003	L709599	REVIEW
03	CLIMATE CONTROL UNIT	RF-10385	L736084	OK
04	AIRBAG CONTROL MODULE	RF-86324	L993038	OK
05	REAR CAMERA MODULE	RF-16610	L551512	OK
06	SEAT RAIL FIXING	RF-19025	L323269	OK
07	SEAT RAIL FIXING	RF-48697	L889826	OK
08	DOOR LOCK ASSEMBLY	RF-17292	L286964	OK
09	RIGHT SIDE PANEL	RF-65397	L285195	REVIEW
10	BATTERY SUPPORT	RF-85019	L755177	OK
11	CLIMATE CONTROL UNIT	RF-56248	L525053	REVIEW
12	RIGHT SIDE PANEL	RF-72075	L993991	REVIEW
13	BRAKE HOSE SUPPORT		L235373	OK
14	AIRBAG CONTROL MODULE		L269979	OK
15	DOOR LOCK ASSEMBLY		L484165	OK
16	REAR CAMERA MODULE	RF-71071	L669967	OK
17	LOWER ARM FASTENER	RF-55399	L896327	OK
18	SEAT RAIL FIXING	RF-31173	L231609	OK
19	ENGINE WIRING HARNESS	RF-93794	L318147	REVIEW
20	BRAKE HOSE SUPPORT	RF-32626	L669005	OK
21	DOOR LOCK ASSEMBLY	RF-32012	L222743	OK



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 588 988 84

Document: SQ2D-042-6555

BATCH B297842
SERIAL SN5308821496

STATION QC-16
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
CLIMATE CONTROL UNIT	54.57	 DATA MATRIX DMISQ2DIP042IJ2IL111956	75.34	Nm	PASS
REAR CAMERA MODULE	9.33		23.94	mm	PASS
PARKING SENSOR	48.14		54.25	Nm	PASS
BRAKE HOSE SUPPORT	44.38		60.66	mm	PASS
BRAKE HOSE SUPPORT	18.70	44.92	35.71	deg	PASS
CLIMATE CONTROL UNIT	16.99	25.68	20.71	Nm	PASS
SEAT RAIL FIXING	22.26	28.02	26.17	mm	PASS
BATTERY SUPPORT	37.28	48.75	42.82	Nm	PASS
REAR CAMERA MODULE	50.32	82.81	72.21	mm	DATA MATRIX 010595000018282321J04040 
REAR CAM	34.52	49.77	47.11	Nm	
ENGINE W	32.64	43.88	33.74	Nm	
BATTERY SUPPORT	49.87	70.30	68.79	Nm	
ENGINE WIRING HARNESS	49.24	69.15	68.91	Nm	PASS
AIRBAG CONTROL MODULE	28.81	35.54	34.56	V	PASS
SEAT RAIL FIXING	15.16	25.45	24.94	V	PASS
CLIMATE CONTROL UNIT	53.30	74.57	56.10	Nm	PASS



DATA MATRIX SN26708411714-P42

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 886 709 91

Document: SQ2D-043-9986

PAGE 43/50

DATE: 12/07/2026 13:33

FINAL QUALITY GATE

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A  DATA MATRIX SN416954559741-P43
Protective film removed ☐ OK ☐ NOK ☐ N/A	Harness routed ☐ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Fastener mark present ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Harness routed ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Harness routed ☒ OK ☐ NOK ☐ N/A	Seal continuous ☐ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Harness routed ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Fastener mark present ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Harness routed ☐ OK ☐ NOK ☐ N/A
Inspector: 	

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 552 466 94

Document: SQ2D-044-6359

PAGE 44/50

DATE: 12/07/2026 19:17

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-68946	L172880	OK
02	DOOR LOCK ASSEMBLY	RF-66221	L514370	REVIEW
03	AIRBAG CONTROL MODULE	RF-35383	L880980	OK
 DATA MATRIX DMSC2DP4491L180131	ASSEMBLY	RF-91538	L757305	OK
	ROL MODULE	RF-53790	L462276	OK
	ASSEMBLY	RF-85491	L823804	REVIEW
07	AIRBAG CONTROL MODULE	RF-94891	L971761	OK
08	CLIMATE CONTROL UNIT	RF-18782	L281637	OK
09	BATTERY SUPPORT	RF-45575	L814729	OK
10	FRONT AXLE BRACKET	RF-30605	L191182	OK
11	SEAT RAIL FIXING	RF-73261	L567806	OK
12	CLIMATE CONTROL UNIT	RF-47691	L808453	OK
13	RIGHT SIDE PANEL	RF-69567	L152743	OK
14	CLIMATE CONTROL UNIT	RF-50712	L365411	OK
15	AIRBAG CONTROL MODULE	RF-74381	L628178	OK
16	BATTERY SUPPORT	RF-43827	L943287	OK
17	FRONT AXLE BRACKET	RF-36625	L505335	REVIEW
18	PARKING SENSOR	RF-78234	L651535	OK
19	RIGHT SIDE PANEL	RF-58902	L887401	OK
20	BRAKE HOSE SUPPORT	RF-98503	L39029	OK
21	FRONT AXLE BRACKET	RF-59240	L804066	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 815 265 47

Document: SQ2D-045-6809

PAGE 45/50

DATE: 12/07/2026 14:43

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BATTERY SUPPORT	RF-44848	L996674	REVIEW
02	ENGINE WIRING HARNESS	RF-73692	L552949	OK
03	REAR CAMERA MODULE	RF-33098	L124268	OK
04	RIGHT SIDE P. DATA MATRIX (01)09506000187373(21)DM0452	RF-88041	L595383	OK
05	DOOR LOCK ASSEMBLY	RF-32876	L288731	REVIEW
06	BATTERY SUPPORT	RF-70737	L394442	OK
07	ENGINE WIRING HARNESS	RF-72210	L171540	OK
08	DOOR LOCK ASSEMBLY	RF-86633	L714186	OK
09	CLIMATE CONTROL UNIT	RF-77911	L560058	OK
10	REAR CAMERA MODULE	RF-73476	L745877	OK
11	LOWER ARM FASTENER	RF-91422	L171962	OK
12	FRONT AXLE BRACKET	RF-40810	L801308	OK
13	REAR CAMERA MODULE	RF-58656	L677613	REVIEW
14	ENGINE WIRING HARNESS	RF-34190	L433346	OK
15	REAR CAMERA MODULE	RF-86377	L202732	REVIEW
16	BRAKE HOSE SUPPORT	RF-35169	L623436	REVIEW
17	ENGINE WIRING HARNESS	RF-53131	L260375	OK
18	FRONT AXLE BRACKET	RF-55363	L351531	REVIEW
19	DOOR LOCK ASSEMBLY	RF-38222	L144640	REVIEW
20	CLIMATE CONTROL UNIT	RF-55433	L708588	OK
21	PARKING SENSOR	RF-94716	L843637	OK

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 474 364 97

Document: SQ2D-046-2496

PAGE 46/50

DATE: 12/07/2026 11:47

MEASUREMENT REPORT

BATCH B660041
SERIAL SN3052604513

STATION QC-08
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
AIRBAG CONTROL MODULE	31.38	40.69	33.25	Nm	PASS
FRONT AXLE BRACKET	23.28	47.86	37.94	mm	PASS
PARKING SENSOR	47.89	65.28	48.67	mm	PASS
LOWER ARM FASTENER	20.56	44.55	24.11	V	PASS
BATTERY SUPPORT	5.75	14.72	11.47	mm	PASS
BRAKE HOSE SUPPORT	5.76	18.96	16.06	Nm	PASS
REAR CAMERA MODULE	1.27	33.57	7.86	V	PASS
LOWER ARM FASTENER	9.35	33.28	17.10	Nm	PASS
RIGHT SIDE PANEL	47.27	74.69	69.84	V	PASS
CLIMATE CONTROL UNIT	31.37	49.43	42.19	V	PASS
AIRBAG CONTROL MODULE	10.97	23.23	19.72	Nm	PASS
BATTERY SUPPORT	54.80	88.32	77.60	Nm	PASS
SEAT RAIL FIXING	32.48	60.35	43.03	mm	PASS
BRAKE HOSE SUPPORT	42.14	63.39	54.68	Nm	PASS
REAR CAMERA MODULE	9.75	28.67	15.03	mm	PASS
FRONT AXLE BRACKET	2.31	36.78	14.37	mm	PASS
LOWER ARM FASTENER	31.01	59.08	51.36	mm	PASS
DOOR LOCK ASSEMBLY	51.81	83.57	78.39	Nm	PASS
CLIMATE CONTROL UNIT	45.83	69.90	49.47	deg	PASS
RIGHT SIDE PANEL	41.50	56.11	53.00	Nm	PASS
FRONT AXLE BRACKET	35.47	69.16	55.70	deg	PASS
BRAKE HOSE SUPPORT	34.43	57.56	40.17	mm	PASS
PARKING SENSOR	21.00	32.86	27.98	deg	PASS
ENGINE WIRING HARNESS	18.68	21.43	19.54	mm	PASS

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 592 269 59

Document: SQ2D-047-3464

PAGE 47/50

DATE: 12/07/2026 10:12

FINAL QUALITY GATE

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Gap within limit	☒ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Gap within limit	☐ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Harness routed	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☒ OK ☐ NOK ☐ N/A	Fastener mark present	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Label readable	☒ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Fastener mark present	☐ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Label re	☒ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
No visit	☒ OK ☐ NOK ☐ N/A	Harness routed	☒ OK ☐ NOK ☐ N/A
Inspector:			



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 238 385 56

Document: SQ2D-048-4735

PAGE 48/50

DATE: 12/07/2026 03:40

COMPONENT TRACEABILITY

REFERENCE / LOT / VERIFICATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	DOOR LOCK ASSEMBLY	RF-76214	L172806	REVIEW
02	RIGHT SIDE PANEL	RF-51885	L655169	REVIEW
03	AIRBAG CONTROL MODULE	RF-86991	L425682	OK
04	BATTERY SUPPORT	RF-12133	L245711	OK
05	LOWER ARM FASTENER	RF-81033	L582895	OK
06	ENGINE WIRING HARNESS	RF-54896	L679923	OK
07	RIGHT SIDE PANEL	RF-11349	L908778	OK
08	REAR CAMERA MODULE	RF-56550	L898512	OK
09	REAR CAMERA MODULE	RF-36664	L636730	OK
10	AIRBAG CONTROL MODULE	RF-74765	L410432	OK
11	LOWER ARM FASTENER	RF-32228	L809873	OK
12	LOWER ARM FASTENER	RF-88758	L746325	OK
13	CLIMATE CONTROL UNIT	RF-31849	L668178	OK
14	PARKING SENSOR	RF-51751	L159239	OK
15	ENGINE WIRING HARNESS	RF-81763	L623046	OK
16	BATTERY SUPPORT	RF-91951	L671404	OK
17	PARKING SENSOR	RF-75843	L344769	OK
18	AIRBAG CONTROL MODULE	RF-80832	L145906	OK
19	BATTERY SUPPORT	RF-43764	L430037	OK
20	SEAT RAIL FIXING	RF-85576	L591031	OK
21	SEAT RAIL FIXING	RF-32445	L652678	OK



DATA MATRIX SN190898910991-P4



QR CODE QR[SQ2D|PAGE=048|INDEX=1|LOT=951615

SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 668 625 27

Document: SQ2D-049-8113

PAGE 49/50

DATE: 12/07/2026 01:07

MEASUREMENT REPORT

BATCH B279921
SERIAL SN1667567414

STATION QC-16
DECISION OK

CHARACTERISTIC		HIGH	VALUE	UNIT	RESULT
FRONT AXLE BRACKET		25.37	13.05	mm	PASS
PARKING SENSOR		49.53	46.94	deg	PASS
REAR CAMERA MODULE		30.79	29.78	V	PASS
AIRBAG CONTROL MODULE	10.09	33.32	29.28	deg	PASS
REAR CAMERA MODULE	17.67	34.13	25.36	V	PASS
PARKING SENSOR	-1.60	9.20	1.57	mm	PASS
REAR CAMERA MODULE	26.66	48.41	34.17	V	PASS
BATTERY SUPPORT	53.82	70.62	63.74	Nm	PASS
LOWER ARM FASTENER	11.78	28.24	19.36	deg	PASS
	49.12	84.05	51.58	V	PASS
	39.73	57.07	46.49	V	PASS
	30.66	35.80		V	PASS
	16.33	22.79		V	PASS
BRAKE HOSE SUPPORT	0.94	33.18		Nm	PASS
CLIMATE CONTROL UNIT	18.21	45.13		V	PASS
SEAT RAIL FIXING	27.66	55.56		V	PASS



SYNTHETIC QUALITY DOSSIER - 2D

Sequence: 204 132 17

Document: SQ2D-050-6903

PAGE 50/50

DATE: 12/07/2026 04:57

MEASUREMENT REPORT

BATCH B835535
SERIAL SN8820125880

STATION QC-11
DECISION HOLD

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
FRONT AXLE BRACKET	40.52	59.28	56.23	mm	PASS
LOWER ARM FASTENER	12.39	14.61	13.29	V	PASS
LOWER ARM FASTENER	-0.49	28.02	25.11	Nm	PASS
BATTERY SUPPORT	23.06	52.17	45.14	deg	PASS
LOWER ARM FASTENER	9.34	25.36	22.93	V	PASS
PARKING SENSOR	1.80	7.88	7.65	Nm	PASS
FRONT AXLE BRACKET	4.88	26.54	18.97	V	PASS
PARKING SENSOR	11.17	42.19	11.67	Nm	PASS
RIGHT SIDE PANEL	14.58	42.72	23.84	mm	PASS
ENGINE WIRING HARNESS	8.93	26.47	23.83	Nm	PASS
DOOR LOCK ASSEMBLY	47.43	51.88	49.70	Nm	PASS
LOWER ARM FASTENER	49.69	75.61	63.81	V	PASS
SEAT RAIL FIXING	21.23	50.64	41.35	Nm	PASS
RIGHT SIDE PANEL	38.09	46.79	46.64	Nm	PASS
ENGINE WIRING HARNESS	20.30	46.26	23.98	V	PASS
DOOR LOCK ASSEMBLY	12.25	31.74	13.14	mm	PASS
DOOR LOCK ASSEMBLY	40.88	73.51	57.27	Nm	PASS
ENGINE WIRING HARNESS	54.11	72.03	70.63	V	PASS
DOOR LOCK ASSEMBLY	9.39	28.43	25.70	mm	PASS
DOOR LOCK ASSEMBLY	48.76	60.81	59.80	deg	PASS
LOWER ARM FASTENER		54.75	51.65	Nm	PASS
CLIMATE CONTROL UNIT		26.27	19.93	V	PASS
RIGHT SIDE PANEL	41.63	63.38	60.57	deg	PASS
DOOR LOCK ASSEMBLY	35.33	56.80	44.57	Nm	PASS

