

SYNTHETIC QUALITY DOSSIER

Sequence: 194 174 12

Document: SQD-001-6812

PAGE 01/50

DATE: 11/07/2026 14:05

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	ENGINE SHIELD	RF-42266	L906416	OK
02	WHEEL ARCH LINER	RF-76100	L461303	OK
03	PARKING SENSOR	RF-16279	L423146	OK
04	STEERING COLUMN	RF-51983	L803690	OK
05	BRAKE LINE SUPPORT	RF-75485	L188455	OK
06	CONTROL UNIT COVER	RF-96228	L205877	HOLD
07	RIGHT SIDE PANEL	RF-37851	L192716	OK
08	BATTERY TRAY	RF-93714	L787481	OK
09	ENGINE SHIELD	RF-18676	L341732	OK
10	LEFT DOOR LOCK	RF-71879	L368477	OK
11	WHEEL ARCH LINER	RF-90245	L896417	OK
12	WIRING HARNESS	RF-66192	L729354	HOLD
13	RIGHT SIDE PANEL	RF-12068	L987341	OK
14	BATTERY TRAY	RF-59203	L899257	OK
15	CLIMATE MODULE	RF-56202	L491907	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 483 582 85
Document : SQD-002-9111

PAGE 02/50

DATE: 11/07/2026 04:58
ASSEMBLY CHECK LIST

LISTE SSR - SERIES K9

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
FUEL PIPE CLIP	M01F6	20	90	X		
STEERING COLUMN	P02F9	40	30	X		
STEERING COLUMN	M19F5	40	0	X		
CLIMATE MODULE	B19F7	20	0	X		
ENGINE SHIELD	P06F4	40	0	X		
LEFT DOOR LOCK	M01F9	15	0			
LOWER ARM ASSEMBLY	B08F3	65	0	X		
SEAT RAIL FIXING	P04F3	65	30	X		
FRONT AXLE ALIGNMENT	B18F8	90	0	X		
STEERING COLUMN	M03F2	8	0	X		
CLIMATE MODULE	P12F4	110	0	X		
RIGHT SIDE PANEL	P16F5	20	30	X		
ENGINE SHIELD	B02F6	40	0	X		
FRONT AXLE ALIGNMENT	M02F3	8	30			
SEAT RAIL FIXING	B09F7					
LEFT DOOR LOCK	M17F					
FRONT AXLE ALIGNMENT	P11F:					
CONTROL UNIT COVER	B05F5	15	45	X		
BATTERY TRAY	M07F3	15	45	X		
WIRING HARNESS	M01F5	12	90			
STEERING COLUMN	M13F8	110	0			
CLIMATE MODULE	P11F1	15	0	X		
ENGINE SHIELD	B07F6	65	45	X		
REAR SENSOR BRACKET	M05F4	40	45	X		
FUEL PIPE CLIP	P09F8	8	45	X		
FRONT AXLE ALIGNMENT	B05F3	12	30	X		
BRAKE LINE SUPPORT	P01F2	65	30	X		
REAR SENSOR BRACKET	M11F1	15	0			
FRONT AXLE ALIGNMENT	B13F9	40	90	X		
REAR SENSOR BRACKET	P10F3	40	45	X		

SYNTHETIC QUALITY DOSSIER

Sequence: 171 632 96

Document: SQD-004-2516

PAGE 04/50

DATE: 11/07/2026 01:31

FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
No visible damage ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A  PO82529051114
Reference matches order ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Panel alignment ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Harness routing ☐ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Panel alignment ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Inspector signature: 	

SYNTHETIC QUALITY DOSSIER

Sequence: 844 609 59

Document: SQD-005-4786

PAGE 05/50

DATE: 11/07/2026 11:37

MEASUREMENT REPORT**Vehicle / batch information**

Product **PX-K9**
Serial **SN9200202976**
Operator **OP800**

Batch **B269924**
Station **QC-17**
Global result **OK**

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
STEERING COLUMN	39.55	60.62	54.75	mm	OK
RIGHT SIDE PANEL	9.87	20.00	19.34	V	OK
WIRING HARNESS	7.84	20.42	11.33	V	OK
WHEEL ARCH LINER	34.52	54.65	38.35	Nm	OK
BRAKE LINE SUPPORT	7.89	24.65	24.50	V	OK
WIRING HARNESS	3.08	22.98	19.55	deg	OK
BRAKE LINE SUPPORT	35.32	38.95	36.10	Nm	OK
CLIMATE MODULE	29.84	33.78	30.37	mm	OK
CONTROL UNIT COVER				V	OK
LOWER ARM ASSEMBLY				V	OK
LOWER ARM ASSEMBLY				deg	OK
REAR SENSOR BRACKET	24.10	28.22	26.30	deg	OK
ENGINE SHIELD	33.12	47.81	47.00	mm	OK
FRONT AXLE ALIGNMENT	34.86	43.33	42.93	mm	OK
STEERING COLUMN	8.27	23.63	21.47	mm	OK
WIRING HARNESS	11.60	25.33	13.46	mm	OK
LOWER ARM ASSEMBLY	27.03	31.14	29.43	mm	OK
FRONT AXLE ALIGNMENT	24.35	46.60	42.67	Nm	OK
FRONT AXLE ALIGNMENT	5.48	24.12	14.20	deg	OK
FUEL PIPE CLIP	33.90	39.35	34.17	V	OK
SEAT RAIL FIXING	0.49	14.89	2.70	V	OK
REAR SENSOR BRACKET	14.71	17.21	16.62	V	OK
RIGHT SIDE PANEL	35.56	57.39	51.62	mm	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 640 150 52
Document: SQD-006-7998

PAGE 06/50
DATE: 11/07/2026 00:20
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER PO-96406211

MODEL / VARIANT PX-A7

SERIAL NUMBER SYN159694392301

INSPECTION PLAN QP-86.3

DECISION ACCEPTED

Inspection summary

LEFT DOOR LOCK	92.97	Nm	PASS
FUEL PIPE CLIP	4.20	Nm	PASS
WIRING HARNESS	86.79	mm	PASS
STEERING COLUMN	59.18	deg	PASS
REAR SENSOR BRACKET	91.45	mm	PASS
DR LOCK	72.02	deg	PASS
3 COLUMN	97.25	deg	PASS



Approved by:

[Signature]



SYNTHETIC QUALITY DOSSIER

Sequence: 890 493 21
Document: SQD-007-2397

PAGE 07/50
DATE: 11/07/2026 21:27
FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Surface condition ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Protect ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Surface ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Gap wi ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A

Inspector signature:

SYNTHETIC QUALITY DOSSIER

Sequence: 126 239 59

Document: SQD-008-8348

PAGE 08/50

DATE: 11/07/2026 02:41

MEASUREMENT REPORT

Vehicle / batch information

Product PX-R2
Serial SN3401152239
Operator OP819

Batch B441084
Station QC-20
Global result OK

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
PARKING SENSOR	33.27	50.76	39.99	Nm	OK
LEFT DOOR LOCK	18.47	28.21	23.09	deg	OK
REAR SENSOR BRACKET	21.29	24.28	22.39	deg	OK
FRONT AXLE ALIGNMENT	20.67	23.90	23.55	mm	OK
CLIMATE MODULE	0.26	18.64	1.88	deg	OK
CLIMATE MODULE	9.19	10.49	9.95	mm	OK
REAR SENSOR BRACKET	30.31	34.77	32.26	deg	OK
FRONT AXLE ALIGNMENT	23.31	39.27	33.86	mm	OK
SEAT RAIL FIXING	22.35	33.91	30.74	mm	OK
CONTROL UNIT COVER	18.26	38.49	19.55	Nm	OK
LEFT DOOR LOCK	2.61	12.02	11.74	V	OK
BRAKE LINE SUPPORT	6.52	26.18	11.06	V	OK
SEAT RAIL FIXING	10.69	22.93	21.47	mm	 RF5350847625Q1
CLIMATE MODULE	9.69	15.77	9.96	Nm	
REAR SENSOR BRACKET	22.39	36.57	33.46	deg	OK
LEFT DOOR LOCK	35.29	53.03	50.22	Nm	OK
CONTROL UNIT COVER	39.96	51.76	42.29	V	OK
BRAKE LINE SUPPORT	17.47	37.63	18.80	V	OK
LOWER ARM ASSEMBLY	24.19	43.90	29.72	Nm	OK
FRONT AXLE ALIGNMENT	0.46	22.46	7.67	mm	OK
WHEEL ARCH LINER	-1.87	12.56	-0.45	deg	OK
FRONT AXLE ALIGNMENT	22.07	37.88	24.50	deg	OK
REAR SENSOR BRACKET	16.72	26.25	24.25	V	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 449 814 12

Document: SQD-009-3414

PAGE 09/50

DATE: 11/07/2026 21:42

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	SEAT RAIL FIXING	RF-20606	L909001	OK
02	BATTERY TRAY	RF-42648	L494603	OK
03	WIRING HARNESS	RF-24860	L566228	HOLD
04	CONTROL UNIT COVER	RF-95440	L641137	OK
05	PARKING SENSOR	RF-66958	L583847	OK
06	PARKING SENSOR	RF-45065	L666349	OK
07	RIGHT SIDE PANEL	RF-95711	L132038	OK
08	SEAT RAIL FIXING		L518141	HOLD
09	BRAKE LINE SUPPOF		L741338	OK
10	STEERING COLUMN	RF-11452	L689454	OK
11	CLIMATE MODULE	RF-27161	L890347	OK
12	WIRING HARNESS	RF-50478	L490997	OK
13	REAR SENSOR BRACKET	RF-74389	L117004	OK
14	WIRING HARNESS			HOLD
15	BRAKE LINE SUPPORT	RF-95313	L424790	HOLD



LOT-664081-09



SYN009229497479

SYNTHETIC QUALITY DOSSIER

Sequence: 124 944 47

Document: SQD-010-2614

PAGE 10/50

DATE: 11/07/2026 07:35

ASSEMBLY CHECK LIST

LISTE SSR - SERIES K9

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
WHEEL ARCH LINER	B18F3	8	0	X		
CLIMATE MODULE	B02F2	15	45	X		
FRONT AXLE ALIGNMENT	B14F9	110	90	X		
SEAT RAIL FIXING	P18F1	8	0	X		
SEAT RAIL FIXING	B08F5	65	30	X		
BRAKE LINE SUPPORT	M01F7	90	0	X		
CONTROL UNIT COVER	B07F5	12	0	X		
RIGHT SIDE PANEL	B08F9	8	45	X		
CONTROL UNIT COVER	B01F7	15	90	X		
FRONT AXLE ALIGNMENT	B10F8	40	90	X		
PARKING SENSOR	M15F9	110	45	X		
WHEEL ARCH LINER	B11F7	12	30	X		
LEFT DOOR LOCK	B17F1	15	90	X		
CONTROL UNIT COVER	B19F1	12	0	X		
REAR SENSOR BRACKET	M06F5	12	45	X		
WHEEL ARCH LINER	B02F9	15	90	X		
WIRING HARNESS	P08F2	65	45	X		
SEAT RAIL FIXING	M01F8	15	0	X		
RIGHT SIDE PANEL	P13F5	8	90			
SEAT RAIL FIXING	M09F2	15	30	X		
WHEEL ARCH LINER	M02F1	90	0			
LOWER ARM ASSEMBLY	B08F7	90	45	X		
WIRING HARNESS	P14F3	40	45	X		
WIRING HARNESS	M19F3	40	0	X		
BATTERY TRAY	B02F5	15	45			
WHEEL ARCH LINER	P11F8	12	30	X		
PARKING SENSOR	B06F5	65	30	X		
FUEL PIPE CLIP	P05F5	20	0	X		
FUEL PIPE CLIP	B07F6	65	45	X		
CONTROL UNIT COVER	P04F6	40	45			



SYNTHETIC QUALITY DOSSIER

Sequence: 256 585 25

Document: SQD-011-1758

PAGE 11/50

DATE: 11/07/2026 12:04

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-96164299
MODEL / VARIANT	R2-HYB
SERIAL NUMBER	SYN370673734510
INSPECTION PLAN	QP-36.6
DECISION	ACCEPTED

Inspection summary

CONTROL UNIT COVER	46.60	mm	PASS
ENGINE SHIELD	38.80	deg	PASS
WHEEL ARCH LINER	53.18	deg	PASS
WHEEL ARCH LINER	48.58	deg	PASS
LEFT DOOR LOCK	85.59	Nm	PASS
BATTERY TRAY	10.98	Nm	PASS
PARKING SENSOR	2.67		

Approved by:



Quality Stamp




SYNTHETIC QUALITY DOSSIER

Sequence: 326 227 38
Document: SQD-012-7396

PAGE 12/50
DATE: 11/07/2026 02:10
TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	LEFT DOOR LOCK	RF-94308	L964556	OK
02	SEAT RAIL FIXING	RF-84390	L107798	OK
03	REAR SENSOR BRACKET	RF-19364	L743816	OK
04	BATTERY TRAY	RF-66087	L918695	HOLD
05	WHEEL ARCH LINER	RF-10120	L793912	HOLD
06	FUEL PIPE CLIP	RF-10120	L882338	OK
07	SEAT RAIL FIXING	RF-19654	L711062	OK
08	WHEEL ARCH LINER	RF-71402	L157958	OK
09	CONTROL UNIT COVER	RF-68199	L595806	HOLD
10	WHEEL ARCH LINER	RF-32338	L941145	OK
11	WIRING HARNESS	RF-21577	L866034	OK
12	FUEL PIPE CLIP	RF-16638	L212681	HOLD
13	SEAT RAIL FIXING	RF-62450	L755341	OK
14	PARKING SENSOR	RF-54836	L220816	OK
15	CONTROL UNIT COVER	RF-73323	L119610	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 688 209 19

Document: SQD-013-7157

PAGE 13/50

DATE: 11/07/2026 08:41

ASSEMBLY CHECK LIST

AUDIT PROCESS SHEET

DESIGNATION		TORQUE	ANGLE	OK	REWORK	NOTE
WHEEL ARCH LINER		15	90	X		
CLIMATE MODULE	P13F9	15	45	X		
FRONT AXLE ALIGNMENT	B04F7	15	0	X		
SEAT RAIL FIXING	P14F2	90	45	X		
STEERING COLUMN	P17F3	65	30			
WHEEL ARCH LINER	M17F7	8	90			
SEAT RAIL FIXING	P03F9	8	0			
STEERING COLUMN	M18F7	12	0	X		
FRONT AXLE ALIGNMENT	P12F1	90	0	X		
SEAT RAIL FIXING	P15F2	90	90	X		
LOWER ARM ASSEMBLY	M10F2	110	0	X		
FUEL PIPE CLIP	B08F6	110	30	X		
STEERING COLUMN	B06F7	12	90	X		
CLIMATE MODULE	B19F9	15	45	X		
BRAKE LINE SUPPORT	P14F3	8	30	X		
CONTROL UNIT COVER	P16F9	90	30	X	X	
CONTROL UNIT COVER						
FUEL PIPE CLIP						
CONTROL UNIT COVER						
FRONT AXLE ALIGNMENT	M11F1	65	0			
WIRING HARNESS	P12F8	40	0			
CONTROL UNIT COVER	B09F8	12	45	X		
LEFT		20	30	X		
WHEEL		8	30	X	X	
WHEEL		110	45	X		
SEAT RAIL FIXING	B10F4	65	90	X		
FUEL PIPE CLIP	P09F3	90	0	X		
PARKING SENSOR	P07F1	20	90			
BATTERY TRAY	M09F4	65				
BATTERY TRAY	M12F8	20				

SYN013489278109

PO80203056370

LOT-289774-13

LOT-638306-13

SYNTHETIC QUALITY DOSSIER

Sequence: 634 879 18

Document: SQD-014-4064

PAGE 14/50

DATE: 11/07/2026 07:05

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER PO-7682642



RF5260226319Q3

MODEL / VARIANT K9-VU

BER SYN279473485892

PLAN QP-41.8

ACCEPTED

Summary

PARKING SENSOR

70.94

Nm

PASS

FRONT AXLE ALIGNMENT

72.21

mm

PASS

FRONT AXLE ALIGNMENT

48.92

mm

PASS

WIRING HARNESS

31.08

deg

PASS

FUEL PIPE CLIP

44.76

Nm

PASS

CLIMATE MODULE

11.99

Nm

PASS

FUEL PIPE CLIP

16.90

deg

PASS

Approved by:



LOT-586263-14

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 117 274 96
Document: SQD-015-9255

PAGE 15/50
DATE: 11/07/2026 14:13
FINAL INSPECTION

EXTERIOR / DIMENSIONAL		FUNCTION / TRACEABILITY	
Gap within limit	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ LOT-951494-15 /A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Harness routing	☒ /A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Harness routing	☒ /A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Panel alignment	☒ /A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Panel alignment	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Panel alignment	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Torque c	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Surface	RF6547709749Q1 ☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Inspector signature:			

SYNTHETIC QUALITY DOSSIER

Sequence: 837 760 46
Document: SQD-016-7464

Vehicle / batch information

Product PX-K9
Serial SN6915049356
Operator OP614

Batch B781301
Station QC-13
Global result OK

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
PARKING SENSOR	30.20	36.00	31.47	deg	OK
BATTERY TRAY	5.13	11.52	7.43	mm	OK
FUEL	38.60	43.70	41.85	mm	OK
BRAK	20.20	40.23	27.53	Nm	OK
BRAK	15.78	25.30	22.14	V	OK
REAF	8.80	15.12	10.52	mm	OK
ENGL	18.47	19.77	19.41	Nm	OK
ENGL	27.64	35.82	34.64	Nm	OK
STEE	14.35	28.48	26.80	Nm	OK
SEAT RAIL FIXING	24.54	48.33	47.81	deg	OK
ENGINE SHIELD	9.53	19.23	14.94	V	OK
LEFT DOOR LOCK	30.20	31.71	30.46	mm	OK
LEFT DOOR LOCK	29.63	38.26	37.58	deg	OK
PARKING SENSOR	18.45	23.27	21.70	V	OK
WIRING HARNESS	25.22	49.20	42.93	mm	OK
FRONT AXLE ALIGNMENT	33.08	43.63	42.21	Nm	OK
PARKING SENSOR	20.25	23.32	21.79	mm	OK
ENGINE SHIELD	15.37	22.85	20.89	V	OK
FRONT AXLE ALIGNMENT	18.70	43.65	19.54	deg	OK
REAR SENSOR BRACKET	19.02	20.51	19.41	Nm	OK
STEERING COLUMN	26.38	39.39	37.61	mm	OK
CLIMATE MODULE	32.60	51.72	45.30	V	OK
FUEL PIPE CLIP	3.61	21.55	8.35	mm	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 515 499 66

Document: SQD-017-6729

PAGE 17/50

DATE: 11/07/2026 12:18

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	FRONT AXLE ALIGNMENT	RF-56710	L817325	OK
02	WHEEL ARCH LINER	RF-98686	L860312	OK
03	SEAT RAIL FIXING	RF-76884	L244050	HOLD
04	FRONT AXLE ALIGNMENT	RF-48560	L760749	OK
05	SEAT RAIL FIXING	RF-12152	L235775	OK
06	SEAT RAIL FIXING	RF-97658	L915234	HOLD
07	LEFT DOOR LOCK	RF-60419	L983846	HOLD
08	BRAKE LINE SUPPORT	RF-62824	L177026	OK
09	REAR SENSOR BRACKET	RF-47905	L945023	OK
10	LEFT DOOR LOCK	RF-30100	L451490	OK
11	SEAT RAIL FIXING	RF-92926	L453603	HOLD
12	STEERING COLUMN	RF-10966	L370186	OK
13	FUEL PIPE CLIP	RF-17705	L409395	HOLD
14	PARKING SENSOR	RF-76968	L740634	HOLD
15	REAR SENSOR BRACKET	RF-43826	L957590	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 479 467 87

Document: SQD-018-9108

PAGE 18/50

DATE: 11/07/2026 10:50

FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Protective film removed ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Protective film removed ☐ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Surface condition	Surface condition ☒ OK ☐ NOK ☐ N/A
 RF1523552857Q1	
Protective film removed ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Panel alignment ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
No visible damage ☒	☐ OK ☐ NOK ☐ N/A
Inspector signature: _____	 PO15135608313

SYNTHETIC QUALITY DOSSIER

Sequence: 191 898 14
Document: SQD-019-9162

Vehicle / batch information

Product PX-V4
Serial SN6429727710
Operator OP734



ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
STEERING COLUMN	27.66	31.03	28.03	deg	OK
WIRING HARNESS	26.01	43.61	29.14	Nm	OK
BRAKE LINE SUPPORT	36.05	48.06	37.19	deg	OK
PARKING SENSOR	8.23	11.72	9.26	V	OK
WHEEL ARCH LINER	13.34	34.73	31.09	V	OK
SEAT RAIL FIXING	32.80	40.32	35.73	V	OK
WIRING HARNESS	7.03	9.63	8.59	Nm	OK
FRONT AXLE ALIGNMENT	10.07	13.81	13.39	mm	OK
CONTROL UNIT COVER	15.42	21.63	21.35	V	OK
CLIMATE MODULE	4.09	13.31	4.76	deg	OK
WIRING HARNESS	7.50	14.76	9.47	mm	OK
LOWER ARM ASSEMBLY	13.19	15.78	15.05	deg	OK
WIRING HARNESS	-1.25	9.11	0.33	Nm	OK
BRAKE LINE SUPPORT	38.20	41.60	40.25	V	OK
BRAKE LINE SUPPORT	23.39	43.87	42.04	mm	OK
LEFT DOOR LOCK	5.73	28.20	13.13	V	OK
BATTERY TRAY	11.33	33.75	21.97	mm	OK
FRONT AXLE ALIGNMENT	30.58	32.26	31.00	V	OK
PARKING SENSOR	14.19	31.15	16.12	mm	OK
REAR SENSOR BRACKET	-0.34	16.39	12.08	deg	OK
CLIMATE MODULE	29.06	37.37	35.62	V	OK
LEFT DOOR LOCK	31.14	55.04	45.62	V	OK
LOWER ARM ASSEMBLY	26.35	44.72	39.12	V	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 580 272 24

Document: SQD-020-5773

PAGE 20/50

DATE: 11/07/2026 21:35

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	FRONT AXLE ALIGNMENT	RF-96167	L733828	OK
02	CLIMATE MODULE	RF-34555	L280409	OK
03	STEERING COLUMN	RF-11907	L358699	OK
04	WHEEL ARCH LINER	RF-61535	L435861	
05	CONTROL UNIT COVER	RF-59630	L299002	
06	WIRING HARNESS	RF-26947	L132203	OK
07	CLIMATE MODULE	RF-95419	L799631	OK
08	FRONT AXLE ALIGNMENT	RF-38639	L665577	OK
09	LEFT DOOR LOCK	RF-89509	L984191	OK
10	LEFT DOOR LOCK	RF-97343	L230768	OK
11	ENGINE SHIELD	RF-53600	L816267	HOLD
12	RIGHT SIDE PANEL	RF-10936	L459889	OK
13	WIRING HARNESS	RF-66469	L800373	OK
14	LEFT DOOR LOCK	RF-51646	L591870	OK
15	ENGINE SHIELD	RF-76814	L363569	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 581 467 69
Document: SQD-021-2196

PAGE 21/50
DATE: 11/07/2026 02:02
ASSEMBLY CHECK LIST

AUDIT PROCESS SHEET

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
WIRING HARNESS	P15F7	40	45	X		
LOWER ARM ASSEMBLY	M11F3	15	30	X		
CONTROL UNIT COVER	P07F5	15	45	X		
WIRING HARNESS	M16F3	65	45	X		
PARKING SENSOR	M17F4	8	45			
WIRING HARNESS	B04F1	20	90	X		
FUEL PIPE CLIP	P06F6	20	90	X		
SEAT RAIL FIXING	P02F4	90	90	X		
ENGINE SHIELD	P18F3	110	30	X		
SEAT RAIL FIXING	P08F2	40	0			
RIGHT SIDE PANEL	P14F1	20	45	X		
CLIMATE MODULE			90	X		
FRONT AXLE ALIGNMENT			90	X		
PARKING SENSOR	P01F6	20	0	X		
WIRING HARNESS	P04F5	15	45	X		
PARKING SENSOR	P12F3	12	90	X		
STEERING COLUMN	P13F3	65	0	X		
FRONT AXLE ALIGNMENT	B17F1	110	90	X		



SYNTHETIC QUALITY DOSSIER

Sequence: 688 968 68
Document: SQD-022-8755

PAGE 22/50
DATE: 11/07/2026 02:17
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-82954510
MODEL / VARIANT	M4-STD
SERIAL NUMBER	SYN599873890208
INSPECTION PLAN	QP-27.8
DECISION	CONDITIONAL

Inspection summary

BRAKE LINE SUPPORT	63.91	Nm	PASS
WIRING HARNESS	22.38	mm	PASS
CLIMATE MODULE	85.21	mm	PASS
LEFT DOOR LOCK	72.21	mm	PASS
SEAT RAIL FIXING	12.49	deg	PASS
STEERING COLUMN	4.45	Nm	PASS
LOWER ARM ASSEMBLY	72.65	Nm	PASS



Approved by:

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 518 536 81
Document: SQD-023-6479

PAGE 23/50
DATE: 11/07/2026 16:31
FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Surface condition ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Seal continuous ☐ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
No visible damage ☐ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Panel alignment ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Inspector signature: 	

SYNTHETIC QUALITY DOSSIER

Sequence: 717 208 29
Document : SQD-024-8825

PAGE 24/50

DATE: 11/07/2026 22:02
ASSEMBLY CHECK LIST

CONTROL PLAN - MODULE V4

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
FRONT AXLE ALIGNMENT	B19F3	65	30	X		
CLIMATE MODULE	B12F3	8	0	X		
LOWER ARM ASSEMBLY	M01F3	40	30	X		
BRAKE LINE SUPPORT	B16F3	8	90			
BATTERY TRAY	M10F5	12	45		X	
LEFT DOOR LOCK	P19F8	12	90	X		
LEFT DOOR LOCK	P16F1	12	30	X	X	
PARKING SENSOR	B07F9	90	0	X		
CLIMATE MODULE	M18F3	15	45	X		
RIGHT SIDE PANEL	M14F3	12	90	X		
MENT	M15F9	15	90			
	P07F5	12	0	X		
MENT	B11F6	15	0	X		
	P04F4	15	90			
MBLY	P07F8	20	0	X	X	
	P17F4	65	45	X		
	M10F4	110	30	X		
CONTROL UNIT COVER	B15F4	15	30	X	X	
PARKING SENSOR	B03F5	40	30	X		
BATTERY TRAY	P03F3	40	45			
RIGHT SIDE PANEL	M04F8	90	45	X		
BATTERY TRAY	M13F6	90	30	X		
WIRING HARNESS	M05F7	12	90	X		
WHEEL ARCH LINER	B09F1	15	90	X		
RIGHT SIDE PANEL	P04F2	40	45	X		
FUEL PIPE CLIP	P10F7	90	0	X		
CONTROL UNIT COVER	B19F8	15	90	X		
LEFT DOOR LOCK	M08F1	8	45	X		
WIRING HARNESS	P16F5	8	30	X		
CLIMATE MODULE	M11F4	90	30	X		



SYNTHETIC QUALITY DOSSIER

Sequence: 758 863 68
Document: SQD-025-5256

PAGE 25/50
DATE: 11/07/2026 03:11
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-68233421
MODEL / VARIANT	K9-VU
SERIAL NUMBER	SYN608505589769
INSPECTION PLAN	QP-21.4
DECISION	CONDITIONAL

Inspection summary

FRONT AXLE ALIGNMENT	42.21	mm	PASS
SEAT RAIL FIXING	68.04	mm	PASS
FRONT AXLE ALIGNMENT	56.45	mm	PASS
WHEEL ARCH LINER	92.92	Nm	PASS
ENGINE SHIELD	44.35	Nm	PASS
FUEL PIPE CLIP	47.41	mm	PASS
STEERING COLUMN	97.98	Nm	PASS
PO64545322687			

Approved by:

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 825 110 62

Document: SQD-026-9875

PAGE 26/50

DATE: 11/07/2026 08:07

FINAL INSPECTION

EXTERIOR / DIMENSIONAL

Reference matches order



LOT-651645-26

FUNCTION / TRACEABILITY

☒ OK ☐ NOK ☐ N/A

Protective film removed

☒ OK ☐ NOK ☐ N/A

Panel alignment

☒ OK ☐ NOK ☐ N/A

Torque confirmed

☒ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Witness mark

☒ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Limit

☒ OK ☐ NOK ☐ N/A

Label presence

☒ OK ☐ NOK ☐ N/A

Damage

☒ OK ☐ NOK ☐ N/A

Prot



PO81788026680

☒ OK ☐ NOK ☐ N/A

Unlocked

☐ OK ☐ NOK ☐ N/A

Surface condition

☒ OK ☐ NOK ☐ N/A

Locked

☒ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Connector locked

☐ OK ☐ NOK ☐ N/A

Seal continuous

☒ OK ☐ NOK ☐ N/A

Torque confirmed

☒ OK ☐ NOK ☐ N/A

Fastener witness mark

☒ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

Tc



LOT-193952-26

☐ OK ☐ NOK ☐ N/A

Panel alignment

☒ OK ☐ NOK ☐ N/A

No visible damage

☒ OK ☐ NOK ☐ N/A

Inspector signature:

SYNTHETIC QUALITY DOSSIER

Sequence: 498 946 86

Document: SQD-027-7088

PAGE 27/50

DATE: 11/07/2026 21:42

MEASUREMENT REPORT

Vehicle / batch information

Product PX-A7
Serial SN4743021387
Operator OP347



B760328

QC-11

OK

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
PARKING SENSOR	22.20	47.10	26.17	Nm	OK
WIRING HARNESS	33.26	58.24	54.11	mm	OK
RIGHT SIDE PANEL	-0.39	22.26	1.50	V	OK
RIGHT SIDE PANEL	25.85	41.27	41.12	V	OK
PARKING SENSOR	8.06	27.68	24.18	Nm	OK
WIRING HARNESS	22.97	25.37	24.77		
BRAKE LINE SUPPORT	16.44	20.61	17.71		
FRONT AXLE ALIGNMENT	38.57	55.33	49.71		
LEFT DOOR LOCK	12.45	22.61	15.20	mm	OK
REAR SENSOR BRACKET	3.71	14.87	5.19	Nm	OK
RIGHT SIDE PANEL	11.36	34.41	29.75	deg	OK
SEAT RAIL FIXING	18.66	41.58	21.42	mm	OK
RIGHT SIDE PANEL	31.69	41.25	34.62	mm	OK
RIGHT SIDE PANEL	39.68	59.19	52.41	Nm	OK
RIGHT SIDE PANEL	38.58	39.90	39.41	deg	OK
FRONT AXLE ALIGNMENT	-1.40	20.37	12.18	Nm	OK
STEERING COLUMN	3.53	17.81	8.71	deg	OK
CLIMATE MODULE	3.71	28.47	19.70	V	OK
BRAKE LINE SUPPORT	-2.34	10.99	0.95	V	OK
CONTROL UNIT COVER	2.16	11.10	3.99	mm	OK
ENGINE SHIELD	28.19	39.94	31.58	Nm	OK
CLIMATE MODULE	4.40	9.72	7.35	mm	OK
BRAKE LINE SUPPORT	36.08	56.51	53.36	Nm	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 783 106 63
Document: SQD-028-2857

PAGE 28/50
DATE: 11/07/2026 20:22
TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	 RF1263308501Q3	
01	BATTERY TRAY	RF-41817		
02	REAR SENSOR BRACKET	RF-34557	L627454	HOLD
03	FUEL PIPE CLIP	RF-93870	L785112	OK
04	WHEEL ARCH LINER	RF-25219	 PO46467339013	OK
05	LEFT DOOR LOCK	RF-10991		OK
06	WHEEL ARCH LINER	RF-98857	L702189	OK
07	LEFT DOOR LOCK	RF-71569	L820794	OK
08	BATTERY TRAY	RF-96372	L421029	HOLD
09	WIRING HARNESS	RF-88637	L174890	OK
10	WIRING HARNESS	RF-11707	L821243	OK
11	FRONT AXLE ALIGNMENT	RF-47585	L369138	HOLD
12	FRONT AXLE ALIGNMENT	RF-84363	L271111	OK
13	CONTROL UNIT COVER	RF-60111	L830972	OK
14	SEAT RAIL FIXING	RF-98415	L764550	OK
15	 PO13609359820	RF-53128	L529081	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 239 371 43

Document : SQD-029-3427

CONTROL PLAN - MODULE V4

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
BRAKE LINE SUPPORT	B02F8	20	0			
BATTERY TRAY	P11F2	12	90	X		
PARKING SENSOR	B12F9	40	30			
ENGINE SHIELD	M19F3	40	90	X		
BATTERY TRAY	M05F4	65	90	X		
ENGINE SHIELD	M02F9	110	0	X		
WHEEL ARCH LINER	M11F3		0	X		
CONTROL UNIT COVER	P14F6		0	X		
LEFT DOOR LOCK	P19F5		45	X		
LEFT DOOR LOCK	P06F4		90	X		
BATTERY TRAY	B04F7	20	30	X		
WHEEL ARCH LINER	M13F1	90	0			
BRAKE LINE SUPPORT	P05F3	8	30	X		
BATTERY TRAY	P07F1	40	45	X		
BATTERY TRAY	M15F1	8	30			
WHEEL ARCH LINER	M10F6	110	45	X		
ENGINE SHIELD	B04F4	8	0	X		
BATTERY TRAY	M07F9	65	0	X		
PARKING SENSOR	M16F9	110	90	X		
BRAKE LINE SUPPORT	P08F5	110	0	X		
BRAKE LINE SUPPORT	P08F1	15	30	X		
FRONT AXLE ALIGNMENT	M14F5	15	30		X	
FRONT AXLE ALIGNMENT	M04F3	20	30	X		
BRAKE LINE SUPPORT	P19F5	12	0			
CONTROL UNIT COVER	M13F7	40	90	X		
BATTERY TRAY	P08F9	20	45	X		
WIRING HARNESS	M04F9	40	0	X		
BATTERY TRAY	P18F5	20	30	X		
ENGINE SHIELD	P13F4	40	90			
WIRING HARNESS	P06F3	40	90	X		

SYNTHETIC QUALITY DOSSIER

Sequence: 125 775 25
Document: SQD-030-5368

PAGE 30/50

DATE: 11/07/2026 10:24

MEASUREMENT REPORT

Vehicle / batch information

Product **PX-A7**
Serial **SN8112001222**
Operator **OP660**

Batch **B728435**
Station **QC-05**
Global result **OK**



ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	
RIGHT SIDE PANEL	29.91	31.43	30.30	mm	
FRONT AXLE ALIGNMENT	8.53	23.71	22.63	deg	
LEFT DOOR LOCK	9.55	27.55	13.12	V	OK
ENGINE SHIELD	23.32	25.39	24.18	V	OK
SEAT RAIL FIXING	24.36	29.22	25.65	mm	OK
WIRING HARNESS	11.18	30.30	27.75	deg	OK
FUEL PIPE CLIP	11.70				OK
STEERING COLUMN	4.71				OK
RIGHT SIDE PANEL	18.31	31.77	24.39	V	OK
ENGINE SHIELD	25.75	44.63	33.80	deg	OK
CLIMATE MODULE	13.04	29.53	25.38	mm	OK
FUEL PIPE CLIP	32.79	50.57	45.72	V	OK
FRONT AXLE ALIGNMENT	4.19	25.88	5.18	deg	OK
BRAKE LINE SUPPORT	26.51	43.31	33.87	deg	OK
FUEL PIPE CLIP	17.21	23.83	20.46	Nm	OK
RIGHT SIDE PANEL	8.17	12.91	8.69	mm	OK
WIRING HARNESS	-0.62	5.03	4.47	Nm	OK
FRONT AXLE ALIGNMENT	0.67	3.40	1.65	V	OK
STEERING COLUMN	16.39	22.30	19.01	mm	OK
CLIMATE MODULE	21.16	31.15	27.38	mm	OK
BRAKE LINE SUPPORT	28.58	52.63	41.67	deg	OK
STEERING COLUMN	-1.48	18.70	15.08	mm	OK
LOWER ARM ASSEMBLY	31.24	43.75	32.89	Nm	OK



SYNTHETIC QUALITY DOSSIER

Sequence: 447 948 70

Document: SQD-031-5771

PAGE 31/50

DATE: 11/07/2026 12:13

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	RIGHT SIDE PANEL	RF-71684	L614263	OK
02	LEFT DOOR LOCK	RF-36666	L285990	HOLD
03	BRAKE LINE SUPPORT	RF-39936	L833202	OK
04	BRAKE LINE SUPPORT	RF-35529	L797056	OK
05	CONTROL UNIT COVER	RF-77536	L503069	OK
06	RIGHT SIDE PANEL	RF-19589	L233100	OK
07	CONTROL UNIT COVER	RF-44579	L886269	OK
08	LOWER ARM ASSEMBLY	RF-12308	L648596	OK
09	RIGHT SIDE PANEL	RF-60896	L726300	OK
10	CONTROL UNIT COVER	RF-83736	L315887	OK
11	RIGHT SIDE PANEL	RF-36767	L364338	OK
12	SEAT RAIL FIXING	RF-57921	L779315	OK
13	BATTERY TRAY	RF-91750	L560577	OK
14	REAR SENSOR BRACKET	RF-53906	L570694	OK
15	STEERING COLUMN	RF-51176	L554668	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 978 365 92

Document: SQD-032-2512

PAGE 32/50

DATE: 11/07/2026 18:04

ASSEMBLY CHECK LIST

CONTROL PLAN - MODULE V4

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
FRONT AXLE ALIGNMENT	B02F2	90	30			
PARKING SENSOR	M14F1	90	90	X		
BRAKE LINE SUPPORT	B04F5	15	90	X		
CONTROL UNIT COVER	P07F7	15	90	X		
LOWER ARM ASSEMBLY	P06F2	20	30	X		
REAR SENSOR BRACKET	B06F7	110	45	X		
CLIMATE MODULE	B13F4	20	30	X		
SEAT RAIL FIXING	B09F4	15	45	X		
CLIMATE MODULE	M02F4	8	30	X		
CONTROL UNIT COVER	P09F6	110	0	X		
RIGHT SIDE PANEL	P06F6	8	30	X		
PARKING SENSOR	P19F6	8	45	X		
WHEEL ARCH LINER	P02F9	15	30	X		
BATTERY TRAY	M13F5	20	0			
FUEL PIPE CLIP	M18F3	20	90	X		
REAR SENSOR BRACKET	M04F3	8	0	X		
FRONT AX	M02F6	8	30	X		
REAR SEN	P18F6	20	0			
STEERING	P09F2	90	0			
SEAT RAIL	P01F7	20	30	X		
LEFT DOG	B07F4	15	90	X		
CLIMATE I	B12F1	20	90	X		
WHEEL AF	M07F3	40	0	X		
CONTROL	M08F4	15	30			
WIRING H.	M10F4	90	90	X		
REAR SEN	P06F6	15	0	X		
LOWER ARM ASSEMBLY	B07F9	110	0	X		
CLIMATE MODULE	B18F1	15	30	X		
LOWER ARM ASSEMBLY	P09F2	15	30			
FRONT AXLE ALIGNMENT	M15F3	110	30			

SYNTHETIC QUALITY DOSSIER

Sequence: 179 463 52
Document: SQD-033-5767

PAGE 33/50
DATE: 11/07/2026 13:11
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER

MODEL / VARIANT

SERIAL NUMBER

SYN729590977922

INSPECTION PLAN

QP-12.8

DECISION

ACCEPTED



Inspection summary

PARKING SENSOR	19.46	mm	PASS
LEFT DOOR LOCK	2.92	mm	PASS
BATTERY TRAY	15.40	mm	PASS
STEERING COLUMN	72.86	Nm	PASS
LOWER ARM ASSEMBLY	82.84	deg	PASS
STEERING COLUMN	63.29	Nm	PASS
SEAT RAIL FIXING	23.78	deg	PASS



Approved by:

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 813 776 96

Document: SQD-034-2224

PAGE 34/50

DATE: 11/07/2026 07:43

FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Seal continuous ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☐ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ N/A
Inspector signature: 	 RF5679157361Q1

SYNTHETIC QUALITY DOSSIER

Sequence: 347 918 74

Document: SQD-035-3290

Vehicle / batch information

Product PX-V4

Serial SN7584078281

Operator OP533

Batch B814150

Station QC-01

Global result REVIEW

ITEM / CHARACTERISTIC	 SYN035225133076		VALUE	UNIT	STATUS
FUEL PIPE CLIP	-1.34	9.30	4.08	Nm	OK
WIRING HARNESS	2.65	27.01	24.07	V	OK
BRAKE LINE SUPPORT	34.12	56.02	46.38	mm	OK
BRAKE LINE SUPPORT	14.43	39.16	18.22	mm	OK
FUEL PIPE CLIP	21.92	29.97	29.55	V	OK
RIGHT SIDE PANEL	36.85	45.58	43.53	V	OK
WHEEL ARCH LINER	-1.61	0.97	0.29	mm	OK
LOWER ARM ASSEMBLY	7.28	 SYN035127928748		V	OK
RIGHT SIDE PANEL	35.77			mm	OK
REAR SENSOR BRACKET	-2.03	16.40	13.67	deg	OK
ENGINE SHIELD	3.08	19.67	8.25	deg	OK
ENGINE SHIELD	8.41	24.00	15.32	mm	OK
STEERING COLUMN	19.01	34.80	30.27	deg	OK
CLIMATE MODULE	-1.60	19.14	13.05	Nm	OK
REAR SENSOR BRACKET	-0.48	12.55	7.26	mm	OK
FUEL PIPE CLIP	37.27	50.29	38.31	mm	OK
RIGHT SIDE PANEL	11.12	32.27	15.27	deg	OK
WIRING HARNESS	32.65	51.97	42.61	V	OK
WHEEL ARCH LINER	27.41	33.52	28.96	V	OK
PARKING SENSOR	7.94	28.96	24.95	V	OK
REAR SENSOR BRACKET	-0.24	 SYN035336673794	9.61	V	OK
STEERING COLUMN	-1.09		1.41	V	OK
SEAT RAIL FIXING	36.54	61.44	46.02	Nm	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 661 444 94

Document: SQD-036-6242

PAGE 36/50

DATE: 11/07/2026 15:40

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-52308875
MODEL / VARIANT	R2-HYB
SERIAL NUMBER	SYN922692739483
INSPECTION PLAN	QP-52.4
DECISION	ACCEPTED

Inspection summary

			
		SYN036218870108	
RIGHT SIDE PANEL	97.71	Nm	PASS
LEFT DOOR LOCK	90.12	deg	PASS
REAR SENSOR BRACKET	77.38	mm	PASS
CONTROL UNIT COVER	93.76	mm	PASS
CLIMATE MODULE	24.94	Nm	PASS
LEFT DOOR LOCK	34.96	Nm	PASS
CLIMATE MODULE	54.46	Nm	PASS



Approved by:

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 179 737 34

Document: SQD-037-5893

PAGE 37/50

DATE: 11/07/2026 19:54

FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Reference matches order ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Panel alignment ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Panel alignment ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Gap within limit ☐ OK ☐ NOK ☐ N/A	Panel alignment ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Panel alignment	☒ OK ☐ NOK ☐ N/A
Inspector signature: _____	



SYNTHETIC QUALITY DOSSIER

Sequence: 274 282 44

Document: SQD-038-9507

PAGE 38/50

DATE: 11/07/2026 04:55

MEASUREMENT REPORT

Vehicle / batch information

Product PX-R2
Serial SN9466300975
Operator OP980



Global result OK

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
LOWER ARM ASSEMBLY	24.17	44.38	36.12	V	OK
FUEL PIPE CLIP	36.44	58.33	36.93	deg	OK
BATTERY TRAY	6.19	26.65	15.41	mm	OK
BATTERY TRAY	18.08	22.64	21.16	Nm	OK
WIRING HARNESS	9.84	15.54	11.76	deg	OK
REAR SENSOR BRACKET	7.35	11.24	7.52	Nm	OK
REAR SENSOR BRACKET	8.40	33.03	18.19	Nm	OK
BATTERY TRAY	21.78	40.08	28.62	V	OK
RIGHT SIDE PANEL	35.72	48.18	41.18	deg	OK
ENGINE SHIELD	4.36	12.83	10.58	Nm	OK
BRAKE LINE SUPPORT	0.11	13.41	10.51	mm	OK
BRAKE LINE SUPPORT	3.35	27.36	20.46	Nm	OK
WIRING HARNESS	15.12	27.74	22.12	mm	OK
WHEEL ARCH LINER	-1.99	12.01	8.31	mm	OK
CLIMATE MODULE	27.53	51.91	36.71	Nm	OK
SEAT RAIL FIXING	19.54	38.31	32.41	mm	OK
CLIMATE MODULE	2.58	24.40	11.94	deg	OK
RIGHT SIDE PANEL	31.90	35.96	33.19	V	OK
ENGINE SHIELD	31.37	50.59	46.00	deg	OK
WIRING HARNESS	6.44	28.89	22.90	mm	OK
CLIMATE MODULE	0.80	3.44	2.15	V	OK
STEERING COLUMN	39.63	45.94	41.26	V	OK
LOWER ARM ASSEMBLY	7.11	28.70	9.27	Nm	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 261 943 87
Document: SQD-039-9591

PAGE 39/50
DATE: 11/07/2026 10:47
TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	FRONT AX	768	L102288	OK
02	CLIMATE I	206	L292287	OK
03	BRAKE LINE SUPPORT	RF-50075	L384729	OK
04	ENGINE SHIELD	RF-18695	L480833	OK
05	CLIMATE MODULE	PO23067062058	L194987	HOLD
06	RIGHT SIDE PANEL	RF-18150	L233605	HOLD
07	SEAT RAIL FIXING	RF-97918	L436496	OK
08	FRONT AXLE ALIGNMENT	RF-45998	L898920	OK
09	LOWER ARM ASSEMBLY	RF-37450	L612374	OK
10	FRONT AXLE ALIGNMENT	RF-94130	L169228	OK
11	RIGHT SIDE PANEL	RF-73624	L913552	OK
12	LEFT DOOR LOCK	RF-72877	L260920	HOLD
13	SEAT RAIL FIXING	RF-64286	L620761	OK
14	CLIMATE MODULE	RF-94294	L388198	HOLD
15	ENGINE SHIELD	RF-60131	L686451	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 782 187 55

Document: SQD-040-4787

PAGE 40/50

DATE: 11/07/2026 19:35

ASSEMBLY CHECK LIST

LISTE SSR - SERIES K9

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
CLIMATE MODULE	M06F1	15	30	X		
FUEL PIPE CLIP	B06F5					
LEFT DOOR LOCK	M09F5					
WHEEL ARCH LINER	B10F8					
SEAT RAIL FIXING	P05F1					
BATTERY TRAY	P12F4	110	30	X		
STEERING COLUMN	B06F5	110	0	X		
CLIMATE MODULE	P10F2	12	90	X		
BRAKE LINE SUPPORT	B14F9	40	90	X		
WIRING HARNESS	B05F2	8	90	X		
REAR SENSOR BRACKET	M06F1	110	90	X		
CONTROL UNIT COVER	P09F9	110	45	X		
WHEEL ARCH LINER	B10F7	65	45	X		
BATTERY TRAY	M19F4	15	0	X		
FRONT AXLE ALIGNMENT	M06F2	110	0	X		
RIGHT SIDE PANEL	P19F8	65	45	X		
SEAT RAIL FIXING	P13F5	40	45	X		
CONTROL UNIT COVER	B05F5	20	30	X		
PARKING SENSOR	P14F4	8	45	X		
WIRING HARNESS	M16F9	110	90	X	X	
RIGHT SIDE PANEL	P14F2	110	90	X		
BATTERY TRAY	P09F5	90	30	X		
RIGHT SIDE PANEL	P05F4	20	45			
CLIMATE MODULE	P10F4	8	0	X		
ENGINE SHIELD	M05F2	8	0	X		
WIRING HARNESS	B18F3	12	45	X	X	
BATTERY TRAY	B09F2	90	90	X		
LEFT DOOR LOCK	M18F4	40	45	X		
BATTERY TRAY	P10F6	90	30	X		
SEAT RAIL FIXING	P13F5	20	0	X		

SYNTHETIC QUALITY DOSSIER

Sequence: 657 767 35
Document: SQD-041-9813

PAGE 41/50
DATE: 11/07/2026 23:47
CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-28948522
MODEL / VARIANT	R2-HYB
SERIAL NUMBER	SYN118917779546
INSPECTION PLAN	QP-62.5
DECISION	CONDITIONAL

Inspection summary



CONTROL UNIT COVER	59.41	mm	PASS
WHEEL ARCH LINER	24.71	mm	PASS
LEFT DOOR LOCK	79.84	mm	PASS
WHEEL ARCH LINER	61.52	Nm	PASS
LEFT DOOR LOCK	21.01	Nm	PASS
BRAKE LINE SUPPORT	89.84	deg	PASS
WHEEL ARCH LINER	79.89	deg	PASS

Approved by: _____

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 682 416 47

Document: SQD-042-8225

DATE: 11/07/2026 22:57

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	ENGINE SHIELD	RF-70439	L627100	OK
02	BATTERY TRAY	RF-30428	L357445	HOLD
03	SEAT RAIL FIXING	RF-45802	L475384	OK
04	RIGHT SIDE PANEL	RF-18919	L577368	OK
05	LEFT DOOR LOCK	RF-56554	L257696	HOLD
06	BRAKE LINE SUPPORT	RF-90426	L341313	OK
	BATTERY TRAY	RF-49124	L217456	OK
	FUEL PIPE CLIP			HOLD
	ENGINE SHIELD			HOLD
	BRAKE LINE SUPPORT	RF-82062	L430286	OK
11	RIGHT SIDE PANEL	RF-14950	L748334	OK
12	STEERING COLUMN	RF-30117	L364361	OK
13	LEFT DOOR LOCK	RF-45478	L801547	OK
14	FUEL PIPE CLIP	RF-29917	L338957	OK
15	CLIMATE MODULE	RF3818717055Q3	L158437	HOLD



SYN042298023378



PO76925568982



RF3818717055Q3

SYNTHETIC QUALITY DOSSIER

Sequence: 297 556 40
Document: SQD-043-1591



CONTROL PLAN - MODULE V4

DESIGNATION	POSTE	TORQUE	ANGLE	OK	REWORK	NOTE
CLIMATE MODULE	B04F5	90	45	X		
ENGINE SHIELD	P02F7	12	90	X		
WHEEL ARCH LINER	B12F9	65	45	X		
BRAKE LINE SUPPORT	M01F9	110	45	X		
BRAKE LINE SUPPORT	M05F6	20	90			
LEFT DOOR LOCK	M09F9	8	0	X	X	
FUEL PIPE CLIP	M04F7	12	90	X		
BRAKE LINE SUPPORT	M05F3	20	45			
RIGHT SIDE PANEL	B01F6	20	45	X		
FRONT AXLE ALIGNMENT	B03F3	65	30	X		
BRAKE LINE SUPPORT	B11F4	40	90			
WIRING HARNESS	M08F9	65	30	X		
RIGHT SIDE PANEL	M09F3	15	0	X		
SEAT RAIL FIXING	B06F8	40	45	X		
WHEEL ARCH LINER	B18F6	15	45	X		
RIGHT SIDE PANEL	B06F6	20	90	X		
LEFT DOOR LOCK	B08F2	8	90	X		
CLIMATE MODULE	M04F8	110	30	X		

CERTIFICATE OF CONFORMITY

This synthetic record confirms that the listed characteristics were inspected.

PRODUCTION ORDER	PO-34968850
MODEL / VARIANT	R2-HYB
SERIAL NUMBER	SYN559272202643
INSPECTION PLAN	QP-25.8
DECISION	ACCEPTED



Inspection summary

SEAT RAIL FIXING	15.70	mm	PASS
BATTERY TRAY	93.91	Nm	PASS
LOWER ARM ASSEMBLY	33.39	deg	PASS
BRAKE LINE SUPPORT	28.29	deg	PASS
PARKING SENSOR	42.39	Nm	PASS
CLIMATE MODULE	23.77	deg	PASS
ENGINE SHIELD	22.99	mm	PASS

Approved by: _____

Quality stamp



SYNTHETIC QUALITY DOSSIER

Sequence: 405 641 48
Document: SQD-045-8243

PAGE 45/50

DATE: 11/07/2026 20:58
FINAL INSPECTION

EXTERIOR / DIMENSIONAL	FUNCTION / TRACEABILITY
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
r witness mark ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
tinuous ☐ OK ☐ NOK ☐ N/A	Harness routing ☐ OK ☐ NOK ☐ N/A
le damage ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Seal c  ☐ N/A RF5637107025Q1	Harness routing ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Inspector signature: 	



RF7955053201Q2

Vehicle / batch information

Product	PX-V4	Batch	B311598
Serial	SN1020048813	Station	QC-08
Operator	OP597	Global result	OK

ITEM / CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	STATUS
LOWER ARM ASSEMBLY	0.15	18.72	9.41	V	OK
REAR SENSOR BRACKET	19.26	20.90	20.07	Nm	OK
CLIMATE MODULE	34.30	57.63	55.39	deg	OK
REAR SENSOR BRACKET	15.50	28.26	26.42	mm	OK
WIRING HARNESS	22.04	31.91	24.93	mm	OK
BRAKE LINE SUPPORT	23.87	39.47	38.61	mm	OK
WHEEL ARCH LINER	9.57	13.71	10.37	deg	OK
STEERING COLUMN	38.70	56.90	48.23	V	OK
CONTROL UNIT COVER	PO80497900391			Nm	OK
LOWER ARM ASSEMBLY				V	OK
CONTROL UNIT COVER	2.03	12.81	8.78	V	OK
WHEEL ARCH LINER	10.25	22.70	20.00	V	OK
CLIMATE MODULE	34.00	58.76	52.93	deg	OK
WHEEL ARCH LINER	23.72	40.50	37.77	V	OK
WHEEL ARCH LINER	-0.24	10.06	2.94	V	OK
PARKING SENSOR	12.05	25.63	14.12	deg	OK
REAR SENSOR BRACKET	19.32	36.01	35.16	deg	OK
ENGINE SHIELD	34.14	37.79	35.45	mm	OK
LOWER ARM ASSEMBLY	5.08	30.03	13.87	mm	OK
LOWER ARM ASSEMBLY	14.85	37.02	20.06	V	OK
BRAKE LINE SUPPORT	31.96	36.76	32.59	Nm	OK
LOWER ARM ASSEMBLY	23.56	41.34	37.36	mm	OK
CLIMATE MODULE	22.78	29.38	27.35	V	OK

SYNTHETIC QUALITY DOSSIER

Sequence: 261 515 13

Document: SQD-047-4969

PAGE 47/50

DATE: 11/07/2026 04:56

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	SEAT RAIL FIXING	RF-16869	L403141	HOLD
02	LOWER ARM ASSEMBLY	RF-96149	L387495	HOLD
03	CLIMATE MODULE	RF-92750	L423500	HOLD
04	LEFT DOOR LOCK	RF-42311	L757204	OK
05	REAR SENSOR BRACKET	RF-18848	L398322	HOLD
06	ENGINE SHIELD	RF-30554	L196849	OK
07	FUEL PIPE CLIP	RF-39963	L996910	OK
08	BRAKE LINE SUPPORT	RF-19278	L177814	OK
09	LEFT DOOR LOCK	RF-98865	L994355	HOLD
10	WIRING HARNESS	RF-10336	L902441	OK
11	CLIMATE MODULE	RF-91229	L999234	OK
12	WHEEL ARCH LINER	RF-72835	L356601	OK
13	LOWER ARM ASSEMBLY	RF-66979	L368263	OK
14	LEFT DOOR LOCK	 LOT-129878-47	8755	OK
15	BRAKE LINE SUPPORT		L765595	OK

SYNTHETIC QUALITY DOSSIER


Sequence: 499 369 35

Document: SQD-048-1823

PAGE 48/50

DATE: 11/07/2026 10:06

FINAL INSPECTION

EXTERIOR / DIMENSIONAL		FUNCTION / TRACEABILITY	
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒		☒ OK ☐ NOK ☐ N/A
 LOT-149138-48			
Panel alignment	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Torque confirmed	☐ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Label presence	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Label  RF5473448170Q2	☐ OK ☐ NOK ☐ N/A
Panel alignment	☒ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Inspector signature: 			

Vehicle / batch information

Product

PX-A7

Batch

B777656

Serial

SN3145804740

Station

QC-11

Operator

OP734

Final result

REVIEW



PO69961523109

ITEM / CHARACTERISTIC	L		VALUE	UNIT	STATUS
FUEL PIPE CLIP	35.23	53.10	50.10	mm	OK
STEERING COLUMN	18.56	40.44	19.66	deg	OK
CONTROL UNIT COVER	30.25	50.91	31.40	mm	OK
WIRING HARNESS	8.85	11.08	10.04	mm	OK
LOWER ARM ASSEMBLY	 RF9318000538Q1	38.44	35.83	V	OK
LOWER ARM ASSEMBLY		55.81	44.75	V	OK
RIGHT SIDE PANEL	10.28	32.50	11.43	deg	OK
SEAT RAIL FIXING	8.98	12.62	9.55	Nm	OK
RIGHT SIDE PANEL	31.82	51.39	49.47	deg	OK
FUEL PIPE CLIP	13.48	18.70	18.60	V	OK
LEFT DOOR LOCK	1.83	16.68	3.75	Nm	OK
LEFT DOOR LOCK	36.22	58.09	57.50	deg	OK
REAR SENSOR BRACKET	15.97	32.83	20.50	deg	OK
PARKING SENSOR	2.55	21.77	3.16	mm	OK
LOWER ARM ASSEMBLY	-0.27	2.56	1.08	Nm	OK
SEAT RAIL FIXING	-2.01	3.66	-0.86	Nm	OK
CONTROL UNIT COVER	32.80	42.59	36.14	mm	OK
LEFT DOOR LOCK	7.00	9.54	7.17		
WIRING HARNESS	25.35	33.64	29.59		
FUEL PIPE CLIP	21.16	24.96	22.14		
LOWER ARM ASSEMBLY	10.12	29.77	26.55		
BRAKE LINE SUPPORT	9.38	21.54	13.62		
CONTROL UNIT COVER	28.87	45.02	33.54		



RF7399563002Q2

SYNTHETIC QUALITY DOSSIER

Sequence: 492 447 51

Document: SQD-050-7904

PAGE 50/50

DATE: 11/07/2026 16:12

TRACEABILITY / LABEL RECORD

REFERENCE AND CONSUMPTION LOG

STEP	PART / OPERATION	REFERENCE	LOT	VALIDATION
01	STEERING COLUMN	RF-86193	L834217	HOLD
02	REAR SENSOR BRACKET	RF-53551	L424527	HOLD
03	CONTROL UNIT COVER	RF-52515	L810228	HOLD
04	CONTROL UNIT COVER	RF-10270	L518893	HOLD
05	FRONT AXLE ALIGNMENT	RF-39458	L528802	OK
06	LEFT DOOR LOCK	RF-82540	L581013	OK
07	RIGHT DOOR LOCK	RF-57924	L921516	OK
08	RIGHT DOOR LOCK	RF-75184	L602590	OK
09	WIRING HARNESS	RF-10908	L689247	OK
10	ANTI RAIL FIXING	RF-66626	L371289	OK
11	PARKING SENSOR	RF-40422	L854206	OK
12	BATTERY TRAY	RF-11346	L854803	OK
13	WIRING HARNESS	RF-11695	L727693	OK
14	CONTROL UNIT COVER	RF-57818	L471823	HOLD
15	RIGHT SIDE PANEL	RF-60954	L278059	OK

