

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-39922834
MODEL / VARIANT	PX-STD
SERIAL NUMBER	MX185695318328
INSPECTION PLAN	QP-56.2
DECISION	ACCEPTED

Inspection summary

Inspector signature:



QR CODE <https://example.invalid/more/0>



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 410 443 20

Document: MXQD-002-7905

PAGE 02/60

DATE: 13/07/2026 00:31

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	PARKING SENSOR	RF-43052	L557766	OK
02	REAR CAMERA MODULE	RF-74937	L703971	REVIEW
03	BATTERY SUPPORT	RF-23698	L620559	OK
04	CLIMATE CONTROL UNIT	RF-24773	L764138	REVIEW
05	BRAKE HOSE SUPPORT	RF-27775	L379416	OK
06	ENGINE WIRING HARNESS	RF-97319	L899815	REVIEW
07	PARKING SENSOR	RF-19210	L379239	REVIEW
08	RIGHT SIDE PANEL	RF-36796	L918096	OK
09	SEAT RAIL FIXING	RF-22485	L523476	OK
10	REAR CAMERA MODULE	RF-63561	L884384	OK
11	FRONT AXLE BRACKET	RF-28332	L706688	OK
12	AIRBAG CONTROL MODULE	RF-80453	L666290	OK
13	ENGINE WIRING HARNESS	RF-20010	L475923	OK
14	FRONT AXLE BRACKET	RF-15168	L519381	OK
15	FRONT AXLE BRACKET	RF-11847	L261823	OK
16	CLIMATE CONTROL UNIT	RF-98695	L298532	OK
17	FRONT AXLE BRACKET	RF-35052	L501011	REVIEW
18	BRAKE HOSE SUPPORT	RF-31291	L794403	OK
19	AIRBAG CONTROL MODULE	RF-50783	L286585	OK
20	DOOR LOCK ASSEMBLY	RF-59779	L550356	OK
21	FRONT AXLE BRACKET	RF-81124	L890262	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 313 991 69

Document: MXQD-003-7083

PAGE 03/60

DATE: 13/07/2026 16:28

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDI	
Protective film removed	 DATA MATRIX: 2001908248844	Harness routing	☐ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Protective film removed	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Reference matches order	☐ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Seal continuous	☐ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 440 169 82
Document: MXQD-004-7919

PAGE 04/60

DATE: 13/07/2026 23:46
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Gap within limit	☒ OK ☐ NOK ☐ N/A	Harness routing	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Harness routing	QR CODE GR(MX) ☐ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A	Label presence	☒ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	mark	☐ OK ☐ NOK ☐ N/A
Torque confirmed	CODE 39 MX-04-04-9451 ☐ OK ☐ NOK ☐ N/A		☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Connector locked	DATA MATRIX 5N92475549903-AD03 ☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Label presence	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 749 126 77

Document: MXQD-005-7446

PAGE 05/60

DATE: 13/07/2026 13:47

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B279994

STATION QC-10

SERIAL SN2661862880

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
SEAT RAIL FIXING	20.21	39.53	33.22	V	PASS
BATTERY SUPPORT	34.19	47.24	39.34	deg	PASS
REAR CAMERA MODULE	54.55	88.64	80.22	deg	PASS
BATTERY SUPPORT	54.59	59.50	58.09	V	PASS
DOOR LOCK ASSEMBLY	49.12	84.39	51.42	V	HOLD
CLIMATE CONTROL UNIT	47.00	72.29	71.72	deg	PASS
FRONT AXLE BRACKET	16.64	26.74	16.75	Nm	PASS
SEAT RAIL FIXING	-2.47	16.22	5.65	mm	HOLD
BATTERY SUPPORT	37.67	71.29	42.69	Nm	PASS
DOOR LOCK ASSEMBLY	4.43	32.77	29.94	mm	PASS
SEAT RAIL FIXING	19.73	35.03	21.74	V	PASS
LOWER ARM FASTENER	-1.99	17.18	0.51	Nm	PASS
DOOR LOCK ASSEMBLY	22.28	40.88	39.84	deg	HOLD
BRAKE HOSE SUPPORT	25.88	51.11	30.40	Nm	PASS
SEAT RAIL FIXING	17.64	27.93	21.69	V	PASS
BATTERY SUPPORT	6.06	10.00	6.41	mm	PASS
BATTERY SUPPORT	25.26	56.21	27.37	V	PASS
AIRBAG CONTROL MODULE	18.82	32.78	29.43	deg	PASS
BATTERY SUPPORT	32.87	63.02	52.44	mm	PASS
CLIMATE CONTROL UNIT	36.90	46.24	40.71	mm	PASS
LOWER ARM FASTENER	1.09	11.29	6.86	Nm	PASS
PARKING SENSOR	44.04	64.69	46.38	V	PASS
REAR CAMERA MODULE	26.97	57.81	52.18	deg	PASS
CLIMATE CONTROL UNIT	34.27	54.31	38.48	mm	PASS

Sequence: 688 384 33

PAGE 06/60

DATE: 13/07/2026 08:58

CONTROL CERTIFICATE

PRODUCTION ORDER

PO-90033148

MODEL / VARIANT

MX-A7

SERIAL NUMBER

MX982519054273

INSPECTION PLAN

QP-97.1

DECISION

ACCEPTED

Inspection summary

[illegible]

Inspector signature: _____

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 728 651 60

Document: MXQD-007-3604

PAGE 07/60

DATE: 13/07/2026 23:30

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	SEAT RAIL FIXING	RF-55032	L941105	OK
02	BATTERY SUPPORT	RF-77097	L264088	REVIEW
03	ENGINE WIRING HARNESS	RF-77102	L770984	REVIEW
04	AIRBAG CONTROL MODULE	RF-24319	L253120	OK
05	RIGHT SIDE PANEL	RF-84490	L288658	OK
06	BRAKE HOSE SUPPORT	RF-25370	L561134	REVIEW
07	AIRBAG CONTROL MODULE	RF-69421	L382098	OK
08	BRAKE HOSE SUPPORT	RF-48158	L695692	OK
09	AIRBAG CONTROL MODULE	RF-73806	L137262	OK
10	LOWER ARM FASTENER	RF-72280	L104641	OK
11	RIGHT SIDE PANEL	RF-69001	L669607	OK
12	LOWER ARM FASTENER	RF-79396	L232250	OK
13	PARKING SENSOR	RF-55808	L722725	OK
14	REAR CAMERA MODULE	RF-31680	L395064	REVIEW

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 596 952 70

Document : MXQD-008-9687

PAGE 08/60

DATE: 13/07/2026 05:40

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BRAKE HOSE SUPPORT	RF-60317	L454170	OK
02	FRONT AXLE BRACKET	RF-40531	L725891	OK
03	RIGHT SIDE PANEL	RF-69375	L812366	OK
04	SEAT RAIL FIXING	RF-16218	L399744	OK
05	FRONT AXLE BRACKET	RF-28348	L216498	OK
06	CLIMATE CONTROL UNIT	RF-97151	L637369	REVIEW
07	ENGINE WIRING HARNESS	RF-91368	L158958	REVIEW
08	PARKING SENSOR	RF-52169	L221110	OK
09	PARKING SENS	RF-75375	L787007	REVIEW
10	SEAT RAIL FIX	RF-73542	L100834	OK
11	IT SIDE PANEL	RF-10549	L737142	OK
12	BRAKE HOSE SUPPORT	RF-58174	L305993	OK
13	DOOR LOCK ASSEMBLY	RF-79510	L731307	OK
14	REAR CAMERA MODULE	RF-83095	L186573	OK
15	BATTERY SUPPORT	RF-71048	L911862	OK
16	REAR CAMERA MODULE		L123171	REVIEW
17	DOOR LOCK ASSEMBLY	RF-33801	L492215	REVIEW
18	LOWER ARM FASTENER	RF-60874	L596843	OK
19	PARKING SENSOR	RF-26853	L368979	OK
20	FRONT AXLE BRACKET	RF-38494	L973168	OK
21	RIGHT SIDE PANEL	RF-73277	L990952	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 631 903 66

Document: MXQD-009-8927

PAGE 09/60

DATE: 13/07/2026 03:36

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL

FUNCTION / IDENTITY

Connector locked ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

Surface condition ☐ OK ☐ NOK ☐ N/A

Cover installed ☒ OK ☐ NOK ☐ N/A

Seal continuous ☒ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

Harness routing ☐ OK ☐ NOK ☐ N/A

Reference matches order ☒ OK ☐ NOK ☐ N/A



ad



CODE 128 LOT-925465-P09



☒ OK ☐ NOK ☐ N/A



Protective film removed ☒ OK ☐ NOK ☐ N/A

Reference matches order ☐ OK ☐ NOK ☐ N/A

Cover installed ☒ OK ☐ NOK ☐ N/A

Fastener witness mark ☒ OK



DATA MATRIX D46MX(P009)05(L876)

Harness routing ☒ OK ☐ NOK ☐ N/A

Reference matches order ☒ OK ☐ NOK ☐ N/A

Cover installed ☐ OK ☐ NOK ☐ N/A



DATA MATRIX 1

Torque confirmed ☒ OK ☐ NOK ☐ N/A

Reference matches order ☐ OK ☐ NOK ☐ N/A

Harness routing ☒ OK ☐ NOK ☐ N/A

Surface condition ☒ OK ☐ NOK ☐ N/A

Torque confirmed ☒ OK ☐ NOK ☐ N/A

Label presence ☒ OK ☐ NOK ☐ N/A

Gap within limit ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 293 174 20
Document: MXQD-010-4955

PAGE 10/60

DATE: 13/07/2026 07:31

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B487863 SERIAL SN1333045641
STATION QC-25 DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
REAR CAMERA MODULE	12.86	28.81	23.12	deg	PASS
BRAKE HOSE SUPPORT	17.16	49.77	44.09	deg	PASS
CLIMATE CONTROL UNIT	38.44	65.08	48.63		HOLD
AIRBAG CONTROL MODULE	48.01	67.77	64.03		PASS
DOOR LOCK ASSEMBLY	45.07	74.58	48.69		HOLD
AIRBAG CONTROL MODULE	50.38	59.51	57.70	Nm	PASS
REAR CAMERA MODULE	4.56	10.23	4.88	V	PASS
FRONT AXLE BRACKET	16.81	44.89	29.07	mm	PASS
REAR CAMERA				deg	PASS
PARKING SENSOR				Nm	PASS
RIGHT SIDE PANEL				deg	PASS
ENGINE WIRING HARNESS				Nm	PASS
SEAT RAIL FIXING				deg	PASS
FRONT AXLE BRACKET					PASS
DOOR LOCK ASSEMBLY					PASS
PARKING SENSOR	17.73	35.47	23.16		HOLD
REAR CAMERA MODULE	45.80	56.93			HOLD
DOOR LOCK ASSEMBLY	21.80	28.21		mm	HOLD
RIGHT SIDE PANEL	17.26	49.73	17.52	V	PASS
AIRBAG CONTROL MODULE	24.75	56.07	28.26	deg	PASS
LOWER ARM FASTENER	26.65	49.04	29.04	V	HOLD
FRONT AXLE BRACKET	32.24	63.78	57.76	deg	PASS
RIGHT SIDE PANEL	38.75	67.41	54.62	mm	PASS
ENGINE WIRING HARNESS	53.57	89.09	76.44	deg	HOLD

Sequence: 884 585 99
Document: MXQD-011-7324

DATE: 13/07/2026 00:28

QC
PASS

Sequence: 901 941 75

Document: MXQD-012-5215

DATE: 13/07/2026 02:25

CERTIFICATE OF CONFORMITY

PO-11074742

R2-HYB

MX777802955132

QP-69.3

ACCEPTED

Inspection summary

Inspector signature: _____

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

PAGE 13/60

DATE: 13/07/2026 06:12

COMPONENT TRACEABILITY LOG

Sequence: 466 335 86
Document: MXQD-013-8988

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BATTERY SUPPORT	RF-53593	L981560	OK
02	RIGHT SIDE PANEL	RF-75348	L177898	OK
03	AIRBAG CONTROL MODULE	RF-34885	L486285	REVIEW
04	PARKING SENSOR	RF-56288	L150540	OK
05	BRAKE HOSE SUPPORT	RF-69143	L709444	REVIEW
06	FRONT AXLE BRACKET	RF-66673	L122461	OK
07	RIGHT SIDE PANEL	RF-68090	L764217	REVIEW
08	BRAKE HOSE SUPPORT	RF-27019	L274470	OK
09	LOWER ARM FASTENER	RF-83808	L995418	OK
10	BATTERY SUPPORT	RF-34261	L699230	OK
11	CLIMATE CONTROL UNIT	RF-51821	L583667	OK
12	AIRBAG CONTROL MODULE	RF-27193	L631620	OK
13	DOOR LOCK ASSEMBLY	RF-50591	L997135	REVIEW
14	ENGINE WIRING HARNESS	RF-48592	L641818	OK
15	REAR CAMERA MODULE	RF-32909	L238592	OK
16	LOWER ARM FASTENER	RF-72630	L295072	OK
17	REAR CAMERA MODULE	RF-27229	L149470	OK
18	DOOR LOCK ASSEMBLY	RF-29981	L860499	OK
19	PARKING SENSOR	RF-23616	L841274	REVIEW
20	SEAT RAIL FIXING	RF-53990	L575292	OK
21	AIRBAG CONTROL MODULE		L730694	REVIEW



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 278 243 57
Document: MXQD-014-3685

PAGE 14/60
DATE: 13/07/2026 14:09
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL			FUNCTION / IDENTITY		
Seal continuous	☒ OK ☐ NOK ☐ N/A		Reference matches order	☒ OK ☐ NOK ☐ N/A	
Protective film removed	☐ OK ☐ NOK ☐ N/A		No visible damage	☒ OK ☐ NOK ☐ N/A	
Fastener witness mark	☒ OK ☐ NOK ☐ N/A		Surface condition	☒ OK ☐ NOK ☐ N/A	
Torque confirmed	☒ OK ☐ NOK ☐ N/A		Surface condition	☒ OK ☐ NOK ☐ N/A	
Gap within limit	☒ OK ☐ NOK ☐ N/A		Cover installed	☐ OK ☐ NOK ☐ N/A	
Fastener witness mark	☒ OK ☐ NOK ☐ N/A		No visible damage	☒ OK ☐ NOK ☐ N/A	
Reference matches order	☒ OK ☐ NOK ☐ N/A		Harness routing	☐ OK ☐ NOK ☐ N/A	
Label presence	☒ OK ☐ NOK ☐ N/A		Gap within limit	☐ OK ☐ NOK ☐ N/A	
Reference matches order	☒ OK ☐ NOK ☐ N/A		Fastener witness mark	☒ OK ☐ NOK ☐ N/A	
Label presence	☐ OK ☐ NOK ☐ N/A		No visible damage	☐ OK ☐ NOK ☐ N/A	
Label presence	☒ OK ☐ NOK ☐ N/A		No visible damage	☒ OK ☐ NOK ☐ N/A	
Gap within limit	☒ OK ☐ NOK ☐ N/A		No visible damage	☐ OK ☐ NOK ☐ N/A	



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 196 657 48

Document: MXQD-015-8260

PAGE 15/60

DATE: 13/07/2026 23:03

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B266397

STATION QC-23

SERIAL SN5022856224

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	27.31	45.26	27.52	Nm	PASS
RIGHT SIDE PANEL	15.71	30.33	29.25		
REAR CAMERA MODULE	3.70	34.88	19.33		
AIRBAG CONTROL MODULE	7.95	16.11	12.71		
DOOR LOCK ASSEMBLY	23.00	45.89	41.35		
ENGINE WIRING		51.95	51.13	deg	PASS
AIRBAG CONTROL		4.72	-1.88	Nm	PASS
AIRBAG CONTROL		76.47	58.09	mm	PASS
PARKING SENSOR	9.25	33.07	12.02	deg	HOLD
LOWER ARM FASTENER	52.57	83.18	71.44	V	HOLD
SEAT RAIL FIXING	2.25		3.02	V	PASS
ENGINE WIRING HARNESS	0.76		24.01	deg	PASS
LOWER ARM FASTENER	0.74	35.87	23.11	V	PASS
FRONT AXLE BRACKET	50.43	62.19	60.88	V	PASS
DOOR LOCK ASSEMBLY	21.76	26.93	25.58	mm	PASS
PARKING SENSOR	46.66	82.26	71.34	V	PASS
ENGINE WIRING HARNESS	54.23	56.78	54.53	deg	HOLD
PARKING SENSOR	34.01	53.50	44.39	mm	PASS
DOOR LOCK ASSEMBLY	5.25	33.28	7.01	Nm	HOLD
SEAT RAIL FIXING	50.37	61.96	52.02	mm	PASS
ENGINE WIRING HARNESS	48.57	73.21	64.68	V	HOLD
AIRBAG CONTROL MODULE	45.45	65.51	56.99	V	PASS
PARKING SENSOR	35.26	39.41	38.41	deg	PASS
DOOR LOCK ASSEMBLY	45.08	63.24	45.45	deg	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 299 949 22
Document: MXQD-016-9445

DATE: 13/07/2026 15:26

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B898445
STATION QC-08

SERIAL SN9664402416
DECISION REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
SEAT RAIL FIXING	15.43	44.06	33.14	deg	HOLD
CLIMATE CONTROL UNIT	41.83	64.97	46.11	V	PASS
FRONT AXLE BRACKET	5.17	10.19	9.88	mm	PASS
AIRBAG CONTROL MODULE	34.99	39.52	36.45	deg	HOLD
PARKING SENSOR	18.91	50.51	19.22	deg	PASS
SEAT RAIL FIXING	51.55	82.79	71.08	Nm	PASS
BATTERY SUPPORT	4.26	16.99	15.08	Nm	PASS
CLIMATE CONTROL UNIT	0.45	11.82	1.78	mm	PASS
RIGHT SIDE PANEL	46.04	63.80	60.71	deg	PASS
REAR CAMERA MODULE	12.46	31.11	28.15	mm	PASS
DOOR LOCK ASSEMBLY	25.55	57.72	46.43	mm	PASS
RIGHT SIDE PANEL	36.00	57.19	53.84	deg	PASS
FRONT AXLE BRACKET	39.73	52.29	40.60	mm	HOLD
RIGHT SIDE PANEL	34.30	65.58	64.49	V	PASS
DOOR LOCK ASSEMBLY	51.28	53.76	53.01	V	PASS
REAR CAMERA	33.16	51.24	46.44	Nm	PASS
AIRBAG CONTROL MODULE	5.80	33.70	31.94	deg	PASS
ENGINE WIRING HARNESS	19.55	23.86	22.53	Nm	HOLD
REAR CAMERA MODULE	29.95	61.44	42.49	deg	PASS
SEAT RAIL FIXING	37.49	62.71	38.00	mm	HOLD
SEAT RAIL FIXING	24.05		35.55	Nm	PASS
BATTERY SUPPORT	51.40		73.97		
CLIMATE CONTROL UNIT	13.16	36.99	24.32		
RIGHT SIDE PANEL	52.87	57.84	54.00	V	PASS

Sequence: 955 757 48

Document: MXQD-017-9524

DATE: 13/07/2026 07:20

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

MODEL / VARIANT K9-VU

SERIAL NUMBER MX989993913534

INSPECTION PLAN QP-69.8

DECISION	CONDITIONAL
----------	-------------

Inspection summary

[illegible]

Inspector signature: _____

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 658 560 29

Document: MXQD-018-1521

PAGE 18/60

DATE: 13/07/2026 04:37

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	DOOR LOCK ASSEMBLY	RF-95699	L502181	OK
02	PARKING SENSOR	RF-57568	L135594	OK
03	DOOR LOCK ASSEMBLY	RF-46163	L218229	OK
04	FRONT AXLE BRACKET	RF-25701	L505775	OK
05	RIGHT SIDE PANEL	RF-73752	L251424	OK
06	BRAKE HOSE SUPPORT	RF-96287	L512198	REVIEW
07	SEAT RAIL FIXING	RF-94755	L690700	OK
08	SEAT RAIL FIXING	RF-64281	L557252	OK
09	AIRBAG CONTROL MODULE	RF-14604	L273892	OK
10	ENGINE WIRING HARNESS	RF-48252	L108159	REVIEW
11	SEAT RAIL FIXING	RF-45139	L975148	OK
12	AIRBAG CONTROL MODULE	RF-51000	L738264	OK
13	LOWER ARM FASTENER	RF-40321	L311301	OK
14	ENGINE WIRING HARNESS	RF-82654	L143599	OK
15	LOWER ARM FASTENER	RF-15499	L139416	REVIEW
16	DOOR LOCK ASSEMBLY	RF-78107	L223745	OK
17	BATTERY SUPPORT	RF-97123	L462903	REVIEW
18	FRONT AXLE BRACKET	RF-89721	L236814	OK
19	BATTERY SUPPORT	RF-83333	L846277	OK
20	RIGHT SIDE PANEL	RF-73920	L461324	OK
21	LOWER ARM FASTENER	RF-85954	L256505	OK



DATA MATRIX (01)00506000274592(21)00

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 918 598 96
Document: MXQD-019-2595

PAGE 19/60
DATE: 13/07/2026 07:19
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Surface condition ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
Label presence ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 337 502 70

Document: MXQD-020-1268

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
No visible damage	☒ OK ☐ NOK ☐ N/A	No visible damage	☐ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Label presence	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	No 	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Label presence 	☐ OK ☐ NOK ☐ N/A
No visible damage	☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Gap within limit	☐ N/A	Seal continuous 	☒ OK ☐ NOK ☐ N/A
No visible damage	☐ N/A	Torque confirmed 	☒ OK ☐ NOK ☐ N/A
	☐ N/A	Protective film removed 	☐ OK ☐ NOK ☐ N/A
Cover installed	☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Surface condition	☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 382 104 17

Document: MXQD-021-9095

PAGE 21/60

DATE: 13/07/2026 19:04

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B971674
STATION QC-03SERIAL SN5089519912
DECISION OK

CHARAC

CLIMATE C

ENGINE W

PARKING S

RIGHT SIDE PANEL

QR CODE <https://example.invalid/mixed021016731>

CODE 128 LOT-411907-P21

	LOW	HIGH	VALUE	UNIT	RESULT
	-0.33	2.82	-0.13	deg	PASS
	5.18	32.50	19.83	deg	HOLD
	9.49	41.03	20.16	V	PASS
	33.36	43.10	40.38	deg	HOLD
	8.68	32.36	10.36	Nm	HOLD
	24.50	34.35	25.24	deg	PASS
	34.35	40.58	39.73	V	PASS
BATTERY SUPPORT	32.81	52.29	41.49	Nm	PASS
ENGINE WIRING HARNESS	29.56	59.23	58.15	mm	PASS
PARKING SENSOR	49.81	64.43	54.15	mm	PASS
BRAKE HOSE SUPPORT	10.96	31.71	15.09	Nm	HOLD
LOWER ARM FASTENER	10.68	33.88	11.64	deg	HOLD
PARKING SENSOR	29.65	57.53	50.58	deg	PASS
READ CAMERA MODULE	49.41	54.64	54.44	mm	PASS
RIG	8.92	40.38	23.28	mm	HOLD
LOW	9.15	25.83	13.39	mm	PASS
RIG	12.82	38.05	26.51	deg	PASS
LOWER ARM FASTENER	14.88	21.42	16.80	mm	HOLD
AIRBAG CONTROL MODULE	51.34	70.96	65.78	mm	PASS
DOOR LOCK ASSEMBLY	43.11	72.61	71.35	Nm	PASS
SEAT RAIL FIXING	25.29	35.87	27.23	V	PASS
CLIMATE CONTROL UNIT	47.77	53.50	51.38	V	PASS
RIGHT SIDE PANEL	47.86	55.97	50.17	deg	HOLD
CLIMATE CONTROL UNIT	1.69	18.49	9.92	V	PASS
CLIMATE CONTROL UNIT					

Document: MXQD-022-6884

PAGE 22/60

DATE: 13/07/2026 23:20

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER

PO-70430420

MODEL / VARIANT

PX-STD

SERIAL NUMBER

MX329512512162

INSPECTION PLAN

QP-14.4

DECISION

ACCEPTED



CODE 39 MX-22-03-6802

Inspection summary



CODE 128 PO30273656615

Inspector signature: _____



DATA MATRIX DIMENSIONS

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 688 846 94
Document: MXQD-023-5515

PAGE 23/60

DATE: 13/07/2026 06:42

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-53483	L176440	OK
02	CLIMATE CONTROL UNIT	RF-95364	L465895	OK
03	REAR CAMERA MODULE	RF-45156	L895880	OK
04	FRONT AXLE BRACKET	RF-65944	L853853	OK
05	CLIMATE CONTROL UNIT	 CODE 39 MX-23-02-4286		REVIEW
06	AIRBAG CONTROL MODULE			REVIEW
07	BATTERY SUPPORT			REVIEW
08	DOOR LOCK ASSEMBLY	RF-80239	L278113	REVIEW
09	REAR CAMERA MODULE	RF-90586	L103453	OK
10	RIGHT SIDE PANEL	RF-38233	L717822	REVIEW
11	DOOR LOCK ASSEMBLY	RF-64995	L295793	REVIEW
12	SEAT RAIL FIXING	RF-21491	L596093	OK
13	ENGINE WIRING HARNESS	RF-77074	L231743	OK
14	BATTERY SUPPORT	RF-89513	L468779	OK
15	CLIMATE CONTROL UNIT	RF-43882	L681544	OK
16		RF-24895	L918537	OK
17		RF-42359	L902605	OK
18	PARKING SENSOR	RF-89856	L778993	OK
19	AIRBAG CONTROL MODULE	RF-10971	L658422	OK
20	DOOR LOCK ASSEMBLY	RF-20686	L298940	OK
21	DOOR LOCK ASSEMBLY	RF-87286	L559708	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 934 604 27
Document: MXQD-024-5752

PAGE 24/60
DATE: 13/07/2026 10:20
COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-89496	L194357	OK
02	LOWER ARM FASTENER	RF-11876	L760459	OK
03	REAR CAMERA MODULE	RF-48253	L383873	OK
04	FRONT AXLE BRACKET	RF-62374	L441545	OK
05	BATTERY SUPPORT	RF-98910	L119270	OK
06	BRAKE HOSE SUPPORT	RF-51184	L623906	OK
07	LOWER ARM FASTENER	RF-91413	L195673	OK
08	PARKING SENSOR	RF-55664	L534524	OK
09	DOOR LOCK ASSEMBLY	RF-30674	L751216	OK
10	BRAKE HOSE SUPPORT	RF-41333	L266282	REVIEW
11	ENGINE WIRING HARNESS	RF-75815	L332694	OK
12	 CODE 39 MX-24-03-3707	RF-20641	L533217	REVIEW
13		RF-95013	L410935	REVIEW
14	FRONT AXLE BRACKET	RF-61502	L406081	OK
15	BRAKE HOSE SUPPORT	RF-83930	L155864	REVIEW
16	ENGINE WIRING HARNESS	RF-98199	L606656	
17	FRONT AXLE BRACKET	RF-69910	L948503	
18	ENGINE WIRING HARNESS	RF-96088	L382593	OK
19	ENGINE WIRING HARNESS	RF-51836	L969220	OK
20	PARKING SENSOR	RF-98690	L651890	OK
21	BATTERY SUPPORT	RF-55836	L783153	REVIEW

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Cover installed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Harness routing	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A		☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A		☒ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 961 622 29
Document: MXQD-026-5376

BATCH / CONTROL INFORMATION

BATCH B262533
STATION QC-18

SERIAL SN4551010371
DECISION REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
BRAKE HOSE SUPPORT	20.61	37.76	33.30	mm	PASS
CLIMATE CONTROL UNIT	0.59	3.17	1.12	mm	PASS
BATTERY SUPPORT	27.04	47.79	40.46	deg	PASS
PARKING SENSOR	53.59	85.47	59.73	deg	PASS
SEAT RA	27.54	35.46	CODE 128 LOT-667566-P26	mm	HOLD
BATTERY SUPPORT	13.92	20.59	17.81	mm	PASS
BRAKE HOSE SUPPORT	32.28	54.22	35.15	deg	HOLD
BRAKE HOSE SUPPORT	40.53	50.33	47.46	deg	PASS
AIRBAG CONTROL MODULE	5.43	33.55	12.28		PASS
REAR CAMERA MODULE	42.58	63.29	57.85	CODE 128 LOT-761505-P26	PASS
LOWER ARM FASTENER	8.17	32.46	12.61	mm	PASS
REAR CAMERA MODULE	24.84	49.86	25.33	deg	PASS
LOWER ARM FASTENER	22.09	40.28	35.32	mm	PASS
FRONT AXLE BRACKET	25.10	32.00	28.00	mm	PASS
CLIMATE CONTROL UNIT	5.21	25.84	7.48	deg	PASS
BATTERY SUPPORT	9.29	32.88	28.94	V	PASS
AIRBAG CONTROL MODULE	40.09	63.32	61.14	deg	PASS
DOOR LOCK ASSEMBLY	14.93	27.16	19.33	V	PASS
REAR CAMERA MODULE	34.80	37.95	37.67	Nm	PASS
BRAKE HOSE SUPPORT	26.78	49.20	29.11	V	PASS
SEAT RAIL FIXING	48.26	70.76	53.67	mm	PASS
REAR CAMERA MODULE	43.28	77.84	63.53	mm	PASS
PARKING SENSOR	1.75	34.45	3.42	deg	PASS
BATTERY SUPPORT	48.68	50.83	50.66	Nm	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 288 107 76

Document: MXQD-027-2590

PAGE 27/60

DATE: 13/07/2026 11:00

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-53240670
MODEL / VARIANT	K9-VU
SERIAL NUMBER	MX832277898338
INSPECTION PLAN	QP-85.4
DECISION	CONDITIONAL

Inspection summary

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 331 924 74

Document: MXQD-028-2244

PAGE 28/60

DATE: 13/07/2026 16:42

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY



CODE 128 PO10443509450

PRODUCTION ORDER

PO-27690588

MODEL / VARIANT

K9-VU



CODE 128 LOT-531486-P28

SERIAL NUMBER

MX763620642502

INSPECTION PLAN

QP-22.3

DECISION

ACCEPTED

Inspection summary



Inspector signature:

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 695 626 87
Document: MXQD-029-5628

PAGE 29/60
DATE: 13/07/2026 09:21
COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	AIRBAG CONTROL MODULE	RF-47571	L865445	OK
02	LOWER ARM FASTENER	RF-46677	L144194	OK
03	LOWER ARM FASTENER	RF-39917	L281750	OK
04	CLIMATE CONTROL UNIT	RF-98543	L192765	OK
05	CLIMATE CONTROL UNIT	RF-17801	L671636	OK
06	PARKING SENSOR	RF-73008	L208141	OK
07	FRONT AXLE BRACKET	RF-94271	L216148	OK
08	CLIMATE CONTROL UNIT	RF-56569	L773405	REVIEW
09	AIRBAG CONTROL MODULE	RF-37213	L630131	OK
10	FRONT AXLE BRACKET	RF-41413	L322531	OK
11	BRAKE HOSE SUPPORT	RF-41037	L638998	OK
12	DOOR LOCK ASSEMBLY	RF-11805	L858646	OK
13	AIRBAG CONTROL MODULE	RF-93625	L901866	OK
14	BRAKE HOSE SUPPORT	RF-48834	L729217	OK
15	BATTERY SUPPORT	RF-48806	L672957	REVIEW
16	RIGHT SIDE PANEL	RF-13521	L413111	OK
17	RIGHT SIDE PANEL	RF-80826	L952993	OK
18	CLIMATE CONTROL UNIT	RF-24819	L940340	REVIEW
19	RIGHT SIDE PANEL	RF-47065	L189345	OK
20	BATTERY SUPPORT	RF-13710	L584284	OK
21	BATTERY SUPPORT	RF-15987	L316448	OK



DATA MATRIX: 01/09500002332310

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 854 350 20


Document: MXQD-030-8221

PAGE 30/60

DATE: 13/07/2026 08:43

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Connector locked ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Label presence ☐ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Surface ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Seal continuous	No visible damage ☐ OK ☐ NOK ☐ N/A
Harness routing	Label presence ☐ OK ☐ NOK ☐ N/A
Cover installed	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Connector locked ☐ OK ☐ NOK ☐ N/A
Reference matches order ☐ OK ☐ NOK ☐ N/A	
Protective film removed ☐ NOK ☐ N/A	



BATCH / CONTROL INFORMATION

BATCH

B508838

STATION

QC-12

SERIAL

SN1038693955

DECISION

OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	42.34		42.57	V	HOLD
RIGHT SIDE PANEL	45.93		59.06	mm	HOLD
ENGINE WIRING HARNESS		32.73	32.38	Ni	HOLD
REAR CAMERA MODULE		45.06	21.58	mm	PASS
CLIMATE CONTROL UNIT		77.86	65.16	deg	PASS
PARKING SENSOR	48.55	81.54	56.82	V	PASS
REAR CAMERA MODULE	18.77	31.81	21.06	deg	HOLD
ENGINE WIRING HARNESS	7.63	33.74			
CLIMATE CONTROL UNIT	20.50	28.28			
LOWER ARM FASTENER	1.72	12.00			
CLIMATE CONTROL UNIT	53.89	75.23			
BATTERY SUPPORT	44.89	70.72			
REAR CAMERA MODULE	31.72	50.33			
RIGHT SIDE PANEL	22.92	51.54			
AIRBAG CONTROL MODULE	12.11	30.45			
DOOR LOCK ASSEMBLY	44.24	64.78			
SEAT RAIL FIXING	27.36	52.62	36.84	V	HOLD
FRONT AXLE BRACKET	38.60	73.68	41.16	V	HOLD
DOOR LOCK ASSEMBLY	43.98	75.26	51.32	mm	PASS
SEAT RAIL FIXING	45.23	56.64	55.37	Ni	PASS
SEAT RAIL FIXING	23.83	25.89	25.73	Ni	PASS
REAR CAMERA MODULE	28.43	59.15	48.58	V	PASS
AIRBAG CONTROL MODULE	2.41	14.54	4.78	V	PASS
PARKING SENSOR	30.02	56.88	36.30	V	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 788 582 79
Document: MXQD-032-4797

PAGE 32/60
DATE: 13/07/2026 09:32
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B103333
STATION QC-11


SERIAL SN5576082217
DECISION REVIEW

CHARACTERISTIC	VALUE	UNIT	RESULT
PARKING SENSOR	7.38	mm	PASS
RIGHT SIDE PANEL	15.01		
LOWER ARM FASTENER	3.64		
BRAKE HOSE SUPPORT	24.34		
	49.98		
	44.66	mm	PASS
	20.70	mm	PASS
DOOR LOCK ASSEMBLY	7.02	V	PASS
LOWER ARM FASTENER	12.25	deg	HOLD
ENGINE WIRING HARNESS	0.91	Nm	HOLD
PARKING SENSOR	11.55	V	PASS
AIRBAG CONTROL MODULE	-3.00	Nm	HOLD
LOWER ARM FASTENER	41.81	Nm	PASS
CLIMATE CONTROL UNIT	52.58	Nm	PASS
BRAKE HOSE SUPPORT	17.96	deg	PASS
BRAKE HOSE SUPPORT	54.87	deg	HOLD
CLIMATE CONTROL UNIT	11.82	Nm	PASS
AIRBAG CONTROL MODULE	34.21	deg	PASS
DOOR LOCK ASSEMBLY	10.25	mm	PASS
BATTERY SUPPORT	24.10	deg	PASS
AIRBAG CONTROL MODULE	30.82	mm	PASS
DOOR LOCK ASSEMBLY	12.50	deg	PASS
AIRBAG CONTROL MODULE	47.62	deg	PASS
RIGHT SIDE PANEL	24.56	deg	HOLD

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 178 386 95
Document: MXQD-033-2935

PAGE 33/60
DATE: 13/07/2026 01:10
CONTROL CERTIFICATE



CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-81314478
MODEL / VARIANT	K9-VU
SERIAL NUMBER	MX841089939802
INSPECTION PLAN	QP-58.4
DECISION	




Inspection summary



QR CODE <https://example.invalid/mixed/033/03/1961>

Inspector signature:



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 978 941 98

Document: MXQD-034-9911

PAGE 34/60

DATE: 13/07/2026 18:28

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-11419	L924245	OK
02	BATTERY SUPPORT	RF-76709	L462407	REVIEW
03	LOWER ARM FASTENER	RF-42470	L435909	OK
04	CLIMATE CONTROL UNIT	RF-40877	L966268	REVIEW
05	PARKING SENSOR	RF-97993	L852435	REVIEW
06	RIGHT SIDE PANEL	RF-91764	L430833	OK
07	FRONT AXLE BRACKET	RF-94070	L281550	OK
08	BATTERY SUPPORT	RF-87965	L986512	OK
09	BATTERY SUPPORT	RF-96771	L112692	REVIEW
10	PARKING SENSOR	RF-45224	L652970	OK
11	BRAKE HOSE SUPPORT	RF-34213	L946337	OK
12	 IIT	RF-14168	L558649	OK
13	AIRBAG CONTROL MODULE	RF-62041	L385201	OK
14	LOWER ARM FASTENER	RF-87198	L135880	OK
15	CLIMATE CONTROL UNIT	RF-94203	L792625	OK
16	BRAKE HOSE SUPPORT	RF-39936	L184129	OK
17	BATTERY SUPPORT	RF-96959	L919461	REVIEW
18	REAR CAMERA MODULE	RF-45692	L473499	OK
19	BATTERY SUPPORT	RF-91218	L397619	OK
 DATA MATR	REAR CAMERA MODULE		L455213	OK
21 	LOWER ARM FASTENER	 DATA MATR: 04560P034/018	L127475	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 602 581 67
Document: MXQD-035-7801

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Harness routing	☒ OK ☐ NOK ☐ N/A	Cover installed	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
No visible damage	☐ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Harness routing	☐ OK ☐ NOK ☐ N/A
Protective film removed	☐ OK ☐ NOK ☐ N/A	Surface condition	☐ OK ☐ NOK ☐ N/A
Gap within limit	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 773 632 74

Document: MXQD-036-6566

PAGE 36/60

DATE: 13/07/2026 22:22

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
No visible damage ☒ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Protective film removed ☐ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Cover installed ☒ OK ☐ NOK ☐ N/A
Protective film removed ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Reference matches order ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Protective film removed ☐ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 475 455 20
Document: MXQD-037-4799

DATE: 13/07/2026 22:03

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B183854 SERIAL SN9658604754
STATION QC-12 DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
REAR CAMERA MODULE	-1.40	14.16	-0.05	Nm	PASS
SEAT RAIL	21.58	54.82	49.38	mm	PASS
DOOR LOCK ASSEMBLY	13.95	41.93	28.38	V	PASS
PARKING SENSOR	54.80	57.00	56.01	Nm	HOLD
REAR CAMERA MODULE	45.79	80.34	76.37	V	PASS
FRONT AXLE BRACKET	11.29	42.59	27.46	V	PASS
CLIMATE CONTROL UNIT	35.70	53.92	44.34	V	PASS
FRONT AXLE BRACKET	40.27	54.99	53.36	mm	PASS
RIGHT SIDE PANEL	29.64	47.78	37.09	Nm	PASS
DOOR LOCK ASSEMBLY	39.74	49.64	45.03	V	PASS
REAR CAMERA MODULE	41.71	60.13	52.86	V	HOLD
RIGHT SIDE PANEL	4.93	39.43	16.07	deg	PASS
RIGHT SIDE PANEL	17.37	51.67	24.16	deg	PASS
AIRBAG CONTROL MODULE	23.02	38.11	35.48	V	HOLD
ENGINE WIRING HARNESS	28.45	59.03	44.43	V	PASS
BRAKE HOSE SUPPORT	12.67	2	43.86	mm	HOLD
PARKING SENSOR	42.56	DATA MATRIX DM(MX(P037)) 8	42.97	V	PASS
RIGHT SIDE PANEL	50.81	75.96	56.67	mm	HOLD
SEAT RAIL FIXING	30.26	52.51	36.58	deg	PASS
BRAKE HOSE SUPPORT	51.69	73.47	52.64	Nm	PASS
ENGINE WIRING HARNESS	38.33	49.22	41.11	Nm	HOLD
ENGINE WIRING HARNESS	18.51	35.77	23.05	mm	PASS
DOOR LOCK ASSEMBLY	7.70	17.06	14.44	deg	PASS
RIGHT SIDE PANEL	46.70	77.64	49.93	mm	PASS

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER	PO-26815478
MODEL / VARIANT	PX-STD
SERIAL NUMBER	MX582814352860
INSPECTION PLAN	QP-14.7
DECISION	CONDITIONAL

Inspection summary

Inspector signature:

CODE 128 PO38300417744



S



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 931 572 76

Document: MXQD-039-5105

PAGE 39/60

DATE: 13/07/2026 02:20

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	BRAKE HOSE SUPPORT	RF-33277	L267795	REVIEW
02	SEAT RAIL FIXING	RF-18598	L419280	OK
03	SEAT RAIL FIXING	RF-90000	L189430	OK
04	ENGINE WIRING HARNESS	RF-74436	L927493	OK
05	CLIMATE CONTROL UNIT	RF-43173	L146308	OK
06	RIGHT SIDE PANEL	RF-17840	L219605	OK
07	LOWER ARM FASTENER		L786938	REVIEW
08	DOOR LOCK ASSEMBLY		L651650	REVIEW
09	LOWER ARM FASTENER	RF-3bU08	L267276	OK
10	BRAKE HOSE SUPPORT	RF-25597	L797388	REVIEW
11	BATTERY SUPPORT	RF-30917	L160389	OK
12	REAR CAMERA MODULE	RF-28435	L391380	OK
13	SEAT RAIL FIXING	RF-98097	L245748	REVIEW
14	AIRBAG CONTROL MODULE	RF-43109	L231970	OK
15	BRAKE HOSE SUPPORT	RF-27396	L393936	OK
		-35393	L353541	OK
		-66639	L984792	OK
		-15293	L702066	REVIEW
		RF-36793	L133140	OK
19	FRONT AXLE BRAKE			
20	BRAKE HOSE SUPPORT	RF-68910	L529516	OK
21	AIRBAG CONTROL MODULE	RF-61440	L959182	

QR CODE: <https://example.invalid/mixed/039/05/>

CODE 39 MX-39-02-7101

CODE 128 P092489047823

CODE 39 MX-39-01-8265

QR CODE: 371448X-039-03

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 426 786 17

Document: MXQD-040-1480

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION		LOT	STATUS / NOTE
01	DOOR LOCK ASSEMBLY		L842683	OK
02	FRONT AXLE BRACKET		L176258	REVIEW
03	REAR CAMERA MODULE		L776972	OK
04	BRAKE HOSE SUPPORT		L216158	OK
05	SEAT RAIL FIXING	RF-22042	L927101	OK
06	ENGINE WIRING HARNESS	RF-95694	L567319	OK
07	SEAT RAIL FIXING	RF-50943	L414517	OK
08	BATTERY SUPPORT	RF-27390	L634303	REVIEW
09		RF-62080	L444467	REVIEW
10		RF-70131	L552427	OK
11		RF-41955	L413039	REVIEW
12	LOWER ARM FASTENER	RF-86290	L785466	OK
13	REAR CAMERA MODULE	RF-93899	L347692	OK
14	BRAKE HOSE SUPPORT	RF-92320	L722784	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 552 332 47

Document: MXQD-041-9848

PAGE 41/60

DATE: 13/07/2026 15:02

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Fastener witness mark ☒ OK ☐ NOK ☐ N/A	Surface condition ☐ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Connector locked ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
	
Harness routing ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK QR CODE: https://example.invalid/
Cover installed ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	No visible damage ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Gap within limit ☐ OK ☐ NOK ☐ N/A
Fastener witness mark ☐ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
No visible damage ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 944 781 15

Document: MXQD-042-8528

PAGE 42/60

DATE: 13/07/2026 22:03

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B671136

STATION QC-25

SERIAL SN2862647899

DECISION REVIEW

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT	
SEAT RAIL FIXING	21.25	54.30	31.08	Nm	PASS	
ENGINE WIRING HARNESS	7.57	26.47	13.81	deg	PASS	
REAR CAMERA MODULE	0.85	22.01	13.85	mm	PASS	
REAR CAMERA MODULE	15.48	43.18	15.78	deg	PASS	
REAR CAMERA MODULE	5.36	29.74	10.92	V	PASS	
REAR CAMERA MODULE	33.53	43.75	40.93	Nm	PASS	
REAR CAMERA MODULE	53.54	84.22	73.43	mm	PASS	
REAR CAMERA MODULE	54.04	73.69	68.35	deg	PASS	
ENGINE WIRING HARNESS	48.01	71.55	49.57	Nm	HOLD	
PARKING SENSOR	53.81	82.41	65.52	Nm	PASS	
BRAKE HOSE SUPPORT	51.49	75.21	60.50	deg	PASS	
FRONT AXLE BRACKET	16.26	29.10	18.38	deg	PASS	
SEAT RAIL FIXING	36.70	44.47	40.30	Nm	PASS	
AIRBAG CONTROL MODULE	14.09	41.52	19.50	Nm	PASS	
RIGHT SIDE PANEL	39.75	67.15	43.06	mm	PASS	
DOOR LOCK ASSEMBLY	10.72	19.34	18.63	deg	HOLD	
BATTERY SUPPORT	25.09	42.98	33.61	deg	PASS	
LOW	11.04	37.13	20.62	deg	PASS	
LOW	19.67	33.57	27.47	Nm	PASS	
RIGH	30.83	62.85	60.12	Nm	PASS	
BATTERY SUPPORT	10.71	37.91	22.25	Nm	PASS	
REAR CAMERA MODULE	33.80	57.37	36.75	V	PASS	
BRAKE HOSE SUPPORT	51.16	67.27	62.28	V	PASS	
PARKING SENSOR	32.11	63.26	45.04	mm	HOLD	



DATA MATRIX 010



QR CODE (https://)

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 480 943 78

Document: MXQD-043-1863

PAGE 43/60

DATE: 13/07/2026 22:33

CONTROL CERTIFICATE

CERTIFICATE OF CONFORMITY

PRODUCTION ORDER

PO-14465253

MODEL / VARIANT

K9-VU

SERIAL NUMBER

MX785354620942

INSPECTION PLAN

QP-71.1

DECISION

ACCEPTED

Inspection summary

			
		 CODE 128 LOT-415752-P43	 JE 39 MX-43-01-7541

Inspector signature:

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 871 780 24

Document: MXQD-045-9221

PAGE 45/60

DATE: 13/07/2026 19:44

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	PARKING SENSOR	RF-78561	L855258	OK
02	CLIMATE CONTROL UNIT	RF-65559	L880281	OK
03	CLIMATE CONTROL UNIT	RF-22801	L365983	REVIEW
04	SEAT RAIL FIXING	RF-62594	L217132	OK
05	AIRBAG CONTROL MODULE	RF-96421	L474666	OK
06	LOWER ARM FASTENER	RF-72683	L906833	OK
07	BATTERY SUPPORT	RF-33366	L833982	OK
08	REAR CAMERA MODULE	F-92662	L643868	REVIEW
09	LOWER ARM FASTENER	RF-47597	L721500	OK
10	LOWER ARM FASTENER	RF-35602	L811975	OK
11	SEAT RAIL FIXING	RF-99696	L784967	REVIEW
12	RIGHT SIDE PANEL	RF-69959	L880679	OK
13	PARKING SENSOR	RF-86921	L922490	OK
14	ENGINE WIRING HARNESS	RF-42747	L608302	OK
15	DOOR LOCK ASSEMBLY	RF-35524	L292950	OK
16	BATTERY SUPPORT	RF-41940	L291967	OK
17	ENGINE WIRING HARNESS			
18	DOOR LOCK ASSEMBLY			
19	ENGINE WIRING HARNESS			
20	FRONT AXLE BRACKET		L755334	REVIEW
21	SEAT RAIL FIXING		L444160	OK

SYNTHETIC MIXED QUALITY DOSSIER
Sequence: 571 357 31
Document: MXQD-046-4412

PAGE 46/60
DATE: 13/07/2026 21:42
FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Torque confirmed		Torque confirmed ☒ OK ☐ NOK ☐ N/A
	☐ OK ☐ NOK ☐ N/A	Reference matches order ☐ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Protective film removed ☐ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Gap within limit ☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A	Torque confirmed ☐ OK ☐ NOK ☐ N/A
Harness routing	☒ OK ☐ NOK ☐ N/A	Torque confirmed ☒ OK ☐ NOK ☐ N/A
Connector locked	☒ OK ☐ NOK ☐ N/A	No visible damage ☐ OK ☐ NOK ☐ N/A



SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 997 890 66
Document: MXQD-047-7886

PAGE 47/60

DATE: 13/07/2026 18:55

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B548992
STATION QC-21

SERIAL SN4125589789
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
DOOR LOCK ASSEMBLY	49.71	74.73	61.96	deg	PASS
RIGHT SIDE PANEL	40.15	55.68	51.12	Nm	PASS
LOWER ARM FASTENER	8.83	41.74	17.19	deg	PASS
CLIMATE CONTROL UNIT	17.04	49.49	38.53	V	PASS
BRAKE HOSE SUPPORT	19.58	37.96	33.47	deg	PASS
RIGHT SIDE PANEL	34.75	69.79	48.05	deg	HOLD
REAR CAMERA MODULE	39.65	54.48	53.27	Nm	PASS
CLIMATE CONTROL UNIT	43.65	53.92	46.27	V	HOLD
PARKING SENSOR	35.93	53.58	47.08	V	PASS
FRONT AXLE BRACKET	16.03	25.89	17.34	deg	PASS
RIGHT SIDE PANEL	34.73	58.93	46.53	deg	HOLD
SEAT RAIL FIXING	34.53	55.97	40.44	Nm	PASS
SEAT RAIL FIXING	40.59				
RIGHT SIDE PANEL	39.91			V	PASS
CLIMATE CONTROL UNIT	29.81	36.58	32.18	V	HOLD
BATTERY SUPPORT	43.10	60.27	48.98	Nm	PASS
				deg	PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 559 365 94
Document: MXQD-048-3809

PAGE 48/60

DATE: 13/07/2026 18:06

MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B940890
STATION QC-31

SERIAL SN5309398424
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
RIGHT SIDE PANEL	1.80	28.25	27.71	V	PASS
FRONT AXLE BRACKET	42.67	56.83	49.92	deg	PASS
FRONT AXLE BRACKET	23.23			deg	PASS
FRONT AXLE BRACKET	44.80			mm	HOLD
BRAKE HOSE SUPPORT	50.71	82.81	65.38	V	PASS
SEAT RAIL FIXING	37.74	63.87	61.66	mm	PASS
CLIMATE CONTROL UNIT	32.65	46.75	34.65	Nm	HOLD
PARKING SENSOR	44.53	56.02	47.80	Nm	PASS
DOOR LOCK ASSEMBLY	9.96	44.69	40.78	mm	PASS
AIRBAG CONTROL MODULE	34.00	49.96	38.97	mm	HOLD
DOOR LOCK ASSEMBLY	54.48	83.08	64.26	Nm	PASS
AIRBAG CONTROL MODULE	22.13	49.49	32.65	mm	PASS
LOWER ARM FASTENER	52.35	74.21	60.75	mm	HOLD
AIRBAG CONTROL MODULE	28.11	36.85	35.73	mm	PASS
BATTERY SUPPORT	7.74	28.53	10.57	Nm	PASS
DOOR LOCK ASSEMBLY	47.34	54.70	51.30	V	HOLD
PARKING SENSOR	4.23	24.62	22.64	V	PASS
AIRBAG CONTROL MODULE	22.46	66.28	53.14	Nm	PASS
ENGINE WIRING HARNESS	19.55	54.15	46.79	V	HOLD
REAR CAMERA MODULE	44.32	61.64	53.24	Nm	PASS
AIRBAG CONTROL MODULE	51.61	69.96	62.96	mm	PASS
ENGINE WIRING HARNESS	18.78	42.73	38.46	mm	HOLD
REAR CAMERA MODULE	7.82	42.41	32.72	mm	HOLD
DOOR LOCK ASSEMBLY	3.21	24.01	18.11	Nm	PASS

Sequence: 885 603 50

Document: MXQD-049-8678

PAGE 49/60

DATE: 13/07/2026 06:57

CONTROL CERTIFICATE



PRODUCTION ORDER

PO-26579440

MODEL / VARIANT

PX-STD

SERIAL NUMBER

MX142476961155

INSPECTION PLAN

QP-92.3

DECISION

ACCEPTED



CODE 39 MX-49-05-5900

Inspection summary



CODE 39 MX-49-01-3906



Inspector signature: _____

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 713 909 71

Document: MXQD-050-7488

PAGE 50/60

DATE: 13/07/2026 18:19

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	DOOR LOCK ASSEMBLY	RF-21409	L967022	REVIEW
02	REAR CAMERA MODULE	RF-30018	L253297	OK
03	PARKING SENSOR		L446479	
04	DOOR LOCK		L304345	
05	FRONT AXLE		L189657	
06	BRAKE HOSE SUPPORT		L705511	
07	CLIMATE CONTROL UNIT		L754660	
08	CLIMATE CONTROL UNIT		L820993	
09	BRAKE HOSE SUPPORT		L224394	
10	AIRBAG CONTROL MODULE		L147655	
11	FRONT AXLE BRACKET		L884169	
12	FRONT AXLE BRACKET		L635798	OK
13	CLIMATE CONTROL UNIT	RF-30926	L704197	OK
14	PARKING SENSOR	RF-85612	L619651	OK
15	BRAKE HOSE SUPPORT			
16	ENGINE WIRING HARNESS			
17	LOWER ARM FASTENER			REVIEW
18	REAR CAMERA MODULE			OK
19	ENGINE WIRING HARNESS			OK
20	SEAT RAIL FIXING			OK
21	SEAT RAIL FIXING	RF-21895	L165760	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 969 134 93

Document: MXQD-051-6814

PAGE 51/60

DATE: 13/07/2026 12:27

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Connector locked	☒ OK ☐ NOK ☐ N/A	Harness routing	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A
Surface condition	☐ OK ☐ NOK ☐ N/A	Gap within limit	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
No visible damage	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A
Protective film removed	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☐ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A	Connector locked *	☒ OK ☐ NOK ☐ N/A
Cover installed	☐ OK ☐ NOK ☐ N/A	Surface condition	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☐ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Cover installed	☒ OK ☐ NOK ☐ N/A	No visible damage	☒ OK ☐ NOK ☐ N/A



QR CODE: <https://example.invalid/mixed0516814282>

QR CODE: <https://example.invalid/mixed0516814282>

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 741 882 81

Document: MXQD-052-3062

PAGE 52/60

DATE: 13/07/2026 04:21

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL	FUNCTION / IDENTITY
Connector locked ☒ OK ☐ NOK ☐ N/A	Seal continuous  CODE 39 MX-52-04-8845 ☐ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Surface condition ☒ OK ☐ NOK ☐ N/A
Harness routing ☒ OK ☐ NOK ☐ N/A	Harness routing ☒ OK ☐ NOK ☐ N/A
Gap within limit ☒ OK ☐ NOK ☐ N/A	Cover installed ☐ OK ☐ NOK ☐ N/A
Surface condition ☒ OK ☐ NOK ☐ N/A	Fastener witness mark ☒ OK ☐ NOK ☐ N/A
Reference matches order ☒ OK ☐ NOK ☐ N/A	Connector locked ☒ OK ☐ NOK ☐ N/A
 CODE 128 MX0520142856224 ☒ OK ☐ NOK ☐ N/A	Label presence ☐ OK ☐ NOK ☐ N/A
 CODE 39 MX-52-03-8306 ☒ OK ☐ NOK ☐ N/A	Reference matches order  CODE 39 MX-52-05-5475 ☐ OK ☐ N/A
Seal continuous  CODE 128 PO99000560663 ☒ OK ☐ NOK ☐ N/A	Seal co ☒ OK ☐ NOK ☐ N/A
Cover inst ☒ OK ☐ NOK ☐ N/A	Label presence ☒ OK ☐ NOK ☐ N/A
Seal continuous ☒ OK ☐ NOK ☐ N/A	Seal continuous ☒ OK ☐ NOK ☐ N/A
Torque confirmed ☒ OK ☐ NOK ☐ N/A	Protective film removed ☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 331 736 70
Document: MXQD-053-5987

PAGE 53/60
DATE: 13/07/2026 09:17
MEASUREMENT AND TRACEABILITY

BATCH / CONTROL INFORMATION

BATCH B162550
STATION QC-25

SERIAL SN9719198169
DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
PARKING SENSOR	-2.20	16.91	1.82	Nm	PASS
RIGHT SIDE PANEL	47.69	73.42	71.35	mm	PASS
ENGINE WIRING HARNESS	10.89	32.53	27.44	deg	PASS
BRAKE HOSE SUPPORT	39.95	53.57	43.63	Nm	HOLD
AIRBAG CONTROL MODULE	19.69	24.24	21.05	V	HOLD
DOOR LOCK ASSEMBLY	32.91	38.20	33.36	deg	PASS
PARKING SENSOR	45.88	50.95	48.02	V	PASS
SEAT RAIL FIXING	48.46	65.85	49.90	Nm	PASS
REAR CAMERA MODULE	16.57	27.86	24.37	deg	PASS
REAR CAMERA MODULE	22.10	48.16	41.68	deg	PASS
DOOR LOCK ASSEMBLY	16.52	23.93	20.83	V	PASS
ENGINE WIRING HARNESS	0.38	13.46	10.47	mm	PASS
BRAKE HOSE SUPPORT	52.42	54.88	54.53	deg	PASS
AIRBAG CONTROL MODULE	48.41	81.73	78.44	mm	PASS
ENGINE WIRING HARNESS	7.07	25.81	22.56	Nm	PASS
ENGINE WIRING HARNESS	46.78	72.33	62.72	V	PASS
CLIMATE CONTROL UNIT	38.00	59.81	59.02	V	PASS
FRONT AXLE BRACKET	46.68	51.68	48.23	V	PASS
REAR CAMERA MODULE	49.42	84.73	61.62	V	PASS
CLIMATE CONTROL UNIT	44.19	73.42	68.63	deg	PASS
PARKING SENSOR	45.50	70.70	54.45	mm	PASS
BATTERY SUPPORT	50.35	63.80	63.34	mm	PASS
REAR CAMERA MODULE	4.27	25.78	14.06	deg	HOLD
DOOR LOCK ASSEMBLY	13.02	24.94	21.96	Nm	HOLD

Document: MXQD-054-9191

CONTROL CERTIFICATE

DECISION

ACCEPTED

CODE 128 LOT-468246-P54

CODE 128 LOT-468246-P5

Inspector signature: _____

QC
PASS

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 762 404 81

Document: MXQD-055-9393

PAGE 55/60

DATE: 13/07/2026 19:06

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	PARKING SENSOR	RF-75620	L188736	 CODE 128 LOT-663301-P55
02	PARKING SENSOR	RF-58550	L574891	
03	CLIMATE CONTROL UNIT	RF-28137	L153183	REVIEW
04	ENGINE WIRING HARNESS	RF-51426	L818309	OK
05	REAR CAMERA MODULE	 QR CODE: https://example.com/track/055-009	L371756	OK
06	SEAT RAIL FIXING		L388937	OK
07	BRAKE HOSE SUPPORT		L364551	OK
08	AIRBAG CONTROL MODULE		L796406	OK
09	DOOR LOCK ASSEMBLY	RF-18826	 CODE 39 MX-55-01-7525	OK
10	REAR CAMERA MODULE	RF-13456		REVIEW
11	ENGINE WIRING HARNESS	RF-85763	L211611	OK
12	PARKING SENSOR	RF-67840	L998491	OK
13	FRONT AXLE BRACKET	RF-24751	L645821	OK
14	BATTERY SUPPORT	RF-36771	L594430	OK
15	DOOR LOCK ASSEMBLY	RF-11226	L142728	OK
16	ENGINE WIRING HARNESS	RF-36168	L630503	OK
17	BATTERY SUPPORT	RF-37375	L694591	OK
18	BATTERY SUPPORT	RF-36043	L441111	OK
19	RIGHT SIDE PANEL	RF-97216	L304012	OK
20	FRONT AXLE BRACKET	RF-15148	L113195	OK
21	FRONT AXLE BRACKET	RF-78320	L450145	OK

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 732 504 88

Document: MXQD-056-6878

PAGE 56/60

DATE: 13/07/2026 09:37

COMPONENT TRACEABILITY LOG

REFERENCE / LOT / VALIDATION RECORD

STEP	COMPONENT / OPERATION	REFERENCE	LOT	STATUS / NOTE
01	CLIMATE CONTROL UNIT	RF-70599	L816092	OK
02	ENGINE WIRING HARNESS	RF-37974	L156287	OK
03	CLIMATE CONTROL UNIT	RF-65988	L274453	OK
04	PARKING SENSOR	RF-58343	L405152	OK
05	FRONT AXLE BRACKET	RF-79963	L433484	OK
06	REAR CAMERA MODULE	RF-66850	L857887	OK
07	CLIMATE CONTROL UNIT	RF-66883	L788275	REVIEW
08	BATTERY SUPPORT	RF-69233	L766452	OK
09	BRAKE HOSE SUPPORT	RF-43454	L507332	REVIEW
10	BATTERY SUPPORT	RF-67873	L776052	OK
11	RIGHT SIDE PANEL	RF-66696	L255913	OK
12	PARKING SENSOR	RF-40473	L983920	OK
13	FRONT AXLE BRACKET	RF-81876	L310039	OK
14	ENGINE WIRING HARNESS	RF-42941	L369557	OK
15	SEAT RAIL FIXING	RF-86594	L351053	OK
16	AIRBAG CONTROL MODULE	RF-72414	L143896	REVIEW
17	BRAKE HOSE SUPPORT	RF-72491	L260297	OK
18	RIGHT SIDE PANEL	RF-28578	L780427	OK
19	FRONT AXLE BRACKET	RF-29174	L770129	REVIEW
20	LOWER ARM FASTENER	RF-55527	L633754	OK
21	ENGINE WIRING HARNESS	RF-11896	L969551	OK



DATA MATRIX: 010950600027395

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 450 908 28

Document: MXQ: 057-8074

PAGE 57/60

DATE: 13/07/2026 06:54

FINAL INSPECTION CHECKLIST

VISUAL / DIMENSIONAL		FUNCTION / IDENTITY	
Protective film removed	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☒ OK ☐ NOK ☐ N/A
Connector locked	☐ OK ☐ NOK ☐ N/A	Connector locked	☒ OK ☐ NOK ☐ N/A
Surface condition	☒ OK ☐ NOK ☐ N/A	Reference matches order	☒ OK ☐ NOK ☐ N/A
Gap within limit	☐ OK ☐ NOK ☐ N/A	Seal continuous	☒ OK ☐ NOK ☐ N/A
No visible damage	 CODE 128 PO58346999914	matches order	☒ OK ☐ NOK ☐ N/A
Label presence	☒ OK ☐ NOK ☐ N/A	Fastener witness mark	☒ OK ☐ NOK ☐ N/A
Fastener witness mark	☒ OK ☐ NOK ☐ N/A		☒ OK ☐ NOK ☐ N/A
Seal continuous	☒ OK ☐ NOK ☐ N/A		☒ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Cover installed	☒ OK ☐ NOK ☐ N/A
Reference matches order	☐ OK ☐ NOK ☐ N/A	Harness routing	☒ OK ☐ NOK ☐ N/A
Reference matches order	☒ OK ☐ NOK ☐ N/A	Torque confirmed	☐ OK ☐ NOK ☐ N/A
Torque confirmed	☒ OK ☐ NOK ☐ N/A	Label presence	☒ OK ☐ NOK ☐ N/A

SYNTHETIC MIXED QUALITY DOSSIER

Sequence: 676 110 87

Document: MXQD-058-4245

BATCH / CONTROL INFORMATION

BATCH B402550

STATION QC-26

SERIAL SN1172932423

DECISION OK

CHARACTERISTIC	LOW	HIGH	VALUE	UNIT	RESULT
ENGINE WIRING HARNESS	4.75	33.95	20.02	Nm	PASS
FRONT AXLE BRACKET	21.38	52.16	42.89	Nm	PASS
LOWER ARM FAST	35.30	57.98	56.94		HOLD
BRAKE HOSE SUPP	-2.88	11.49	11.00		PASS
SEAT RAIL FIXING	38.11	43.11	41.06		HOLD
DOOR LOCK ASSEMBLY	48.24	80.88	69.84		HOLD
PARKING SENSOR	16.72		38.95	V	PASS
FRONT AY					PASS
SEAT RAIL					HOLD
DOOR LO					
ENGINE WIRING HARNESS	31.30	44.25			
BRAKE HOSE SUPPORT	24.12	47.42			
RIGHT SIDE PANEL	8.39	30.08			PASS
AIRBAG CONTROL MODULE	26.66	47.15			PASS
LOWER ARM FASTENER	41.06	60.33			PASS
AIRBAG CONTROL MODULE	-0.09	14.53			PASS

Sequence: 517 946 72

Document: MXQD-059-3646

PAGE 59/60

DATE: 13/07/2026 06:21

CONTROL CERTIFICATE

PRODUCTION ORDER PO-92110526

PO-92110526

MODEL / VARIANT MX-A7

MX-A7

SERIAL NUMBER MX287783733046

MX287783733046

INSPECTION PLAN QP-22.4

QP-22.4

DECISION

CONDITIONAL

CONDITIONAL

Inspection summary

[illegible]

Inspector signature: _____

QC
PASS

Sequence: 849 219 28
Document: MXQD-060-7768

DATE: 13/07/2026 15:59

CONTROL CERTIFICATE

PRODUCTION ORDER

MODEL / VARIANT PX-STD

SERIAL NUMBER

MX449420999525

INSPECTION PLAN QP-52.7

DECISION

ACCEPTED

Inspector signature: _____

QC
PASS