Radiographic Examination Report

Meridian NDT Services (fictional) | Document no. RT-2230

Report no.	RT-2230
Client / project	Northfield Refining - Crude Hydrotreater Unit
Lot / spool	LOT 24-117 / SPOOL-04
Weld ID	W01
Drawing	B313-SPOOL-04 rev C
Code / acceptance	ASME B31.3 normal fluid service, Level 1
Method / coverage	RT, 100 %
Source / technique	Ir-192, single wall single image
Film / IQI	RT-2230-F1..F3 / ISO 12 FE
Examination date	10/10/2026
Result	**ACCEPT - no relevant indication**

Authorised signatory	*J. Moreau*
Role	NDT Level II interpreter
Date	10/10/2026

SYNTHETIC DOCUMENT - generated for software testing - not a real certificate or record