

		NLNG PROJECTS		Doc No: Rev: 00
		DAILY SURVEILLANCE REPORT		Ref Doc.: 18.019-E-0018
				REPORT NO: EGSL-QSU-039
CLIENT: NLNG	JOB NO. 18/MOC/PDR/019P	LOCATION: IA SOUTH-SIDE INFRASTRUCTURE PHASE II		DATE: 18.02.2025
DESCRIPTION OF EVENTS 1. Inspection for concrete placement on drainage 2. Inspection for tape placement before sealant application				
Manpower: 80				
 2025/02/18 14:03				
1. Inspection for concrete placement on drainage		2. Inspection for tape placement before sealant application		
Concerns and Proposed Corrections:				
INITIATOR NAME:				
Photo Attachment: YES				
QAQC				
NAME: NWOHA VICTOR SIGNATURE:  DATE: 18/02/2025				

