

# INSPECTION AND TEST PLAN FOR RA FLOORING FOR HOSPITAL AND SCHOOL

## CONTRACT NO: B250117ESD

|                                                                                                                                                                                                                                                                      |                                                                                               |                                                                                     |                                                                                     |                                                                                                                                                                                  |              |                           |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|---------------------------|
|                                                                                                                                                                                                                                                                      |                                                                                               |  |  |                                                                                               |              |                           |
| A                                                                                                                                                                                                                                                                    | 24-02-26                                                                                      | F. KPAKUE                                                                           | A. OKOSUN                                                                           | O. ESIEVO                                                                                                                                                                        |              | APPROVED FOR CONSTRUCTION |
| OA                                                                                                                                                                                                                                                                   | 20-02-26                                                                                      | F. KPAKUE                                                                           | A. OKOSUN                                                                           | O. ESIEVO                                                                                                                                                                        |              | ISSUED FOR APPROVAL       |
| O                                                                                                                                                                                                                                                                    | 12-01-26                                                                                      | F. KPAKUE                                                                           | A. OKOSUN                                                                           | O. ESIEVO                                                                                                                                                                        |              | ISSUED FOR REVIEW         |
| ISSUE                                                                                                                                                                                                                                                                | DATE                                                                                          | BY                                                                                  | CHKD                                                                                | APPD                                                                                                                                                                             | CLIENT APP.  | DESCRIPTION               |
| WHEN REVISION HAVE BEEN MADE TO THIS DOCUMENT THE INDEX OF ISSUE SHALL BE INDICATED IN A TRIANGLE NEAR THE PART(S) CONCERNED                                                                                                                                         |                                                                                               |                                                                                     |                                                                                     |                                                                                                                                                                                  |              |                           |
| <b>CLASSIFICATION:</b> MOST CONFIDENTIAL <input type="checkbox"/> CONFIDENTIAL <input type="checkbox"/> RESTRICTED <input type="checkbox"/> UNRESTRICTED <input checked="" type="checkbox"/>                                                                         |                                                                                               |                                                                                     |                                                                                     |                                                                                                                                                                                  |              |                           |
| This document is confidential. The copyright therein is vested in Nigeria LNG Ltd. Recipients must obtain the written authority of the said company before wholly or partly duplicating these contents or disclosing the same to others.<br><br>All rights reserved. |                                                                                               |                                                                                     |                                                                                     |  <b>REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL</b><br><b>CONTRACT NO: B250117ESD</b> |              |                           |
| DISCIPLINE: QUALITY                                                                                                                                                                                                                                                  |                                                                                               |                                                                                     |                                                                                     | Project No: B250117ESD                                                                                                                                                           |              |                           |
| LOCATION: BONNY ISLAND, NIGERIA                                                                                                                                                                                                                                      |                                                                                               |                                                                                     | AREA: RA                                                                            |                                                                                                                                                                                  | PAGE 1 OF 15 |                           |
| UNIT:<br>8500                                                                                                                                                                                                                                                        | NIGERIA LNG LTD<br><br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |                                                                                     |                                                                                     | DOC NO: N/A                                                                                                                                                                      |              | REV: A                    |
|                                                                                                                                                                                                                                                                      |                                                                                               |                                                                                     |                                                                                     | CONTRACTOR DOC. NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                                                                                                                  |              |                           |

**REVISION LOG**

| <b><u>REVISION</u></b> | <b><u>DATE</u></b> | <b><u>PAGES</u></b> | <b><u>REMARKS</u></b>     |
|------------------------|--------------------|---------------------|---------------------------|
| O                      | 12/01/26           | NIL                 | ISSUED FOR REVIEW         |
| OA                     | 20/02/26           | 5,8 & 11            | ISSUED FOR REVIEW         |
| A                      | 24/02/26           | NIL                 | APPROVED FOR CONSTRUCTION |

**APPROVAL TABLE**

| <b><u>Key For Inspection Levels:</u></b>                                                                                                                   | <b>All QC Activities are complete and Item ready for operation</b> |                 |                                                                                                                                                                         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|-----------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| H=Mandatory Hold Point<br>W= Witness (Mandatory Notification)<br><br>S= Sample Inspection      T= Test<br>R= Review Records        V= Visual<br>M= Monitor | EGSL- Executor                                                     | Fortune Kpakue  | Signature: _____ Date: _____                                                                                                                                            |
|                                                                                                                                                            | NLNG                                                               | Ekeneme.Patrick | Signature:  Signed by: _____<br>Date: 24/2/2026<br><small>A0CC664047924B8...</small> |

REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL



LOCATION: BONNY ISLAND, NIGERIA

AREA: RA

PROJECT NO: **B250117ESD**UNIT:  
6500
 NIGERIA LNG LTD  
**INSPECTION AND TEST PLAN FOR RA FLOORING OF  
HOSPITAL AND SCHOOL**

PAGE 2 of 14

DOC NO: N/A

Rev: A

CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005



**TABLE OF CONTENTS**

1. INTRODUCTION ..... 4

1.1 PROJECT OVERVIEW..... 4

1.2 SCOPE OF WORK ..... 4

2. NORMATIVE REFERENCE ..... 5

3. DEFINITIONS AND ABBREVIATIONS ..... 5

4. INSPECTION INTERVENTION NOTIFICATION ..... 6

4.1 Quality codes ..... 6

4.2 SIGN-OFF/APPROVAL..... 6

5. LIST OF QA/QC FORMS..... 7

6. INSPECTION AND TEST PLAN FOR WORKS ..... 8

|                                                     |                                                                                               |          |                                                                                       |        |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                               |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                               | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> |          | PAGE 3 of 14                                                                          |        |
|                                                     |                                                                                               |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                                               |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |



1. INTRODUCTION

Nigeria LNG Limited (NLNG), a leading producer of Liquefied Natural Gas (LNG), operates a world-class Plant Complex located on Bonny Island, Rivers State, Nigeria. The facility currently comprises six (6) operational Natural Gas Liquefaction trains with a total production capacity of twenty-two (22) million tonnes of LNG and five (5) million tonnes of Natural Gas Liquids (NGL) per annum. The plant includes comprehensive gas receiving, treating, storage, and loading infrastructure. Expansion works are ongoing to deliver a seventh train, with construction activities already at an advanced stage.

As part of the broader infrastructure upgrades to support the increasing demands of the Non-Plant Asset Rehabilitation Program and improve the overall quality of life within the NLNG Residential Area (RA), specific attention has been given to the Refurbishment of the Racetracks in the RA Sports Complex and the Refurbishment of the Floors in the RA Hospital and School. These projects aim to enhance recreational, health, and educational facilities for staff and residents. The refurbishment works are crucial in addressing wear and deterioration due to high usage over the years, and they align with NLNG’s commitment to operational excellence, health, safety, and environmental (HSE) standards.

By prioritizing these internal infrastructure improvements, NLNG ensures that the residential area remains conducive, safe, and fit-for-purpose for both work and family life, especially considering the growing population brought about by the influx of workers and contractors associated with the Non-Plant Asset Rehabilitation Program and related community development initiatives.

1.1 PROJECT OVERVIEW

This scope of work covers the Refurbishment of the Racetracks in NLNG RA Sports Complex and Refurbishment of the Floors of RA Hospital and School. This is part of the Non-Plant Asset Rehabilitation Program (NPARP), which is implementing an integrated plan to rehabilitate and restore NLNG non-plant assets. This program will restore standardized care strategy, keep evergreen, improve customer satisfaction, restore safe environment to live in & work, and preserve value.

The main objective of this project is to reconstruct the existing racetrack to enable it to meet the global standard for general field athletics, daily training, as well as for staging regional or local competitions, both in-company or with external parties or companies. This project therefore seeks to close the identified gaps and reduce the risks associated with the continuous maintenance, slips, trip hazards, and to ensure clean, safe, durable, and credible facilities that meet up the global practices and standards as well as aesthetics. The same objectives also apply to the refurbishment of the floors of the RA Hospital and School.

1.2 SCOPE OF WORK

|                                                     |                                                                                               |          |                                                                                       |        |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                               |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                               | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> |          | PAGE 4 of 14                                                                          |        |
|                                                     |                                                                                               |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                                               |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |



The project scope shall be the Refurbishment of the Floors in the RA Hospital and Ra international School. These include:


**REFURBISHMENT OF RA HOSPITAL AND SCHOOL**

a) Demolition/Clearance

- Careful stripping of existing floor surfacing Waste/debris generated to be carted away from the site by the contractor.
- Surface preparation as per OEM recommendation to receive the self-leveling screed.
- Application of primer Eurocol 0-441, adhering to project specifications and OEM recommendations.
- Application of Eurocol 640 adhesive bonding agent following OEM recommendation and instruction.
- Installation of project approved PVC floors covering sheet (tiles).

**2. NORMATIVE REFERENCE**

- |                                |                                         |
|--------------------------------|-----------------------------------------|
| • EGSL-NLNG-RRFHS-QA-PLN-5001  | Quality Control Plan                    |
| • B250117ESD                   | REFURBISHMENT OF RA HOSPITAL AND SCHOOL |
| • ISO 9001:2015                | Quality Management Systems requirements |
| • EGSL-NLNG-RRFHS-CIV-MST-5000 | Method Statement for Civil works        |
| • DEP 34.11.00.11 – Gen.       | Site Preparations and Earthworks        |
| • BS 6031                      | Code of Practice for Earthworks.        |
| • Din EN 13813                 | European standard for Screed material   |



**3. DEFINITIONS AND ABBREVIATIONS**

- |                          |                                                                                 |
|--------------------------|---------------------------------------------------------------------------------|
| • <b>Contractor:</b>     | Evomec Global Services Limited                                                  |
| • <b>Company/Client:</b> | Nigeria LNG Limited (NLNG)                                                      |
| • <b>Project:</b>        | Refurbishment of the Floors of R.A Hospital and School                          |
| • <b>Record:</b>         | Document stating results achieved or providing evidence of activities performed |
| • <b>AFC</b>             | Approved for Construction                                                       |
| • <b>API</b>             | American Petroleum Institute                                                    |
| • <b>BM</b>              | Benchmark                                                                       |
| • <b>DEP</b>             | Design and Engineering Practice.                                                |
| • <b>EN</b>              | European Standards (Eurocode)                                                   |
| • <b>EPC</b>             | Engineering, Procurement, and Construction                                      |
| • <b>GPS</b>             | Global Positioning System                                                       |
| • <b>HSE</b>             | Health, Safety, and Environment                                                 |



|                                                     |                                                                        |          |                                                                                       |        |
|-----------------------------------------------------|------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                        |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                        | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD                                                        |          | PAGE 5 of 14                                                                          |        |
|                                                     | <b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                        |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |

- **ISO** International organization for standardization
- **ITP:** Inspection and Test Plan
- **LNG** Liquefied Natural Gas
- **NLNG** Nigeria Liquefied Natural Gas
- **QA/QC** Quality Assurance & Quality Control
- **QMS** Quality Management System
- **RFI** Request for Inspection
- **Site:** The site locations where WORK is to be performed
- **TBM** Temporary Benchmark
- **Third party:** Independent body besides the contractor and client.
- **TS** Total Station

#### 4. INSPECTION INTERVENTION NOTIFICATION

##### 4.1 Quality codes

The following codes in the table below shall be adopted to ensure quality control during earthworks.

HOLD POINT = H = Mandatory Hold Point.

This is a mandatory notification to NLNG. All activities at this level must not proceed without the approval of the NLNG inspection/Project team.

WITNESS = W = Witness Inspection Point

A prior notification to NLNG is mandatory. All activities at this level may proceed by EGSL, whose responsibility is to execute the scope of work. If NLNG is not present at the stipulated time, provided there is no rescheduling or cancellation from NLNG.

REVIEW = R = Record Review.

This point is used for review of documents, drawings, or records for the works being performed and/or carried out. Notification is not required.

INSPECTION = I = Random Inspection.

An inspection where Evomec Global Services Limited and NLNG plan to audit, monitor, or witness the activity in process at random or periodic basis. Notification is not required.

INSPECTION = S = Surveillance Point.

A designated place or activity where a process requires extra care or control without interruption, and the process continues without stoppage.

##### 4.2 SIGN-OFF/APPROVAL

|                                                     |                                                                                               |          |                                                                                       |        |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                               |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                               | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> |          | PAGE 6 of 14                                                                          |        |
|                                                     |                                                                                               |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                                               |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |



Witness Point shall be signed off by EGSL and NLNG. However, if NLNG is absent, they will be required to sign afterward, as where applicable, and it will be indicated on the form as reviewed, meaning that the NLNG Rep was not physically present at the time of test inspection.

5. LIST OF QA/QC FORMS

- EGSL-FORM-250 – INSPECTION REPORT OF FLOORING WORKS (SELF LEVELLING)
- EGSL-CIV-CKL-018 – SURFACE PREPARATION CHECKLIST
- EGSL-FORM-251 – INSPECTION REPORT OF LAYING OF FORBO VINYL SHEETS AND WELDING ACTIVITIES

|                                                     |                                                                                               |          |                                                                                       |        |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                               |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                               | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> |          | PAGE 7 of 14                                                                          |        |
|                                                     |                                                                                               |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                                               |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |



## 6. INSPECTION AND TEST PLAN FOR RA HOSPITAL AND SCHOOL FLOORING

| INSPECTION AND TEST PLAN                                                           |                                                                                                                                             |                                  |                                |                                                                                                |                                          |                               |                                                                                                                                                                                                                                                                                                                                     |
|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|--------------------------------|------------------------------------------------------------------------------------------------|------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Title of ITP: <b>INSPECTION AND TEST PLAN FOR RA HOSPITAL AND SCHOOL FLOORING.</b> |                                                                                                                                             | Date: <b>08/07/2025</b>          | INSPECTION AND TEST PLAN       |                                                                                                |                                          | Location: <b>BONNY ISLAND</b> |                                                                                                                                                                                                                                                                                                                                     |
| Project: <b>REFURBISHMENT OF THE FLOORS OF RA HOSPITAL AND SCHOOL</b>              |                                                                                                                                             |                                  |                                |                                                                                                |                                          | Doc No:                       |                                                                                                                                                                                                                                                                                                                                     |
|                                                                                    |                                                                                                                                             |                                  |                                |                                                                                                | Inspection Level and Verification Record |                               |                                                                                                                                                                                                                                                                                                                                     |
| Activity No                                                                        | Description of Operation Activity                                                                                                           | Controlling Procedures/ Document | Acceptance Criteria/Reference  | Quality Records to be used to verify compliance                                                | Involvement                              |                               | Remarks                                                                                                                                                                                                                                                                                                                             |
|                                                                                    | Activity Description:                                                                                                                       |                                  |                                |                                                                                                | EGSL                                     | NLNG                          |                                                                                                                                                                                                                                                                                                                                     |
| 1.0                                                                                | DOCUMENTATION                                                                                                                               |                                  |                                |                                                                                                | Inspection level                         |                               |                                                                                                                                                                                                                                                                                                                                     |
| 1.1                                                                                | Check all drawings, specifications, and method statements approved for AFC                                                                  | Project Approved MDR             | Project Approved MDR           | Conformance reports                                                                            | H                                        | R                             | All project drawings and specifications must be approved for construction with latest revision                                                                                                                                                                                                                                      |
| 1.2                                                                                | Check the calibration status of all tests and measuring equipment, laboratory, etc.                                                         | GFS IG.34.85.22-Gen              | Control of measuring equipment | Third party calibration certificate. Status checklist                                          | H                                        | R                             | All measuring and test equipment shall have a valid calibration certificate                                                                                                                                                                                                                                                         |
| 2.0                                                                                | MATERIAL RECEIVING/ VERIFICATION INSPECTION                                                                                                 |                                  |                                |                                                                                                |                                          |                               |                                                                                                                                                                                                                                                                                                                                     |
| 2.1                                                                                | Quality check shall be carried out for acceptance or rejection on project supplied materials to verify compliance with Quality requirements | DEP 34.17.10.32                  | DEP 34.17.10.32                | Material Receiving Inspection Report (MRIR)<br>Data Sheet<br>Manufacturer material certificate | R                                        | R                             | <b>FOR EVERY PROJECT MATERIAL SUPPLIED AT SITE</b> <ul style="list-style-type: none"> <li>Provide Supplier/ Manufacturer's Material Certificates of test / Compliance/ Analysis</li> <li>Verify Quality and Quantity of materials supplied as per P.O / Waybill</li> <li>Packing List and other applicable documentation</li> </ul> |

|                                                     |                                                                        |          |                                            |  |
|-----------------------------------------------------|------------------------------------------------------------------------|----------|--------------------------------------------|--|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                        |          |                                            |  |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                        | AREA: RA | PROJECT NO: <b>B250117ESD</b>              |  |
| UNIT:<br>6500                                       | <b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |          | PAGE 8 of 14                               |  |
|                                                     |                                                                        |          | DOC NO: N/A      Rev: A                    |  |
|                                                     |                                                                        |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005 |  |





|            |                                                                                                                                                    |                                                                                   |                                                                                              |                  |          |            |                                                                                                             |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------|------------------|----------|------------|-------------------------------------------------------------------------------------------------------------|
| <b>2.0</b> | <b>SUBSTRUCTURE SURFACE PREPARATION</b>                                                                                                            |                                                                                   |                                                                                              |                  |          |            |                                                                                                             |
| <b>2.1</b> | Check surface profile, firmness, dryness, & cleanliness, confirm that the surface is dust-free and correct levelling and with square edge to kerbs | Method Statement                                                                  | Specification<br>DIN EN 13813: CT-C30-F10-A1.OEM installation instruction                    | EGSL-CIV-CKL-018 | <b>H</b> | <b>W/M</b> | Ensure the surface preparation meet OEM recommended standard                                                |
| <b>2.2</b> | Moisture content testing<br>Confirm the substrate is dry to the moisture content recommended by the Epoxy manufacturer                             | Method Statement                                                                  | Project Specification, DIN EN 13813: CT-C30-F10-A1.                                          | EGSL-CIV-CKL-018 | <b>H</b> | <b>W/M</b> |                                                                                                             |
| <b>3.0</b> | <b>INSTALLATION OF PROJECT FLOORING MATERIAL</b>                                                                                                   |                                                                                   |                                                                                              |                  |          |            |                                                                                                             |
| <b>3.1</b> | Application of EUROCOL 975 (Self-leveling Screed)                                                                                                  | Project Specification:<br>DIN EN 13813: CT-C30-F10-A1 OEM recommendation          | Project Specification:<br>DIN EN 13813: CT-C30-F10-A1.OEM surface preparation recommendation | EGSL-FORM-250    | <b>H</b> | <b>M/H</b> | Ensure the screed surface meet recommendation thickness (5-10mm)                                            |
| <b>3.2</b> | Application of EUROCOL 044-1 (EUOPRIMER MULTI PLUS)                                                                                                | Project Specification<br>OEM mix ratio and Application method                     | Project Specification<br>OEM mix ratio and Application method                                | EGSL-FORM-250    | <b>H</b> | <b>M/H</b> | Ensure that application of the Europrimer is as per manufacturer recommendation and project specification.  |
| <b>3.3</b> | Application of EUROCOL 640 (EUROSTAR SPECIAL)                                                                                                      | GEV-EMICODE EC 1PLUS, EN 13999-2/4. OEM application method. Project Specification | GEV-EMICODE EC 1PLUS, EN 13999-2/4.OEM application method. Project Specification             | EGSL-FORM-250    | <b>H</b> | <b>H/M</b> | Ensure that application of the Eurocol 640 is as per manufacturer recommendation and project specification. |
| <b>3.4</b> | INSTALLATION OF FORBO VINYL PVC FLOORS(TILE)                                                                                                       | OEM application method. Project Specification                                     | OEM application method. Project Specification                                                | EGSL-FORM-251    | <b>H</b> | <b>M/W</b> | Ensure surface meets requirement for top layer.                                                             |

|                                                     |                                                                                           |          |                                            |        |
|-----------------------------------------------------|-------------------------------------------------------------------------------------------|----------|--------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                           |          |                                            |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                           | AREA: RA | PROJECT NO: <b>B250117ESD</b>              |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |          | PAGE 9 of 14                               |        |
|                                                     |                                                                                           |          | DOC NO: N/A                                | Rev: A |
|                                                     |                                                                                           |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005 |        |



|                                                                                                                                                                                                                            |                                                                  |            |       |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|------------|-------|
| <b>Key For Inspection Levels:</b><br>H = Mandatory Hold Point (Do Not proceed without Signature)<br>W = Witness (Mandatory Notification)<br><br>S = Sample Inspection R = Review Records T = Test<br>M = Monitor V= Visual | All QAQC Activities are Complete and Item is Ready for Operation |            |       |
|                                                                                                                                                                                                                            | EGSL REP<br>Name                                                 | Signature: | Date: |
|                                                                                                                                                                                                                            | NLNG REP<br>Name                                                 | Signature: | Date  |

|                                                     |                                                                                               |                                            |                                                                                       |        |
|-----------------------------------------------------|-----------------------------------------------------------------------------------------------|--------------------------------------------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                               |                                            |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                               | AREA: RA                                   | PROJECT NO: <b>B250117ESD</b>                                                         |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> | PAGE 10 of 14                              |                                                                                       |        |
|                                                     |                                                                                               | DOC NO: N/A                                |                                                                                       | Rev: A |
|                                                     |                                                                                               | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005 |                                                                                       |        |

|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|----|------------|----------------------|----|------------|-----------------------------|----|-------|--|
|   | REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |    |            |                      |    |            | DOC. No.: EGSL-FORM-QC-22F1 |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            | REV.                        |    | DATE: |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            | PAGE 1 of 1                 |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            | REF. DOC.                   |    |       |  |
| QC CODE:                                                                                                                                                            |                                                     |    |            |                      |    | REPORT No: |                             |    |       |  |
| PLACE:                                                                                                                                                              |                                                     |    |            |                      |    |            |                             |    |       |  |
| DWG/CHART / SPECIFICATION:                                                                                                                                          |                                                     |    |            |                      |    |            |                             |    |       |  |
| ITEM / EQUIPMENT / MATERIAL                                                                                                                                         |                                                     |    |            |                      |    |            |                             |    |       |  |
| AS-BUILT OF PIONTS                                                                                                                                                  |                                                     |    |            |                      |    |            |                             |    |       |  |
| MONITORING POINT ID                                                                                                                                                 | DESIGN COORDINATES                                  |    |            | AS-BUILT COORDINATES |    |            | DIFFERENCES                 |    |       |  |
|                                                                                                                                                                     | EN                                                  | NE | Z          | EN                   | NE | Z          | dE                          | dN | dZ    |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
|                                                                                                                                                                     |                                                     |    |            |                      |    |            |                             |    |       |  |
| PREPARED BY:                                                                                                                                                        |                                                     |    |            |                      |    |            |                             |    |       |  |
| Construction CTR/SCTR QC                                                                                                                                            |                                                     |    | EVOME QC   |                      |    | NLNG       |                             |    |       |  |
| NAME:                                                                                                                                                               |                                                     |    | NAME:      |                      |    | NAME:      |                             |    |       |  |
| SIGNATURE:                                                                                                                                                          |                                                     |    | SIGNATURE: |                      |    | SIGNATURE: |                             |    |       |  |
| Date:                                                                                                                                                               |                                                     |    | Date:      |                      |    | Date:      |                             |    |       |  |

|                                                     |                                                                                           |          |                                                                                       |        |
|-----------------------------------------------------|-------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|--------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                           |          |  |        |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                           | AREA: RA |                                                                                       |        |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |          | PROJECT NO: <b>B250117ESD</b>                                                         |        |
|                                                     |                                                                                           |          | PAGE 11 of 14                                                                         |        |
|                                                     |                                                                                           |          | DOC NO: N/A                                                                           | Rev: A |
|                                                     |                                                                                           |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |        |

**PROJECT TITLE: REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL****PROJECT NUMBER:****CONTRACTOR:****CONSTRUCTION QUALITY CONTROL**

Contract No.:

Project No.:

Form No. EGSL-CIV-CKL-018

Rev. No.:

Report No.: \_\_\_\_\_

**Surface Preparation Checklist**

Date

Time:

Destination (AREA):

Structure Name :

Drawing No. :

| No. | Description of QC Activity                                                                                                                                                           | Inspection result and Signature/Date |                  |           |                |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------|-----------|----------------|
|     |                                                                                                                                                                                      | Contractor QC                        |                  | AGPC Rep. |                |
|     |                                                                                                                                                                                      | Result                               | Signature / Date | Result    | Signature Date |
| 1   | Substrate inspection<br>- Subfloor structurally sound and stable.<br>- No loose, hollow, or weak areas<br>- No visible cracks (or cracks properly repaired).                         |                                      |                  |           |                |
| 2   | Moisture & Surface Cleaning Check<br>- Verify Surface is dry (no rising damp) and clean<br>- Verify surface is from dust, oil, contaminates and grease.                              |                                      |                  |           |                |
| 3   | Priming (EUROCOL 044-1)<br>- Verify correct primer selected for substrate type<br>- Verify primer applied evenly<br>- No puddling of primer<br>- Primer fully dried before levelling |                                      |                  |           |                |

&lt;Legend&gt; A: Acceptable, UA : Un Acceptable, RR : Repair Required, N/A : Not Applicable

Remarks:

**SURFACE REPAIR (if required)**

Description of Repair:

Signed :  
Contractor Construction

Name :

Date :

Signed :  
Contractor QA/QC

Name :

Date :

Signed :  
NLNG Representative

Name :

Date : \_\_\_\_\_

REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL



LOCATION: BONNY ISLAND, NIGERIA

AREA: RA

PROJECT NO: **B250117ESD**UNIT:  
6500

NIGERIA LNG LTD  
**INSPECTION AND TEST PLAN FOR RA FLOORING OF  
HOSPITAL AND SCHOOL**

PAGE 12 of 14

DOC NO: N/A

Rev: A

CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005

|   | <b>REFURBISHMENT OF RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b><br><br><b>INSPECTION REPORT OF FLOORING WORKS<br/>(SELF LEVELLING APPLICATION)</b> | Doc. no: EGSL-FORM- CIV-250-A<br>REV.      Date:<br>PAGE 1 of 1<br>REF. DOC: |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>REPORT No:</b>                                                                                                                                                   |                                                                                                                                                   |                                                                              |
| <b>PLACE:</b>                                                                                                                                                       |                                                                                                                                                   |                                                                              |
| <b>DWG/CHART / SPECIFICATION:</b>                                                                                                                                   |                                                                                                                                                   |                                                                              |
| <b>ITEM / EQUIPMENT / MATERIAL</b>                                                                                                                                  |                                                                                                                                                   |                                                                              |
| <b>MEASURING DEVICE TYPE AND TRACEABILITY:</b>                                                                                                                      |                                                                                                                                                   |                                                                              |
| S/No.                                                                                                                                                               | Description of QC Activities                                                                                                                      | INSPECTION RESULT & SIGNATURE/DATE                                           |
|                                                                                                                                                                     |                                                                                                                                                   | EVOMEK QC      NLNG QC                                                       |
|                                                                                                                                                                     |                                                                                                                                                   | Result      Signature/Date      Result      Signature/Date                   |
| 1                                                                                                                                                                   | Confirm material inspection meet project requirement and fit for purpose.                                                                         |                                                                              |
| 2                                                                                                                                                                   | Check approved installation location is as per project scope.                                                                                     |                                                                              |
| 3                                                                                                                                                                   | Check surface preparation as per project requirement, free from debris, oil, wet, dust and dirty.                                                 |                                                                              |
| 4                                                                                                                                                                   | Check application of Primer (EUROCOL 044-1) is as per OEM recommendation and approved mix ratio.                                                  |                                                                              |
| 5                                                                                                                                                                   | Confirm that primer setting time conform with OEM recommendation                                                                                  |                                                                              |
| 6                                                                                                                                                                   | Check application of Self leveling screed (Eurocol 975) meets project requirement and OEM recommendation.                                         |                                                                              |
| 7                                                                                                                                                                   | Verify Surface smooth & level<br>-No cracks / pinholes / segregation                                                                              |                                                                              |
| 8                                                                                                                                                                   | Verify surface ready for floor finish installation                                                                                                |                                                                              |
| Legend: <b>A</b> - Accepted <b>UA</b> - Un Accepted <b>N/A</b> - Not Applicable                                                                                     |                                                                                                                                                   |                                                                              |
| <b>Remarks:</b>                                                                                                                                                     |                                                                                                                                                   | <b>INSPECTION NOTIFICATION REFERENCE</b><br><br>RFI No.<br><br>ISSUE DATE:   |
| <b>EVOMEK QA/QC</b>                                                                                                                                                 |                                                                                                                                                   | <b>COMPANY QC NLNG</b>                                                       |
| <b>NAME</b>                                                                                                                                                         |                                                                                                                                                   | <b>NAME</b>                                                                  |
| <b>SIGNATURE</b>                                                                                                                                                    |                                                                                                                                                   | <b>SIGNATURE</b>                                                             |
| <b>Date</b>                                                                                                                                                         |                                                                                                                                                   | <b>Date</b>                                                                  |

|                                                     |                                                                            |                                                                                       |
|-----------------------------------------------------|----------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                            |  |
| LOCATION: BONNY ISLAND, NIGERIA                     | AREA: RA                                                                   | PROJECT NO: <b>B250117ESD</b>                                                         |
| UNIT:<br>6500                                       | NIGERIA LNG LTD                                                            | PAGE 13 of 14                                                                         |
|                                                     | <b>INSPECTION AND TEST PLAN FOR RA FLOORING OF<br/>HOSPITAL AND SCHOOL</b> | DOC NO: N/A      Rev: A                                                               |
|                                                     |                                                                            | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |

|   | <b>REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL</b><br><br><b>INSPECTION REPORT OF LAYING OF FORBO VINYL SHEETS AND WELDING ACTIVITIES</b>     | Doc. no: EGSL-FORM- CIV-251-A<br>REV.      Date:<br>PAGE 1 of 1<br>REF. DOC: |                        |                                   |                |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|------------------------|-----------------------------------|----------------|
| <b>REPORT No:</b>                                                                                                                                                   |                                                                                                                                                       |                                                                              |                        |                                   |                |
| <b>PLACE:</b>                                                                                                                                                       |                                                                                                                                                       |                                                                              |                        |                                   |                |
| <b>DWG/CHART / SPECIFICATION:</b>                                                                                                                                   |                                                                                                                                                       |                                                                              |                        |                                   |                |
| <b>ITEM / EQUIPMENT / MATERIAL</b>                                                                                                                                  |                                                                                                                                                       |                                                                              |                        |                                   |                |
| <b>MEASURING DEVICE TYPE AND TRACEABILITY:</b>                                                                                                                      |                                                                                                                                                       |                                                                              |                        |                                   |                |
| S/No.                                                                                                                                                               | Description of QC Activities                                                                                                                          | INSPECTION RESULT & SIGNATURE/DATE                                           |                        |                                   |                |
|                                                                                                                                                                     |                                                                                                                                                       | EVOMEK QC                                                                    |                        | NLNG QC                           |                |
|                                                                                                                                                                     |                                                                                                                                                       | Result                                                                       | Signature/Date         | Result                            | Signature/Date |
| 1                                                                                                                                                                   | Confirm Surface approved for flooring (dry, dust free, clean, self levelling fully cured according to project spec and moisture content within limit) |                                                                              |                        |                                   |                |
| 2                                                                                                                                                                   | Check adhesive applied evenly.                                                                                                                        |                                                                              |                        |                                   |                |
| 3                                                                                                                                                                   | Check Sheets laid without bubbles; joint aligned properly.                                                                                            |                                                                              |                        |                                   |                |
| 4                                                                                                                                                                   | Check Heat welding completed according to project specification.                                                                                      |                                                                              |                        |                                   |                |
| 5                                                                                                                                                                   | Confirm that Excess adhesive cleaned (no surface stains)                                                                                              |                                                                              |                        |                                   |                |
| 6                                                                                                                                                                   | Check Surface free from wrinkles, No visible gaps at seams (Uniform appearance)                                                                       |                                                                              |                        |                                   |                |
| 7                                                                                                                                                                   | Verify final cleaning done                                                                                                                            |                                                                              |                        |                                   |                |
| Legend: <b>A</b> - Accepted <b>UA</b> - Un Accepted <b>N/A</b> - Not Applicable                                                                                     |                                                                                                                                                       |                                                                              |                        |                                   |                |
| <b>Remarks:</b>                                                                                                                                                     |                                                                                                                                                       |                                                                              |                        | INSPECTION NOTIFICATION REFERENCE |                |
|                                                                                                                                                                     |                                                                                                                                                       |                                                                              |                        | RFI No.                           |                |
|                                                                                                                                                                     |                                                                                                                                                       |                                                                              |                        | ISSUE DATE:                       |                |
| <b>EVOMEK QA/QC</b>                                                                                                                                                 |                                                                                                                                                       |                                                                              | <b>COMPANY QC NLNG</b> |                                   |                |
| <b>NAME</b>                                                                                                                                                         |                                                                                                                                                       |                                                                              | <b>NAME</b>            |                                   |                |
| <b>SIGNATURE</b>                                                                                                                                                    |                                                                                                                                                       |                                                                              | <b>SIGNATURE</b>       |                                   |                |
| <b>Date</b>                                                                                                                                                         |                                                                                                                                                       |                                                                              | <b>Date</b>            |                                   |                |

|                                                     |                                                                                           |          |                                                                                       |
|-----------------------------------------------------|-------------------------------------------------------------------------------------------|----------|---------------------------------------------------------------------------------------|
| REFURBISHMENT OF RA FLOORING OF HOSPITAL AND SCHOOL |                                                                                           |          |  |
| LOCATION: BONNY ISLAND, NIGERIA                     |                                                                                           | AREA: RA | PROJECT NO: <b>B250117ESD</b>                                                         |
| UNIT:<br>6500                                       | NIGERIA LNG LTD<br><b>INSPECTION AND TEST PLAN FOR RA FLOORING OF HOSPITAL AND SCHOOL</b> |          | PAGE 14 of 14                                                                         |
|                                                     |                                                                                           |          | DOC NO: N/A      Rev: A                                                               |
|                                                     |                                                                                           |          | CONTR. DOC NO: EGSL-NLNG-RRFHS-QA-ITP-5005                                            |