

INTERIOR PUNCH LIST							DATE:25/02/2026		
Location: GE Apartment 9 & 10							INSPECTION RESULT		
GENERAL PUNCH LIST FOR EVOMEK							CTR	COMPANY	
S/N	Issued by	Punch List Item Description	Dicipline	Issued Date	Close-out Date	P.L STATUS	Sign/Date	Sign/Date	REMARK
GE Apartment - 09									
1	NLNG	False ceiling painting in the bedroom is pending. Painting shall be carried out after completion of screeding works and adequate surface preparation.	CONSTRUCTION	25/02/2026					
2	NLNG	Switch cover for the bedroom switch is missing and shall be provided. Openings around the switch shall be properly filled, dressed, and painted in accordance with project specifications to achieve a neat and finished appearance.	CONSTRUCTION	25/02/2026					
3	NLNG	Bedroom door wooden frame is not properly lapped to the wall. Adjust and ensure the frame laps correctly and fits flush with the wall after door installation, in accordance with project specifications and approved finishing standards.	CONSTRUCTION	25/02/2026					
4	NLNG	Final wall painting finish is not satisfactory. Carry out final painting in accordance with approved project specifications, ensuring proper surface preparation, uniform coverage, and a smooth, defect-free finish.	CONSTRUCTION	25/02/2026					
5	NLNG	Material receiving inspection for DLS Paint (Green Beige RAL 100) was not conducted. Ensure material receiving inspection is carried out in accordance with approved QA/QC procedures and project specifications prior to application.	QUALITY	25/02/2026					
6	NLNG	Opening around strip light for low-profile lighting wall is not properly sealed. Seal all gaps neatly and securely to ensure proper finish, alignment, and compliance with project specifications.	CONSTRUCTION	25/02/2026					
7	NLNG	Towel rail in the main bathroom is loose. Tighten and secure properly to ensure firm fixing and compliance with project specifications	CONSTRUCTION	25/02/2026					
8	NLNG		CONSTRUCTION	25/02/2026					
9	NLNG		CONSTRUCTION	25/02/2026					
10	NLNG	Kitchen countertop skirting is not installed. Install skirting as per approved drawings and project specifications. Broken edges of the countertop shall be properly dressed, cleaned, and sealed to achieve a neat finish and prevent moisture penetration	CONSTRUCTION	25/02/2026					
11	NLNG	Wall edge screeding and leveling are incomplete. Carry out proper screeding and leveling to achieve straight and even alignment	CONSTRUCTION	25/02/2026					
12	NLNG	Gaps and edges of main bathroom tiles are not properly finished. Seal and finish neatly to ensure water tightness and compliance with project specifications	CONSTRUCTION	25/02/2026					
GE Apartment - 10									
1	NLNG	Gaps and edges of visitors bathroom tiles are not properly finished. Seal and finish neatly to ensure water tightness and compliance with project specifications	CONSTRUCTION	25/02/2026					
2	NLNG	Bedroom -Opening around strip light for low-profile lighting wall is not properly sealed. Seal all gaps neatly and securely to ensure proper finish, alignment, and compliance with project specifications.	CONSTRUCTION	25/02/2026					
3	NLNG	Remove dust, debris, and construction residues from window frames and glass surfaces	CONSTRUCTION	25/02/2026					
4	NLNG	Tag all existing switches for identification, relocate the TV switch downward to the desired position, and move the light switch to the previous TV switch location, ensuring proper mounting, alignment, and full functional verification.	CONSTRUCTION	25/02/2026					
PREPARED AND AGREED BY						FINAL CLOSE-OUT			
CTR/SIGN (QA/AC): KPAKUE FORTUNE			CTR/SIGN (CONSTRUCTION):			CTR/SIGN:		NLNG/SIGN:	
Signed by:  348149CE7BF5412...									