

ROAD DAMAGE INTELLIGENCE

Contractor Repair Report

Report ID	REPORT-TICKET-001	Ticket ID	TICKET-001
Status	Completed	Severity	Medium

1. Contractor & Location

Contractor	Someash Thirunavukkarasu
Contractor ID	pKhOouMr3BWom3oTLOWHO18tLgu1
Area	Velachery
Latitude	12.9758
Longitude	80.2205

2. Pothole Details

Severity	Medium
Length	51 cm
Width	42 cm
Depth	7.8 cm
Estimated Volume	30 L


3. Repair Timeline

Ticket Raised	03 Oct 2026, 10:30:00 AM UTC
Repair Started	04 Oct 2026, 03:32:29 AM UTC
Repair Completed	04 Oct 2026, 03:32:29 AM UTC
Response Time	17h 2m 29s
Repair Duration	0s
Total Resolution	17h 2m 29s

4. Repair Description

Road damage repaired and surface restored.

5. Before & After Repair Images



Before Filling



After Filling / Repaired

The report documents the pothole condition before filling and the repaired road surface after filling.