| | | | | |
|---|---|---|---|---|
| | PT IAS SUPPORT INDONESIA | DATE | : | 16-Jul-25 |
| | CHECK LIST PREVENTIVE MAINTANANCE<br>MECHANICAL ELECTRICAL | | | |
| | SITE INFORMATION | | | |

## Preventive Maintenance Report

Periode Jul-25

**APSD Site ID** :

**APSD Site Name** : Bandara Kualanamu Pole 2

**Region** : Sumbagut

**Province** : Sumatra Utara

**City** : Medan

**Address** : Jl. Bandara Kuala Namu, Ps. Enam Kuala Namu, Kec. Beringin, Kabupaten Deli Serdang, Sumatera Utara 20553

**Longitude** : 98.861139

**Latitude** : 3.618278

**Site Height** : 18

**Tower Type** : Pole PJU 18 m

**Site Type** : Green Field

**Anchor Tenant** : APSD

**Total Tenant** : 1

**Tenant List** :

| No. | Tenant | Equipment Type | Sisa Token | Power Source |
|---|---|---|---|---|
| 1 | | | | |
| 2 | | | | |
| 3 | | | | |
| 4 | | | | |
| dst | | | | |
| | | | | |

**OM Vendor Name** : PT. Naer Tunas Indonesia

| | PT IAS SUPPORT INDONESIA | DATE | : | 16-Jul-25 |
|---|---|---|---|---|
| | CHECK LIST PREVENTIVE MAINTANANCE<br>MECHANICAL ELECTRICAL | | | |
| | SITE INFORMATION | | | |

| | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **APSD Site ID** | : | 0 | | | | | | |
| **APSD Site Name** | : | Bandara Kualanamu Pole 2 | | | | | | |
| **Date** | : | 16/07/2025 | | | | | | |
| **Time** | : | 10.25 | | | | | (WIB)/WITA/WIT | |
| **PIC Field Name** | : | Hamdani | | | | | | |
| **PIC Field Number** | : | | | | | | | |
| **GROUNDING** | | | | | | | | |
| **Grounding Measurment** | : | | | | | Ohm | (< 1 Ohm) | |
| **Grounding Control Box** | : | 0.24 | | | | Ohm | (< 1 Ohm) | |
| **Tower Leg** | : | 0.26 | | | | Ohm | (< 1 Ohm) | |
| **Fence** | : | 0 | | | | Ohm | (< 1 Ohm) | |
| **Grounding EGB** | : | 0.20 | | | | Ohm | (< 1 Ohm) | |
| **Grounding Status** | : | | | | | | | |
| **Lightening Rod** | : | (OK) | NOK | N/A | Remaks | : | ( uncompleted condition / stolen / broken / worse connection ) | |
| **Bar Grounding Tower** | : | (OK) | NOK | N/A | Remaks | : | ( uncompleted condition / stolen / broken / worse connection ) | |
| **Bar Grounding Control Box** | : | (OK) | NOK | N/A | Remaks | : | ( uncompleted condition / stolen / broken / worse connection ) | |
| **Down Conductor Cable** | : | (OK) | NOK | N/A | Remaks | : | ( uncompleted condition / stolen / broken / worse connection ) | |
| **Bolt Connection** | : | (OK) | NOK | N/A | Remaks | : | ( uncompleted condition / stolen / broken / worse connection ) | |
| **TOWER** | | | | | | | | |
| **Tower Type** | : | SST | | Monopole | | Triangle | (Pole) | Mini Tower |
| **Painting Condition** | : | OK | NOK | (N/A) | Remaks | : | ( tower loosen paint 70 % ), ..... | |
| **Contruction Condition** | : | (OK) | NOK | | Remaks | : | ( paving down / tower leg cracked), ..... | |
| **Tower Cleaning** | : | (OK) | NOK | | Remaks | : | ( cleaning from spider nest/bee/etc ), ..... | |
| **Tower Lamp/OBL** | : | OK | NOK | (N/A) | Remaks | : | ( broken, cracked, unshielded), ..... | |
| **Photo Sensor** | : | (OK) | NOK | N/A | Remaks | : | ( broken, cracked, unshielded), ..... | |
| **Tower Verticality** | : | (OK) | NOK | N/A | | | | |
| **Pole Sticker** | : | OK | NOK | (N/A) | | | | |
| **Baseplate Leg Painting** | : | OK | NOK | (N/A) | | | | |
| **LIGHTING** | | | | | | | | |
| **Tower Lamp(OBL) Amount** | : | 0 | Unit | | | | | |
| **Yard Lamp Amount (Mercury/TL)** | : | 1 | Unit | | | | | |
| **Tower Lamp(OBL) Condition** | : | OK | NOK | (N/A) | Remaks | : | ( broken, cracked, unshielded), ..... | |
| **Site Photo Sensor** | : | OK | NOK | (N/A) | Remaks | : | ( sensor respon checking), ..... | |
| **Yard Lamp Shield** | : | (OK) | NOK | N/A | Remaks | : | (lamp shield checking broken / no ), ..... | |
| **FENCE** | | | | | | | | |
| **Fence Condition** | : | OK | NOK | (N/A) | Remaks | : | ( collapsed, broken ), ..... | |
| **Site Cleaning** | : | (OK) | NOK | | Remaks | : | ( cleaning from grass/garbage ), ..... | |
| **Paving Block/Gravel** | : | (OK) | NOK | | Remaks | : | ..... | |
| **Barbared Wire** | : | OK | NOK | (N/A) | Remaks | : | ..... | |
| **Fance Door** | : | OK | NOK | (N/A) | Remaks | : | ..... | |
| **OTHER** | | | | | | | | |
| **Safety Sign Board** | : | OK | NOK | (N/A) | Remaks | : | ( uninstalled, undetected ), ..... | |
| **Warning Sign Board** | : | OK | NOK | (N/A) | Remaks | : | ( uninstalled, undetected ), ..... | |
| **Combination Lock/Padlock** | : | (OK) | NOK | N/A | Remaks | : | ( uninstalled, undetected ), ..... | |
| **Site Keeper Status** | : | OK | NOK | (N/A) | | | | |
| **Notification Sticker** | : | OK | NOK | (N/A) | | | | |

| | | | | |
|---|---|---|---|---|
| SUPPORT | PT IAS SUPPORT INDONESIA | DATE | : | 16-Jul-25 |
| | CHECK LIST PREVENTIVE MAINTANANCE<br>MECHANICAL ELECTRICAL | | | |
| | BASE SERVICE | | | |

| | | |
|---|---|---|
| **APSD Site ID** | : | 0 |
| **APSD Site Name** | : | Bandara Kualanamu Pole 2 |
| **Date** | : | 16-Jul-25 |
| **Time** | : | 10.25 (WIB)/WITA/WIT |
| **PIC Field Name** | : | Hamdani |
| **PIC Field Number** | : | |

**OTHER**

| | | | | |
|---|---|---|---|---|
| **MEMBERS COMPLETENESS** | : (Complate/lengkap) | Not complate/tidak lengkap | At elevation/pada ketinggian ..... Meter | |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |
| **TOWER CORROSION/KOROSI PADA TOWER** | : (No) | Yes,minor | Yes,major | |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |
| **TOWER ALIGMENT/KETEGAKAN TOWER** | : (Align and vertical/simetris & tegak lurus) | | Not Align & not vertical/tidak tegak lurus | |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |
| **PEDESTAL & BASEPLATE CONDITION/KONDISI PONDASI & BASEPLATE** | : (Good/bagus) | Cracked/retak | Corrosion/Baseplate berkarat | |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |
| **SOIL & GRAVEL CONDITION INSIDE & AROUND SITE AREA/KONDISI TANAH DI DALAM & DI LUAR AREA** | : (Normal) | Landslide/penurunan | Flooded/tergenang | Washed away/tergerus |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |
| **BUILDING EXISTING CONDITION/KONDISI BANGUNAN EXISTING** | : Normal | Cracked/retak | Leakage/Bocor | Other/lainya : (Site GF) |
| Need future investigation/butuh investigasi lebih lanjut ? | : Yes | (No) | Remaks/Keterangan | |

Other Information :

| PT.NAER |
|---|
| **INSPECTION BY** |
| |
| (HAMDHANI) |

| | PT IAS SUPPORT INDONESIA | DATE | : | 16-Jul-25 |
|---|---|---|---|---|
| SUPPORT | CHECK LIST PREVENTIVE MAINTANANCE MECHANICAL ELECTRICAL | | | |
| | TENANT | | | |

| | | | |
|---|---|---|---|
| **APSD Site ID** | : 0 | **Date** | : 16-Jul-25 |
| **APSD Site Name** | : Bandara Kualanamu Pole 2 | **Time** | : 10.25 (WIB)/WITA/WIT |
| | | **Operator** | : APSD |

## AIR CONDITIONER

**Equipment type** : Indoor (Outdoor) AC Amount : Unit

| Measurment | Remaks | AC # 1 | AC # 2 | AC # 3 | AC # 4 |
|---|---|---|---|---|---|
| Broken AC | Ac Status | Yes No | Yes No | Yes No | Yes No |
| AC merek | Brand name | ..... | ..... | ..... | ..... |
| AC Type | Type | Inverter Non inverter | Inverter Non inverter | Inverter Non inverter | Inverter Non inverter |
| S/N Outdoor | | ..... | ..... | ..... | ..... |
| S/N Indoor | | ..... | ..... | ..... | ..... |
| Power | PK | ..... | ..... | ..... | ..... |
| Current Max | Maksimal ampare | ..... | ..... | ..... | ..... |
| Pressure | Psi | ..... | ..... | ..... | ..... |
| Current Measurment | Ampare | ..... | ..... | ..... | ..... |
| AC Outdoor Condition | Leak/not leak | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| AC Indoor Condition | Leak/not leak | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| Pipe Condition | Leak/not leak | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| Auto Restart | Operation | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| Switch Contactor | Test switch | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| Ac Temperatur Setting | < 24 C | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |
| Room Temperator | ..... C | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) | OK NOK (N/A) |

## EXHAUST FAN

**Exhaust fan condition** : OK NOK (N/A) Exhaust fan cleaning : OK NOK (N/A)

## SHALTER

| | | | | | | |
|---|---|---|---|---|---|---|
| Shalter roof | : | OK NOK | (N/A) | Remaks | : | ( leak, broken), ..... |
| Wall shalter | : | OK NOK | (N/A) | Remaks | : | ( cracked, leak, broken), ..... |
| Fence condition | : | OK NOK | (N/A) | Remaks | : | ( collapsed, broken), ..... |
| Room cleaning | : | OK NOK | Leak | Remaks | : | ..... |
| Roof cleaning | : | OK NOK | Leak | Remaks | : | ..... |
| Fire extinguisher | : | OK NOK | (N/A) | Remaks | : | ( expired/not expired), ..... |
| Door hinge lubrication | : | OK NOK | (N/A) | Remaks | : | ..... |
| Shalter foundation | : | OK NOK | (N/A) | Remaks | : | ..... |

## ALARM SYSTEM

| | | | | | | |
|---|---|---|---|---|---|---|
| Heat detector | : | OK NOK | (N/A) | Remaks | : | ( uninstalled, undetected ), ..... |
| Smoke detector | : | OK NOK | (N/A) | Remaks | : | ( uninstalled, undetected ), ..... |
| Ring bell | : | OK NOK | (N/A) | Remaks | : | ( uninstalled, undetected ), ..... |

## GROUNDING

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Grounding status | | : (OK) | NOK | N/A | Remaks | : | ( broken, stolen, wors conection, ), ..... |
| Measurment | Control box | : (OK) | NOK | N/A | | Ohm | ( < 1 Ohm) |
| | External grounding bar | : (OK) | NOK | N/A | | Ohm | ( < 1 Ohm) |
| | Internal groundig bar | : OK | NOK | (N/A) | | Ohm | ( < 1 Ohm) |

## KWH ELECTRICAL MEASURMENT

| | | | | | | |
|---|---|---|---|---|---|---|
| Phase voltage R-N (200 V - 240 V) | : | 0 | 220 V +/- 5% max 10 V | Phase voltage R-T (200 V - 240 V) | : | 0 380 V +/- 5% max 10 V |
| Phase voltage S-N (200 V - 240 V) | : | 0 | 220 V +/- 5% max 10 V | Phase voltage S-T (200 V - 240 V) | : | 0 380 V +/- 5% max 10 V |
| Phase voltage T-N (200 V - 240 V) | : | 0 | 220 V +/- 5% max 10 V | Phase voltage N-G (< 5V) | : | 0 |
| Phase voltage R-S (200 V - 240 V) | : | 0 | 380 V +/- 5% max 10 V | KWH Meter Record | : | 0 kWh |

## PLN VISUAL CHECK

| | | | | | | |
|---|---|---|---|---|---|---|
| PLN power supplied | : | | kVA | ..... Phase | | |
| MCB input | : | | | | | |
| MCB Condition | : | (OK) | NOK | N/A | | |
| 1 Phase | : | | A | ..... Pcs | | |
| 3 Phase | : | | A | ..... Pcs | | |
| COS | : | | A | | | |

## PERMANENT GENSET (if any)

| | | | | |
|---|---|---|---|---|
| Phisyc condition | : | OK NOK (N/A) | Remaks : | |
| Fuel tank condition | : | OK NOK (N/A) | Remaks : | (no leak,spill & corrosion) |
| Secondary containment | : | OK NOK (N/A) | Remaks : | |
| Hazardous sign (flamable sign and no smoking sign) | : | OK NOK (N/A) | Remaks : | |
| Genset pad | : | OK NOK (N/A) | Remaks : | |
| Genset safety/cage/house (if any) | : | OK NOK (N/A) | Remaks : | |

| | PT IAS SUPPORT INDONESIA | DATE | : | 16-Jul-25 |
|---|---|---|---|---|
| SUPPORT | CHECK LIST PREVENTIVE MAINTANANCE<br>MECHANICAL ELECTRICAL | | | |
| | TENANT | | | |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| APSD Site ID | : | 0 | | | Date | : | 16-Jul-25 | | |
| APSD Site Name | : | Bandara Kualanamu Pole 2 | | | Time | : | 10.25 | (WIB)/WITA/WIT | |
| | | | | | Operator | : | APSD | | |
| PLN ID | : | | | | Spill kit (sawdust) | : | OK | NOK | (N/A) |
| Seal | | | | | Locked genset | : | OK | NOK | (N/A) |
| KWH record | : | (OK) | NOK | N/A | MSDS fuel genset and oil | : | OK | NOK | (N/A) |
| Terminal/OKA | : | (OK) | NOK | N/A | if there is re-fuelling process, generator vendor employee user personnel equipment : OK NOK N/A Remaks : | | | | |
| MCB | : | (OK) | NOK | N/A | Generator anchored to foundation : | | OK | NOK | (N/A) Remaks : |
| Trafo | : | (OK) | NOK | N/A | (if trafo broken/has been shared with community/othe operator) | | | | |

**PLN FUNCTION TEST**

| | | | | | |
|---|---|---|---|---|---|
| MCB in the KWH 'ON' Position | | | | | |
| A. Current flows to the MCCB for devices | : | (OK) | NOK | N/A | ( Current measurement result = visual check ), ..... |
| B. R,S, & T indicator lamps are lit | : | OK | NOK | (N/A) | |
| MCB for devices to ' ON Position' | : | (OK) | NOK | N/A | ( MCB in position ), ..... |
| KWH meter spin normally | : | (OK) | NOK | N/A | ( Spin normally ) ..... |

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |




| Foto A-1 |
|---|
| Site condition |




| Foto A-2 |
|---|
| Tampak akses |




| Foto A-3 |
|---|
| Tampak halaman site (Before Cleaning) |




| Foto A-4 |
|---|
| Tampak halaman site (After Cleaning) |

N/A

| Foto A-5 |
|---|
| Name Plate |




| Foto A-6 |
|---|
| Tampak Pedestal/Kaki tower |

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |




| Foto B-1 |
|---|
| Status grounding - Splitzen |

N/A

| Foto B-2 |
|---|
| Status grounding - Bolt connection |

N/A

| Foto B-3 |
|---|
| OBL |

N/A

| Foto B-4 |
|---|
| Yard lamp |

N/A

| Foto B-5 |
|---|
| Pengukuran grounding - Fance/Pagar |




| Foto B-6 | |
|---|---|
| Pengukuran grounding - Pedestal | 0.26 |

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |

N/A

Foto C-1

Pengukuran grounding - Box control

N/A

Foto C-2

Tampak kebocoran site (rooftop only)




Foto C-3

Tower view A-B




Foto C-4

Tower view B-C




Foto C-5

Tower view C-D




Foto C-6

Tower view D-A

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |




| Foto D-1 |
|---|
| Tower view - From bottom to top 1 |




| Foto D-2 |
|---|
| Tower view - From bottom to top 2 |




| Foto D-3 |
|---|
| Tower view - From bottom to top 3 |




| Foto D-4 |
|---|
| Tower view - From top to bottom 1 |




| Foto D-5 |
|---|
| Tower view - From top to bottom 2 |




| Foto D-6 |
|---|
| Tower view - From top to bottom 3 |

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |

| | |
|---|---|
| N/A | N/A |
| Foto E-1<br>Site view - Panoramic 0 | Foto E-2<br>Site view - Panoramic 30 |
| N/A | N/A |
| Foto E-3<br>Site view - Panoramic 60 | Foto E-4<br>Site view - Panoramic 90 |
| N/A | N/A |
| Foto E-5<br>Site view - Panoramic 120 | Foto E-6<br>Site view - Panoramic 150 |

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |

N/A

Foto F-1

Site view - Panoramic 180

N/A

Foto F-2

Site view - Panoramic 210

N/A

Foto F-3

Site view - Panoramic 240

N/A

Foto F-4

Site view - Panoramic 270

N/A

Foto F-5

Site view - Panoramic 300

N/A

Foto F-6

Stiker notification di rumah site keeper (if any)

PT IAS SUPPORT INDONESIA

CHECK LIST PREVENTIVE MAINTANANCE

MECHANICAL ELECTRICAL

BASE SERVICE

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |




| Foto G-1 |
|---|
| Tower segment 1 |




| Foto G-2 |
|---|
| Tower segment 2 |




| Foto G-3 |
|---|
| Tower segment 3 |




| Foto G-4 |
|---|
| Tower segment 4 |




| Foto G-5 |
|---|
| Tower corrosion |




| Foto G-6 |
|---|
| Tower corrosion |

**PT IAS SUPPORT INDONESIA**

**CHECK LIST PREVENTIVE MAINTANANCE**

**MECHANICAL ELECTRICAL**

**BASE SERVICE**

| | | | | | |
|---|---|---|---|---|---|
| APSD Site ID | : APSD-DSER-078-08 | Date | : | 16-Jul-25 | |
| APSD Site Name | : Bandara Kualanamu Pole 2 | Time | : | 10.25 | (WIB)/WITA/WIT |
| | | Operator | : | APSD | |




| Foto H-1 |
|---|
| Pedestal & baseplate condition |




| Foto H-2 |
|---|
| Pedestal & baseplate condition |




| Foto H-3 |
|---|
| Soil & gravel condition |




| Foto H-4 |
|---|
| Soil & gravel condition |




| Foto H-5 |
|---|
| Foto Safety |

N/A

| Foto H-6 |
|---|
| Building existing condition |