









		<div><div> ghaziabad</div><div>RTO</div></div>	<div><div> UP14CL0424</div><div>Registration No</div></div>
		<div><div> 2024-07</div><div>Manufacturing Year</div></div>	<div><div> 2024-08-22</div><div>Registration Date</div></div>
		<div><div> 1</div><div>No of Owners</div></div>	<div><div> 42000</div><div>Odometer Reading</div></div>
		<div><div> Petrol</div><div>Fuel Type</div></div>	<div><div> Petrol</div><div>Transmission</div></div>
		<div><div> red</div><div>Color</div></div>	<div><div> SUV</div><div>Vehicle Type</div></div>
<div>NA</div> <div>Engine Number (last Five)</div>	<div>11096</div> <div>Chassis Number (Last Five)</div>	<div>Customer Name</div> <div>Customer Name</div>	<div>Yes</div> <div>Original RC Availabl</div>
<div>2024-08-20</div> <div>Fitness Expire Date</div>	<div>2024-08-20</div> <div>Tax Expire Date</div>	<div>2024-08-20</div> <div>Insurance Expire Date</div>	<div>2024-08-20</div> <div>Permit Expire Date</div>
<div>Nitin Singh</div> <div>Executive Name</div>	<div>prakash chobey, Tinsukia, 786171, Indi</div> <div>Location</div>		

Summary		Overall Score 9 /10	
<div>Exterior Detail</div> <div><div></div><div>9/10</div></div>	<div>Interior Detail</div> <div><div></div><div>9/10</div></div>	<div>Exterior Detail</div> <div><div></div><div>9/10</div></div>	<div>Interior Detail</div> <div><div></div><div>9/10</div></div>
<div>Remarks</div>			



Profile Picture



Profile Picture



Profile Picture



Profile Picture



Profile Picture



Profile Picture

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (04/06/2024) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary