

		<div>📍 ghaziabad</div> <div>RTO</div>		<div>UP14CL0424</div> <div>Registration No</div>			
		<div>2024-07</div> <div>Manufacturing Year</div>		<div>2024-08-22</div> <div>Registration Date</div>			
		<div>1</div> <div>No of Owners</div>		<div>42000</div> <div>Odometer Reading</div>			
		<div>Petrol</div> <div>Fuel Type</div>		<div>Petrol</div> <div>Transmission</div>			
		<div>red</div> <div>Color</div>		<div>SUV</div> <div>Vehicle Type</div>			
		<div>NA</div> <div>Engine Number (last Five)</div>		<div>11096</div> <div>Chassis Number (Last Five)</div>		<div>Customer Name</div> <div>Customer Name</div>	
<div>2024-08-20</div> <div>Fitness Expire Date</div>		<div>2024-08-20</div> <div>Tax Expire Date</div>		<div>2024-08-20</div> <div>Insurance Expire Date</div>			
<div>2024-08-20</div> <div>Permit Expire Date</div>		<div>Nitin Singh</div> <div>Executive Name</div>		<div>prakash chobey, Tinsukia, 786171, Indi</div> <div>Location</div>			
Summary				Overall Score 9 /10			
<div>Exterior Detail</div> <div><div></div><div>9/10</div></div>				<div>Interior Detail</div> <div><div></div><div>9/10</div></div>			
<div>Exterior Detail</div> <div><div></div><div>9/10</div></div>				<div>Interior Detail</div> <div><div></div><div>9/10</div></div>			
Remarks							



**Profile Picture**



**Profile Picture**



**Profile Picture**



**Profile Picture**



**Profile Picture**



**Profile Picture**

**Disclaimer:** This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (04/06/2024) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

**Note:** To check the genuinity of condition report please scan the QR code on 1st page of report.

# The odometer reading is at the time of inspection of car, actual odometer reading might vary