

Summary Report for Sub Contractor

Project Name : Zano

IssueTo Name : MPA Painting (Carlo)

Date : 20/10/2015




Inspections : 11







Page : 1 of 3



Report Filtered by :

Location Name: Building **Sub Location:** Level 01

Status: Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 2447022	Defect	Building > Level 01 > Common Areas > Lobby > Lift Lobby	Wall paper coming off joint	gromagnino	17/09/15	Builder	2015-09-19	Open				
1245144 2188986	Defect	Building > Level 01 > Apartments > 102 > Balcony	Missing paint	gromagnino	14/09/15	Builder	2015-09-16	Open				
1245144 2187728	Defect	Building > Level 01 > Apartments > 106 > Balcony	Missing paint	gromagnino	14/09/15	Builder	2015-09-16	Open				

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 2186125	Defect	Building > Level 01 > Apartments > 110 > Balcony	Paint - Incomplete	gromagnino	14/09/15	Builder	2015-09-16	Open				
1245144 2187254	Defect	Building > Level 01 > Apartments > 107 > Balcony	Paint missing and caulk	tstrachan	14/09/15	Builder	2015-09-16	Open				
1245144 2187680	Defect	Building > Level 01 > Apartments > 106	Paint missing	gromagnino	14/09/15	Builder	2015-09-16	Open				
1245144 2188521	Defect	Building > Level 01 > Apartments > 104 > Balcony	Clean paint off pipe	tstrachan	14/09/15	Builder	2015-09-16	Open				
1245144 2187075	Defect	Building > Level 01 > Apartments > 108 > Balcony	Paint - Re-Paint	gromagnino	14/09/15	Builder	2015-09-16	Open				

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 2186307	Defect	Building > Level 01 > Apartments > 110 > Balcony	Paint - Incomplete	gromagnino	14/09/15	Builder	2015-09-16	Open				
1245144 2186478	Defect	Building > Level 01 > Apartments > 109 > Balcony	Paint missing and next to down pipe	tstrachan	14/09/15	Builder	2015-09-16	Open				
1310143 7627776	Defect	Building > Level 01 > Apartments > 104 > Balcony	Paint - Remove Paint from condenser unit / on wall facing side of unit	tstrachan	23/07/15	Builder	2015-07-31	Open	