

Summary Report for Sub Contractor

Project Name : Zano

IssueTo Name : Finadri Windows (John Wighton)

Date : 20/10/2015



Inspections : 3

Page : 1 of 1

Report Filtered by :

Location Name: Building **Sub Location:** Level 01

Status: Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 1935988	Defect	Building > Level 01 > Apartments > 113 > Bedroom 01	Visible screw	nimaih	11/09/15	Superintendent	2015-09-21	Open				
1245144 1936157	Defect	Building > Level 01 > Apartments > 113 > Bedroom 02	Visible screw	nimaih	11/09/15	Superintendent	2015-09-21	Open				
1245144 1934313	Defect	Building > Level 01 > Apartments > 110 > Bedroom 02	Visible screws	tstrachan	11/09/15	Superintendent	2015-09-21	Open	