

Summary Report for Sub Contractor

Project Name : Zano

IssueTo Name : Aardvark (Kevan)

Date : 20/10/2015



Inspections : 2

Page : 1 of 1

Report Filtered by :

Location Name: Building **Sub Location:** Level 01

Status: Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
12451439 936927	Incomplete Works	Building > Level 01 > Apartments > 104 > Balcony	Fitting off light correctly	tstrachan	19/08/15	Builder	2015-08-22	Open				
12451437 531302	Defect	Building > Level 01 > Apartments > 103 > Balcony	External light not install correctly	wfarrugia	22/07/15	Builder	2015-07-25	Open	