

Summary Report for Sub Contractor

Project Name: Zano

IssueTo Name: ABD Group (Chris Baker)

Date: 20/10/2015 **Inspections**: 3 **Page**: 1 of 1

Report Filtered by:

Location Name: Building Sub Location: Level 01

Status: Open

ID	Inspection	Location	Description	Inspected	Date	Raised	Fix By	Status	Image 1	Image 2	Drawing	Sign Off
	Type			By	Raised	By	Date					
1004142	Incomplete	Building >	Concrete - patching	jderbyshir	17/03/1	Builder	2015-03	Open			ROTE IN CHILD HUNG TO S	
6550587	Works	Level 01 >	required	e	5		-17					
		Common									17.7	
		Areas >									t f t t t	
		Passage							W125			
1245144	Defect	Building >	Mark on joinery	nimaih	11/09/1	Superin	2015 00	Onon	Prompts State and State an			
	Defect		wiark on joinery	Шшаш		1 -	l	Open	The same of the sa			
1935148		Level 01 >			5	tendant	-21					
		Apartments >										
		112 > Laundry										
1245144	Defect	Building >	Make good joinery	tstrachan	11/09/1	Superin	2015-09	Open				
1927994		Level 01 >			5	tendant	-21					
		Apartments >										
		102 > Laundry										

