

Summary Report for Sub Contractor

Project Name : Zano

IssueTo Name : Vapa Specialist Cleaners (Tony Hoang)

Date : 20/10/2015






Inspections : 8





Page : 1 of 2

Report Filtered by :

Location Name: Building **Sub Location:** Level 01

Status: Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245143 7793651	Defect	Building > Level 01 > Apartments > 110 > Balcony	Remove marks on concrete	wfarrugia	25/07/15	Builder	2015-08-01	Open				
1245144 1935465	Defect	Building > Level 01 > Apartments > 112 > Living	Clean	nimaih	11/09/15	Superintendent	2015-09-21	Open				
1245144 1934253	Defect	Building > Level 01 > Apartments > 110 > Bedroom 02	Clean	nimaih	11/09/15	Superintendent	2015-09-21	Open				

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1245144 1932453	Defect	Building > Level 01 > Apartments > 108 > Balcony	clean precast	nimaih	11/09/15	Superintendent	2015-09-21	Open				
1245144 1930753	Defect	Building > Level 01 > Apartments > 104 > Bedroom 01	Clean	nimaih	11/09/15	Superintendent	2015-09-21	Open				
1245144 1929769	Defect	Building > Level 01 > Apartments > 103 > Bath	Clean angle	tstrachan	11/09/15	Superintendent	2015-09-21	Open				
1245144 0392190	Defect	Building > Level 01 > Apartments > 101 > Bath	Clean left side of mirror	gromagnino	24/08/15	Builder	2015-09-03	Open				
1245144 0393025	Defect	Building > Level 01 > Apartments > 101 > Bath	Cleaning - Incomplete in whole of bathroom paint spots and grout still on tiled walls	gromagnino	24/08/15	Builder	2015-08-24	Open	