

## Summary Report for Sub Contractor

**Project Name :** Zano

**IssueTo Name :** Omnifloor Pty Ltd (Greg Simon)

**Date :** 20/10/2015



**Inspections :** 2

**Page :** 1 of 1

**Report Filtered by :**

**Location Name:** Building      **Sub Location:** Level 01

**Status:** Open

ID	Inspection Type	Location	Description	Inspected By	Date Raised	Raised By	Fix By Date	Status	Image 1	Image 2	Drawing	Sign Off
1310143 7627252	Defect	Building > Level 01 > Apartments > 104 > Kitchen	Timber floor boards cut short - too big of a gap to caulk	vincec	23/07/15	Builder	2015-07-31	Open				
1245144 1930214	Defect	Building > Level 01 > Apartments > 104 > Kitchen	Floorboards finish short of island bench	nimaih	11/09/15	Superintendent	2015-09-21	Open	